



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019567/Ktd3e2

73 BRAS BASAH ROAD

Date: 13-04-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 8146G	Veh. Inspected	SMK 7021G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1067921-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	05/11/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT SCENIC (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VF1RFA00662476759	Colour	METALLIC BLUE
Odometer	46936 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	GOODYEAR	8 mm
L/H Front Tyre	195/55 R20	GOODYEAR	8 mm
R/H Rear Tyre	195/55 R20	GOODYEAR	8 mm
L/H Rear Tyre	195/55 R20	GOODYEAR	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2019	Inspect Date / Time	05/11/2019 (11:36 AM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------