

ASS. REC. BY:

REF:

CS/INC19019567/Ktd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hazakysa B Ibrahim

of

INC

Date/Time:

10:01am @ 5/11/19

Estimated Cost:

Bill to:

OD ☒ TP WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 7021G

Insured:

SJU 8146G

at Workshop m/s

Thiam Heng Huet

Tel:

8263 6295

of

176 Sm Ming Drive #05-14

Policy No:

Claim No:

MT/1067921-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/10/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 11:17am @ 5/11/19

Person Contacted:

Steven

H.O.D. Endorsement:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction
	Estimate <input checked="" type="checkbox"/> SMK 7021G-X
	11/11/19 8:45oc email

ASS. REC. BY:

REF:

INC1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smk 70216

Yr Regn:

04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Peric

C.G

1461

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

46936

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIRFA 0066 2476759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/10/19

D.O.I.

5/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to
GIA & EM not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

F.M.P.S

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Wednesday, 6 November 2019 9:13 AM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: FW: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

RE-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 5 November 2019 10:49 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear Hazalya,

Thank you for the assignment.

Please be informed that SJN6248X (HUI YANG MOTOR) the vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]

Sent: Tuesday, 5 November 2019 10:01 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 05/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	David Phua	MT/1069328-002	SMA1928H	AUTOMOTIVE REPAIR CENTRE PTE. LTD.	38 WOODLANDS INDUSTRIAL PARK E1 #05-18 SINGAPORE 757700	Lin Shu Juan / 6468 8834	10:00-16:00	SJX695A	30/10/19	
2	Eric Tang	MT/1069802-002	SMG3831H	JWG INTERNATIONAL PTE. LTD	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT	/ 6909 8882		SHB8335R	04/11/19	

3	Fiona Shen	MT/1069712-002	SMJ97895	JWG INTERNATIONAL PTE. LTD	SINGAPORE 568047 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047	/ 6909 8882	SH2763B	02/11/19		
4	Jared Liu	MT/1068817-002	PC81K	SERVE YOU MOTOR SERVICE	BLK 5033 #01-265 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536	Elaine Chia / 9239 3188	SIG7545T	22/10/19		
5	David Phua	MT/1069721-002	SDE2368C	SMRT AUTOMOTIVE SERVICES PTE LTD	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Peh Eng Hock / 88583566	SKG8799J	02/11/19	68662673 (88583566) or 65555556 (Esther)	
6	Fiona Shen	MT/1065847-003	SJG6248X	HUI YANG MOTOR SERVICE	176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721	Bel / 64515752	SIV4202Z	05/10/19		
7	Charlotte Chew	MT/1067762-002	SLV3347Y	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295	SHC6277T	20/10/19		
8	Helena Tan	MT/1067921-002	SMK7021G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295	SIU8146G	22/10/19		
9	Chryllis Quah	MT/1069704-002	SLO5075U	TTS EUROCARS PTE LTD	383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717	Ms.Kavi / 97637000	SLC2471C	02/11/19		

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim

Admin Assistant

Motor Department

T +65 6430 7902

www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Thiam Heng Huat Pte Ltd

Mobile: 82636295 Email: thiamhenghuat@gmail.com

VRN: SMK7021G



NOT Authorized
- 61 Sup B 4500k
Returning After Pcing
4 days

List items					
S/N	Parts description		QTY	UNIT PRICE	AMOUNT
1	Tailgate		R 1	\$ 2,171.00	\$ 2,171.00
2	Tailgate hinge		R 2	\$ 187.00	\$ 374.00
3	Tailgate damper		Sm 2	\$ 195.00	\$ 390.00
4	Tailgate outer cover		Red Cam 1	\$ 688.00	\$ 688.00
5	Tailgate outer cover centre logo		na 1	\$ 194.00	\$ 194.00
6	Tailgate outer cover "Scenic" emblem		na 1	\$ 165.00	\$ 165.00
7	Tailgate "Renault" emblem		na 1	\$ 162.00	\$ 162.00
8	Tailgate outer garnish		Sm CBT 1	\$ 458.00	\$ 458.00
9	Tailgate outer garnish handle		Sm 1	\$ 186.00	\$ 186.00
10	Rear number plate lamps		Sm 2	\$ 108.00	\$ 216.00
11	Tailgate weather strip		Sm 1	\$ 296.00	\$ 296.00
12	Tailgate inner lock assembly		R 1	\$ 286.00	\$ 286.00
13	Tailgate inner lock striker		R 1	\$ 154.00	\$ 154.00
14	Tailgate inner lock assembly switch		Sm 1	\$ 389.00	\$ 389.00
15	Tailgate inner lock assembly sensor		Sm 1	\$ 354.00	\$ 354.00
16	Tailgate inner trim board		Sm 1	\$ 1,873.10	\$ 1,873.10
17	Tailgate windscreen glass moulding		na 1	\$ 321.00	\$ 321.00
18	Tailgate lamp o/s		Sm 1	\$ 642.00	\$ 642.00
19	Taillamp o/s		Sm 1	\$ 798.00	\$ 798.00
20	Taillamp panel o/s		R 1	\$ 366.00	\$ 366.00
21	Rear Bumper upper	1480	Bm 1	\$ 1,650.00	\$ 1,650.00
22	Rear Bumper lower	650	na 1	\$ 752.00	\$ 752.00
23	Rear Bumper tow cover		Sm 1	\$ 85.00	\$ 85.00
24	Rear bumper side retainer		olmny 2	\$ 85.00	\$ 170.00
25	Rear Bumper reflector o/s		cmj 1	\$ 186.00	\$ 186.00
26	Rear Bumper lower silver moulding	302	Red 119Sm 1	\$ 551.00	\$ 551.00
27	Rear Bumper inner pad		Sm CBT 1	\$ 345.00	\$ 345.00
28	Rear Bumper reinforcement	555.40	Ry 1	\$ 769.00	\$ 769.00
29	Rear Bumper side support		Sm 2	\$ 154.00	\$ 308.00
30	Rear Bumper Centre support		Sm 2	\$ 147.00	\$ 294.00
31	Rear Bumper side cover		Sm 2	\$ 484.00	\$ 968.00
32	End Panel inner		R 1	\$ 563.00	\$ 563.00
33	End Panel outer		R 1	\$ 563.00	\$ 563.00

Repair Estimate

34	End Panel top garnish	Sm 1	\$ 489.00	\$ 489.00	X
35	Rear bumper lower cowl	Sm 1	\$ 337.00	\$ 337.00	X
36	Rear fender o/s	Sm 1	\$ 979.00	\$ 979.00	X
37	Rear fender inner cowl o/s	Sm 1	\$ 243.00	\$ 243.00	X
38	Rear fender splash guard o/s	Sm 1	\$ 56.00	\$ 56.00	X
39	Rear fender glass moulding o/s	Sm 1	\$ 189.00	\$ 189.00	X
40	Rear fender inner trim o/s	Sm 1	\$ 437.00	\$ 437.00	X
41	Rear fender air vent o/s	Sm 1	\$ 216.00	\$ 216.00	X
Subtotal				\$ 20,633.10	
List discount				10.00%	
Total				\$ 18,569.79	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	End panel top garnish clips	nn 6	\$ 6.50	\$ 39.00	X
2	Rear Bumper clips	nn 10	\$ 6.50	\$ 65.00	X
3	Reverse sensor	Sm 2	\$ 280.00	\$ 560.00	X
4	Reverse camera	Sm 1	\$ 400.00	\$ 400.00	X
5	End panel sealant	nn 1	\$ 100.00	\$ 100.00	X
6	Rear licence plate & frame	Sm 1	\$ 55.00	\$ 55.00	X
7	Rear windscreen sealant	nn 1	\$ 100.00	\$ 100.00	X
8	Tailgate inner trim clips	nn 10	\$ 6.50	\$ 65.00	X
9	Tailgate outer cover clips	nn 6	\$ 6.50	\$ 39.00	X
10	Rear fender glass sealant o/s	nn 1	\$ 100.00	\$ 100.00	X
11	Rear fender inner cowl clips o/s	nn 8	\$ 6.50	\$ 52.00	X
12	Rear fender inner trim clips o/s	nn 8	\$ 6.50	\$ 52.00	X
13	Sundries	nn 1	\$ 50.00	\$ 50.00	X
Total				\$ 1,677.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00	5000
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	200
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	X
4	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	X
5	Supply spray paint material and necessary items to respray rear bumper, tailgate, end panel and other affected area / panel.	6	\$ 1,200.00	8000
6	To rust proof all affected portions after repair.	0.5	\$ 100.00	X
Total labour			\$ 2,800.00	

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Grand Total \$ 23,046.79

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2019 14:19
Date Of Accident	22/10/2019 08:15
Exact Location Of Accident	ALONG HAVELOCK ROAD AT TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK7021G
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	201735055D
Email Address	DENNIS.DENG@MUNICHAUTOCARE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96826300

Vehicle Particulars

Manufacturer	RENAULT
Model	GRAND SCENIC IV 1.5 DCI AT EU6
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994322
Cover Note Number	

Driver

Name of Driver	CHIAM CHOON AIK GERALD
NRIC No	S1288547D
Date Of Birth	19/11/1957
Occupation	OUTDOOR
Date Of Driving Pass	10/11/1976
Driving Experience	42 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84482257
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	23 JALAN WAJEK
Postcode	588476
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GOJEK-PASSENGER
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20191022/2081.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU8146G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHIAM CHOON AIK GERALD
Approximate Age	61
Injuries Sustain	
Injured person in which vehicle?	SMK7021G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	23 JALAN WAJEK
Postcode	588476

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 22 OCT 2019

Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.:

SKETCH PLAN



A: SMK 7021G
B: SJU 8146G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at a traffic junction along Havelock Rd and suddenly a car came from behind and knock me on the rear. Driver of other car said he didnt know why his brakes are not working.

Vehicle No: SMK 7021G
Place of Accident: Havelock Road
Time 0820 Accident Date: 22.10.2019
3rd Party: SJU 8146G (Ng Jew Hong S7512712Z)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 2 OCT 2019

Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191022/2081

1 of 3

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20191022/2081

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/10/2019 14:01	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHIAM CHOON AIK GERALD			Address: 23 JALAN WAJEK SINGAPORE 588476	
ID Type / ID No.: NRIC NO / S1288547D			Contact No.: Home/Office:	Mobile: 84482257
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 61	Date of Birth: 19/11/1957	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: PDVL DRIVER			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/10/2019 08:15	Type of Location: Straight Road
Location: Along Road 1 HAVELOCK ROAD				
Along Havelock Road at traffic junction				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJU8146G	Car				Slightly Damaged	1
SMK7021G	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20191022/2081

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20191022/2081

CONTINUATION OF REPORT

Driver			
Name	NG YEW HONG		ID No. S7512712Z
Related Vehicle	SJU8146G (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHIAM CHOON AIK GERALD		ID No. S1288547D
Related Vehicle	SMK7021G (Car)		Contact No. 84482257
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	22/10/2019	Date Discharge	22/10/2019
No. of Days granted Medical Leave	04	Degree of Injury	NIL

Brief Details.

On the 22/10/2019 at about 0815hrs, I was driving my vehicle(SMK7021G) along Havelock Road, on lane 2 of 4 lanes. The road surface was slightly wet and a slight drizzle on the weather. Subsequently, I stopped my vehicle at the traffic junction when the light turned red. As I was waiting for the light to turn green, I suddenly felt an impact coming from the rear side of my vehicle. I then alighted from my vehicle and discovered that a vehicle(SJU8146G) had knocked onto my vehicle. The front left side of the vehicle had knocked onto the rear right side of my vehicle. There were damages to my vehicle as well. I spoke to the driver and he informed me that his brakes had failed causing the accident. I then exchanged particulars with the driver and left. Afterwards, I checked through my rear view camera and saw that the car had came in from the lane on my right and suddenly switched lanes causing it to knock onto my vehicle. Due to the accident, I felt pain on my back and neck. I then went to Mount Alvernia Hospital and was given 4 days of MC. I wish to state that I have the footage of the incident in my rear view camera.

Damages to my vehicle:

- 1) Dents on rear right side of vehicle
- 2) Scratches on rear right side of vehicle



**SINGAPORE
POLICE FORCE**



T/20191022/2081

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 3

Report No. T/20191022/2081

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 QAMARUL FITRI BIN JEFFREY

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/10/2019 14:01

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAL BINTE AHMAD

Contact No: 65476219

SN 070

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE