

ASS. REC. BY:

REF: CS/ A29 1909615/Hcf362

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Winnie Fan

of ALG

Date/Time: 6.11.19 10.57a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FB13 5005U

Insured: SG D 6366B

at Workshop to/for Lightning Bike

Tel: 94318235

of 2574 Jalan Besar

Policy No:

Claim No: 1000103114SG

Sum Insured:

Excess:

Make of Vch:

D.O.A. 25.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.11.19 11.40a.m

Person Contacted: Ah Chong

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FB13 5005U - X
	SG D 6366B - X

ASS. REC. BY:

H-ANN

REF: A19

PRS

ASSIGNMENT

From: _____ Date: 6.11.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBB 5005 U

at Workshop m/s Lightning Bike

of 2579 Jalan Besar Singapore 208931

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: An chong 94318335

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBB 5005 U Yr Regn: 18/07/2017

Type: M.Car (M.Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki DRZ 400sm C.C. 398

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 120021km T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JS1B811/200107732

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: (Good) / Jammed / Leaked / Burnt or

Brake: (Good) / Jammed / Leaked / Burnt or

Mod: Nil (S/Rim) / STD A/Rim or

Tyre Size: F: 120/70/17

R: 160/60/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 4 - PIN mm

Rear

R/Bal: 4 - PIN mm

L/Bal: _____ mm

L/Bal: _____ mm

D.O.A: 25/10/19

D.O.L: 6/11/19

Survey held at Lightning Bike

Des. of Damages (Frt) / Rear / (O/S) / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* FBB 5005 U
PRS case

MV - 3200

PV 1500

NV 1700

RECEIVED 26 NOV 2019

workshop
 * Just inform know this bike for front repair now over \$1700, workshop say non economic replacement &

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee: 120

Transportation

S + RS \$

Photos

Others

TOTAL

Rep. Format: DOR

Lump Sum / P.P.C.

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

120

11

120

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019 Edit Reg		06 Nov 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	GAN GIAP LEONG,, ID: S0185989G		
Main Claimant:	-		
Vehicle Reg. No.:	FBB5005U	Date of Loss:	25/10/2019 00:00 - :59
Claim Type:	TP / 1000103114SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SGD6366B	Policy No. (Claimant):	
		Excess:	
Repairer:	Lightning Bike Pte Ltd (HQ) 257A Jalan Besar, 208931 Jalan Besar - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 15/11/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (07/11/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

-FW: OUR REF.: M78-112045.19 (FBB 5005U @ 25.10.2019) // AIG REF NO : S...

From: AIG SGP, Claims-Survey
To:
Cc: Fong, Andy-SY
Sent: 11/6/2019 10:57:39 AM

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

7B Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Wednesday, November 06, 2019 10:34 AM
To: Fan, Winnie-LW; Hor, Yinrul; Azlan, Syazairdina; Chin, Lee-Ying; AIG SGP, Claims-Survey; Lim, Sheng Yang
Cc: 'Mcs Auto'; 'Judy Soh'; Leong, Kah Yin Hidden on 03-09-2017, 03:47:55; 'Hassim, Mohd Fitri'; Abu Kassim, Noor Mariesa; 'Md Ishak, Mohd Imran'
Subject: [EXTERNAL] OUR REF.: M78-112045.19 (FBB 5005U @ 25.10.2019) // AIG REF NO : SGD 6366B

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: MOHAMED ALIFF BIN ZAINUDIN

ACCIDENT INVOLVING FBB 5005U & SGD 6366B ON 25 OCT 2019 ALONG JUNCTION OF TECK WHYE AVE NEAR BLK 7 AT ABOUT 07:50 HRS

We refer to your email of even date below and your list of surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<u>Name of Surveyor</u>	<u>Company Name</u>
Ken	Keno Assessors & Services
Kelvin	Kelvin Automotive Appraising Services

Please be informed that the said vehicle can be inspected at:-

Venue : **LIGHTNING BIKE**
257a, Jalan Besar
Singapore 208931
Contact : Ah Chong (Tel.: 9431-8235)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Tuesday, 5 November, 2019 12:50 PM
To: Yinrul.Hor@aig.com; 'Azlan, Syazairdina'; Lee-Ying.Chin@aig.com; AIGSGP_ClaimsSurvey@aig.com; 'Lim, Sheng Yang'
Cc: 'Mcs Auto'; 'Judy Soh'; 'Leong, Kah Yin'; 'Hassim, Mohd Fitri'; 'Abu Kassim, Noor Mariesa'; 'Md Ishak, Mohd Imran'
Subject: OUR REF.: M78-MISC.19 (FBB 5005U @ 25.10.2019) // AIG REF NO : SGD 6366B
Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: MOHAMED ALIFF BIN ZAINUDIN

ACCIDENT INVOLVING FBB 5005U & SGD 6366B ON 25 OCT 2019 ALONG JUNCTION OF TECK WHYE AVE NEAR BLK 7 AT ABOUT 07:50 HRS

We are instructed by MOHAMED ALIFF BIN ZAINUDIN to notify you of a road traffic accident ON 25 OCT 2019 ALONG JUNCTION OF TECK WHYE AVE NEAR BLK 7 AT ABOUT 07:50 HRS involving our client's vehicle registration number FBB 5005U and vehicle registration number SGD 6366B driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL: 6534-2811 (ext 115)

FAX : 6535-6802

C.c. VEHICLE OWNER OF SGD 6366B

GAN GIAP LEONG

285D, Toh Guan Road,

#12-62,

Singapore 604285

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 326B

Vehicle Details

Vehicle No.: FBB5005U
Vehicle to be Exported: No
Intended Deregistration Date: 07 Nov 2019
Vehicle Make: SUZUKI
Vehicle Model: DRZ400SMK7
Primary Colour: Black
Manufacturing Year: 2006
Engine No.: K419169637
Chassis No.: JS1B8111200107732
Maximum Power Output: -
Open Market Value: \$6,042.00
Original Registration Date: 18 Apr 2007
First Registration Date: 18 Apr 2007
Transfer Count: 2
Actual ARF Paid: \$907.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Mar 2022
COE Category: D - Motorcycle
COE Period(Years): 5
PQP Paid: \$3,128.00
COE Rebate Amount: \$1,500.00
Total Rebate Amount: \$1,500.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Nov 2019

OK



Advertisement

zuhairikahar
★★★★★

Chat

Make Offer

Advertisement

S\$4,500

Share

31

DRZ400SM

Woodlands

Meet up

Used

Selling off my beautiful and striking DRZ400SM.

Condition:

Interior - 8/10

Exterior - 8.5/10

One of the most striking and beautiful DRZ400SM bike you have ever imagine. Once you are on the road, people will just keep looking at this bike!

Overall, in good condition! This bike doesn't give me any problem. Selling off as I have another bike that is always in used. Also I will be existing in few days time!!

Sad though to sell off this bike but... No choice. Better to sell off than letting this baby of mine stay put in a park.

*LED VINCE EXHAUST (WITH CERT)

*Inspection done. Passed!

Things that I've recently changed

Battery

Magnetic coil

Cable clutch

Rectifier

Chain

So no need to worry if you buy this bike from me because everything is smooth and steady.

NEGOTIABLE FOR FAST AND SERIOUS BUYER

FULLY PAID

COE 11 NOVEMBER 2021

NON-RENEWABLE

7 days ago in Class 2A



Insurance

Meet-up

Woodlands

Listed by zuhairikahar

Very Responsive

Verified

Check seller profile



Reviews for zuhairikahar



effigafendi

MV - 3200
PV - 1500
NV - 1700

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2019 13:37
Date Of Accident	25/10/2019 07:50
Exact Location Of Accident	TRAFFIC LIGHT JUNCTION OF TECK WHYE AVE NEAR BLK 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBB5005U
Insured/Policyholder	
Name Of Registered Owner	MOHAMED ALIFF BIN ZAINUDIN
NRIC No	S8740326B
Email Address	ALIFF.GOOD@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90679879
Alternative Phone No	OFFICE-90679879

Vehicle Particulars

Manufacturer	SUZUKI
Model	DRZ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5108965649 (TP)
Cover Note Number	

Driver

Name of Driver	MOHAMED ALIFF BIN ZAINUDIN
NRIC No	S8740326B
Date Of Birth	11/12/1987
Occupation	INDOOR
Date Of Driving Pass	19/07/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90679879
Fax Number	
Contact Address	OFFICE 90679879

Address	BLK 136 TECK WHYE LANE #02-305
Postcode	S680136
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191025/7025

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGD6366B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GAN
NRIC/Passport Number	
Contact Number	96488333
Address	
Postcode	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED ALIFF BIN ZAINUDIN

Approximate Age

Injuries Sustain

2 DAYS MC BY NG TENG FONG, SLIGHT INJURY ON LIMBS
FBB5005U

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

YES

Address

Postcode

Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vcom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107



© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

© 2000 Blackwell Science Ltd, *Journal of Internal Medicine* 247: 101–107

Police Report



**SINGAPORE
POLICE FORCE**



T/20191025/7025

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20191025/7025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/10/2019 19:37		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMED ALIFF BIN ZAINUDIN			Address: 136 TECK WHYE LANE #02-305 SINGAPORE 680136		
ID Type / ID No.: NRIC NO / S8740326B			Contact No.: Home/Office: Mobile: 90679879		
Nationality: SINGAPORE CITIZEN			Email: ALIFF.GOOD@GMAIL.COM		
Sex: Male	Age: 31	Date of Birth: 11/12/1987	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: Electrical engineer (general)			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 25/10/2019 07:50	Type of Location: T-Junction
Location: Traffic light junction at Teck Whye Ave near Blk 7				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB5005U	Motorcycle	SUZUKI	DRZ	Blue	Seriously Damaged	0
SGD6366B	Car	RENAULT	Megan	Grey	Slightly Damaged	3

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
FBB5005U	NTUC Income Insurance Co-Operative Limited	5108965649	17/04/2019	16/04/2020	

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191025/7025

2 of 4

Report No. T/20191025/7025

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMED ALIFF BIN ZAINUDIN	ID No.	S87403268
Related Vehicle	FBB5005U (Motorcycle)	Contact No.	90679879
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	25/10/2019	Date Discharge	25/10/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Passenger			
Name	PASSENGER 3	ID No.	NIL
Related Vehicle	SGD6366B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	PASSENGER 2	ID No.	NIL
Related Vehicle	SGD6366B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report



**SINGAPORE
POLICE FORCE**



T/20191025/7025

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191025/7025

CONTINUATION OF REPORT

Driver			
Name	GAN	ID No.	NIL
Related Vehicle	SGD6366B (Car)	Contact No.	96488333
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	25/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	PASSENGER 1	ID No.	NIL
Related Vehicle	SGD6366B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Approaching a T junction, I was riding at +/- 40km/h going straight. A car SGD6366B turned right from opposite direction towards (Teck Whye Crescent). The said vehicle's failure to observe proper road safety result in a collision between me (FB55005U) and the said vehicle. I sustained some injuries on my limbs and was conveyed by ambulance to Ng Teng Fong Hospital. My motorcycle was subsequently removed by the authority.

Police Report



**SINGAPORE
POLICE FORCE**



T/20191025/7025

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20191025/7025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MOHAMED HUSNUL TAUFIQ BIN MD YUSOF
Contact No.: 65476358

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
25/10/2019 19:37

Classification Of Case:

FOR MOTORCYCLE

4. Hot Oil (H.O.)

Motorcycle

Vehicle No: **FBB 50054**

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	acc	✓	1
1001	995065	Front Tyre	acc	✓	1
1007	995095	Front Rim	acc	✓	1
1003	994872	Front Tyre Rim Spoke	acc	✓	1
1004	991771	Front Fender Wheel Guard	acc	✓	1
1005	991283	Front Brake acc <i>low</i>	acc	✓	1
1006	991281	Front Brake acc <i>Handle</i>	acc	✓	2
1007	991785	Front Fork Assy	acc	✓	1
1008	991787	Front Fork Inner Tube	?	✓	1
1009	991789	Front Fork Outer Tube	?	✓	1
1010	991167	Front Fork Bracket	acc	✓	1
1011	991182	Front Fork Oil Seal	acc	✓	1
1012	991174	Front Fork Garnish			
1013	992376	Front Headlamp Rim			
1014	992328	Front Headlamp	scr	✓	1
1015	992337	Front Headlamp Bracket	acc	✓	1
1016	992345	Front Headlamp Fairing	acc	✓	1
1017	992130	Front Windshield			
1018	992134	Front Wing Mirror	acc	✓	1
1019	995245	Front LH Signal Lamp	acc	✓	1
1020	995246	Front RH Signal Lamp	acc	✓	1
1021	992556	Meter Gauge	?	✓	1
1022	992553	Meter Assy	?	✓	1
1023	991019	ERP Bracket	acc	✓	1
1024	991020	ERP Unit	acc	✓	1
1025	992446	Ignition Switch			
1026	992442	Ignition Key Assy			
1027	990706	Cowling Stay			
1028	994470	Steering Stem	?	✓	1
1029	994427	Steering Cone	acc	✓	1
1030	992299	Handle Bar	?	✓	1
1031	992312	Handle Bar Switch	?	✓	1
1032	992310	Handle Bar Grip			
1033	995184	Handle Bar Balancer LH	acc	✓	1
1034	992300	Handle Bar Balancer RH	acc	✓	1
1035	992179	Fuel Tank	?	✓	1
1036	990438	Brake Reservoir			
1037	990621	Clutch Lever	?	✓	1
1038	992293	Hand Brake Lever			
1039	991119	Side Fairing	acc	✓	1
1040	994220	Side Fairing Top Garnish	acc	✓	1
1041	994219	Side Fairing Inner Garnish	acc	✓	1
1042	991118	Fairing Shield			
1043	992047	Front Top Fairing Inner Garnish			
1044	991123	Fairing Top Garnish			
1045	990538	Center Fairing	acc	✓	1
1046	993378	Rear Fairing	acc	✓	1
1047	991121	Fairing Stopper			
1048	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1049	995074	Radiator	acc	✓	1
1050	992738	Radiator Cowling	acc	✓	1
1051	994146	Seat Assy			
1052	990915	Engine Crash Bar			
1053	990928	Engine Guard			
1054	990219	Battery			
1055	990224	Battery Cover			
1056	990223	Battery Bracket			
1057	991144	Foot Brake	acc	✓	1
1058	991154	Front Foot Rest	acc	✓	1
1059	991779	Front Foot Rest Bracket	acc	✓	1
1060	994269	Side Stand	scr	✓	1
1061	992549	Main Stand			
1062	990615	Clutch Engine Cover			
1063	992478	Kick Starter Rubber	acc	✓	1
1064	992477	Kick Starter Lever	acc	✓	1
1065	991145	Foot Gear Shifter			
1066	993500	Rear Foot Rest			
1067	993501	Rear Foot Rest Bracket			
1068	992581	Exhaust Muffler Heat Shield			
1069	991058	Exhaust Muffler Assy	acc	✓	1
1070	993719	Rear LH Shock Absorber			
1071	993720	Rear RH Shock Absorber			
1072	995065	Rear Tyre			
1073	991200	Rear Rim	?	✓	1
1074	994872	Rear Tyre Rim Spoke			
1075	993474	Rear Fender Wheel Guard			
1076	993443	Rear Fender Mudflap			
1077	992940	Rear Brake Disc			
1078	992936	Rear Brake Caliper			
1079	995236	Rear Spocket			
1080	990585	Chain			
1081	990580	Chain Guard			
1082	994530	Swing Arm	?	✓	1
1083	993819	Rear Sub frame	?	✓	1
1084	995245	Rear LH Signal Lamp			
1085	995246	Rear RH Signal Lamp			
1086	995251	Rear Taillamp			
1087	993626	Rear Number Plate			
1088	994192	Side Box			
1089	992927	Rear Box			
1090	992928	Rear Box Bracket			
1091	991328	Emblem			
1092	990247	Sticker			
		Engine having motor H.O. scr		✓	1
		gear Term L.H. H.O.		✓	1
		oil Filter motor handle acc		✓	1

Page of Report

Assessor:

H. ANN

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2019 Edit Reg		06 Nov 2019 00:00 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: GAN GIAP LEONG,, ID: S0185989G									
Main Claimant: -									
Vehicle Reg. No.: FBB5005U		Date of Loss: 25/10/2019 00:00 - :59 [150 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1000103114SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SGD6366B		Policy No. (Claimant):							
		Excess:							
Repairer: Lightning Bike Pte Ltd (HQ) 257A Jalan Besar, 208931 Jalan Besar - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 15/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (07/11/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBB5005U (10001031145G)
[SGD6366B]**

TP

-
**Oct 25 2019 12:00AM
[GAN GIAP LEONG,]
Lightning Bike Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	07/11/19 12:02	Chassis Number														Load JPG	☒			
2	07/11/19 12:02	Odometer Reading														Load JPG	☒			
3	07/11/19 12:02	General View														Load JPG	☒			
4	07/11/19 12:02	General View														Load JPG	☒			
5	07/11/19 12:02	General View														Load JPG	☒			
6	07/11/19 12:02	General View														Load JPG	☒			
7	07/11/19 12:02	General View														Load JPG	☒			
8	07/11/19 12:02	General View														Load JPG	☒			
9	07/11/19 12:02	General View														Load JPG	☒			
10	07/11/19 12:02	General View														Load JPG	☒			
11	07/11/19 12:02	General View														Load JPG	☒			
12	07/11/19 12:02	General View														Load JPG	☒			
13	07/11/19 12:03	General View														Load JPG	☒			
14	07/11/19 12:03	General View														Load JPG	☒			
15	07/11/19 12:03	General View														Load JPG	☒			
16	07/11/19 12:03	General View														Load JPG	☒			
17	07/11/19 12:03	General View														Load JPG	☒			
18	07/11/19 12:03	General View														Load JPG	☒			
19	07/11/19 12:03	General View														Load JPG	☒			
20	07/11/19 12:03	General View														Load JPG	☒			
21	07/11/19 12:03	General View														Load JPG	☒			
22	07/11/19 12:03	General View														Load JPG	☒			
23	07/11/19 12:03	General View														Load JPG	☒			
24	07/11/19 12:03	General View														Load JPG	☒			
25	07/11/19 12:03	General View														Load JPG	☒			
26	07/11/19 12:03	General View														Load JPG	☒			
27	07/11/19 12:03	General View														Load JPG	☒			
28	07/11/19 12:03	General View														Load JPG	☒			
29	07/11/19 12:03	General View														Load JPG	☒			
30	07/11/19 12:03	General View														Load JPG	☒			
31	07/11/19 12:03	General View														Load JPG	☒			
32	07/11/19 12:03	General View														Load JPG	☒			
33	07/11/19 12:03	General View														Load JPG	☒			
34	07/11/19 12:03	General View														Load JPG	☒			
35	07/11/19 12:03	General View														Load JPG	☒			
36	07/11/19 12:03	General View														Load JPG	☒			
37	07/11/19 12:03	General View														Load JPG	☒			
38	07/11/19 12:03	General View														Load JPG	☒			
39	07/11/19 12:03	General View														Load JPG	☒			
40	07/11/19 12:03	General View														Load JPG	☒			
41	07/11/19 12:03	General View														Load JPG	☒			
42	07/11/19 12:03	General View														Load JPG	☒			
43	07/11/19 12:03	General View														Load JPG	☒			

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	07/11/19 12:03	General View		Load JPG	☒
45	07/11/19 12:03	General View		Load JPG	☒
46	07/11/19 12:03	General View		Load JPG	☒
47	07/11/19 12:03	General View		Load JPG	☒
48	07/11/19 12:03	General View		Load JPG	☒
49	07/11/19 12:03	General View		Load JPG	☒
50	07/11/19 12:03	General View		Load JPG	☒
51	07/11/19 12:04	General View		Load JPG	☒
52	07/11/19 12:04	General View		Load JPG	☒
53	07/11/19 12:04	General View		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	07/11/19 16:53	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19019613/HCF3E2

Date: 28/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : FBB5005U

Insured Vehicle No : SGD6366B

Date of Loss: 25/10/2019

Nature of Claim: TP

Claim No: 1000103114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB5005U

Make & Model: SUZUKI DRZ400SMK7, 398cc

Engine No: K419169637

Reg. Date: 18/04/2007 (Man. Year: 2006)

Chassis No: JS1B8111200107732

Colour: Black

Odometer: 120021 km

Engine Capacity: 398 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17

Rear Tyre Size: 160/60 R17

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/11/2019

Date Inspected: 06/11/2019 Inspected At:

Lightning Bike Pte Ltd (HQ)

257A Jalan Besar

Singapore 208931

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT RIM	Damaged	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
4	2		*FRONT BRAKE LEVEL	Crushed	0.00 F	*- F
5	2		*FRONT BRAKE HANDLE	Bent	0.00 F	*- F
6	1		*FRONT FORK ASSY	Crushed	0.00 F	*- F
7	1		*FRONT FORK INNER TUBE	* Check	0.00 F	*- F
8	1		*FRONT FORK OUTER TUBE	* Check	0.00 F	*- F
9	1		*FRONT FORK BRACKET	Cracked	0.00 F	*- F
10	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
11	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
12	1		*FRONT HEADLAMP BRACKET	Crushed	0.00 F	*- F
13	1		*FRONT HEADLAMP FAIRING	Crushed	0.00 F	*- F
14	1		*FRONT WING MIRROR	Missing	0.00 F	*- F
15	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
16	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
17	1		*METER CASING	* Check	0.00 F	*- F
18	1		*METER ASSY	* Check	0.00 F	*- F
19	1		*ERP BRACKET	Crushed	0.00 F	*- F
20	1		*ERP UNIT	Crushed	0.00 F	*- F
21	1		*STEERING STEM	* Check	0.00 F	*- F
22	1		*STEERING CONE	Crushed	0.00 F	*- F
23	1		*HANDLE BAR	* Check	0.00 F	*- F
24	1		*HANDLE BAR SWITCH	* Check	0.00 F	*- F
25	1		*HANDLE BAR BALANCER LH	Crushed	0.00 F	*- F
26	1		*HANDLE BAR BALANCER RH	Crushed	0.00 F	*- F
27	1		*FUEL TANK	* Check	0.00 F	*- F
28	1		*CLUTCH LEVER	* Check	0.00 F	*- F
29	1		*SIDE FAIRING	Crushed	0.00 F	*- F
30	1		*SIDE FAIRING TOP GARNISH	Crushed	0.00 F	*- F
31	1		*SIDE FAIRING INNER GARNISH	Crushed	0.00 F	*- F
32	1		*CENTER FAIRING	Crushed	0.00 F	*- F
33	1		*REAR FAIRING	Cracked	0.00 F	*- F
34	1		*RADIATOR	Crushed	0.00 F	*- F
35	1		*RADIATOR COWLING	Crushed	0.00 F	*- F
36	1		*FOOT BRAKE	Damaged	0.00 F	*- F
37	1		*FRONT FOOT REST	Damaged	0.00 F	*- F
38	1		*FRONT FOOT REST BRACKET	Damaged	0.00 F	*- F
39	1		*SIDE STAND	Scratched	0.00 F	*- F
40	1		*KICK STARTER RUBBER	Crushed	0.00 F	*- F
41	1		*KICK STARTER LEVER	Crushed	0.00 F	*- F
42	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
43	1		*REAR RIM	* Check	0.00 F	*- F
44	1		*SWING ARM	* Check	0.00 F	*- F
45	1		*REAR SUB FRAME	* Check	0.00 F	*- F
46	1		*ENGINE HOUSING OUTER L/H	Scratched	0.00 F	*- F
47	1		*GEAR LEVEL L/H	Bent	0.00 F	*- F
48	1		*OIL FILTER OUTER COVER L/H	Crushed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >