

INS. CASE OWNER:

CC 4/AIG1901 9629, B d... 93

LKK:
IDAC:

Surveyor: LTG DOI: 6/11/19 Date / Time: 06/11/19
Registered in Merimen: 6/11/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SDP 774R Claim No. : _____
Name of Insured : HEA SHYH LIMAN Policy No. : 200408029-04
Insured Tel No. : _____ HP: _____ Make / Model : MARDA
Excess Sec II :SS _____ D.O.A : 21/10/19 Place of Accident : 12 HOLLAND AVE
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SJS 2667U



INSRS: _____
WSP: Team Auto Pro
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / CIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: 6/1/2020 Confirm with Adel Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 24 If NO or B 28, Ass. Lia : _____

Repair Cost: \$S 4000.00

Loss of Rental (LOR): \$S 840.00 (7 days) x \$120

Loss of Use (LOU): \$S - (5 x days)

Loss of Income (LOI): \$S - (5 x days)

LOR only LOU only LOR + LOU LOR + LO (Tick only one)

GIA/LTA Search: \$S 29.00

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost: \$S -

Total: \$S 4869.00 Global Sum \$S: 4850.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 4850.00 Name 1: Team Auto Pro Pte Ltd

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

COPY SENT
10/1/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320

REF: AIG

ASSIGNMENT

From: _____ Date: 6/11/19

Veh No: SJS 26674 Yr Reg: 7/8/2009
Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJ 526674

Make: Hyundai Avante CC 1591
Colour: Blue A/C: Insured / Std / NI / NAat Workshop in/s Sean Autopart
at 160 Sin Ming Dr #01-14

Sp. Reading 206 988 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: G4FC9U653 #28

Policy No.:

C/No: KMHD41BR3U759143

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 185/55/15

R: 185/55/15

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

25,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 31/10/19

D.O.I. 6/11/19

Survey held at

Sean Autopart

Des. of Damages: P/F / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

H/S 4,000/- Term limit 20/11/19 (Red \$ 7835.28 / 662)

MV 25,000/-
PV 13,915/-
NV 11,085/-Term limit
7/11/19

Date/Time, File Pass to?

 : Prel. Report

Days Of Repair:

1)

 : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:

Transportation:

D + RS, \$

Photos

Others

:

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: After-Paint: _____
 Contacts : _____

Vehicle Nos : SJS 2667 U
 Model : HYUNDAI AVANTE
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet	1	\$ 1,062.20	\$ 1,062.20
2	Bonnet lock	1	\$ 65.00	\$ 65.00
3	Front grille logo	1	\$ 58.00	\$ 58.00
4	Front bumper	1	\$ 1,232.20	\$ 544.40 1,232.20
5	Front bumper side retainer	2	\$ 51.00 124.60	\$ 102.00 249.20
6	Front bumper grille centre	1	\$ 65.90	\$ 65.90
7	Front bumper fog lamp RH	1	\$ 198.50	\$ 198.50
8	Headlamp RH	1	\$ 643.50	\$ 643.50
9	Headlamp lower bracket	1	\$ 86.10	\$ 86.10
10	Front fender RH	1	\$ 862.40	\$ 862.40
11	Front fender inner shield RH	1	\$ 183.60	\$ 183.60
12	Front fender insulator	1	\$ 84.60	\$ 84.60
13	Front fender emblem VVT	1	\$ 89.80	\$ 89.80
14	Front shock absorber RH	1	\$ 319.60	\$ 319.60
15	Front lower arm RH	1	\$ 394.50	\$ 394.50
16	Front knuckle arm RH	1	\$ 365.80	\$ 365.80
17	Front knuckle arm bearing RH	1	\$ 135.00	\$ 135.00
18	Washer tank	1	\$ 188.60	\$ 188.60
19	Washer tank motor	1	\$ 135.60	\$ 135.60
20	Front support panel	1	\$ 986.50	\$ 986.50
Parts Sub Total :				\$ 3,874.60 7,406.60
20% Discount				\$ 774.92 1,481.32
PARTS TOTAL :				\$ 3,099.68 5,925.28

RX
 NDX
 NDX
 DDV
 NECV
 NDX
 BRV
 CUTV
 NDX
 DDV
 TNV
 NDX
 NECV
 NDX
 DDV
 NDX
 BTV
 BRV
 DDV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Front grille clip	1	\$ 50	\$ 50.00
3	Front fender inner shield clip	1	\$ 30.00	\$ 30.00
4	Front bumper clips	1	\$ 50.00	\$ 50.00
5	Headlamp clips	2	\$ 50.00	\$ 100.00
6	Radiator coolant	1	\$ 60.00	\$ 60.00
7	A/C compressor fluid	1	\$ 60.00	\$ 60.00
8	Alloy rim RH	1	\$ 650.00	\$ 650.00
9	Tyre RH	1	\$ 350.00	\$ 350.00
SPECIAL NETT TOTAL :				\$ 90.00 1,430.00

NAX
 NDX
 NECV
 NECV
 NECV
 NDX
 NDX
 NDX

Nos.	LABOUR		\$\$
1	Panel beat	200.00 ↑	\$600.00 1,600.00
2	Rust proofing		\$ 30.00 800.00
3	Spray paint	200.00 ↑	\$ 600.00 1,600.00
4	To R&R a/c condenser to confirm on the a/c temperature /top up gas		\$ 180.00 X
5	To R&R radiator and pressure test cooling system		\$ 180.00 X
6	To check wiring		\$30.00 100.00 /
7	To R&R undercarriage parts.		\$ 80.00 350.00 ✓
8	To R&R tyre and balancing		\$ 50.00 NN X
9	Full wheel alignment		\$ 60.00 120.00
LABOUR TOTAL :			\$ (1,800.00) 4,480.00

PARTS TOTAL: \$3099.68 5,925.28
SPECIAL NETT TOTAL: \$ 90.00 1,430.00
LABOUR TOTAL: \$ 1800.00 4,480.00
GRAND TOTAL: \$ 11,835.28

@ 20%
4989.68
997.94
3991.74

TGrim Mir
7/11/19
L/S repair

H/S 4,000/2
TGrim
Mir
20/11/19

Resurvey
TGrim Mir
8/11/19

Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Hyundai : Avante/Elantra/Lantra : 2006-11 (-HD-)
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°54'	-0°54'	-1°00' 0°00'
6°11'	6°11'	3°49' 4°49'
-0°07'	-0°07'	-0°05' 0°05'
17°28'	17°29'	12°52' 13°52'
16°35'	16°35'	11°52' 13°52'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°43'	-2°43'	-1°00' 0°00'
6°16'	6°16'	3°49' 4°49'
-0°06'	-0°06'	-0°05' 0°05'
18°41'	18°41'	12°52' 13°52'
15°57'	15°57'	11°52' 13°52'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
1°49'	1°50'	
-0°05'	-0°05'	
-1°12'	-1°12'	
-0°13'	-0°13'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-2°45'	-2°46'	-1°30' -0°30'
-0°04'	-0°04'	0°00' 0°10'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-0°59'	-0°59'	-1°30' -0°30'
0°04'	0°04'	0°00' 0°10'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-1°46'	-1°46'	
0°00'	0°00'	0°01' 0°20'
-0°04'	-0°04'	

CONDITIONS:
 (1)Item (2)Done (3)Distorted (4)Cracked (5)OK or (6)Scuffed
 (7)Distorted (8)Shifted (9)Distorted (10)Broken (11)Necessary (12)Missing
 (13)Tom (14)Unconfirmed (15)Not Working

ACT/DIAG:
 (1)Replace (✓) (2)Repair (X) (3)Check (T)
 (4)Not Consistent (NC)

Aug 2015

MOTOR CAR (RH)

Vehicle No: SJS 26674

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frnt RH Door			
1317	991654	Frnt RH Door Protector			
1318	991601	Frnt RH Door Hinge			
1319	991685	Frnt RH Door Wing Mirror			
1320	991583	Frnt RH Door Garnish			
1321	991639	Frnt RH Door Glass Outer Moulding			
1322	991588	Frnt RH Door Glass Inner Moulding			
1323	991584	Frnt RH Door Glass			
1324	991595	Frnt RH Door Glass Regulator			
1325	991596	Frnt RH Door Glass Regulator Motor			
1326	991662	Frnt RH Door Rubber			
1327	991636	Frnt RH Door Outer Handle			
1328	991607	Frnt RH Door Inner Handle			
1329	991625	Frnt RH Door Lock w/Key			
1330	991624	Frnt RH Door Lock			
1331	991562	Frnt RH Door Central Lock			
1332	991675	Frnt RH Door Switch			
1333	991617	Frnt RH Door Inner Trim Board			
1334	991568	Frnt RH Door Checker			
1335	991575	Frnt RH Door Felt			
1336	991688	Frnt RH Door Wire Harness			
1337	991683	Frnt RH Door Window Glass Pillar			
1338	991640	Frnt RH Door Outer Pillar			
1339	991613	Frnt RH Door Inner Pillar			
1340	991646	Frnt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frnt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frnt Bumper			DDV
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			NECV 2
1008	991433	Frnt Bumper Reinforcement			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler			
1030	991821	Frnt RH Headlamp Assy			
1032	995089	Frnt RH Side Lamp			
1105	995071	Frnt RH Fender			DDV
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
994070		Roof Top Panel			
994098		Roof Top Moulding			
994085		Roof Top Air-bag			
994084		Roof Top Air-bag Sensor			
994083		Roof Top Air-bag Control Unit			
992958		Rear Bumper			
992976		Rear Bumper Bracket			
993068		Rear Bumper Side Retainer			
993045		Rear Bumper Reinforcement			
993077		Rear Bumper Sponge			
993040		Rear Bumper Protector			
993026		Rear Bumper Moulding			
993023		Rear Bumper Lower Spoiler			
995116		Rear RH Taillamp			
993456		Rear RH Fender			
993450		Rear RH Fender Protector			
990247		Sticker			
		Frnt bumper fog lamp RH			DDV
		Headlamp RH			DDV
		Right fender door shield RH			DDV
		Fog lamp lower arm RH			DDV
		Washer tank			DDV
		Washer motor			DDV
		Frnt bumper panels			DDV
		clips - fit inner shield			DDV
		Frnt bumper			DDV
		headlamp			DDV
		Front support panel			DDV

No of Items: 12

Assessor: [Signature]

2/19/20

IT'S NEVER TOO EARLY TO THINK ABOUT YOUR 2020 DRIVE

VISIT THE LEXUS SHOWCASE @ TAMPINES MALL FROM 8-14 NOV



Post an Advertisement
Sell it yourself! Advertise it at just \$58 until it's SOLD!

Volkswagen Jetta 1.4L TSI Highline



Upper Drive, Low Depreciation.
The Car Is Extremely Well Maintained By Us

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Back (1 ... 5 6 7 8 9 ... 12) Next >

Sort by Reg. Date

20 results/page

224 vehicles

Hyundai Avante

	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Any	Any	> 10 year(x) old	Any	Any	Any	All
 Hyundai Avante 1.6A S (New 5-yr COE)	-	N/A	12-Aug-2009	1,591 cc	-	Sedan	SOLD
100% Quality Buy, Full Loan Available At Monthly \$500 Plus, Interest Rate From 3.88%, Price Include New Paint/New Leather Seats, Rims, Showroom Condition Guarantee, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Pre-owned Car Are Selling...							
Car World Automobile Posted: 10-Oct-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							
 Hyundai Avante 1.6A S (New 5-yr COE)	\$25,800	\$5,150 /yr	12-Aug-2009	1,591 cc	-	Sedan	Available
100%loan Full Loan In House Or Bank View At Phoenix Motor Trading Enterprise							
Posted: 07-Oct-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							
 Hyundai Avante 1.6A (COE till 08/2024)	-	N/A	12-Aug-2009	1,591 cc	-	Sedan	SOLD
1 Owner And Super Good Condition.Easy Handling And Fun To Drive Responsive Engine Performance + Fuel Efficiency. Much Treasured And Well Maintained By Ex-Owner A Software Engineer. Excellent Condition We Are The Case Trust Company. No Gimmicks, Honest De...							
Car House Pte Ltd Posted: 18-Sep-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							
 Hyundai Avante 1.6A S (New 5-yr COE)	-	N/A	12-Aug-2009	1,591 cc	-	Sedan	SOLD
New 5 Year COE Monthly \$600 Plus, Income \$3k And Above To Apply, Hurry Before It's Sold, Purchase From An Award Winning Dealership! Accident Free, Quality Pre-Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In Hou...							
88 Motor Trading Posted: 12-Sep-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							
GET YOUR COE RENEWAL LOAN	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.						
 Hyundai Avante 1.6A S (COE till 08/2024)	-	N/A	12-Aug-2009	1,591 cc	-	Sedan	SOLD
Fully Agent Maintained, Superbly Well Maintained By Previous Lady Owner. Just Converted From OPC To Normal Plate, Super Low Mileage, 100% Accident Free. Guarantee No Further Repair Needed. Flexible Loan Scheme And Trade In Are Welcome, Please Contact...							
SmartCars Boutique Pte Ltd Posted: 23-Aug-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							
 Hyundai Avante 1.6A (COE till 08/2024)	\$25,800	\$5,420 /yr	11-Aug-2009	1,591 cc	-	Sedan	Available
Sell As Normal Plate Not OPC! Monthly \$600 Plus, Income \$2.8k And Above To Apply, Hurry Before It's Sold, Purchase From An Award Winning Dealership! Accident-Free, Quality Pre-Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexib...							
88 Motor Trading Posted: 30-Oct-2019 Tags: 2009 Hyundai Avante, 2009 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai							

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	851B
Vehicle Details	
Vehicle No.:	SJS2667U
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	G4FC9U653628
Chassis No.:	KMHDU41BR9U759143
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,325.00
Original Registration Date:	07 Aug 2009
First Registration Date:	07 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$11,325.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Aug 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,664.00
COE Rebate Amount:	\$13,915.00
Total Rebate Amount:	\$13,915.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Nov 2019

OK

Agreed with

MV 25,000/2
PV 13,915/2
NV 11,085/2

*TCRM / mi
7/11/19*

PRE-REPAIR INSPECTION REQUEST – SJS2667U vs SDP775R (OI) on D.O.A.: 31/10/2019

From: Hor, Yinrul
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Marissa, Azlan, Syazairina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashri
Sent: 11/6/2019 11:35:08 AM
Attachments:  PRS 2667 SDP775R.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd.**

Claim no : 677537464RSG003
Case Owner : Foo Chit Yan

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.as

11.59am @ 6/11/19
v: In
P: peach
S: Mr Lim

From: TeamAutoPro North [mailto:teamautopt@gmail.com]
Sent: Tuesday, November 05, 2019 5:07 PM
To: Chan, Yoke Shi; Chin, Lee-Ying; Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Abu Kassim, Noor Marissa; Supramaniam, Darshene; Tan, Lily (AIG); Hor, Yinrul
Subject: [EXTERNAL] 2 Days Notice: SJS 2667 U (Our Ref) and SDP 775 R (Your Ref) Dated 31st October 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,
Road Traffic Accident Involving SJS 2667 U (Our Ref) and SDP 775 R (Your Ref)
Dated 31st October 2019, Time around 18:40HRS
@ HOLLAND DRIVE BLK 10A CAR PARK EXIT

We represent our client; BIZTEK LEASING, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SJS 2667 U and your insured's vehicle registration number: SDP 775 R.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim-LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel** -

Contact Person	Eric Lee	8269 9999
Email Address	teamautopt@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Singapore 575722	

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Peach
Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SJS2667U (6775374648SG)**
[SDP775R]

TP
BIZTEK LEASING
Oct 31 2019 6:00PM
[CHIA SHYH CHUAN]
Team Autopro Pte Ltd (sin Ming)

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 27/12/2019 11:24 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4869.00) - SJS2667U - Claim Handler: Foo, Chit Yan

Approved:4869.00;Cost of Repair: \$4,000.00 (Subject to final repair bill). Rental: \$700.00 - \$840.00 (\$100.00 - \$120.00 x 7 days) GIA / LTA: \$29.00

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2019 Edit Reg		06 Nov 2019 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHIA SHYH CHIUAN , ID: S1612140A									
Main Claimant: BIZTEK LEASING , Co. Reg. No.: 53329851B									
Vehicle Reg. No.:	SJS2667U	Date of Loss:	31/10/2019 18:00 - :59 [122 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6775374648SG	Policy/Cover Note No.:	2100408029 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDP775R	Policy No. (Claimant):	5108794524						
Excess:									
Repairer: Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 15/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (27/12/2019): Alert - Adj Mandate Approved (S\$4869.00) - SJS2667U - Claim Handler: Foo, Chit Y...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS2667U (6775374648SG)
[SDP775R]
TP
BIZTEK LEASING
Oct 31 2019 6:00PM
[CHIA SHYH CHIUAN]
Team Autopro Pte Ltd (sin Ming)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>	
Letters/Correspondences														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit			
Assessment Reports														1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	16/12/19 15:38	Adjuster Immediate Advice											Load HTM			
Photos/Images														3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
2	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
3	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
4	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
5	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
6	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
7	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
8	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
9	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
10	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
11	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
12	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
13	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
14	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
15	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
16	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
17	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
18	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
19	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
20	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
21	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
22	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
23	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
24	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
25	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
26	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
27	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
28	16/12/19 14:07	General View											Load JPG <input checked="" type="checkbox"/>			
29	16/12/19 14:07	Chassis Number											Load JPG <input checked="" type="checkbox"/>			
30	16/12/19 14:07	Odometer Reading											Load JPG <input checked="" type="checkbox"/>			
31	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
32	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
33	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
34	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
35	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			
36	16/12/19 14:08	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
38	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
39	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
40	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
41	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
42	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
43	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
44	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
45	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
46	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
47	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
48	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
49	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
50	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
51	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
52	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>
53	16/12/19 14:08	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/11/19 14:42	EMAIL FROM AIG DD 06112019		<input type="checkbox"/>
2	06/11/19 14:42	NOTICE & GIA REPORT		<input type="checkbox"/>
3	22/11/19 09:13	TP ESTIMATE- MARKED		<input type="checkbox"/>
4	16/12/19 14:04	LOD		<input type="checkbox"/>
5	16/12/19 14:04	RENTAL RECEIPT		<input type="checkbox"/>
6	16/12/19 14:04	GIA SEARCH FEE		<input type="checkbox"/>
7	16/12/19 15:39	OI GIA REPORT (W/CORRECT SKETCH PLAN AND STATEMENT)		<input type="checkbox"/>
8	14/01/20 08:30	WORKSHOP INVOICE		<input type="checkbox"/>
9	14/01/20 08:30	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
10	14/01/20 08:30	Release Voucher		<input type="checkbox"/>
11	14/01/20 08:30	LETTER TO OI		<input type="checkbox"/>

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/11/19 15:27	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SDP775R (Insd veh)	Model:	HYUNDAI AVANTE 1.6 HD (A)
	SJS2667U (TP veh)		
Date of Accident:	31/10/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	11,835.28
Final Repair Cost	:	\$	4,850.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	7 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,850.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 4,850.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

14 Jan
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019629/BDA3Q2

Date: 14/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100408029
 Claimant: SJS2667U Insured Vehicle No: SDP775R
 Vehicle No: SJS2667U Nature of Claim: TP Claim No: 6775374648SG
 Date of Loss: 31/10/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS2667U
 Make & Model: HYUNDAI AVANTE, 1.6 HD (A) Engine No: G4FC9U653628
 Reg. Date: 07/08/2009 (Man. Year: 2009) Chassis No: KMHDU41BR9U759143
 Colour: Blue Odometer: 206988 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,355.28	3,189.68	4,165.60	56.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	1,800.00	2,680.00	59.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,835.28	4,989.68	6,845.60	57.84
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,835.28	4,000.00	7,835.28	66.20
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,869.00		
Global Sum Settlement (S\$)		4,850.00		

INSPECTION

Date of Assignment: 06/11/2019
 Date Inspected: 06/11/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN
 MING AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,062.20 FL	*- FL
2	1		*BONNET LOCK	Not Damaged	65.00 FL	*- FL
3	1		*FRONT GRILLE LOGO	Not Damaged	58.00 FL	*- FL
4	1		*FRONT BUMPER	Dented	1,232.20 FL	*544.40 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	249.20 FL	*102.00 FL
6	1		*FRONT BUMPER GRILLE CEENTRE	Not Damaged	65.90 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP RH	Broken	198.50 FL	*198.50 FL
8	1		*HEADLAMP RH	Cut	643.50 FL	*606.00 FL
9	1		*HEADLAMP LOWER BRACKET	Not Damaged	86.10 FL	*- FL
10	1		*FRONT FENDER RH	Dented	862.40 FL	*688.00 FL
11	1		*FRONT FENDER INNER SHIELD RH	Torn	183.60 FL	*183.60 FL
12	1		*FRONT FENDER INSULATOR	Not Necessary	84.60 FL	*- FL
13	1		*FRONT FENDER EMBLEM VVT	Necessary	89.80 FL	*42.80 FL
14	1		*FRONT SHOCK ABSORBER RH	Not Damaged	319.60 FL	*- FL
15	1		*FRONT LOWER ARM RH	Dented	394.50 FL	*282.00 FL
16	1		*FRONT KNUCKLE ARM RH	Not Damaged	365.80 FL	*- FL
17	1		*FRONT KNUCKLE ARM BEARING RH	Not Damaged	135.00 FL	*- FL
18	1		*WASHER TANK	Bent	188.60 FL	*154.70 FL
19	1		*WASHER TANK MOTOR	Broken	135.60 FL	*114.60 FL
20	1		*FRONT SUPPORT PANEL	Dented	986.50 FL	*958.00 FL
21	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
22	1		*FRONT GRILLE CLIP	Not Damaged	50.00 FS	*- FS
23	1		*FRONT FENDER INNER SHIELD CLIP	Necessary	30.00 FS	*30.00 FS
24	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	2		*HEADLAMP CLIPS	Necessary	100.00 FS	*30.00 FS
26	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
27	1		*A/C COMPRESSER FLUID	Not Necessary	60.00 FS	*- FS
28	1		*ALLOY RIM RH	Not Damaged	650.00 FS	*- FS
29	1		*TYRE RH	Not Damaged	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,836.60	3,964.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,481.32	774.92
Total Parts (\$\$)	7,355.28	3,189.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,600.00	800.00
2	RUST PROOFING	New	300.00	30.00
3	SPRAY PAINT	New	1,600.00	800.00
4	TO R&R A/C CONDENSER TO CONFIRM ON THE A/C TEMPERATURE /TOP UP GAS	New	180.00	0.00
5	TO R&R RADIATOR AND PRESSURE TEST COOLING SYSTEM	New	180.00	0.00
6	TO CHECK WIRING	New	100.00	30.00
7	TO R&R UNDERCARRIAGE PARTS	New	350.00	80.00
8	TO R&R TYRE AND BALANCING	New	50.00	0.00
9	FULL WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			4,480.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >