

ASS. REC. BY:

REF: CS3/CTI19019648/Bqd30

Special Instructions:

Surveyor:

Mr. Kim

## ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

5/11/19 @ 6:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIX 1296C

Insured:

GBJ 79055

at Workshop m/s:

T &amp; S Motor

Tel:

6484 5518

of

Blk 5035 AMK Ind. park 2 #01-357

Policy No:

DM CVSN 3064761900P

Claim No:

SNMIAD205211C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment:

Date/Time:

10:53am 6/11/19

Person Contacted:

Ivake

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Validated (X)

Six 1296C - X

GBJ 79055 - X

18/11/19

Submit PRS

ASS. REC. BY:

REF:

CTI

oline

## ASSIGNMENT

From:

Date:

6/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJX 1296 L

at Workshop m/s

T &amp; S Motor

of PRV EQ35 ANK 1nd PAR2 #01-357

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 12,000/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJX 1296 L

Yr Regn:

17/5/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Orionta

cc 1477

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

151605

T/Radio: Insured / Std / NI / NA

Eng/No:

INZY080433

C/No:

MR053H42305165484

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55/15

CRUCERO

R:

195/55/15

YOKO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CRUCERO

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/11/19

D.O.I.

6/11/19

Survey held at

T &amp; S Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 4,000/2 - 5,000/2

RECEIVED 18 NOV 2019

MV 12,000/2

PV 7,533/2

NV 4,467/2

TOTAL

7/11/19

Date/Time, File Pass to?



: Preli. Report

1) 18/11/19



: Final Report

Date/Time, File Return to?

2)

Rep. Format:

PRV.

Lump Sum / L.R. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wheel end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

190

190

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 5 November 2019 6:22 PM  
**To:** Candice Lee; Jeffrey Tay  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D205211-GBJ7905S-CBS- Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SJX 1296C/TSS/ca

### Without Prejudice SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Candice Lee [mailto:accident@kscgp.com]  
**Sent:** Tuesday, November 5, 2019 4:13 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D205211-GBJ7905S-CBS- Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SJX 1296C/TSS/ca

Dear Boon Sen,

Thank you for your email.

We enclose herein the 2<sup>nd</sup> notice to conduct pre-repair inspection. Our clients are not agreeable to your proposed list of surveyors.

Please let us hear from you soon.

Thank you.

Regards,  
Candice  
For and on behalf of Mr Gurdeep Singh Sekhon  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]  
**Sent:** Tuesday, 5 November, 2019 10:48 AM  
**To:** Candice Lee; Jeffrey Tay  
**Subject:** RE: OUR REF: SNM19D205211-GBJ7905S-CBS- Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SKX 1296C/TSS/ca

Without prejudice

Dear Sir,  
LKK  
STA  
LBS

### Chong Boon Sen

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Candice Lee [<mailto:accident@kscgp.com>]  
**Sent:** Tuesday, November 5, 2019 10:37 AM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>  
**Subject:** RE: OUR REF: SNM19D205211-GBJ7905S-CBS- Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SKX 1296C/TSS/ca

Dear Boon Sen,

We refer to the above matter.

Please let us have your list of surveyors for our client's consideration.

Thank you.

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

---

**From:** Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

**Sent:** Monday, 4 November, 2019 5:17 PM

**To:** Chong Boon Sen; Jeffrey Tay; [Accident@kscgp.com](mailto:Accident@kscgp.com)

**Subject:** OUR REF: SNM19D205211-GBJ7905S-CBS- Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SKX 1296C/TSS/ca

Dear Boon Sen,

Please conduct PRS for SKX1296C.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Candice Lee [<mailto:accident@kscgp.com>]

**Sent:** Monday, 4 November, 2019 3:33 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** Notice to conduct pre-repair inspection - Your insured veh: GBJ 7905S - Our ref: SKX 1296C/TSS/ca

Dear Sirs,

We refer to the above matter.

We enclose herein the notice to conduct pre-repair inspection for your necessary action.

Please let us hear from you soon.

Thank you.

Regards,

Candice

For and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0979 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

---

This email has been scanned by the MxScan Email Security System.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the MxScan Email Security System.

---

---

This email has been scanned by the MxScan Email Security System.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the MxScan Email Security System.

---

---

This email has been scanned by the MxScan Email Security System.

---

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 645Z

### Vehicle Details

Vehicle No.: SJX1296L

Vehicle to be Exported: No

Intended Deregistration Date: 07 Nov 2019

Vehicle Make: TOYOTA

Vehicle Model: VIOSE AUTO

Primary Colour: Silver

Manufacturing Year: 2010

Engine No.: 1NZY080493

Chassis No.: MR053HY9305165484

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,331.00

Original Registration Date: 17 May 2010

First Registration Date: 17 May 2010

Transfer Count: 2

Actual ARF Paid: \$12,331.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 May 2020

PARF Rebate Amount: \$6,165.00

### Intended COE Rebate Details

COE Expiry Date: 16 May 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$26,102.00

COE Rebate Amount: \$1,368.00

Total Rebate Amount: \$7,533.00

The information contained herein is correct as at 07 Nov 2019

OK

MV 12,000/2

PV 7,533/2

NV 4,467/2

TGum  
7/11/19



**Toyota Vios 1.5A E** - N.A 14-Jun-2010 1,497 cc - Sedan **SOLD**

High Paper Value! Ideal For Short Term Drive Or Renew 5/10 Years COE! Full/High Loan Are Available At Low-Interest Rate! Original Stock Condition! High Trade-In Are Welcome! 100% Accident-Free! View To Believe It, Call Now Before It's Gone.

Starise Automobile

Posted: 23-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E** - N.A 25-May-2010 1,497 cc - Sedan **SOLD**

High Loan! High Trade In! Popular Car Suitable For COE Renewal! Make Use Of The Low COE Prices! Call Now!

Posted: 11-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E** - N.A 17-May-2010 1,497 cc - Sedan **SOLD**

100% Loan Available, We Are Full Loan Specialist, Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone.

Laxli

Posted: 23-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Transform the look of your car**

Think your used car needs a fresh face? You can consider changing the colour. Find your preferred workshop providing the best quality car spray paint service here.

Find out more!



**Toyota Vios 1.5A J (New 5-yr COE)** \$32,800 \$6,550 /yr 13-May-2010 1,497 cc 116,889 km Sedan **Available**

One Meticulous Owner. Manufacture In 2010. Facelifted. Elegant White Colour Unit. Best Ownership And Condition In Town. Most Reliable Japanese Sedan Vios Ideally For Daily Drives Yet Fuel Efficient. Great Fuel Consumption Rate Of 1L/15km. 11,000km Mileage Clocked A...

PREMIUM AD

Posted: 06-Nov-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E** - N.A 03-May-2010 1,497 cc - Sedan **SOLD**

Road Tax Until 02 May 2020. The Best Car For Renew Coe. Genuine Mileage. High Paper Value. Trade In Welcome. Flexible In House Financing Option/ Bank Loan Option Available. Low Interest Rate. View To Believe It, Call Now To Enquiry Or Arrange A Viewing Before...

Swee Seng Motors

Posted: 24-Aug-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E (New 5-yr COE)** \$29,800 \$5,950 /yr 20-Apr-2010 1,497 cc 96,000 km Sedan **Available**

100% Loan Available, We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

Laxli

Posted: 29-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E (New 10-yr COE)** - N.A 19-Apr-2010 1,497 cc - Sedan **SOLD**

10 Years COE Available, Flexible Loan Available, Low Monthly Instalment, Low Mileage, Low Depreciation, Excellent Maintained Condition, No Repairs Needed.

Posted: 17-Sep-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E Sports (New 5-yr COE)** \$31,888 \$6,370 /yr 05-Apr-2010 1,497 cc 104,302 km Sedan **Available**

We Are The COE Specialist. No Gimmicks, Honest Dealing, Full Agent Maintained, 1 Owner With Low Mileage Clocked. Car In Superb Condition, Full Loan Available! 100% Approval. Trade-In Welcome, Bank Loan Available. Please Call Our Friendly Salesman For An Appoi...

PREMIUM AD

Posted: 25-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A G** \$13,800 N.A 22-Mar-2010 1,497 cc 97,000 km Sedan **Available**

100% Loan Available, We Only Select The Best Unit To Sell. All Our Car Come With Trade In Welcomed. Buy With A Peace Of Mind As Car Is In Fantastic Condition. Hurry, Call For Availability Or Viewing Appointment.

Laxli

Posted: 31-Oct-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



**Toyota Vios 1.5A E (New 5-yr COE)** - N.A 16-Mar-2010 1,497 cc - Sedan **SOLD**

Excellent Unit Believe It Or Not Authentic Low At Mileage 102k Km, (Proved Of Pictures), Full Body Kit, Clean And Beautiful Interior, 100% Accident Free, No Gimmicks No Hidden Cost, No Monkey Business, Buy With Peace Of Mind, 100% In House Loan Available, Act Now An...

Posted: 14-Sep-2019 Tags: 2010 Toyota Vios, 2010 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

**Toyota Vios 1.5A E (New 5-yr COE)** - N.A 01-Mar-2010 1,497 cc - Sedan **SOLD**

Well Maintained By Previous Owners, Bank And In House Loan Available. Call Me Now To View The Car!

DIRECT OWNER

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/11/2019 16:14
Date Of Accident	03/11/2019 12:25
Exact Location Of Accident	SLIP RD FM TOA PAYOH LOR 1 TO TOA PAYOH LOR 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX1296L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HL LIMO PTE. LTD.
Co Reg No	201624645Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98292169
Alternative Phone No	OFFICE-98292169

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5112551500
Cover Note Number	

### Driver

Name of Driver	ADNAN BIN ABDUL AZIZ
NRIC No	S1406100B
Date Of Birth	19/11/1960
Occupation	OUTDOOR
Date Of Driving Pass	28/05/1998
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98292169
Fax Number	
Contact Number	OFFICE-98292169
EEmail Address	NOEMAIL

Address	533 WOODLANDS DR 14 #06-573
Postcode	S730533
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TANGLIN POLICE DIVISIONAL HQ ( 'E' DIVISION )
Police Station Address	ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3910000 - FAX NO: 63964900
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	JENSEN PNG
Phone Number	91168159
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ7905S
Vehicle Make/Model/Colour	RENAULT VAN
Details Of Properties	

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HO LIP TENA
NRIC/Passport Number	S8811545G
Contact Number	98394826
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	ADNAN BIN ABDUL AZIZ
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SJX1296L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- 4 NOV 2019

IDAC BUKIT BATOK (VAC)  
611 Bukit Batok Street 23  
Singapore 650445  
Tel: 650 5512 Fax: 650 0722  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



E/20191104/7020

1 of 2

**POLICE REPORT (NP299)**

Police Station Of Origin  
Tanglin Division HQ  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-3910000

Report No. E/20191104/7020

Date/Time Report Made 04/11/2019 13:28		Vide Report No.		Station Diary No.	
Name Of Informant ADNAN BIN ABDI H A717		Address APT RI K 533 WOODLANDS DRIVE 14 #06-573 SINGAPORE 730533			
ID Type / ID No. NRIC NO / S1406100B		Contact No. Home/Office: Mobile: 98292169			
Nationality SINGAPORE CITIZEN		Email Address addig3@gmail.com			
Occupation PHC Driver		Sex Male	Age 58	Date of Birth 19/11/1960	Race Malay
Institution/School Name		Language English			
Date/Time Of Incident 03/11/2019 12:25 - 03/11/2019 12:35		Location Of Incident near 237 LORONG 1 TOA PAYOH			
<b>Brief details.</b>					


As soon as I moved from Lor 1 to reach slip end at broken lines to turn into Lor 6 to Braddell Road/Flyover, a company Enerprof Van driven by a male Singaporean Chinese driver lost control, accelerated and bumped into the back of my Toyota Vios car at about 12.29pm. There was a medium thud and jerk and my car shook. The day was fine bright and clear, no rain, nor any water, oil spill or wetness on the road and traffic was mild. I was ferrying a rider from Lor 1 Toa Payoh pickup to send him to Seletar Mall on a Gojek trip RB-2963549714. Neither rider nor I was injured but personally I felt a little shock and slight discomfort. I came out, took several snap photos of our vehicles, road angles and traffic

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 04/11/2019 13:28
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



E/20191104/7020

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20191104/7020

conditions. The van driver and I exchanged our particulars. I told the Van driver the damage is substantially large and I will definitely file for claims. Rider's trip had to be aborted, he left a while later on another PH car after agreed to be my witness. The van driver told me he had just went for his therapy for his back problem. I told him my rental car company will get in touch with his party for claims.

Person Name	ADNAN BIN ABDUL AZIZ		
ID Type	NRIC NO	ID No	S1406100B
Gender	Male	Age	58
Race	Malay	Language	English
Occupation	PHC Driver	Address Type	
Address	APT BLK 533 WOODLANDS DRIVE 14 #06-573 SINGAPORE 730533		Mobile No 98292169
Is Informant A Victim?	Yes		
Person Name	ADNAN BIN ABDUL AZIZ (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of interpreter: Not applicable	Date/Time: 04/11/2019 13:28
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2019		18 Nov 2019 10:19 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Co. Reg. No.: -	
Main Claimant:	HL LIMO PTE. LTD., Co. Reg. No.: 201624645Z	
Vehicle Reg. No.:	SJX1296L	Date of Loss: 03/11/2019 12:00 - :59 [113 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205211C02	Policy/Cover Note No.: DMCVSN30647619000
Vehicle Reg. No. (Insured):	GBJ7905S	Policy No. (Claimant): 5112551500
		Excess: S\$0.00
Repairer:	T & S MOTOR SERVICE (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #04-10, 568047 Ang Mo Kio - Tel:	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 27/11/2019]	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		
















































  

ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents


\*SJX1296L (SNM19D205211C02)  
[GBJ7905S]  
TP  
HL LIMO PTE. LTD.  
Nov 3 2019 12:00PM  
[-]  
T & S MOTOR SERVICE







Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)							Thumbnail	Print	
1	04/11/19 16:23	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)							Thumbnail	Print	
1	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 16:23	Accident Photo <small>[Linked Accident Report Documents]</small>								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
2	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
3	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
4	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
5	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
6	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
7	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
8	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
9	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
10	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
11	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
12	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
13	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
14	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
15	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
16	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
17	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
18	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
19	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
20	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
21	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
22	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
23	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
24	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
25	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
26	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
27	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
28	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
29	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
30	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>
31	18/11/19 14:31	General View								Load JPG	<input checked="" type="checkbox"/>





Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
				<input checked="" type="checkbox"/>
32	18/11/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/11/19 14:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
34	18/11/19 14:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
35	18/11/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/11/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/11/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/11/19 14:31	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	18/11/19 14:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/11/19 14:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/11/19 14:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/11/19 14:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/11/19 14:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/11/19 14:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	04/11/19 16:21	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	04/11/19 16:21	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	04/11/19 16:22	PR [Linked Accident Report Documents]	 Load TIF	
4	04/11/19 16:22	PR [Linked Accident Report Documents]	 Load TIF	

### Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	04/11/19 16:23	Accident Statement		Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 16:23	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	04/11/19 16:21	Sketch Plan		Load TIF	
2	04/11/19 16:21	Sketch Plan #2		Load TIF	
3	04/11/19 16:22	PR		Load TIF	
4	04/11/19 16:22	PR		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119019648/BQD3E2

Date: 19/11/2019

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30647619000
Claimant Vehicle No :	SJX1296L	Insured Vehicle No :	GBJ7905S
Date of Loss:	03/11/2019	Nature of Claim: TP	Claim No: SNM19D205211C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJX1296L</b>	Engine No:	1NZY080493
Make & Model:	TOYOTA VIOS EA, 1.5 (A)	Chassis No:	MR053HY9305165484
Reg. Date:	17/05/2010 (Man. Year: 2010)	Odometer:	151608 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Crucero 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Crucero 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	18/11/2019	
Date Inspected:	06/11/2019 Inspected At:	T & S MOTOR SERVICE (HQ) BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538
Estimated Period of Repair:	5.0 days	

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2019)
<b>Parts:</b>	143	TOYOTA VIOS EA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJX1296L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >