

27/07/2002

ASS. REC. BY

REF: CS/FWD 19019661/Vyf3

Special Instruction:

EXCESS
\$1500SUNVAYOR MARCUS

ASSIGNMENT (Office)

From (Person): Eileen Bay

of

FWDDate/Time: 6.11.19 16.05p.m

photo a/c

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJN 5334L

Insured:

at Workshop m/s SME motor

Tel:

67476106of 1 Kaki Bukit Ave 6 #02-15Policy No: PNPV2019-00004758

Claim No:

1201900033619

Excess:

\$1500.00

Sum Insured:

D.O.A.

2.11.2019

Make of Veh:

(Client's Record)

6.11.2019

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 6.11.2019 4.16p.m

Person Contacted:

Vehicle IN OUT

photo a/c

Date/Time	Action/Instruction (✓) Estimate
	<u>SJN 5334L - NA / FWD 19019340/24 DCA-02/11/2019</u>
<u>8/11/19</u>	<u>Revert Via Merimen</u>
<u>8/11/19</u>	<u>authorise by Eileen Bay</u>
<u>8/11/19 @ 5.30pm</u>	<u>inform Jacob authorise repair</u>
<u>11/11/19</u>	<u>Rece approved \$8100 from Clara by merimen</u>
<u>11/11/19</u>	<u>Informed Jacob c/A on LS repair</u>
<u>11/11/19</u>	<u>Upload LIS Authorise in Merimen</u>

REF: FWD

ASS. REC. BY:

ASSIGNMENT

From:

Date:

7.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJN 5334 L

at Workshop m/s SME Motor

of 1 Kaki Bukit Ave 6 #02-15

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: \$1500.00

(Client's Record)

Make of Veh:

morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

356.

I/A/C Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJN 5334 L

Yr Regn:

2.09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Mazda 3

c.c.

1598

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading:

145949

T/Radio: Insured / Std / NI / NA

Eng/No:

JM 6BK106280 441203

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

continental

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

7/11/19

mm

D.O.A.

2/11/19

D.O.I.

7/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/1/19 LTA 2388/ coe 18.2.2019

2/3 #7200 confirmed with AH Yung (Red \$3665.00, 33%)

13/1/20 Revert due to Supp Via Merimen

RECEIVED 13 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

13/1/20 Typist

Report Form:

Lump Sum P/B/C

\$7200/-

Days Of Repair:

7

Resurvey No. of Trip:

3

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week end (\$

Survey Fee:

Transportation:

S + RS. SI

Photos:

Others:

TOTAL

250

50

50

11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Nov 2019 11:55 Sendback Est	06 Nov 2019 12:16 S\$10,411.00	06 Nov 2019 16:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HOR YONG FEI, ID: S8066656Z		02/11/2019 14:00 - :59 [128 Months and 14 Days From LTA Reg Date (Man Yr)]						
Vehicle Reg. No.:	SJN5334L	Date of Loss:	PNPV2019-00004758 (Comprehensive) Coverage: 05/03/2019 - 04/03/2020						
Claim Type:	OD / 1201900033619	Policy/Cover Note No.:	Excess: S\$1,500.00						
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/11/2019]								
			View All	Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, November 14, 2019 9:37 AM
To: SEBASTIAN@SMEMOTOR.COM.SG
Cc: gary.siah@smemotor.com.sg; SUR
Subject: VEHICLE SJN5334L DOA: 02/11/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SJN5334L on **LUMP SUM NOT EXCEEDING \$8100/- (excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

YC Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Attention: Motor Claims Department
FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01, Suntec Tower 4
Singapore 038986

AUTHORIZATION FOR LUMP SUM REPAIR

I, [Name] [NRIC] HOR YONG FEI, the owner/ authorized driver of
vehicle [Registration No.] SJWS334L ("Vehicle") do hereby authorize the
SME MOTOR PTE LTD. ("Workshop") to repair the Vehicle on a lump sum basis
instead of part by part.

The Workshop has explained to me the difference between lump sum repair and part by part repair,
which lump sum repair means the Workshop may use a mixture of genuine parts and/or original
equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the
necessary repair.

Signed and acknowledged by:



Signature of Policyholder/ authorized driver*

*to be applicable where the person authorizing is the authorized driver:-

I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs
and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Date: 12/11/19



Gary Seah

Name and signature of workshop personnel including workshop stamp

Date: 12/11/19

View Received Message

This mail is associated with :

SJN5334L (1201900033619)

OD

Nov 2 2019 2:00PM

[HOR YONG FEI]

SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **13/01/2020 13:03 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7200.00) - SJN5334L - Claim Handler: Eileen Bay

Approved:7200.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJN5334L (1201900033619)

OD
Nov 2 2019 2:00PM
[HOR YONG FEI]
SME Motor Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 11/11/2019 12:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8100.00) - SJN5334L - Claim Handler: Eileen Bay

Approved:8100.00.

6747 6106

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SJN5334L (1201900033619)

OD
Nov 2 2019 2:00PM
[HOR YONG FEI]
SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **08/11/2019 15:58 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7400.00) - SJN5334L - Claim Handler: Eileen Bay

Approved:7400.00:Please re-seek mandate after check items verified

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 13 Jan 2020

Preliminary Advice

Vehicle No	: SJN5334L	Accident Date	: 02/11/2019
Make	: MAZDA 3	Policy No.	: PNPV2019-00004758
Assignment Date	: 06/11/2019	Excess	: S\$1,500.00
Date of Inspection	: 07/11/2019	Est. Duration of Repair	: 7.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,865.00 (INCL SUPP \$454.00)
Revised Amount (Lump sum)	:S\$	7,200.00 (INCL SUPP \$454.00)
Check Items (Estimated)	:S\$	
Total	:S\$	7,200.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	23,881.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,119.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 08 Nov 2019

Preliminary Advice

Vehicle No	: SJN5334L	Accident Date	: 02/11/2019
Make	: MAZDA 3	Policy No.	: PNPV2019-00004758
Assignment Date	: 06/11/2019	Excess	: S\$1,500.00
Date of Inspection	: 07/11/2019	Est. Duration of Repair	: 7.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,411.00
Revised Amount	:S\$	4,766.00
Check Items (Estimated)	:S\$	5,365.00
Total	:S\$	10,131.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	23,881.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,119.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 11:13
Date Of Accident	02/11/2019 15:00
Exact Location Of Accident	PIE (TUAS) BEFORE KPE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN5334L
Insured/Policyholder	
Name Of Registered Owner	HOR YONG FEI
NRIC No	S8066656Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91138977
Alternative Phone No	OFFICE-91138977
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA3 SP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00004758
Cover Note Number	
Driver	
Name of Driver	HOR YONG FEI@DUSTY
NRIC No	S8066656Z
Date Of Birth	01/01/1980
Occupation	INDOOR
Date Of Driving Pass	30/01/2010
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91138977
Fax Number	
Contact Number	OFFICE-91138977
Email Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SJT494J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

DATE: 11/11/2015, TIME: 12:15

1. Signature
2. Date
3. Location
4. ...

A B C D E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was on the 2nd lane. I was not able to stop the vehicle on time when the vehicles in front suddenly stopped on the road and I rear ended into the back of a red car SMAB407Z

DECLARATION

I/ We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Center Personnel's Signature
Name:
NRIC ID No:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 656Z

Vehicle Details

Vehicle No.: SJN5334L

Vehicle to be Exported: No

Intended Deregistration Date: 07 Nov 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 SP

Primary Colour: White

Manufacturing Year: 2008

Engine No.: Z6745122

Chassis No.: JM6BK106280441203

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$15,993.00

Original Registration Date: 19 Feb 2009

First Registration Date: 19 Feb 2009

Transfer Count: 4

Actual ARF Paid: \$15,993.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 18 Feb 2029

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

PQP Paid: \$25,727.00

COE Rebate Amount: \$23,881.00

Total Rebate Amount: \$23,881.00

The information contained herein is correct as at 07 Nov 2019

OK

COMING SOON
9-11 NOV
FIND OUT MORE



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2012 Volkswagen Scirocco 1.4 TSI At \$38.8K.



Tastefully Done Up Scirocco 1.4
TSI For Sale! Immaculate
Condition!
Direct Owner StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

16 vehicles

mazda 3

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mazda 3	Any	Any	2009	Any	Any	Any	Available
	Mazda 3 HB 1.6A (New 5-yr COE)	\$33,800	\$6,750 /yr	26-Nov-2009	1,598 cc	91,000 km	Hatchback	Available
Rare And Hot Hatchback Unit! Sporty With Spacious To Drive! Bank Loan, In House Loan, 100% Loan Available! Attractive Interest Rate!...								
Straits Euro Motors Pte Ltd								
Posted: 07-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.6A Luxury (New 5-yr COE)	\$30,800	\$6,150 /yr	30-Sep-2009	1,598 cc	110,821 km	Sedan	Available
3.25% Interest, 100% In House Loan Available! Original Stock Paintwork! Pristine Condition! Smooth Transmission And Responsive Engi...								
Posted: 06-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.6A Luxury (New 5-yr COE)	\$29,800	\$5,950 /yr	28-Oct-2009	1,598 cc	140,000 km	Sedan	Available
Full Loan Available! Easy And Low Cost To Maintain Car! New Paint, Ideal For COE Renewal. Reliable And Low Cost To Maintain Sedan! Jus...								
Posted: 04-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.6A Luxury (New 5-yr COE)	\$32,800	\$6,550 /yr	29-Dec-2009	1,598 cc	91,000 km	Sedan	Available
Bank Loan, In House Loan, 100% Loan Available! Attractive Interest Rate! Trade In Welcome. Extremely Well Maintained By Previous O...								
Straits Euro Motors Pte Ltd								
Posted: 04-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
GET YOUR COE RENEWAL LOAN								
Is your COE expiring? Let us help you renew it!								
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Mazda 3 HB 1.6A (New 5-yr COE)	\$33,800	\$6,750 /yr	24-Dec-2009	1,598 cc	97,888 km	Hatchback	Available
Rare & Popular Mazda Hatchback. Low Mileage Less Than 97k In 10 Years All In Original Condition! Cold Aircon, Responsive Gearbox & En...								
Car (S) Pte Ltd								
Posted: 03-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								
	Mazda 3 1.6A Luxury (New 10-yr COE)	\$43,888	\$4,390 /yr	29-Sep-2009	1,598 cc	105,000 km	Sedan	Available
Owned This Car With 90% Loan Amount Shown! Various Financial Plan To Cater Individual Needs, Flawless Interior And Exterior Condi...								
Posted: 03-Nov-2019 Tags: 2009 Mazda 3, 2009 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda								

Compare

Google Pixel 4

Meet the new Pixel 4, built around the helpful Google software you know & love. Shop now.

mazda 3

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Creative Auto Leasing Pte Ltd » Mazda 3 1.6A Luxury (New 10-yr COE)

Mazda 3 1.6A Luxury (New 10-yr COE)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price \$43,888

Depreciation \$4,390 /yr

Reg Date 29-Sep-2009
(10yrs COE left)

Mileage 105,000 km (10.4k /yr)

Manufactured 2009

Road Tax \$742 /yr

Transmission Auto

Dereg Value N.A.

OMV \$21,324

COE N.A.

ARF \$21,324

Engine Cap 1,598 cc

Power 77.0 kW (103 bhp)

Curb Weight 1,275 kg

No. of Owners 3

Type of Vehicle Mid-Sized Sedan

Features

Powerful And Responsive 1.6L DOHC Engine, 4 Speed Automatic Transmission, Dual Climatic Control Aircon, Keyless Push Start, Airbags, 4 Discs Brakes. View specs of the Mazda 3 Sedan (2009-2014)

Accessories

17" Original Rims, Factory Audio System, Steering Controls, Fog Lights, Leather Seats, Reverse Sensors, Retractable Side Mirrors, 2009 Facelift Model.

Description

Owned This Car With 90% Loan Amount Shown! Various Financial Plan To Cater Individual Needs, Flawless Interior And Exterior Conditions, Extremely Low Mileage Clocked, All Wear And Tears Had Been Minimized, One Of Our Company Carefully Selected Range Of COE Renewal Cars, Our Quality Pre-Owned Cars Are Of Low Depreciation Price, Call Our Knowledgeable Salesman For A Viewing Or Test Drive!. Call To V

Category

COE Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Creative Auto Leasing Pte Ltd

» dealer's pricelist

» 39 vehs sold | 42 vehs available

Address

61 Ubi Ave 2 #04-03

Search cars nearby this location

Location

Automobile Megamart

Office No

68411279

Contact Person(s)

Tian Cheng

88338380

Chia Kian Hong

97460421

Tony

90290899

Terence

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/FWD/OD-538 (11)
Policy No:	PNPV2019-00004758	Date of Loss:	02/11/2019
Vehicle Reg. No.:	SJN5334L	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HOR YONG FEI		

Make/Model:	MAZDA 3, 1.6 SP (A)	Vehicle Reg. Date:	19/02/2009
Vehicle Colour:	WHITE	Chassis No:	JM6BK106280441203
Engine No:	Z6745122		
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **14**

*Not Authorized
 Take ph before party.
 Today.
 15:00
 7/11/19*

Remarks: **VEHICLE IN.**
 Present Location: **SME MOTOR PTE LTD (KAKI BUKIT)**

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		8,436.00
Labour		45.00
Paintwork Labour		1,930.00
Towing		0.00
		0.00
	Gross Total (\$\$)	10,411.00
	+ GST 7.00% (\$\$)	728.77
	Nett Amount (\$\$)	11,139.77

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

This claim is handled by: **CHIA PEI YING**

108656

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 06 Nov 2019)

Parts: 143

MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SJN5334L/06/11/2019 12:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Buc</i>	0.00	0.00	*350.00 F ✓
2	1		*FRT BONNET LOCK <i>Tw</i>	0.00	0.00	*80.00 F ✓
3	2		*FRT BONNET HINGE <i>Bent</i>	0.00	0.00	*60.00 F ✓
4	1		*FRT BONNET RUBBER <i>Rel</i>	0.00	0.00	*35.00 F ✓
5	1		*FRT GRILLE ASSY <i>CNE</i>	0.00	0.00	*195.00 F ✓
6	4		*FRT GRILLE CLIP <i>Rel</i>	0.00	0.00	*10.00 F ✓
7	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*350.00 F ✓
8	2		*FRT BUMPER RETAINER <i>Bent</i>	0.00	0.00	*50.00 F ✓
9	10		*FRT BUMPER CLIP <i>Rel</i>	0.00	0.00	*20.00 F ✓
10	1		*FRT BUMPER LOWER GRILLE <i>Tw</i>	0.00	0.00	*65.00 F ✓
11	1		*NUMBER PLATE GARNISH <i>D.S</i>	0.00	0.00	*45.00 F ✓
12	1		*FRT BUMPER LOWER SPOILER <i>Tw/Bent</i>	0.00	0.00	*330.00 F ✓
13	1		*FRT BUMPER REINFORCEMENT <i>D.S</i>	0.00	0.00	*295.00 F ✓
14	2		*FRT BUMPER BEAM (BELOW HEADLAMP) <i>CNE/Bent</i>	0.00	0.00	*60.00 F ✓
15	2		*HEADLAMP <i>CNE</i>	0.00	0.00	*590.00 F ✓
16	1		*HEADLAMP SUPPORT PANEL <i>CNE</i>	0.00	0.00	*220.00 F ✓
17	1		*BRACE PANEL <i>Tw</i>	0.00	0.00	*30.00 F ✓
18	2		*FRT BUMPER CENTER BRACKET <i>Tw/CNE</i>	0.00	0.00	*56.00 F ✓
19	1		*OIL COOLER <i>Bent/Pur</i>	0.00	0.00	*195.00 F ✓
20	1		*AIRCON CONDENSER <i>D.S</i>	0.00	0.00	*300.00 F ✓
21	1		*RADIATOR <i>CNE/D.S</i>	0.00	0.00	*360.00 F ✓
22	1		*RADIATOR MOTOR ASSY <i>CNE</i>	0.00	0.00	*680.00 F ✓
23	1		*RADIATOR TOP HOSE <i>Tw</i>	0.00	0.00	*30.00 F ✓
24	1		*INTAKE MANIFOLD <i>CNE</i>	0.00	0.00	*650.00 F ✓
25	1		*THROTTLE BODY <i>Tw/Bent</i>	0.00	0.00	*520.00 F ✓
26	1		*AIRCON LIQUID PIPE <i>Tw</i>	0.00	0.00	*185.00 F ✓
27	1		*AIR DUCT <i>CNE</i>	0.00	0.00	*190.00 F ✓
28	1		*AIR HOSE <i>Tw</i>	0.00	0.00	*100.00 F ✓
29	1		*AIR CLEANER BOX <i>Tw</i>	0.00	0.00	*280.00 F ✓
30	1		*FRT RH FENDER <i>Bent/Buc</i>	0.00	0.00	*160.00 F ✓
31	1		*ENGINE TOP COVER <i>Power from CNE</i>	0.00	0.00	*1,800.00 F ✓
32	1		*THROTTLE CABLE <i>Tw</i>	0.00	0.00	*75.00 F ✓
33	1		*FRT BONNET LOCK CABLE <i>Tw</i>	0.00	0.00	*70.00 F ✓

F=Franchise part.

Total Parts (S\$)

8,436.00

SME Motor Pte Ltd/SJN5334L/06/11/2019 12:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	NUMBER PLATE	cm	25.00
2	1	RADIATOR COOLANT	1m	20.00
Sub Total (S\$)				45.00

Estimates on Labour

No	Particulars	Lab.Type		Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	20	30.00
2	REMOVE & REFIX AIRCON AND GAS	New		100.00
3	REMOVE & REFIX ECU AND THROTTLEBODY	New	80	150.00
4	LABOUR CHARGE	New	600	650.00
5	SPRAY PAINTING	New	850	1,000.00
Gross Labour Cost (S\$)				1,930.00

SME Motor Pte Ltd/SJN5334L/06/11/2019 12:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Estimates on Miscellaneous Items

No	Particulars	Amount
<u>Miscellaneous Items</u>		
1	NUMBER PLATE	CM 25.00 ✓
2	RADIATOR COOLANT	1L 20.00 ✓
Sub Total (S\$)		45.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New 20	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	REMOVE & REFIX ECU AND THROTTLEBODY	New 80	150.00
4	LABOUR CHARGE	New 600	650.00
5	SPRAY PAINTING	New 850	1,000.00
Gross Labour Cost (S\$)			1,930.00

SME Motor Pte Ltd/SJN5334L/06/11/2019 12:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ENGINE MOUNTING - LH - To do 120 ✓ \$120
 WASHER TANK - de ✓ - \$130
 ENGINE UNDER COVER - To do ✓ \$35
 AIR GUIDE LH - To do ✓ \$45
 12pc ENGINE UNDER COVER CURS - 2X12

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2019)
Parts: 143 MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN5334L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ENGINE MOUNTING LH	0.00	0.00	*120.00 F
2	1		*WASHER TANK	0.00	0.00	*130.00 F
3	1		*ENGINE UNDER COVER	0.00	0.00	*35.00 F
4	1		*AIR GUIDE LH	0.00	0.00	*45.00 F
5	12		*ENGINE UNDER COVER CLIPS	0.00	0.00	*24.00 F
Total Parts (\$\$)						354.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

234

Parts
 SN
 Le

~~8220~~
 45
 1750

 10,015
 - 203
 9812

P-7250
 S.V-45
 L 1750

 9045
 102

 7236

Us ~~8000~~

29/10/2019

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REPAIR WIER HARNESS	New	100.00
Gross Labour Cost (\$)			100.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Nov 2019 11:55 Sendback Est	06 Nov 2019 12:16 S\$10,411.00	06 Nov 2019 16:05 Edit Adj Rpt	S\$7,200.00 Edit Estimates	S\$7,200.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	27 Nov 2019 12:33	27 Nov 2019 12:35 S\$454.00	27 Nov 2019 12:35			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: HOR YONG FEI , ID: S8066656Z	
Vehicle Reg. No.: SJN5334L	Date of Loss: 02/11/2019 14:00 - :59 [128 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 1201900033619	Policy/Cover Note No.: PNPV2019-00004758 (Comprehensive) Coverage: 05/03/2019 - 04/03/2020
Excess: S\$1,500.00	
Repairer: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)	
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/11/2019]	

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- FWD_SG (13/01/2020): Alert - Adj Mandate Approved (S\$7200.00) - SJN5334L - Claim Handler: Eileen Bay
- FWD_SG (13/01/2020): Alert - Adj Mandate Maintained - SJN5334L - Claim Handler: Eileen Bay
- FWD_SG (11/11/2019): Alert - Adj Mandate Approved (S\$8100.00) - SJN5334L - Claim Handler: Eileen Bay
- FWD_SG (08/11/2019): Alert - Adj Mandate Approved (S\$7400.00) - SJN5334L - Claim Handler: Eileen Bay

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN5334L (1201900033619)

OD

Nov 2 2019 2:00PM

[HOR YONG FEI]
















































SME Motor Pte Ltd
















































Upload Documents Upload Photos Compose New Letter





View View in Browser ▼

Assessment Reports					1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print	
1	06/11/19 12:16	Repairer Estimates	1	Load HTM		
2	27/11/19 12:35	Repairer Estimates Suppl. #1	1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/11/19 14:53	Adjuster Immediate Advice	1	Load HTM		
2	11/11/19 11:39	Adjuster Immediate Advice	1	Load HTM		
3	13/01/20 09:26	Adjuster Immediate Advice	1	Load HTM		

Photos/Images					3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
2	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
3	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
4	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
5	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
6	08/11/19 14:55	General View	1	Load JPG	<input checked="" type="checkbox"/>	
7	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
8	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
9	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
10	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
11	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
12	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
13	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
14	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
15	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
16	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
17	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
18	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
19	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
20	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
21	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
22	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
23	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
24	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
25	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
26	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
27	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
28	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
29	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
30	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
31	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
32	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
33	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	
34	08/11/19 14:56	General View	1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
35	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
65	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
66	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
67	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
70	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
71	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
72	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
73	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
74	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
75	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
76	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
77	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
78	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
79	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
80	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
81	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
82	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>
83	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>
84	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>
85	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>
86	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>
87	08/11/19 14:56	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
88	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
89	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
90	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
91	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
92	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
93	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
94	08/11/19 14:56	General View	 Load JPG	<input checked="" type="checkbox"/>
95	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	15/11/19 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	15/11/19 17:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
136	15/11/19 17:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
137	15/11/19 17:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
138	29/11/19 18:13	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
139	29/11/19 18:13	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
140	29/11/19 18:13	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		SME Motor Pte Ltd (Kaki Bukit)		
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	06/11/19 12:21	E-filed GIA report	 Load PDF	
2	12/11/19 12:19	LUMP SUM AUTHORISATION LETTER	 Load PDF	
No	Relabel/Reorder		Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)		
1	08/11/19 09:35	MARK ESTIMATE	 Load PDF	
2	14/01/20 13:22	SUPPLEMENTARY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19019661/UYP3S2

Date: 14/01/2020

REFERENCE

Insured/Claimant: HOR YONG FEI Policy No: PNPV2019-00004758
Date of Loss: 02/11/2019 Nature of Claim: OD Claim No: 1201900033619

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN5334L**
Make & Model: MAZDA 3, 1.6 SP (A) Engine No: Z6745122
Reg. Date: 19/02/2009 (Man. Year: 2008) Chassis No: JM6BK106280441203
Colour: White Odometer: 145949 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$35,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,790.00	7,250.00	1,540.00	17.52
Miscellaneous Items	45.00	45.00	0.00	0.00
Labour	2,030.00	1,750.00	280.00	13.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,865.00	9,045.00	1,820.00	16.75
Approved Total (Overridden) (S\$)		7,200.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	10,865.00	5,700.00	5,165.00	47.54
+ GST 7.00/7.00% (S\$)	760.55	399.00	361.55	47.54
Nett Amount (S\$)	11,625.55	6,099.00	5,526.55	47.54

INSPECTION

Date of Assignment: 06/11/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 07/11/2019 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
Estimated Period of Repair: 7.0 days 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2020)	
Parts: 143	MAZDA 3 1.6 SP (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SJN5334L)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Buckled	350.00 F	*350.00 F
2	1		*FRT BONNET LOCK	Twisted	80.00 F	*80.00 F
3	2		*FRT BONNET HINGE	Bent	60.00 F	*60.00 F
4	1		*FRT BONNET RUBBER	Necessary	35.00 F	*35.00 F
5	1		*FRT GRILLE ASSY	Cracked	195.00 F	*195.00 F
6	4		*FRT GRILLE CLIP	Necessary	10.00 F	*10.00 F
7	1		*FRT BUMPER	Distorted	350.00 F	*350.00 F
8	2		*FRT BUMPER RETAINER	Bent	50.00 F	*50.00 F
9	10		*FRT BUMPER CLIP	Necessary	20.00 F	*20.00 F
10	1		*FRT BUMPER LOWER GRILLE	Torn	65.00 F	*65.00 F
11	1		*NUMBER PLATE GARNISH	Distorted	45.00 F	*45.00 F
12	1		*FRT BUMPER LOWER SPOILER	Torn / Broken	330.00 F	*330.00 F
13	1		*FRT BUMPER REINFORCEMENT	Distorted	295.00 F	*295.00 F
14	2		*FRT BUMPER BEAM (BELOW HEADLAMP)	Cracked / Bent	60.00 F	*60.00 F
15	2		*HEADLAMP	Cracked	590.00 F	*590.00 F
16	1		*HEADLAMP SUPPORT PANEL	Cracked	220.00 F	*220.00 F
17	1		*BRACE PANEL	Twisted	30.00 F	*30.00 F
18	2		*FRT BUMPER CENTER BRACKET	Twisted / Cracked	56.00 F	*56.00 F
19	1		*OIL COOLER	Bent / Punctured	195.00 F	*195.00 F
20	1		*AIRCON CONDENSER	Distorted	300.00 F	*300.00 F
21	1		*RADIATOR	Cracked / Distorted	360.00 F	*360.00 F
22	1		*RADIATOR MOTOR ASSY	Cracked	680.00 F	*680.00 F
23	1		*RADIATOR TOP HOSE	Not Necessary	30.00 F	*- F
24	1		*INTAKE MANIFOLD	Cracked	650.00 F	*650.00 F
25	1		*THROTTLE BODY	Twisted / Bent	520.00 F	*520.00 F
26	1		*AIRCON LIQUID PIPE	Not Necessary	185.00 F	*- F
27	1		*AIR DUCT	Cracked	190.00 F	*190.00 F
28	1		*AIR HOSE	Torn	100.00 F	*100.00 F
29	1		*AIR CLEANER BOX	Not Necessary	280.00 F	*- F
30	1		*FRT RH FENDER	Bent / Buckled	160.00 F	*160.00 F
31	1		*ENGINE TOP COVER POWER TRAM	Cracked	1,800.00 F	*950.00 F
32	1		*THROTTLE CABLE	Not Necessary	75.00 F	*- F
33	1		*FRT BONNET LOCK CABLE	Twisted	70.00 F	*70.00 F
Supplementary #1						
34	1		*ENGINE MOUNTING LH	Not Necessary	120.00 F	*- F
35	1		*WASHER TANK	Deformed	130.00 F	*130.00 F
36	1		*ENGINE UNDER COVER	Torn	35.00 F	*35.00 F
37	1		*AIR GUIDE LH	Torn	45.00 F	*45.00 F
38	12		*ENGINE UNDER COVER CLIPS	Necessary	24.00 F	*24.00 F

F=Franchise part.

Total Parts (S\$) 8,790.00 7,250.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE (Cracked)	25.00	25.00
2	1	RADIATOR COOLANT (Necessary)	20.00	20.00
Sub Total (S\$)			45.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX ECU AND THROTTLEBODY	New	150.00	80.00
4	LABOUR CHARGE	New	650.00	600.00
5	SPRAY PAINTING	New	1,000.00	850.00
Supplementary #1				
Labour Items				
6	REPAIR WIER HARNESS	New	100.00	100.00
Gross Labour Cost (S\$)			2,030.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >