

22/03/2019

ASS. REC. BY:

Surveyor: Steve

REF: CS/LPC19019740/ES d3lb

Special Instruction:

ASSIGNMENT (Office)

From (Person): Ong lili

of

Lpc

Date/Time: 6/11/19 @ 2:15pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLT 5785M

Insured:

GBD 2146E

at Workshop m/s

Win Automotive

Tel:

9750 6777

of

Blk 6 woodlands Road 399J, Yew Tee Ind. Estate

Policy No:

Claim No:

19/19/19/VCS/022599

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:37pm 6/11/19

Person Contacted:

Ms. Sini

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimate</u> ✓ <u>SJE choose Steve</u>
<u>6/11/19</u>	<u>keep voicemail - phone is not Reachable will try call tomorrow again.</u>
<u>7/11/19</u>	<u>called back again voicemail. call Ms. Sini she said winson is her brother he went overseas and the vehicle is not In.</u>
	<u>SLT 5785M - X</u>
	<u>GBD 2146E - X</u>

ASS. REC. BY Steve

REP: JPC

SJE Steve

ASSIGNMENT

From: Date: 3/12/2019

Estimated Cost: OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 5785 M at Workshop m/s Win Automotive of 81K 6 woodlands Road 39AJ, Yew Insured: Tee Ind. Est.

Policy No. Claims No. Sum Insured: Excess:

(Client's Record) Make of Veh: Before 12pm

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No Est. Repairs: days Res.: Yes or No Loss Dam: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLT 5785 M Yr Regn: 1/11/17 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Make: Toyota Wish c.c 1798

Colour: Grey A/C: Insured / Std / NI / NA Sp. Reading: 38148 T/Radio: Insured / Std / NI / NA

Eng/No: C/No: JT066 29w 50J 007854

Gen. Cond: Good / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15 R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Firm 29

Front R/Bal. 5 mm Rear R/Bal. 5 mm L/Bal. 5 mm L/Bal. 5 mm

D.O.A. D.O.I. 3/12/19 Survey held at Win Automotive

Des. of Damages: (Fr) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	GIA 1up
05/12/19	@ 17:05 pm revised PA to L: L: via email.
11/12/19	Finalize ConL \$3990, 4 days (Winson) (# 3,764.25 Red - 54%)
	13/12/2019

RECEIVED 16 DEC 2019

Date/Time File Desc In? 12/12/19 1) Typ: 4 Final Report

Days Of Repair: 4 Resurvey No. of Trip: 2

Survey Fee:	290
Transportation:	
3 + RS:	ST
Photos:	
Others:	
TOTAL:	290

Add Fee: Site Insp (\$), Interview (\$), Tech. Invs (\$), Wash End (\$)

Report Format: Long Form / Short Form \$3,200/- 4S

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 6 November 2019 2:15 PM
To: Cheonghoh Law; assignments; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: PRS for SLT 5785 M accident involving vehicle GBD 2146 E on 3 November 2019 along/at Blk 574 Choa Chu Kang Street 52 - MSCP (Oref: LCH.lg/W9WAS-90792.19) Our ref: 19/19/19/VC05/022599

Without Prejudice
Save as to Costs

Dear Catherine

Thank you for the confirmation on the appointment of a Single Joint Expert.

Dear Nivitha

Please arrange Steve Chen to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Wednesday, 6 November 2019 2:03 PM
To: ONG LI LI; GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: PRS for SLT 5785 M accident involving vehicle GBD 2146 E on 3 November 2019 along/at Blk 574 Choa Chu Kang Street 52 - MSCP (Oref: LCH.lg/W9WAS-90792.19) Our ref: TBA

Dear Sirs,

We refer to the above matter and to your email of 4 November 2019.

Our client hereby nominate Steve Chen of LKK Auto Consultants Pte Ltd named in paragraph 1 serial no 10 of your said fax to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please contact our client's workshop, Win Automotive Services, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008 for the said survey of SLT 5785 M.

Contact Person : Mr Winson
Telephone : 9750 6777

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	060F
Vehicle Details	
Vehicle No.:	SLT5785M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR0A09592
Chassis No.:	JTDGG20W50J007854
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,109.00
COE Rebate Amount:	\$38,021.00
Total Rebate Amount:	\$52,987.00

The information contained herein is correct as at 05 Dec 2019

OK

MV-85K

Steve Chen (LKK Auto)

From: Winson Tan <winson_tingwei@hotmail.com>
Sent: Tuesday, December 10, 2019 9:38 PM
To: Steve Chen (LKK Auto)
Subject: Re: SLT 5785M gia report/ estimate and dismantle photos.

Hi steve. I recieved your finalized offer settlement at \$3200. And I confirm and accept your finalized.. thanks.

Regards : winson tan

Get [Outlook for Android](#)

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Tuesday, December 10, 2019 6:23:41 PM
To: Winson Tan <winson_tingwei@hotmail.com>
Subject: SLT 5785M gia report/ estimate and dismantle photos.

Dear Winson,

Kindly refer our finalize \$3200 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winson Tan [mailto:winson_tingwei@hotmail.com]
Sent: Monday, December 09, 2019 4:04 PM
To: Steve Chen (LKK Auto)
Subject: Re: SLT 5785M gia report/ estimate and dismantle photos.

hi steve .. i have recieved your estimate finalised and hereby accept and agree of the finalised , here enclosed with the after done spray paint photos for vehicle SLT 5785M. thanks..

regards: winson tan

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Thursday, December 5, 2019 9:09 AM

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 5 December 2019 5:05 pm
To: ONG LI LI; 'MT_Claim_SG'
Cc: SUR
Subject: RE: PRS for SLT 5785 M accident involving vehicle GBD 2146 E on 3 November 2019 along/at Blk 574 Choa Chu Kang Street 52 - MSCP (Oref: LCH.lg/W9WAS-90792.19) Our ref: 19/19/19/VC05/022599
Attachments: PRELI ADVISE - SLT 5785M.pdf

Dear Li Li,

Enclosed preliminary revised of vehicle SLT 5785M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 6 November, 2019 2:15 PM
To: Cheonghoh Law <mail@cheonghoh.sg>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: PRS for SLT 5785 M accident involving vehicle GBD 2146 E on 3 November 2019 along/at Blk 574 Choa Chu Kang Street 52 - MSCP (Oref: LCH.lg/W9WAS-90792.19) Our ref: 19/19/19/VC05/022599

Without Prejudice
Save as to Costs

Dear Catherine

Thank you for the confirmation on the appointment of a Single Joint Expert.

Dear Nivitha

Please arrange Steve Chen to conduct TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 19/19/19/VC05/022599

Date: 05 December 2019

Our Ref: CS/LPC19019740/Esd3

The Motor Claims Department
LONPAC INSURANCE BHD

Dear Sir/Madam,


PRELIMINARY ADVISE REPORT OF VEHICLE NO. SLT 5785M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/12/2019 at the premises of M/s Win Automotive Services and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,964.25</u> .
Revised Estimate Amount	: S\$ <u>3,975.25</u> .
“Check” Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 days

Yours faithfully

Chen Tsue Yee
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 15:24
Date Of Accident	03/11/2019 17:10
Exact Location Of Accident	BLK 574 CHOACHU KANG ST 52 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5785M
Insured/Policyholder	
Name Of Registered Owner	CHEONG JIA YUNG
NRIC No	S8117060F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97858747
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01015020
Cover Note Number	
Driver	
Name of Driver	CHEONG JIA YUNG
NRIC No	S8117060F
Date Of Birth	18/05/1981
Occupation	INDOOR
Date Of Driving Pass	16/04/2004
Driving Experience	15 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97858747
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	NOEMAIL

Address BLK 574 CHOA CHU KANG ST 52
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) Involved In the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : LIM SUAT KEE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO WITH INSURED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD2146E
 Vehicle Make/Model/Colour NISSAN/CABSTAR/GOLD
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver HTIN KYAW LWIN
 NRIC/Passport Number G6008975U
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: CHEN CHEE KIONG
NRIC/FIN No.:
Date: 11/11/18

Reporting Centre Personnel's Signature
Name: CHEN CHEE KIONG
NRIC/FIN No.:

SKETCH PLAN

Vehicle A 3LT 5765 M
 Vehicle B GBD 2146 E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 04/11/2019 @ approximately 17:00hrs, I was driving back home when the incident happened. I turned into my road leading to the MSCP with a lorry (the other party) ^{GBD 2146 E} in front of my car. We were approaching the exit of the MSCP when the lorry suddenly stopped and started reversing into my car. I tried to horn at the lorry to no avail. I was unable to reverse in time to avoid the accident. We (lorry driver and I) exchanged particulars and parted our way subsequently.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

REPORTING CENTRE PERSONNEL
 EXERCISE BUSINESS NO. 100-00-000000
 NAME & SIGNATURE: 
 DESIGNATION: _____ DATE: 11/11/19
 Reporting Centre Personnel's Signature
 Name: CHEN CHEE HOON
 NRIC/FIN No.:

**ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO:SLT 5785M
TOYOTA WISH**

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Estimated by workshop	Disc. (%)	Adjusted cost
1	1pc	front bumper / <i>DD</i>	517.00 /	25	387.75
2	1pc	front bumper sponge / <i>BR</i>	115.00 /	25	86.25
3	1pc	front bumper reinforcement X <i>NN</i>	280.00 X	25	210.00
4	2pcs	front bumper side retainer / <i>BR</i>	130.00 /	25	97.50
5	1pc	front bumper fog lamp cover / <i>BR</i>	90.00 /	25	67.50
6	1pc	front bumper fog lamp / <i>BR</i>	229.00 /	25	171.75
7	1pc	front grille / <i>BR</i>	356.00 /	25	267.00
8	1pc	front support panel X <i>R</i>	954.00 X	25	715.50
9	1pcs	support panel top garnish X <i>NN</i>	96.00 X	25	72.00
10	1pc	bonnet / <i>DD</i>	750.00 /	25	562.50
11	1pcs	bonnet inner lock X <i>NN</i>	92.00 X	25	69.00
12	2pcs	headlamp LH and RH / <i>BR</i>	1700.00 /	25	1275.00
13	1pc	radiator X <i>NN</i>	950.00 X	25	712.50
14	1pc	air con condensor X <i>NN</i>	640.00 X	25	480.00

Total

6899.00

5174.25

Repairs

*3887
- 25%
P - 2915.25
L - 1060
3975.25*

*L/S - 3180.02
= 3200*

To remove and replaced damaged parts including straightening and repositioning

800.00 *500*

Supply paint material and to respray replaced and other affected panels.

600.00 *500*

To check wiring at the damaged section for proper functions.

50.00 *30*

To carry out anti-rust treatment on affected

120.00 *30*

to realign headlamp focus

50.00 X

to vacuum and refill a/c refrigerant r134A

50.00 X

to remove and reinstall radiator and air con condensor

120.00 X *1060*

Total

1790.00

*Steve (LKK) with Ariel
3/12/19, 11.00am
L/S
Ry AL spy
4 days*

6964.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
6/12/19



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC19019740/Esd3e2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 24-12-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 2146E	Veh. Inspected	SLT 5785M
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022599	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	06/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDGG20W50J007854	Colour	GREY
Odometer	38148	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	5 mm
L/H Front Tyre	195/65 R15	FIRENZA	5 mm
R/H Rear Tyre	195/65 R15	FIRENZA	5 mm
L/H Rear Tyre	195/65 R15	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/11/2019	Inspection Date	03/12/2019
Survey held at	WIN AUTOMOTIVE-BLK 6 WOODLANDS RD 399J		
Repairer	-		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5785M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED	517.00	517.00
1	FRONT BUMPER SPONGE	BROKEN	115.00	115.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	280.00	-
2	FRONT BUMPER SIDE RETAINER	BROKEN	130.00	130.00
1	FRONT BUMPER FOG LAMP COVER	BROKEN	90.00	90.00
1	FRONT BUMPER FOG LAMP	BROKEN	229.00	229.00
1	FRONT GRILLE	BROKEN	356.00	356.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	954.00	-
1	SUPPORT PANEL TOP GARNISH	NOT NECESSARY	96.00	-
1	BONNET	DENTED	750.00	750.00
1	BONNET INNER LOCK	NOT NECESSARY	92.00	-
2	HEADLAMP LH AND RH	BROKEN	1,700.00	1,700.00
1	RADIATOR	NOT NECESSARY	950.00	-
1	AIR CON CONDENSOR	NOT NECESSARY	640.00	-
	LESS 25% DISCOUNT		-1,724.75	-971.75
			5,174.25	2,915.25
<u>LABOUR</u>				
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		800.00	500.00
	SUPPLY PAINT MATERIAL AND TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		600.00	500.00
	TO CHECK WIRING AT THE DAMAGED SECTION FOR PROPER FUNCTIONS.		50.00	30.00
	TO CARRY OUT ANTI-RUST TREATMENT ON AFFECTED.		120.00	30.00
	TO REALIGN HEADLAMP FOCUS.	NOT NECESSARY	50.00	-
	TO VACUUM AND REFILL A/C REFRIGERANT R134A.	NOT NECESSARY	50.00	-
	TO REMOVE AND REINSTALL RADIATOR AND AIR CON CONDENSOR.	NOT NECESSARY	120.00	-
			1,790.00	1,060.00
GRAND TOTAL			6,964.25	3,975.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00



Report Ref No. CS/LPC19019740/Esd3e2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report in whole or in part does so at his or her own risk.