

REP: C8/VINCI 9019745 / Unit 3 n2

Special Instruction:

Envelope: MARVELL

ASSIGNMENT (Office)

From (Person): Hazalysa B Ibrahim INC Date/Time: 7/11/19 @ 12:19pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 5728 M Insured: SKN 4822P

at Workshop n/s Blumel Automotive Tel: 6745 2088

of 1 Kaki Bukit Ave 6 # 01-28

Policy No: \_\_\_\_\_ Claim No: MT/1066195-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 8/10/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 12:40pm @ 7/11/19 Person Contacted: Sally ... Vehicle-IN (OUT)

Date/Time	Action/Instruction	Estimated
	SLW 5728 M - x	✓
	SKN 4822P - CC6/A/G/H/O/K/A/20/Unit 392	

DA: 10/19/2019

REP. By: Marcus

INC

ASSIGNMENT

From: Date: 8/11/2019

Veh No: SLW5728M Yr Regn: 2 18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or CA/

To inspect Vehicle No: SLW 5728M

Make: Honda Shuttle Hybrid CC 1496

at Workshop no: Bluwel Automotive

Colour: white A/C: Insured / Std / NI / NA

of: 1 Keeki Aduit Ave 6 # 01-28

Sp Reading: 44828 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: GP71204002

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Insured / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Insured / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/50R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal: 7 mm

R/Bal: 7 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal: 7 mm

L/Bal: 7 mm

Est. Repairs: 5 days Res.: Yes or No

D.O.A: 8/10/19

D.O.I: 8/11/19

Lum Sum: 20 % 3 Val: Yes or No

Survey held at: 2.19pm

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

A car

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

13/10/19 2/5 @ 3800 confirmed with Henry (Real 4529.80, 5490)

RECEIVED 10 NOV 2019

Date/Time, File Past in?

: Prel. Report

Days Of Repair: 5

ij)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return in?

18/11 - typist

Add Fee:  Site Insp \$

Interview \$

Tech. Insp \$

Weekend \$

Survey Fee:

Transportation:

S + PS: \$

Phone:

Fax:

Other:

Total:

250

Report Format:

TP 3800/-

Enter Total MP \$:

## Nivitha (LKK Auto)

---

**From:** Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>  
**Sent:** Thursday, 7 November 2019 12:19 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Thio Tse Kiat; Hazalysa Binte Ibrahim  
**Subject:** Pre Repair Survey for LKK on 07/11/19

Dear LKK,

Please assist to survey the vehicle as per Tse Kiat's instruction :-

### NEW ASSIGNMENT

S/N	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT NO.	DOA / CLAIM NO / OFFICER	REMARKS
1	SLW5728M	SKN4822P	BLUWEL AUTOMOTIVE SERVICE PTE LTD @ 67452088 (MS SALLY)	08/10/19 (MT/1066195-002) RAJESWARY	JUSEQUITY LAW COR (APPOINT LKK – CHU SENG)

Thank You.

Warmest Regards

**Hazalysa Bte Ibrahim**  
Admin Assistant  
Motor Department  
T +65 6430 7902  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [income.com.sg/careers](http://income.com.sg/careers)



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

## IT'S NEVER TOO EARLY TO THINK ABOUT YOUR 2020 DRIVE

VISIT THE LEXUS SHOWCASE @  
TAMPINES 1 MALL FROM 8-14 NOV



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

2014 Porsche 911 Carrera Cabriolet 3.4A PDK, 33000Km



Sport Plus Chrono Package,  
Sport Exhaust Package, Apple  
CarPlay, 18" 5+10J  
Auto Zoom Enterprise



Browse by Category

Sort by Date Posted

14 vehicles

Shuttle Hybrid 1.5A

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Shuttle Hybrid 1.5A	Any	Any	2018	Any	Any	Any



**Honda Shuttle Hybrid 1.5A X** **\$88,800** **\$9,100 /yr** **12-Dec-2018** **1,496 cc** **-** **Stationwa**  
**Fuel Type:** Petrol-Electric  
Almost New Car And Park In Showroom, 2018 New Facelift, Immediate Delivery, Full Accessories With Front And Rear Recording Camera, High Trade In Your Existing Car, 3 Years Or 100,000Km Warranty, Flexible Loan Up To 7 To 9 Years Available, GST Included, Hesitate N...  
Posted: 08-Nov-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



**Honda Shuttle Hybrid 1.5A (OPC)** **\$62,800** **\$6,450 /yr** **21-Sep-2018** **1,496 cc** **7,500 km** **Stationwa**  
**Fuel Type:** Petrol-Electric  
High ARF Of Ard 11k+ Instead Of The Normal 5k Only. 100% Genuine Mileage And Gurantee Not PHV Vehicle As It's Register Under OPC Scheme. Convert To Normal Plate At Only \$78,800. In An Immaculate Condition, Almost Like New. An Opportunity To Snap Up This Car...  
Posted: 07-Nov-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



**Honda Shuttle Hybrid 1.5A** **\$75,800** **\$8,930 /yr** **11-Jan-2018** **1,496 cc** **-** **Stationwa**  
**Fuel Type:** Petrol-Electric  
Elegant White, Almost New Conditon. Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.  
Prime Motor & Leasing  
Posted: 05-Nov-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



**Honda Shuttle Hybrid 1.5A** **\$77,800** **\$8,770 /yr** **28-May-2018** **1,496 cc** **-** **Stationwa**  
**Fuel Type:** Petrol-Electric  
Elegant Black, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.  
Prime Motor & Leasing  
Posted: 05-Nov-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



**Alliance Auto Pte Ltd - Specialty Workshops**  
A Lexus specialise workshop with an extensive investment in the manpower, equipment and genuine parts for Lexus.  
More info about this shop

Compare

**\$77,800** **\$8,830 /yr** **18-May-2018** **1,496 cc** **10,000 km** **Stationwa**  
**1/3**

[http://www.sgcarMart.com/used\\_cars/listing.php?MOD=Shuttle+Hybrid+1.5A&PRC=0&DEP=0&RGD=2018&VEH=0&AVL=2](http://www.sgcarMart.com/used_cars/listing.php?MOD=Shuttle+Hybrid+1.5A&PRC=0&DEP=0&RGD=2018&VEH=0&AVL=2)

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	400G
<b>Vehicle Details</b>	
Vehicle No.:	SLW5728M
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 LED
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB6545014
Chassis No.:	GP71204002
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,448.00
Original Registration Date:	22 Feb 2018
First Registration Date:	22 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Feb 2028
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Feb 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$44,000.00
COE Rebate Amount:	\$35,354.00
<b>Total Rebate Amount:</b>	<b>\$39,104.00</b>

The information contained herein is correct as at 08 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/10/2019 16:51
Date Of Accident	08/10/2019 09:10
Exact Location Of Accident	PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW5728M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOK BOON BING
NRIC No	S7637400G
Email Address	BBLOK76@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94757099
Alternative Phone No	OTHERS-94757099

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) FTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00588623
Cover Note Number	

### Driver

Name of Driver	LOK BOON BING
NRIC No	S7637400G
Date Of Birth	13/11/1976
Occupation	OUTDOOR
Date Of Driving Pass	06/04/1995
Driving Experience	24 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94757099
Fax Number	
Contact Number	OTHERS-94757099
Email Address	BBLOK76@GMAIL.COM

Address 52 MILTONIA CLOSE  
 Postcode 758212  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident: COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : PAX 1  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD) 67415036

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: REQUEST FROM OWNER  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKN4822P  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind a policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurer"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurer's lawyers/Law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated above;
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

8/10/19.

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.:



BLUWEL AUTOMOTIVE SERVICE PTE LTD  
 1 KAKI BUKIT AVE #01-28/53/55  
 SINGAPORE 417883 .TEL 67452088

*not authorized  
 here  
 2/5 = 3800/  
 8/11/19  
 the photo after repair  
 50%*

VEHICLE No:SLW 5728M

- 1PC REAR WINDSCREEN MOULDING
- 1PC TAILGATE
- 1PC TAILGATE OUTER GARNISH
- 1PC TAILGATE 'H' LOGO
- 1PC TAILGATE 'RS' EMBLEM
- 1PC TAILGATE 'HYBRID' EMBLEM
- 1PC TAILGATE INNER LOCK
- 1PC TAILGATE INNER TRIM BOARD
- 1PC TAILGATE WEATHERSTRIP
- 1PC REAR BUMPER
- 2PCS REAR BUMPER SIDE RETAINERS @35.00
- 2PCS REAR BUMPER SIDE COVERS @ 115.00
- 1SET REAR BUMPER CLIPS
- 1PC REAR END PANEL
- 1PC REAR END PANEL TOP GARNISH
- 2PCS TAILLAMPS @460.00
- 1SET REAR REVERSE SENSOR
- 1PC REAR WINDSCREEN SEALANT

<i>rec</i>	\$121.00	—
<i>3ods on</i>	\$1,285.30	—
<i>17</i>	\$345.50	X
<i>rec</i>	\$45.00	—
<i>rec</i>	\$65.00	—
<i>rec</i>	\$68.20	—
<i>twi/shhd</i>	\$295.30	—
<i>17</i>	\$366.10	X
<i>twi</i>	\$195.40	—
<i>o/x</i>	\$1,021.30	—
<i>17</i>	\$70.00	X
<i>17</i>	\$230.00	X
<i>rec</i>	\$50.00	—
<i>o/brt</i>	\$495.20	—
<i>rec</i>	\$166.50	X
<i>17</i>	\$920.00	X
<i>shhd</i>	\$250.00	—
<i>rec</i>	\$50.00	—
	\$6,039.80	

*(20%)*

- TO DISMANTLE & REPLACING REVERSE SENSOR
- TO TRANSFER TAILGATE COMPONENTS
- TO SPRAY RUST PROOFING
- TO DISMANTLE & REFIX UPHOLSTERY CUSHION ETCs
- LABOUR FOR PANEL BEATING & REPLACING PARTS
- TO PUTTY & SPRAY PAINTING
- TO CHECK WIRING

	\$80.00	50
	\$80.00	60
	\$80.00	30
	\$120.00	80
	\$800.00	600
	\$1,080.00	800
	\$50.00	20
TOTAL	\$8329.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Used parts survey is on a "Without Prejudice" basis
- No direct modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date:

*2-3941-50  
 20%  
 3453.36  
 4793.36  
 202  
 3834.68*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19019745/Uvd3n2		
73 BRAS BASAH ROAD		Date: 20-11-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: RAJESWARY		Code: INC		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKN 4822P	Veh. Inspected	SLW 5728M	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1066195-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	07/11/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71204002	Colour	WHITE	
Odometer	44828 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	YOKOHAMA	7 mm	
L/H Front Tyre	205/50 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	205/50 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	205/50 R16	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/10/2019	Inspect Date / Time	08/11/2019 ( 02:19 PM )	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 5728M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN MOULDING	NECESSARY	121.00	121.00
1	TAILGATE	BADLY DENTED	1,285.30	1,285.30
1	TAILGATE OUTER GARNISH	NOT NECESSARY	345.50	-
1	TAILGATE "H" LOGO	NECESSARY	45.00	45.00
1	TAILGATE "RS" EMBLEM	NECESSARY	65.00	65.00
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	68.20	68.20
1	TAILGATE INNER LOCK	TWISTED / SHORTED	295.30	295.30
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	366.10	-
1	TAILGATE WEATHERSTRIP	TWISTED	195.40	195.40
1	REAR BUMPER	DENTED / DEFORMED	1,021.30	1,021.30
2	REAR BUMPER SIDE RETAINERS @\$35.00	NOT NECESSARY	70.00	-
2	REAR BUMPER SIDE COVERS @\$115.00	NOT NECESSARY	230.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED / BENT	495.20	495.20
1	REAR END PANEL TOP GARNISH	SERVICEABLE	166.50	-
2	TAILLAMPS @\$460.00	NOT NECESSARY	920.00	-
1	SET REAR REVERSE SENSOR	SHORTED	250.00	250.00
1	REAR WINDSCREEN SEALANT	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-	-788.34
			<b>6,039.80</b>	<b>3,153.36</b>
<b>LABOUR</b>				
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER TAILGATE COMPONENTS.		80.00	60.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO DISMANTLE & REFIX UPHOLSTERY CUSHION ETCS.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		800.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	800.00
	TO CHECK WIRING.		50.00	20.00
			<b>2,290.00</b>	<b>1,640.00</b>



GRAND TOTAL		8,329.80	4,793.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,800.00

Report Ref No. CS/INC19019745/Uvd3n2

CHUA KANG SENG  
Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.