



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19019786/Qpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 24-04-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 5994X	Veh. Inspected	SLG 3816P
Policy No.	GA431272	Coverage (\$)	0.00
Claim No.	S9M024S2	Excess (\$)	0.00
Assign From		Assign Date	07/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11115724	Colour	WHITE
Odometer	78987	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/10/2019	Inspection Date	08/11/2019
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**