

ASS. REC. BY:

REF: (S3/MSG19019794/Hcf3ed)

Special Instruction:

ok

Surveyor: Hock Ann

## ASSIGNMENT (Office)

From (Person): Christina Wong

of

MSIADate/Time: 7.11.19 16.59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SSV 6234T

Insured:

YIP 5487Rat Workshop m/s yap lee hoo

Tel:

68441555of 1 Koki Bukit Jura C #01-26Policy No: 29071146

Claim No:

610697

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4.11.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 8.11.19 9.24am

Person Contacted:

Shirley

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SSV 6234T - X</u>
	<u>YIP 5487R - X</u>
	<u>Dismantle: 8/11/2019</u>
	<u>After repair: 14/11/2019</u>

verimn

ASS. REC. BY:

REF: MS19

PRS

## ASSIGNMENT

From:

Date:

8.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SVU 6234T

at Workshop m/s

Yap Lee Motor

of 1 kaki Bukit Ave 6 #01-26

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SVU 6234T

Yr Regn:

02/02/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. Vios E

C.C

1497

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

112872km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY9305146921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60/R15

R:

195/60/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

4/11/19

Rear

R/Bal.

5

mm

L/Bal.

5

mm

D.O.I.

8/11/19

Survey held at

Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 74.5 - 5.1K

SVU 6234T

PRS case

MV - 12000

PV - 6815

NV - 5100

RECEIVED 20 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

120

Transportation:

S + RS, SI

Photos

Others

TOTAL

131

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Rep. Format:

PRC

Lump Sum / F.B.I. C

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2019 09:59		07 Nov 2019 16:59 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TONG THAI SENG MARKETING PTE LTD, Co. Reg. No.: 201418667G		
Main Claimant:	GOODYEAR SERVICES, Co. Reg. No.: 53319102E		
Vehicle Reg. No.:	SJV6234T	Date of Loss:	04/11/2019 23:00 - :59 [32 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 610697	Policy/Cover Note No.:	29071146 (Comprehensive) Coverage: 06/02/2019 - 05/02/2020
Vehicle Reg. No. (Insured):	YP5487R	Policy No. (Claimant):	
		Excess:	
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/11/2019]		
Driver/Custodian (Insured):	LI SHUANGHUI (36 / Male), NRIC: S8305739D, Tel: +6598594369 Email:		
Adj Asg. Remarks:	on WP. Liab: clear. Disagree on SJE. Contact: Ms Shirley @ 6844 1555.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	102E
<b>Vehicle Details</b>	
Vehicle No.:	SJV6234T
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1NZY022958
Chassis No.:	MR053HY9305146921
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	02 Feb 2010
First Registration Date:	02 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$12,717.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2020
PARF Rebate Amount:	\$6,358.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	01 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,501.00
COE Rebate Amount:	\$457.00
<b>Total Rebate Amount:</b>	<b>\$6,815.00</b>

The information contained herein is correct as at 11 Nov 2019

OK

toyota vios

Price Range

Depreciation

2010

Vehicle Type

Home » Used Cars » Secure Credit » Toyota Vios 1.5A E (New 5-yr COE)

## Toyota Vios 1.5A E (New 5-yr COE)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$29,800 → 21300	Body value 8000
Depreciation ⓘ	\$5,950 /yr	Reg Date 12-Jan-2010 (5yrs COE left) \$9000
Mileage	145,300 km (14.8k /yr)	Manufactured ⓘ 2009
Road Tax ⓘ	\$684 /yr	Transmission Auto
Dereg Value ⓘ	N.A.	OMV ⓘ \$12,717
COE ⓘ	N.A.	ARF ⓘ \$12,717
Engine Cap	1,497 cc	Power 80.0 kW (107 bhp)
Curb Weight ⓘ	1,095 kg	No. of Owners ⓘ 2
Type of Vehicle	Mid-Sized Sedan	

## Features

1.5L VVT-i 16 Valves Inline DOHC Engine, 107 BHP, 4 Speed Auto Transmission, Low Fuel Consumption At 14Km/L, ABS, EBD, Airbags. View specs of the Toyota Vios (2007-2013)

## Accessories

Two Toned Leather Seats, Sports Rims, Reverse Sensors, Audio Player, Auto Retractable Side Mirrors, Solar Film, New Paintwork!

## Description

5 Years COE. Full Loan Available, Beautiful Interior, New Paint Work. Accident Free. Well Maintained, Regular Servicing By Previous Owner. Smooth Engine And Maintained Gear Box, Buy With Peace Of Mind. Worry Free Model. Low Maintenance, Low Fuel Consumption, Low Insurance Premium. Please Call Now For More Information. Don't Miss It.

## Category

COE Car

## Status

Available

## Resources



## Car Valuation - Free


Find out the market value of your existing car for free. Get started



## Vehicle Evaluation

Request to have this car evaluated professionally. Find out more


Compare



Location Map

## Price Chart

## Summary



Shortlist

Compare

Add to

Report Error

More Actions

## Seller Information

## Company

## Secure Credit

» dealer's pricelist

» 25 vehs sold | 16 vehs a

## Address

210 Turf Club Road Lot A3

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/11/2019 17:54
Date Of Accident	04/11/2019 23:20
Exact Location Of Accident	WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV6234T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOODYEAR SERVICES
Co Reg No	53319102E
Email Address	CRAYCHING@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97797000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5110949673
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD ARUJUDDIN BIN HUSSAIN
NRIC No	S9204623J
Date Of Birth	12/02/1992
Occupation	INDOOR
Date Of Driving Pass	12/03/2013
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91253555
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	104 WOODLANDS AVE 5 #03-09
Postcode	739012
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST N.P.C
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was stationary along lane 1 waiting for the traffic light to change to my favour. Suddenly, moments after, vehicle B hit into the rear of my vehicle A.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5487R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LI SHUANGHUI
NRIC/Passport Number	S8305739D
Contact Number	98594369
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name MUHAMMAD ARUJUDDIN BIN HUSSAIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJV6234T

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



# Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 05/11/2019 18:09

Report No: MT

DOB: 04/11/2019  
Time: 23:00 hrs

Vehicle No: SJV 6234T

Reporting Type:

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



05/11/19 18:09

Policyholder's Signature / Date & Time

*[Signature]*

05/11/19 18:09

Driver's Signature (If driver is not the policyholder) / Date & Time


Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

*[Signature]*

Witnessed by Reporting Centre Personnel

## Sketch Plan Pg. 2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary along lane 1 waiting for the traffic light to change to my favour. Suddenly, moments after, vehicle B hit into the rear of my vehicle A.

### Declaration

I/We declare the foregoing particulars are true in every respect.



05/11/19 / 18:09

Policyholder's Signature / Date & Time

*[Signature]*

05/11/19 / 18:09

Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)  
Customer Care Executive  
Motor Service Centre

*[Signature]*

Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20191105/2014

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

1 of 3

Report No: T/20191105/2014

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made 05/11/2019 04.45	Vide Report No.	Station Diary No. 14
---	-----------------	-------------------------

**Informant's Particulars**

Name of Informant: MUHAMMAD ARUJUDDIN BIN HUSSAIN			Address: 104 WOODLANDS AVENUE 5 #03-09 SINGAPORE 739012		
ID Type / ID No.: NRIC NO / S9204623J			Contact No.: Home/Office: Mobile: 91253555		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 12/02/1992	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 04/11/2019 23:00	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS AVENUE 2				
Woodlands Ave 2 and 5 towards to Causeway Point				
Weather: Clear		Road Surface: Dry		Road Speed Limit
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJV6234T	Car				Slightly Damaged	0
YP5487R	Lorry				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191105/2014

Police Station Of Origin:  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

2 of 3

Report No: T/20191105/2014

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	MUHAMMAD ARUJUDDIN BIN HUSSAIN	ID No.	S9204623J
Related Vehicle	SJV6234T (Car)	Contact No.	91253555
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/11/2019	Date Discharge	05/11/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
<b>Driver</b>			
Name	LI SHUANGHUI	ID No.	S8305739D
Related Vehicle	YP5487R (Lorry)	Contact No.	98594369
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

V1) SJV6234T

V2) YP5487R

On 04/11/2019 at about 2300hrs, I was driving V1 at Woodlands Ave 2 and 5 towards to Causeway Point. V1 was stationary as the traffic light was red, I saw V2 approaching from the back through side and rear mirror. However, I did not expect that V2 did not stop and in result, V2 hit on to V1. V1 rear bumper was damaged and V2 front bumper slightly damaged. No government property damage. I was advised by V1's rental company to lodge a police report and see a doctor.

Hence, I went to KTPH A&E to do a check and was given 2 days MC, KHANE191702110 from 05/11/2019 to 06/11/2019. I am lodging this report as advised by the rental company.



**SINGAPORE  
POLICE FORCE**



T/20191105/2014

Police Station Of Origin  
Woodlands West N.P.C.  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No: 1800-363 9999

3 of 3

Report No: T/20191105/2014

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report.

L /  
Staff Sgt AIK QISONG

Signature Of Informant.

Signature Of Interpreter:  
Not applicable

Date/Time:  
05/11/2019 04:45

Officer In Charge Of Case  
TP / AEIT /  
SI ANG YI TING, STEPHANIE  
Contact No: 65476414

Classification Of Case

Authentication Stamp  
NP168

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2019 09:59		07 Nov 2019 16:59 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	TONG THAI SENG MARKETING PTE LTD, Co. Reg. No.: 201418667G								
Main Claimant:	GOODYEAR SERVICES, Co. Reg. No.: 53319102E								
Vehicle Reg. No.:	SJV6234T	Date of Loss:	04/11/2019 23:00 - :59 [117 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 610697	Policy/Cover Note No.:	29071146 (Comprehensive) Coverage: 06/02/2019 - 05/02/2020						
Vehicle Reg. No. (Insured):	YP5487R	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 08/11/2019]								
Driver/Custodian (Insured):	LI SHUANGHUI (36 / Male) , NRIC: S8305739D, Tel: +6598594369 Email:								
Adj Asg. Remarks:	on WP. Liab: clear. Disagree on SJE. Contact: Ms Shirley @ 6844 1555.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19019794/HCF3E2

Date: 16/12/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29071146

Claimant Vehicle No : SJV6234T

Insured Vehicle No : YP5487R

Date of Loss: 04/11/2019

Nature of Claim: TP Claim No: 610697

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJV6234T**

Make &amp; Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZY022958

Reg. Date: 02/02/2010 (Man. Year: 2009)

Chassis No: MR053HY9305146921

Colour: Silver

Odometer: 112872 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Goodride 5 mm

Rear Left Side: Goodride 5 mm

Front Right Side: Goodride 5 mm

Rear Right Side: Goodride 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 08/11/2019 Inspected At:

Yap Lee Motor (HQ)  
1 Kaki Bukit Avenue 6, #01-26  
Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2019)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJV6234T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.























































Report was unsubmitted during this print-out.
---


























< END OF ESTIMATES >

## Claim Documents

\*SJV6234T (610697)  
[YP5487R]  
TP  
GOODYEAR SERVICES  
Nov 4 2019 11:00PM  
[TONG THAI SENG MARKETING PTE LTD]  
Yap Lee Motor

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 08:39	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	12/11/19 08:39	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
20	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
22	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
23	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
24	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
25	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
26	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
27	12/11/19 08:40	General View	Load JPG	<input checked="" type="checkbox"/>
28	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
29	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
30	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
31	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
32	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
33	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
34	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
35	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
36	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
37	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
38	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
40	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
41	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
42	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>
43	12/11/19 08:41	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/11/19 08:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/11/19 08:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	12/11/19 08:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/11/19 08:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	12/11/19 08:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/11/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
116	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
117	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
118	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
119	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	15/11/19 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/11/19 10:40	PRI Letter	 Load PDF	
2	07/11/19 10:40	PRI Email from Vision Law LLC	 Load PDF	
3	07/11/19 13:21	Disagree on SJE	 Load PDF	
4	07/11/19 13:21	Workshop Details	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19019794/HCF3E2

Date: 16/12/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29071146

Claimant Vehicle No : SJV6234T

Insured Vehicle No : YP5487R

Date of Loss: 04/11/2019

Nature of Claim: TP Claim No: 610697

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJV6234T**

Make &amp; Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZY022958

Reg. Date: 02/02/2010 (Man. Year: 2009)

Chassis No: MR053HY9305146921

Colour: Silver

Odometer: 112872 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Goodride 5 mm

Rear Left Side: Goodride 5 mm

Front Right Side: Goodride 5 mm

Rear Right Side: Goodride 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 07/11/2019

Date Inspected: 08/11/2019 Inspected At:

Yap Lee Motor (HQ)  
1 Kaki Bukit Avenue 6, #01-26  
Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2019)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJV6234T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >