

ASS. REC. BY:

REF:

CS3/MSG1909807/HK. B307

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Jasmine Lok Kheng Kwai

of MSG

Date/Time: 7.11.19 16.57 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 9964T

Insured:

GBC 3434Y

at Workshop m/s Kim Seng Tick

Tel:

6741 5520

of 3021A Ubi Rd 1 #01-42

Policy No: 28862460MRC

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A 5.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 6.11.19 9.26 a.m

Person Contacted:

Ms Lee

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	GBH 9964T - NA / AIG 10/19/654 r3 DOT - 05/11/2019
	GBC 3434Y - NA / AIG 10/19/654 r3 DOT - 05/11/2019
	After repair: 6/12/2019
16/12 3.25pm	Spoken to Ms Lee, only conduct PRS no estimate provided. They choose LKR because we are nearest to their workshop.
	4/12/19 - survey taken / 6/12/19 - after part wh.

ASS. REC. BY:

REF: MSG

ASSIGNMENT

From:

Date:

4.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBH 9964T

at Workshop m/s

Kim Seng Teck

of

B1K 3021A Ubi Rd / #01-42

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 1.00 p.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Sup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 9964T

Yr Regn:

Nov / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. Hien

C.C.

2982

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

1879 / km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P500246523

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/R15C

R:

195/R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

47 mm

R/Bal.

47 mm

L/Bal.

4 mm

L/Bal.

4 mm

D.O.A.

5/11/19

D.O.I.

4/12/19

Survey held at

Kim SENG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range - 2.5 - 3K
Repair Days - 4

* GBH 9964T
PNS use.

MV - 72000
PV - 26254
NV - 45700

RECEIVED 06 JAN 2020

76355542 - winny

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

120

Transportation:

S + RS. SI

Photos

Others

TOTAL

121

Rep. Form:

PRS.

Lump Sum / FB: /

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2019		07 Nov 2019 16:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	S.K. Rosenbauer Pte Ltd, Co. Reg. No.: 198502635H		
Main Claimant:	KST AUTO RENTAL PTE LTD, Co. Reg. No.: 200806860W		
Vehicle Reg. No.:	GBH9964T	Date of Loss:	05/11/2019 16:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28862460MKC (Comprehensive) Coverage: 01/01/2017 - 20/12/2019
Vehicle Reg. No. (Insured):	GBC3434Y	Policy No. (Claimant):	
		Excess:	
Repairster:	Kim Seng Teck Motor Works (HQ) 3021A Ubi Rd 1 #01-42, 408715 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/11/2019]		
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lee @ 6741 5520.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Road Tax Expiry Date

Review Details

Vehicle No.
GBC3434Y

Vehicle Make/Model
NISSAN / NV200 1.5L MT ABS AIRBAG 2WD 6DR

Road Tax Expiry Date :
20 Dec 2019

The information contained herein is correct as at 04 Dec 2019 / 18:41.

Save as PDF

OK →

Print

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
GBH9964T

Make / Model
TOYOTA / HIACE VAN TURBO 5DR MT

Vehicle Type :
A50 - Goods (Closed) Van/Van Panel (Delivery)

Vehicle Attachment 1 :
No Attachment

Vehicle Scheme :
Normal

Chassis No. :
JTFHT02P500246523

Propellant :
Diesel

Engine No. :
1KD2832757

Motor No. :
-

Engine Capacity :
2982 cc

Power Rating :
-

Maximum Power Output :
-

Maximum Laden Weight :

2800 kg

Unladen Weight :

1700 kg

Year Of Manufacture :

2018

Original Registration Date :

21 Nov 2018

Lifespan Expiry Date :

20 Nov 2038

COE Category :

C - Goods Vehicle & Bus

Quota Premium :

\$29,501.00

COE Expiry Date :

20 Nov 2028

Road Tax Expiry Date :

20 May 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

20 Nov 2020

Intended Transfer Date :

27 Dec 2019

CO2 Emission :

210.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

0.066000 (g/km)

HC Emission :

0.002653 (g/km)

NOx Emission :

0.107000 (g/km)

PM Emission :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	860W
Vehicle Details	
Vehicle No.:	GBH9964T
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2832757
Chassis No.:	JTFHT02P500246523
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	21 Nov 2018
First Registration Date:	21 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$26,254.00
Total Rebate Amount:	\$26,254.00

The information contained herein is correct as at 27 Dec 2019

OK


**Toyota Hiace Commuter 2.8A
GL High Roof**
Fuel Type: Diesel

High Roof New 14 Seater Toyota Commuter Model! Cheapest In SG! Full Accessories! Can Register Excursion Private Hire Or Private Bus. No Gimmicks! Call Our Sales Executive And Grab It Before It's Gone! Stock Is Limited. Able To Test Drive!

Net Link Partners Pte Ltd

Posted: 29-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


**Toyota Hiace Commuter 2.8A
GL High Roof**
Fuel Type: Diesel

Latest Model With Toyota Safety Sense. Auto Door, 13+1 Seater. Sell Due To Under-Utilised. 1 Owner. Super Low Km. Original Factory Made Seats From Japan. Rear Foldable Seats. Real Price, No Gimmick. Cheapest Around, Price Beat Guarantee! Call Us For Viewing.

Posted: 28-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota


**Toyota Hiace Commuter 2.8A
GL**
Fuel Type: Diesel

10/18 Toyota Hiace Commuter 2.8 GL, 14 Seater, New Model.

Think One Automobile & Trading

Posted: 03-Nov-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Stat

For old advertisements, view Expired ads

100 result

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpar insurance. Find buy used Toyota, Toyota Singapore, used Toyota Singapore, used Toyota, used vehicles Singapore or even buy used Toyota Singapore. We have new car dealers (parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job open Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

POA: 5/11/19

MV - 72000

PV - 26254

NV - 45700

Being 9yr
km 8000yr
72000

Compare



Post an Advertisement
Sell it yourself! Advertise It at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Audi Q5 2.0(A) TFSI Quattro S-tronic Sport (S-Line)



Most Sporty Q5 In SG!
Expensive 20" Rims! 5+5yrs
Servicing By PAI Low Mileage!
Direct Owner StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of experience

Browse by Category

Sort by Date Posted 100 results

Advanced Search



To get alerted when new
Search Selection are added

Toyota Hiace

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Any	Any	Any	2018	Any	Any	Bus/Mini Bus	



Toyota Hiace Commuter 3.0A GL

Fuel Type: Diesel

Auction Closing Time: 9th Jan 2020 at 11:00 PM

No Key. This Vehicle Is Non GST Chargeable, Kindly Download The Non GST Chargeable Tender Form At This Link:
<https://goo.gl/F8mTB9>

Posted: 03-Jan-2020 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A High Roof

Fuel Type: Diesel

Cheapest Mini Bus In Town. Suitable For All Kind Of Transport Business, Company Private Bus Or Private Hire. Trade In Welcome. Call To View Now!

Posted: 28-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A High Roof

Fuel Type: Diesel

Brand New View To Believe 14 Seaters Mini Bus For Sales! 100% Loan And High Trade-In. Can Register Excursion, Private Hire, Or Private Bus, Call Our Friendly Sales Executive And Find Out More. Price Inclusive Of GST.

Tai Huat Automobile

Posted: 26-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 2.8A

Fuel Type: Diesel

(Hiace Commuter With Front Sensing) Lots Of Safety Features! Come With Lots Of Accessories, High Loan With Low Interest Rate, High Trade In, Call Now To Find Out More!

Posted: 18-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Vios 1.5 (Private Hire)

\$350/week PHV ready Toyota Vios 1.5 for rent @ \$350/weekly, minimum 3 months contract.

More info about this vehicle



Toyota Hiace Commuter 3.0A High Roof

Fuel Type: Diesel

Do We Need To Say? This Baby Has Just Clocked Less Than 6000 Km! Its A Rare Of A Kind In This Leading Toyota Brand In Singapore With Such Condition. Have No Fear On Loan And Insurance As Our Team Are Here To Assist You Throughout The Whole Journey. Call U...

Bell Auto Pte Ltd

Posted: 14-Dec-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Compare

\$77,777	\$8,840 /yr	22-Oct-2018	2,754 cc	-	Bus	Av
----------	-------------	-------------	----------	---	-----	----

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/11/2019 14:58
Date Of Accident	05/11/2019 16:45
Exact Location Of Accident	PIE TWDS PAYA LEBAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH9964T
Insured/Policyholder	
Name Of Registered Owner	KST AUTO RENTAL PTE LTD
Co Reg No	-
Email Address	KSTTEAM@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67415520

Vehicle Particulars

Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORKING

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994113/100868675-00000
Cover Note Number	

Driver

Name of Driver	ONG SEE CHONG(WANG SIZHONG)
NRIC No	S8204757C
Date Of Birth	05/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	26/01/2007
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87166287
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 881 TAMPINES ST 84 #05-92
Postcode	520881
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER(COMPANY)
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG PIE TWDS PAYA LEBAR RD ON THE 3RD LANE OF A5-LANES RD. SUDDENLY VEH(B) BEARING REG NO GBC3434Y FROM MY RIGHT LANE CUT INTO MY LANE AND HIT ONTO MY RIGHT SIDE PORTION OF MY VEH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FRONT ONLY
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3434Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHUA CHENG POH
NRIC/Passport Number	S1140122H
Contact Number	97540431
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 06/11/19
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A-GBH99647
B-GBC34349



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

P/s refer to the statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Signature 06/11/19

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)


























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2019		07 Nov 2019 16:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: S.K. Rosenbauer Pte Ltd , Co. Reg. No.: 198502635H									
Main Claimant: KST AUTO RENTAL PTE LTD , Co. Reg. No.: 200806860W									
Vehicle Reg. No.: GBH9964T		Date of Loss: 05/11/2019 16:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 611971		Policy/Cover Note No.: 28862460MKC (Comprehensive) Coverage: 01/01/2017 - 20/12/2019							
Vehicle Reg. No. (Insured): GBC3434Y		Policy No. (Claimant):							
		Excess:							
Repairer: Kim Seng Teck Motor Works (HQ) 3021A Ubi Rd 1 #01-42, 408715 Ubi - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 08/11/2019]									
Adj Asg. Remarks: on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lee @ 6741 5520.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH9964T (611971)
[GBC3434Y]
TP
KST AUTO RENTAL PTE LTD
Nov 5 2019 4:00PM
[S.K. Rosenbauer Pte Ltd]
Kim Seng Teck Motor Works

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/19 18:49	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	04/12/19 18:49	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
4	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
5	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
6	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
7	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
8	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
9	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
10	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
11	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
12	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
13	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
14	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
15	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
16	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
17	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
18	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
19	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
20	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
21	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
22	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
23	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
24	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
25	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
26	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
27	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
28	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
29	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
30	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
31	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
32	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
33	04/12/19 18:49	General View		Load JPG	<input checked="" type="checkbox"/>
34	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
35	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
36	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
37	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
38	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
39	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
40	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
41	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
42	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>
43	04/12/19 18:50	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	04/12/19 18:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/12/19 18:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/12/19 18:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/12/19 09:43	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/12/19 09:44	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/11/19 09:44	PRI	 Load PDF	
2	07/11/19 10:35	Agree on SJE	 Load PDF	
3	07/11/19 10:35	Workshop Details	 Load PDF	
4	16/12/19 16:07	Status of Driving Licence (OI)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19019807/HCF3E2

Date: 07/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28862460MKC
Claimant
Vehicle No : GBH9964T **Insured Vehicle No :** GBC3434Y
Date of Loss: 05/11/2019 **Nature of Claim:** TP **Claim No:** 611971

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH9964T**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO (M) Engine No: 1KD2832757
 Reg. Date: 21/11/2018 (Man. Year: 2018) Chassis No: JTFHT02P500246523
 Colour: Black Odometer: 18179 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
 Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/11/2019
 Date Inspected: 04/12/2019 Inspected At: Kim Seng Teck Motor Works (HQ)
 3021A Ubi Rd 1 #01-42
 Singapore 408715
 Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Jan 2020)

Parts: N/A TOYOTA HIACE 3.0 D TURBO (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH9964T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >