

27/03/2002

ASS. REC. BY:

REF:

CS/FCT/9019832/T19d301

Special Instruction:

Supervisor: TaukiahASSIGNMENT (Office)From (Person): Jason Tea

of

FCT

Date/Time:

6:27pm @ 7/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL5 5826J

Insured:

SHC 26184

at Workshop m/s

Cycle & Carriage Automotive

Tel:

91865200/

of

200 Pandan Gardens

Policy No:

Claim No:

D19006981MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/11/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 9:32am @ 8/11/19

Person Contacted:

COCOVehicle: IN (OUT)

Date/Time

Action/Instruction

Johnnie (✓)SL5 5826J - XSHC 26184 - CC3/AIG D9015557/Gin20A: 10/7/200922/11/19 @ 9.13am revised to Jason Tea by email.10/12/19 @ 4.23pm confirmed with Larry final fig \$1690, 3 days.(Red. \$495, 23%)

MOTOR SURVEY ASSIGNMENT

Date	04-11-2019	Our Ref No. D19006981MFSH
Accident Date	01-11-2019	Claim Type. Third Party
Insured Vehicle	SHC2618U	Third Party Vehicle. SLS5826J
Survey Location	209 PANDAN GARDENS	
Contact Person.	COCO LU TING	
Contact No.	65684501/ 91865200	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT: QUANTUM AND NUMBER OF REPAIR DAYS AS RECOMMENDED BY OUR SURVEYOR.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Coco Lu Ting <coco.lu@cyclecarriage.com.sg>
Sent: Wednesday, 13 November 2019 8:00 PM
To: Admin-D (LKKAuto)
Cc: Edwin Abcede Caina; assignments; Andre Chow En De; Don Bong Kiong Hua
Subject: RE: SURVEY ARRANGEMENT FOR SLS 5826J TP AGAINST FCI

Dear officer in charge,

Please arrange survey for our customer car on 20/11/2019 9am to 1pm. thank you

Best regards

Coco Lu Ting
Executive – Customer Service
Claim Division Operations Body & Paint Centre
209 Pandan Gardens
Singapore 609339



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 91865200 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 8 November, 2019 12:46 PM
To: Coco Lu Ting <coco.lu@cyclecarriage.com.sg>
Cc: Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; assignments <assignments@lkkauto.com>
Subject: SURVEY ARRANGEMENT FOR SLS 5826J TP AGAINST FCI

This email was sent from outside of your organisation

Dear Coco,

Is the vehicle SLS 5826J in the workshop?

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 December 2019 4:23 PM
To: Songcuan JR Lauro Araos
Cc: SUR; Cheng Jo Jo; Andre Chow En De; Loi Ai Ting; Coco Lu Ting
Subject: RE: SLS5826J (MIT) - FINALIZE TP CLAIM (FIRST CAPITAL)

Dear Larry,

WITHOUT PREJUDICE

Confirm final fig \$1,690.00 before GST and 3 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Wednesday, 4 December 2019 3:51 PM
To: SUR <sur@lkkauto.com>
Subject: FW: SLS5826J (MIT) - FINALIZE TP CLAIM (FIRST CAPITAL)

[CS/FCI19019832/T1qd3](#)

From: Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>
Sent: Wednesday, 4 December, 2019 3:50 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>; Jojo Cheng <jojo.cheng@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>
Subject: SLS5826J (MIT) - FINALIZE TP CLAIM (FIRST CAPITAL)

Dear Taufikh,

Pls. refer to attached files.

Kindly confirm finalized amount of \$ **1,690.00** before Gst.

Thank you so much.

Best regards,

Larry Songcuan
Customer Service

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 22 November 2019 9:13 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006981MFSH/1
Attachments: CSFCI19019832T1qd3.pdf

Dear Jason,

Enclosed herewith preliminary advice of SLS 5826J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 8 November 2019 2:10 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006981MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 7 November 2019 6:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006981MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006981MFSH

Date: 22 November 2019

Our Ref: CS/FCI19019832/T1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLS 5826J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/11/2019 at the premises of M/s CYCLE & CARRIAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,185.00</u> .
Revised Estimate Amount	: S\$ <u>1,690.00</u> .
"Check" Items Amount	: S\$ <u>308.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/11/2019 11:57
Date Of Accident	01/11/2019 10:45
Exact Location Of Accident	BRAS BASAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS5826J
Insured/Policyholder	
Name Of Registered Owner	JONATHAN GOH WEI SHENG
NRIC No	S8934827G
Email Address	JON_GOH89@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-83224467
Alternative Phone No	OTHERS-67639612

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	SPACE STAR-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	ON TRANSPORTATION.PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JONATHAN GOH WEI SHENG
NRIC No	S8934827G
Date Of Birth	23/09/1989
Occupation	INDOOR
Date Of Driving Pass	18/11/2010
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83224467
Fax Number	
Contact Number	OTHERS-67639612
EMail Address	JON_GOH89@LIVE.COM.SG

Address	BLK 184 JELEBU ROAD #29-32
Postcode	670184
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2618U
Vehicle Make/Model/Colour	COMFORT DELGRO TAXI TOYOTA PRIUS
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LEONG WENG ONN
NRIC/Passport Number	
Contact Number	91914369
Address	
Postcode	
Insurance Company Name	MS FIRST CAPITAL INSURANCE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB5549X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 02/11/19
0935 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time: 02/11/19
0935 hrs


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight on the second lane along Bras Basah Rd. Passed by traffic junction next to Singapore Management University Administration Building. Upon reaching Catton hotel, when I slowed down my vehicle, suddenly a blue taxi hit my car from the rear. I came out to check that the front of blue taxi cannot hit the rear bumper of my car. The time which occurred was about 10.45am. The blue taxi behind me was also hit by another taxi behind it. No injury was reported.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Jonathan Goh Wei Sheng (Wu Wei) Blk 184 Jeleeu Rd #29-32 Singapore 670184 Contact No Mobile: 83224467	Cust No/Name	/JONATHAN GOH WEI SHENG (WU WEIS)
	Reg No/Reg Date	SLS5826J / 28/09/201
	Date In/Mileage	/ 0
	Chassis No	MMCXTA03AGH049747
	Engine No	3A92UGD7879
	Make/Model	MIT/SPACE STAR 1.2 CVT
	Colour/Trim	X08 BLACK MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	04/11/2019/ 09:05	BLC	442 / CocoLu	47519

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER				✓ 550.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60, 100.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER				420, 500.00
M SUNDRY REAR NUMBER PLATE WITH FRAME				del 50.00
M SUNDRY SUPPLY PARKING SENSOR				220.00
M SUNDRY Sundry				20.00
M FACE,RR BUMPER	1.00	590.00	00.00	de 590.00
M BRACKET,RR BUMPER	1.00	68.00	00.00	68.00
M BRACKET,RR BUMPER SIDE,LH	1.00	10.00	00.00	10.00
M BRACKET,RR BUMPER SIDE,LH	1.00	10.00	00.00	10.00
M REFLECTOR	1.00	23.00	00.00	23.00
M LAMP ASSY,LICENSE PLATE	1.00	44.00	00.00	44.00

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Confirm & accepted by


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	2,185.00
7% GST on	2185.00	152.95
Total Payable		2,337.95

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



TP CLAIM
FIRST CAPITAL
TAUFIKH (LKK)

VEHICLE NO : SLS 5826 J

MODEL : MIT/SPACE STAR 1.2 CVT

WIP : 47519

Material	:	\$	<u>590.00</u>
Labour	:	\$	<u>1,100.00</u>
Sub-Total	:	\$	<u>1,690.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>1,690.00</u>
GST 7%	:	\$	<u>118.30</u>
Grand Total	:	\$	<u>1,808.30</u>
Finalise By/Date : <u>LARRY ON 04/12/19</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

* TP vehicle no: SHC2618U

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Jonathan Goh Wei Sheng (wu Wei)	Cust No/Name /Mr Jonathan Goh Wei Sheng (wu W
Blk 184	Reg No/Reg Date SLS5826J / 28/09/2017
JeLebu Rd	Date In/Mileage 21/11/2019/ 0
#29-32	Chassis/Package MMCXTA03AGH049747 /DC17S3C
Singapore 670184	Engine No 3A92UGD7879
Contact No Mobile: 83224467	Make/Model MIT/SPACE STAR 1.2 CVT
20/11/2019	Colour/Trim X08 BLACK MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CTP00040	Cash	04/12/2019/ 14:55	BLC	884 / Lauro Songcuan	47519	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER						550.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR						60.00 ✓
E PNT98000 SPRAY PAINT FOR REAR BUMPER						420.00 ✓
M SUNDRY SUNDRIES						20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)						50.00 ✓
X FACE,RR BUMPER ✓			1.00	590.00	00.00	590.00 ✓
Z TEXT TP FIRST CAP - SHC2618U DOA: 01/11/2019 SURVEY: TAUFIKH 20/11/2019 03 DAYS						
<p>Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info!</p>						
Parts		590.00			Nett	1,690.00
Labour		1,030.00		7% GST on	1690.00	118.30
Standard Menu		0.00				
Specialist Job		50.00			Total Payable	1,808.30
Diagnostics Job		0.00				
Sundry/Others		20.00				
Total(w/o GST)		1,690.00				

This is not an official tax invoice.
This is a computer generated document, no signature is required.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19019832/T1qd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2618U	Veh. Inspected	SLS 5826J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006981MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	07/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI SPACE STAR	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MMCXTA03AGH049747	Colour	BLACK	
Odometer	43452	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/55 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/55 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/55 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/55 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2019	Inspection Date	20/11/2019	
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5826J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE WITH FRAME (SN)	DENTED	50.00	50.00
1	PARKING SENSOR (SN)	NOT NECESSARY	220.00	-
1	SUNDRY (SN)	NECESSARY	20.00	20.00
1	FACE, RR BUMPER (SN)	DEFORMED	590.00	590.00
1	BRACKET, RR BUMPER (SN)	NOT NECESSARY	68.00	-
1	BRACKET, RR BUMPER SIDE, LH (SN)	NOT NECESSARY	10.00	-
1	BRACKET, RR BUMPER SIDE, LH (SN)	NOT NECESSARY	10.00	-
1	REFLECTOR (SN)	NOT NECESSARY	23.00	-
1	LAMP ASSY, LICENSE PLATE (SN)	NOT NECESSARY	44.00	-
			1,035.00	660.00
	<u>LABOUR</u>			
	RENEW REAR BUMPER.		550.00	550.00
	REMOVE & INSTALL PARKING SENSOR.		100.00	60.00
	SPRAY PAINT FOR REAR BUMPER.		500.00	420.00
			1,150.00	1,030.00
	GRAND TOTAL		2,185.00	1,690.00
	RECOMMENDED COST OF REPAIRS			1,690.00

Report Ref No. CS/FCI19019832/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.