

22/03/2019

ASS. REC. BY:

REF:

CS3/CT249019842/Hcd302

Special Instruction:

Surveyor: Hock AnnASSIGNMENT (Office)From (Person): Tan Kah Leong

of

CTIDate/Time: 8/11/2019 11:57am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBB 2808P

Insured:

YL 2215A

at Workshop m/s

Alpha Car

Tel:

65098258

of

1 Kaki Bukit Ave 6 # 01-59

Policy No:

DMCVSN1756219022

Claim No:

SNM19D205286002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:23pm 8/11/19

Person Contacted:

callingVehicle IN OUT

Date/Time	Action/Instruction
	Tolimold (x)
	YL 2215A: NA/CT1702457A/K4 DOR: 11/12/2019
	FBB 2808P: x
	Disassemble: 11/11/2019.
	After repair: 18/11/2019


Surveyor **H-ANN**

REF: **CT1**

PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV
 To Inspect Vehicle No: **FBB 2808P**
 at Workshop m/s: **ALPHA CAR**
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh. had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **FBB 2808P** Yr Regn: **08/02/2007**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: **H. PHANTOM 2000** c.c. **1969** 197
 Colour: **Red** A/C: Insured / Std / NI / NA
 Sp. Reading: **32452.1** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **TA2000Q36812**

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: **100/80/17**
 R: **130/90/15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: **5** mm **Dunlop** Rear: **5** mm **LASERTEL**
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **7/11/17** D.O.I. **8/11/17**

Survey held at **ALPHA car**
 Des. of Damages Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range → pending repairs available \$2.5K - \$3K
	* FBB 2808P PRS case
	MV - 2400
	PV - 1376
	NV - 1000
	27/12/2019

RECEIVED-31 DEC 2019

Date/Time, File Pass to? ☐ : Procl. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech. Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS, SI

Prior

Others

TOTAL

190

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Nov 2019		20 Nov 2019 12:25 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	FOO POCK CHIN , ID: S1304213F
Vehicle Reg. No.:	FBB2808P
Claim Type:	TP / SNM19D205286C02
Vehicle Reg. No. (Insured):	YL2215A
Date of Loss:	07/11/2019 08:00 - :59
Policy/Cover Note No.:	DMCVSN17562119022
Policy No. (Claimant):	5082841295-03
Excess:	S\$0.00
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 29/11/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 8 November 2019 11:57 AM
To: jiamin.mak@alt.sg; assignments
Cc: 'Jerdine'; vincent@alt.sg; allister@alt.sg; 'ALPHA CAR SERVICES'
Subject: RE: OUR REF: SNM19D205286-YL2215A-TKL- PRI - FBB 2808 P

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Jiamin,

We refer to your email of below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]
Sent: Friday, November 8, 2019 11:53 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: 'Jerdine' <jerdine.wang@alt.sg>; vincent@alt.sg; allister@alt.sg; 'ALPHA CAR SERVICES' <alphacarservices@hotmail.com>
Subject: RE: OUR REF: SNM19D205286-YL2215A-TKL- PRI - FBB 2808 P

Dear Sir,

We refer to your email dated 8 November 2019.

We have our client's instructions to reject your proposal on your Single Joint Expert.

We propose to use the motor surveyor(s) named in the list below to conduct the joint pre-repair survey as a Single Joint Expert:

WG Appraisal Services

Kindly let us hear from you within 2 working days as per the new NIMA protocol failing which we will proceed with the necessary.

Thank you.

** Kindly be reminded of the change of our address as stated below.*

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

1 Coleman Street
#05-01, The Adelphi
Singapore 179803
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Sent: Friday, November 8, 2019 11:10 AM

To: jiamin.mak@alt.sg

Cc: 'Jerdine' <jerline.wang@alt.sg>; vincent@alt.sg; allister@alt.sg

Subject: RE: OUR REF: SNM19D205286-YL2215A-TKL- PRI - FBB 2808 P

Without Prejudice

Dear Jiamin,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Friday, November 8, 2019 10:48 AM

To: jiamin.mak@alt.sg; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Cc: 'Jerdine' <jerline.wang@alt.sg>; vincent@alt.sg; allister@alt.sg

Subject: OUR REF: SNM19D205286-YL2215A-TKL- PRI - FBB 2808 P

Dear Kah Leong,

Please conduct PRS for FBB2808P.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]

Sent: Thursday, November 07, 2019 4:52 PM

To: Ong Chin Kiat; Claims Dept of CTI

Cc: 'Jerdine'; vincent@alt.sg; allister@alt.sg

Subject: PRI - FBB 2808 P

Your Ref: YL 2215 A

Our Ref: AL.INS.2019.FBB2808P

7 November 2019

**CHINA TAIPING INSURANCE (SINGAPORE)
COMPANY LTD**
3 Anson Road
#16-00 Sringleaf Tower
Singapore 079909

BY EMAIL ONLY

Dear Sirs,

**ACCIDENT INVOLVING FBB 2808 P & YL 2215 A ALONG WOODLANDS STREET 13
TOWARDS WOODLANDS AVENUE 3 ON 7 NOVEMBER 2019 AT ABOUT 0850 HOURS**

We act for the owner of vehicle no. FBB 2808 P.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

ALPHA CAR SERVICES PTE LTD
Blk C Kaki Bukit Ave 4
#01-59 Kaki Bukit Autobay
Singapore 417883
Person In-Charge: Cailing
Mobile Number: 6509 8258

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jerdine.wang@alt.sg / jiamin.mak@alt.sg for future correspondences.

** Kindly be reminded of the change of our address as stated below.*

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**
1 Coleman Street
#05-01, The Adelphi
Singapore 179803
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	213F
Vehicle Details	
Vehicle No.:	FBB2808P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	PHANTOM 200M
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	TA200E0036812
Chassis No.:	TA2000036812
Maximum Power Output:	-
Open Market Value:	\$3,395.00
Original Registration Date:	08 Feb 2007
First Registration Date:	08 Feb 2007
Transfer Count:	3
Actual ARF Paid:	\$510.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Feb 2022
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,071.00
COE Rebate Amount:	\$1,376.00
Total Rebate Amount:	\$1,376.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Nov 2019

OK

Advertisement

Home ▾ Motorbikes ▾ Motorbikes for Sale ▾ Class 2B



mohammadshahrizal

★★★★★ 12

Chat

Make
Offer

\$3,500

Share 43

Honda Phantom TA200

Bukit Panjang

Meetup

Used

Selling at \$3500 (negotiable)

Honda Phantom TA200

COE TILL 31 JAN 2024 (renewable)

4yrs 2mths left!!

Bike fully paid.

No NEA rebate.

Viewing available at my place.

Come down and see for yourself.

1 week ago In Class 2B

Honda

Cruiser

Insurance

Meet-up

Bukit Panjang

Listed by mohammadshahrizal



Mostly Responsive



Check seller profile

Reviews for mohammadshahrizal



rosvki

2019 Jan

Advertisement



DEVIALET



DISCOVER

mv - 2400
 pv - 1376
 nv - 1000

Advertisement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 12:59
Date Of Accident	07/11/2019 08:50
Exact Location Of Accident	WOODLANDS STREET 13 TWDS WOODLANDS AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBB2808P
Insured/Policyholder	
Name Of Registered Owner	FOO POCK CHIN
NRIC No	S1304213F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94786976
Alternative Phone No	OFFICE-94786976

Vehicle Particulars

Manufacturer	HONDA
Model	HONDA PHANTOM 200M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5082841295-03
Cover Note Number	

Driver

Name of Driver	FOO POCK CHIN
NRIC No	S1304213F
Date Of Birth	19/03/1958
Occupation	OUTDOOR
Date Of Driving Pass	03/05/1983
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94786976
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 253 JURONG EAST STREET 24 #04-251
Postcode	600253
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL2215A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	FOO POCK CHIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FB2808P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 253 JURONG EAST STREET 24 #04-251
Postcode	600253

A handwritten signature in black ink, appearing to be "J. J. ...".

Sketch Plan #2

SKETCH PLAN



Vehicle A: 7500 2000 2000

Vehicle B: 7500 2000 2000

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. 1st Report: 1st Report

2. 2nd Report: 2nd Report

3. 3rd Report: 3rd Report

4. 4th Report: 4th Report

5. 5th Report: 5th Report

6. 6th Report: 6th Report

7. 7th Report: 7th Report

8. 8th Report: 8th Report

9. 9th Report: 9th Report

10. 10th Report: 10th Report

11. 11th Report: 11th Report

12. 12th Report: 12th Report

13. 13th Report: 13th Report

14. 14th Report: 14th Report

15. 15th Report: 15th Report

16. 16th Report: 16th Report

17. 17th Report: 17th Report

18. 18th Report: 18th Report

19. 19th Report: 19th Report

20. 20th Report: 20th Report

21. 21st Report: 21st Report

22. 22nd Report: 22nd Report

23. 23rd Report: 23rd Report

24. 24th Report: 24th Report

25. 25th Report: 25th Report

26. 26th Report: 26th Report

27. 27th Report: 27th Report

28. 28th Report: 28th Report

29. 29th Report: 29th Report

30. 30th Report: 30th Report

31. 31st Report: 31st Report

32. 32nd Report: 32nd Report

33. 33rd Report: 33rd Report

34. 34th Report: 34th Report

35. 35th Report: 35th Report

36. 36th Report: 36th Report

37. 37th Report: 37th Report

38. 38th Report: 38th Report

39. 39th Report: 39th Report

40. 40th Report: 40th Report

41. 41st Report: 41st Report

42. 42nd Report: 42nd Report

43. 43rd Report: 43rd Report

44. 44th Report: 44th Report

45. 45th Report: 45th Report

46. 46th Report: 46th Report

47. 47th Report: 47th Report

48. 48th Report: 48th Report

49. 49th Report: 49th Report

50. 50th Report: 50th Report

51. 51st Report: 51st Report

52. 52nd Report: 52nd Report

53. 53rd Report: 53rd Report

54. 54th Report: 54th Report

55. 55th Report: 55th Report

56. 56th Report: 56th Report

57. 57th Report: 57th Report

58. 58th Report: 58th Report

59. 59th Report: 59th Report

60. 60th Report: 60th Report

61. 61st Report: 61st Report

62. 62nd Report: 62nd Report

63. 63rd Report: 63rd Report

64. 64th Report: 64th Report

65. 65th Report: 65th Report

66. 66th Report: 66th Report

67. 67th Report: 67th Report

68. 68th Report: 68th Report

69. 69th Report: 69th Report

70. 70th Report: 70th Report

71. 71st Report: 71st Report

72. 72nd Report: 72nd Report

73. 73rd Report: 73rd Report

74. 74th Report: 74th Report

75. 75th Report: 75th Report

76. 76th Report: 76th Report

77. 77th Report: 77th Report

78. 78th Report: 78th Report

79. 79th Report: 79th Report

80. 80th Report: 80th Report

81. 81st Report: 81st Report

82. 82nd Report: 82nd Report

83. 83rd Report: 83rd Report

84. 84th Report: 84th Report

85. 85th Report: 85th Report

86. 86th Report: 86th Report

87. 87th Report: 87th Report

88. 88th Report: 88th Report

89. 89th Report: 89th Report

90. 90th Report: 90th Report

91. 91st Report: 91st Report

92. 92nd Report: 92nd Report

93. 93rd Report: 93rd Report

94. 94th Report: 94th Report

95. 95th Report: 95th Report

96. 96th Report: 96th Report

97. 97th Report: 97th Report

98. 98th Report: 98th Report

99. 99th Report: 99th Report

100. 100th Report: 100th Report

DECLARATION

I/We declare the foregoing statements are true and correct to the best of my/our knowledge.

Signature of Driver
Date: 10/10/2010

Signature of Witness
Name: [Name]
Address: [Address]
Contact: [Contact]

Signature of Investigator
Name: [Name]
Address: [Address]
Contact: [Contact]



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191107/7007

1 of 3

Report No. T/20191107/7007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/11/2019 12:33		Vide Report No.:	Station Diary No.:
Informant's Particulars			
Name of Informant: FOO POCK CHIN		Address: APT BLK 253 JURONG EAST STREET 24 #04-251 SINGAPORE 600253	
ID Type / ID No.: NRIC NO / S1304213F		Contact No.: Home/Office: Mobile: 94786976	
Nationality: SINGAPORE CITIZEN		Email: SIMONFPC2@GMAIL.COM	
Sex: Male	Age: 61	Date of Birth: 19/03/1958	Type of Informant: Cyclist
Race: Chinese		Language: English	Institution / School Name:
Occupation: Private security officer		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Pedestrian / Cyclist	Drink Drive: No	Date/Time of Accident: 07/11/2019 08:50	Type of Location: WOODLANDS ST 13 TWDS WOODLANDS AVE 3
Location: WOODLANDS STREET 13				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 40 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB 2808P	Motorcycle	OTHERS	HONDA PHANTOM 200M	Red	Seriously Damaged	0
YL 2215A	Lorry		MITSUBISHI		Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20191107/7007

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20191107/7007

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBB 2808P	NTUC Income Insurance Co-Operative Limited	5082841295-03	08/08/2019	07/08/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Cyclist			
Name	FOO POCK CHIN	ID No.	S1304213F
Related Vehicle	FBB 2808P (Motorcycle)	Contact No.	94786976
Hospital/Clinic	FIRST MEDICAL CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/11/2019	Date Discharge	07/11/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On the above mentioned date & time, I was travelling along Woodlands Street 13 towards Woodlands Ave 3. Vehicle B - YL 2215A out of sudden dashed out from the Construction side and didn't spotted me and collided into me. I was injured and seek treatment at FIRST MEDICAL CLINIC & SURGERY and was given 3 days MC.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191107/7007

3 of 3

Report No. T/20191107/7007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SHARIFAH NOR FARIZAN BINTE SYED MOHD
SAID
Contact No.: 65476172

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
07/11/2019 12:33

Classification Of Case:












































...CLAIM SUBFOLDER...(Pending for Survey Report)

























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Nov 2019		20 Nov 2019 12:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case








Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	FOO POCK CHIN, ID: S1304213F								
Vehicle Reg. No.:	FBB2808P	Date of Loss:	07/11/2019 08:00 - :59 [152 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205286C02	Policy/Cover Note No.:	DMCVSN17562119022						
Vehicle Reg. No. (Insured):	YL2215A	Policy No. (Claimant):	5082841295-03						
		Excess:	S\$0.00						
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 29/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





*FBB2808P (SNM19D205286C02)
[YL2215A]
TP
FOO POCK CHIN
Nov 7 2019 8:00AM
[-]
Alpha Car Services Pte Ltd














Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
2	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
3	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
4	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
5	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
6	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
7	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
8	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
9	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
10	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
11	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
12	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
13	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
14	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
15	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
16	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
17	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
18	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
19	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
20	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
21	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
22	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
23	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
24	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
25	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
26	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
27	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
28	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
29	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
30	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
31	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
32	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
33	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
34	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
35	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
36	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
37	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
38	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
39	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
40	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
41	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
42	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>
43	20/11/19 14:05	General View		Load JPG	<input checked="" type="checkbox"/>






Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
58	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
59	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
62	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
63	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
64	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
65	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
66	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
67	20/11/19 14:05	General View	 Load JPG	<input checked="" type="checkbox"/>
68	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	20/11/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/11/19 14:09	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	06/12/19 19:06	Accident Statement	 Load HTM	
2	06/12/19 19:08	Accident Statement	 Load HTM	
3	06/12/19 19:10	Accident Statement	 Load HTM	
4	06/12/19 19:11	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	07/11/19 13:14	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	07/11/19 13:15	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	07/11/19 13:15	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	07/11/19 13:15	Sketch Plan #3	 Load TIF	
4	07/11/19 13:15	Sketch Plan #4	 Load TIF	
5	07/11/19 13:15	Sketch Plan #5	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119019842/HCD3E2

Date: 02/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN17562119022

Claimant Vehicle No : FBB2808P Insured Vehicle No : YL2215A

Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: SNM19D205286C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB2808P

Make & Model: HONDA PHANTOM 200M, 197cc (M) Engine No: TA200E0036812

Reg. Date: 08/02/2007 (Man. Year: 2006) Chassis No: TA2000036812

Colour: Red Odometer: 32452 km

Engine Capacity: 197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80/17 Rear Tyre Size: 130/90/15

Front Left Side: Dunlop 5 mm Rear Left Side: LASERTEC 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 08/11/2019 Inspected At: Alpha Car Services Pte Ltd (HQ)
Blk C, Kaki Bukit Ave 6 #01-59, Kaki
Bukit Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2020)	
Parts:	N/A	HONDA PHANTOM 200M 197cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB2808P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >