

Our Job Ref No : 305347385

Date : 28/11/19

TO: ASW ✓

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : PARAM

: SHC1042L

07/11/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA SJN5949M

2. The finalized amount shall be:

(a) Spare Parts after List discount \$5,605.76

(b) Labour Charges \$1,850.00

Total for Part-By-Part Repair Cost \$7,455.76

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 5 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Ram

Date : 5/12/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

Date: 26.11.2019

REPAIR ESTIMATE

Time: 18:11:48

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305347385
REGN NO : SHC1042L
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 07.09.2017
DATE/TIME IN : 05.11.2019 11:10
ACCIDENT DATE : 05.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-0592-G	PRIG4 PANEL SUB-ASSY FRON	1	1,264.00	25.00	948.00	DD BUC
0002	04-01-0302-0595-G	PRIG4 PANEL SUB-ASSY RR D	1	1,258.30	25.00	943.72	BUC BUC
0003	04-01-0302-3909-G	PRIG4 PANEL SUB-ASSY QUAR	1	836.70	25.00	627.52	BUC
0004	04-01-0302-0810-G	PRIG4 MLDG ASSY BODY ROCK	1	576.00	25.00	432.00	Cra
0005	03-01-0302-2020-G	PRIG4 WHEEL DISC	1	1,555.10	25.00	1,166.32	Cra
0006	28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00		75.00	nee
0007	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00		80.00	nee
0008	03-01-0302-2903-G	PRIG4 ARM ASSY UPPER CONT	1	356.80	25.00	267.60	Im
0009	03-01-0302-0108-G	PRIG4 CARRIER SUB-ASSY RR	1	810.60	25.00	607.95	Om
0010	03-01-0302-2064-G	PRIG4 HUB & BEARING ASSY	1	610.20	25.00	457.65	Bm

SUB-TOTAL : 5,605.76

JOB NATURE

0000 PB PANEL BEATING

800.00

5450.7


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305347385
REGN NO : SHC1042L
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 07.09.2017
DATE/TIME IN : 05.11.2019 11:1
ACCIDENT DATE : 05.11.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 SP	SPRAYPAINT CHARGE	700.00				
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00				
0003 23-01	TOWING FEE	60.00				
0004 20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP	120.00				
0005 20-09	REMOVE/REFIX RR SUSPENSION ASST REPAI	80.00				
0006 20-08	ADJUST REAR WHEEL ALIGNMENT	60.00				
SUB-TOTAL						: 1,850.00
TOTAL						: 7,455.76

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :





TEL: 97297337

T ZONE TOWING PTE LTD

8 Kaki Bukit Ave 4 #06-32 Premier@Kaki Bukit
Singapore 415875

Email: t-zonetowing@live.com.sg

GST Reg No. 201500018C

DelGro Engineering Pte Ltd

1 Road Singapore 579701

6383 6280 Facsimile +65 6280 9755

579701

1 Road Singapore 579701

Road Singapore 609286

Out Way Singapore 728791

Loop Singapore 758156

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 57571

320 Ubi Road 3 Singapore 408649

6553 1111
SPARK Assist
Towing • Accident



No. P 26620

WORK ORDER

Svc Date

06-11-19

Time Received

1120

Member's Name

CDG

Time Arrived

1200

M'ship / NRIC No.

WIS L184

Time Completed

1400

Member's Contact No.

6542 1726

From

S17 T.P. Pand

Car Regr. No.

SHC1042 L

To

59 Loyang Dr

Car Make / Model

Porus

Tow Truck No.

GR5366 Z

Remarks (if any)

No Key Accident

Amount

4. Type of Towing:

- ☒ Normal Tow
☒ King Dolly
☐ Flat Bed
☐ Crane-up

6. Parts Replaced/Remarks:


In Workshop:

- exhaust ☐ Wheel Jammed
Overheating ☐ Steering Faulty
Brake Faulty ☐ Alternator Faulty
Starting Problem ☐ Loss Power
Accident ☐ Engine Stalled
Return Taxi

ADDITIONAL CHARGES


- ☒ Dolly Wheels /Flat bed ☐ Patch Tyre
☐ Basement /Multi-storey ☐ Change Spare Tyre
☐ Crane up /Bogged ☐ Change Battery
Size : _____
☐ Causeway /2nd Link
☐ Jump Start
☐ Collection of key
☐ ERP /Carpark

BODY & PAINT CONDITION RECORD



*please remove any valuables or personal belongings in the car

No Key



: Cracked X : Dented
/ : Scatched O : Missing

Signature of Customer

Tow Driver's Name & Signature

Member's Signature

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Time Completed

1400

Cash Invoice Details (if applicable)

13. Cash Invoice No. :

Customer Acknowledgement

- I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

06-11-19

Date

1200

Time

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY