

Immediate Advice

To: AXA Insurance Pte Ltd

11/11/2019

Survey Details:

Date of loss	7-Nov-19	
Date of appointment	8-Nov-19	
Date of survey	11-Nov-19	
Location of survey	VOLKSWAGEN CENTRE	
	SINGAPORE	

Vehicle Details:

Claim Type:	OD		
Vehicle number	SML 5533D	SML 5533D	
Make and Model	SKODA OCTA	SKODA OCTAVIA RS 2.0 TSI	
Date of registration	30/4/2019		
Excess	\$	1,000.00	
Market Value	\$	115,000.00	
Parf Rebate	\$	67,055.00	
Nett Loss	\$	47,945.00	

Repair details:

Initial Estimate \$ 14,763.00

Proposed/Revised repair cost:

Parts	\$ 10,905.08
Check items (estimate)	\$ 200.00
Labour	\$ 1,820.00
Total	\$ 12,925.08
Lump Sum(if applicable)	\$ -

|--|



Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE
HAVE AUTHORIZE REPAIR.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	