



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2018 SKODA OCTAVIA RS 2.0 TSI (SML5533D)
Date of Loss	7 November 2019
Time of Loss	14.30
Loss Description	SML5533D (INSD) C/W PROPERTY
Comment	

Workshop Details

Total Rebate Amount	67055
Nett Loss Amount	\$47,945.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SML5533D

Registration State SINGAPORE

Mileage 10870

Purchase Date dd/mm/yyyy

Registration Date * 30/04/2019



Age of Vehicle 0


CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2018	2018
Make	SKODA	SKODA

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	GUO PEIFENG	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Model	OCTAVIA RS 2.0 TSI	<input type="text" value="OCTAVIA RS 2"/>
Type		<input type="text" value="▼"/>
Type of Paint		<input type="text"/>
Chassis No	TMBBU7NE1K0065789	<input type="text" value="TMBBU7NE1I"/>
Engine No	DLB029193	<input type="text" value="DLB029193"/>
Engine Capacity		<input type="text" value="1984"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="115000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	9 January 1991	<input type="text" value="dd/mm/yyyy"/> 
Age	28	
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="▼"/>
Driving Experience	5	
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<div>dd/mm/yyyy</div> <div></div>
Address	Singapore	<div></div>
Address type	Residential	<div></div> <div>▼</div>
Gender	Male	<div></div> <div>▼</div>
Marital status	Married	<div></div> <div>▼</div>
Identification #	S9101152B	<div></div>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

11/11/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1000

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Age of Tyres

Front Tyre Size

225/40R18

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Spare wheel

Rear Tyre Size

225/40R18

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss	<div>Yes</div>	<div>No</div>
-----------	----------------	---------------

Part Supplied by AXA	<div>Yes</div>	<div>No</div>
----------------------	----------------	---------------










Save

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	RE
		0	1		7- SPEED DUAL CLUTCH GEARB	Cracked	0	10806.18	No					10806.18	Reviewing	
		0	1		SOUND BAFFLE ENGINE COVER	Cracked	0	98.9	No					98.9	Reviewing	
		0	1		END PLATE FRT LOWER SPOILER	Serviceable	0	0	No					0	Deny	

Labour

Add Approve Deny Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	RE
		0		WHEEL ALIGNMENT	0	300	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	RE
		0		DIAGNOSTIC & PROGRAMMING	0	360	0	0	Reviewing		
		0		R & R GEARBOX	0	1160	0	0	Reviewing		
		0		CHECK SHORT CIRCUIT / HARNES REPAIR	0	200	0	0	Reviewing		
		0		LABOURS					Deny		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 4 DAYS Reviewing		0		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount	\$11,925.08	
CATEGORY		ESTIMATE				ADJUSTED		
Spare Parts		\$0.00				\$10,905.08		
Labour		\$0.00				\$2,020.00		
Excess						-\$1,000.00		

Submit for Review