

ASS. REC. BY: Sun Pin

REF:

NT4C

NS/IN 01019863/Q9f332

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: PC 56251
 Policy No. _____
 Claims No. MT 1069285-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG6136R Yr Regn: 1614 / 2019
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: MAN A95 c.c. 10518Colour: Multicolour Green A/C: Insured / Std / NI / NASp. Reading 042600 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA95ZZ7KF00 9077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or Fleet RmTyre Size: F: 275 / 70 R22-5R: 275 / 70 R22-5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 29/10/2019

Survey held at

Rear

R/Bal. 5/5 mmL/Bal. 5/5 mmD.O.I. 01/11/20195 MRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear Left

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SG 6136Rno policy found

Sun Pin finalised from Prg to 3641, 2 days
used 811, 18%

RECEIVED 15 NOV 2019

Date/Time, File Pass to?

1) 15/11/2019

Date/Time, File Return to?

2)

Rep. Formas:

Lump Sum / L.E.I.:

☐ : Prell. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wheel and (\$

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Others

TOTAL

TP Claims against NTUC Income: Follow-Through Survey

Date: 14/11/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1067181-002	COMFORTDELGRO ENGINEERING PTE LTD	SHC 3347U	SMF 2469M
2	MT/1069285-002	SMRT BUSES LTD	SG 6136R	PC 5625J
3	MT/1071372-001	SMRT BUSES LTD	SMB 1316T	GBG 3513G

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 11:33
Date Of Accident	29/10/2019 19:50
Exact Location Of Accident	ADMIRALTY RD WEST (BEF BS:47079-OPP BRITISH AMERI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG6136R
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN A95

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	GAO RUINA
Passport No/FIN	G2928082M
Date Of Birth	26/04/1988
Occupation	OUTDOOR
Date Of Driving Pass	13/03/2017
Driving Experience	2 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address NO ADDRESS
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 35

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

My bus SG6136R was involved in an accident with a private bus along Admiralty Road West (before BS: 47079 - Opp British American Tobacco). My bus left rear portion was hit by the right front portion of the private bus (PC5625J). No injuries reported. The bus left rear CCTV dislodged. Bus was arranged to off service back to AMKD after exchanging particulars with 3rd party driver. That's all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: PENDING DOWNLOAD
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC5625J
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver KASIM BIN OSMAN
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Nature Of Damage

No. Of Passenger (Including Driver) *

IMPORTANT NOTICE

SKETCH PLAN

Sq 6136 R
PART-35
Bus 10/19/1080

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the **Poleholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **dispute policy liability**.
4. The name and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**

6. The report will be forwarded by the insurers of the GSA (General Management Centre) established by the General Insurance Association of Singapore (GIA) for vehicles and most reports of this nature will be sent to the Traffic Police for their attention by interested parties.

7. By the lodgment of this report to the insurers, you hereby consent to the recording of this report at the centre and to copies of the report being made available elsewhere.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or collected by my insurer collectively the "Personal Information" and disclose and transfer such personal information to all insurers who have insured vehicle(s) involved in the accident (all insured(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers", the Insurers' Insurer/Law Firm, the Motorist's Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of

(i) preventing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external cover of envelope/real package); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(b) all insured(s) who have insured vehicle(s) involved in the accident and the Insurers' Insurer/Law Firm, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and

(c) my Personal Information may/Can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firm, which may be sited outside of Singapore, for one or more of the above purposes;

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;

(e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

(ii) for complying with requirements under any regulations, laws or court orders.



Poleholder's Signature
Date & Time


M. P. 381

Driver's Signature
(if driver is not the poleholder)
Date & Time



Reporting Centre's Signature
Name
MPCEN No.

SKETCH PLAN



EW5
STP

Adressately K. J. 100-14 (Ref. ES:47079-24)
 100-14 (Ref. ES:47079-24)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION U.S.

✓The details of the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date of Birth:

Driver's Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

4000-2700 cm⁻¹

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 292D

Vehicle Details

Vehicle No.: SG6136R

Vehicle to be Exported: No

Intended Deregistration Date: 01 Nov 2019

Vehicle Make: MAN

Vehicle Model: A95

Primary Colour: Multicolor

Manufacturing Year: 2018

Engine No.: 50352281665224

Chassis No.: WMAA95ZZ7KF009077

Maximum Power Output: -

Open Market Value: \$414,047.00

Original Registration Date: 16 Apr 2019

First Registration Date: 16 Apr 2019

Transfer Count: 0

Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Rebate Amount: \$0.00

Total Rebate Amount: \$0.00

The information contained herein is correct as at 01 Nov 2019

OK



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REPAIR LH PORTION REAR		\$1,590.00				1060			
Total Labour		\$1,590.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$772.00				680			
Total Spray Painting & Panel Beating		\$772.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	✓ NEC
			CE824-M IP CAMERA	1.00	\$1,890.00	0.00	\$1,890.00	Replace	✓ R2
Total					\$2,090.00		\$2,090.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



Sun Pin

~~Line~~ Part/Part

before spray & photo

TP without prejudice

Repair day - 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION REAR	\$1,590.00	1060
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	680
Total Spray Painting & Panel Beating	\$772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	NPC
			CE824-M IP CAMERA	1.00	\$1,890.00	0.00	\$1,890.00	Replace	BR
Total					\$2,090.00		\$2,090.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

Sun Pin

Leave Part / Part.

before spray & photo

TP without prejudice.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/11/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG8136R
Case Reference Number	BUS/10/19/1080
Registration Date	16/4/2019
Company Type	SMRT Buses Ltd
Make	A95 MAN E8
Model	MAN A95
Name of Driver	Gao Ruina
Type of Accident	Side Swipe
Accident Date and Time	29/10/2019 7:53 PM
Accident Reported Date and Time	30/10/2019 3:33 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24104105
Special Instruction to ARC, if any	SG8136R-LEFT REAR PORTION PC5625J (TP) INSURED WITH NTUC
Prepared Date and Time	31/10/2019 1:51 PM
Chassis Number	WMAA95ZZ7KF009077
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$772.00	\$680.00
Total Spare Part Cost	\$1,901.00	\$1,901.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,263.00	\$3,641.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0 /
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	31/10/2019 2:33 PM	01/11/2019 3:15 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/11/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION REAR	\$1,590.00	\$1,060.00
Total Labour	\$1,590.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	\$680.00
Total Spray Painting & Panel Beating	\$772.00	\$680.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace <i>NEC</i>
			CE824-M IP CAMERA	1.00	\$1,890.00	10.00	\$1,701.00	Replace	Replace <i>BR</i>
Total					\$2,090.00		\$1,901.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1060
680
200
1701

3641

2 days

4452x



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662823
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG8136R
Case Reference Number	BUS/10/19/1080
Registration Date	16/4/2019
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	MAN A95
Name of Driver	Gao Ruina
Type of Accident	Side Swipe
Accident Date and Time	29/10/2019 7:53 PM
Accident Reported Date and Time	30/10/2019 3:33 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG8136R-LEFT REAR PORTION PC5625J (TP) INSURED WITH NTUC
Prepared Date and Time	31/10/2019 1:51 PM
Chassis Number	WMAA95Z7KF009077
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$2,090.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,452.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	31/10/2019 2:33 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19019883/Qqf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 22-11-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 5625J	Veh. Inspected	SG 6136R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1069285-002	Excess (\$)	0.00
Assign From		Assign Date	01/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WMAA95ZZ7KF009077	Colour	GREEN
Odometer	042600	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2019	Inspection Date	01/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6136R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	CB824-M IP CAMERA	BROKEN	1,890.00	1,890.00
	LESS 10% DISCOUNT		-	-189.00
			1,890.00	1,701.00
<u>SPECIAL NETT ITEMS</u>				
1	STICKER SG LOVE (SN)	NECESSARY	200.00	200.00
			200.00	200.00
			1,590.00	1,060.00
			772.00	680.00
			2,362.00	1,740.00
GRAND TOTAL			4,452.00	3,641.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,641.00

Report Ref No. NS/INC19019883/Qqf3s2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.