

ASS. REC. BY:

REF:

CS/TMS 19019897/Fqf382

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Piona Gun Bo Song

of TMI

Date/Time: 11.11.19 9.20 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 4092C

Insured:

P2 1338T

at Workshop m/s

Combaradelgro

Tel:

6214 8300

of

59 Ioyang Drive

Policy No:

MB010047

Claim No:

M1908760

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.11.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

map'

H.O.D. Endorsement:

Date/Time: 11.11.19 10.03 a.m

Person Contacted:

Jumani

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 4092C - CC3 / III 180307141 K09372 D.O.A - 07/11/2018
	P2 1338T - NA / IV 180307141 Z4 R.O.A - 24/10/2019
12/11/19 @	1.33pm revised to Piona Gun via Meimen.
14/11/19	Ram finalised US \$1200, 3 days cred \$246.08, 647.7)

P.S. REC. BY:

REF: Tm1

Ram

## ASSIGNMENT

From:

Date:

11-11-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 4092C

at Workshop m/s Comfoadulgro  
of 59 Loyang Drive

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 4092C

Yr Regn: 10/Sept 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai IAO

c.c 1685

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading:

565633

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHLB41UMSU07T483.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/11/19

D.O.I.

11/11/19

Survey held at

Comfoadulgro (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt &amp; O/S frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 14 NOV 2019

Date/Time, File Pass to?



Preli. Report

1) 14/11/19 Trans



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Format:

MER-TP

Lump Sum / P.P. Fee

1200

250

Our Job Ref No : 305347762

Date : 13/11/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : PARA

: SHB4092C

08/11/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC PZ1338T

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

**Final Lumpsum Repair cost**

\$1,200.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Rgm

Date : 14/11/19

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2019 17:36 Sendback Est	08 Nov 2019 17:42 S\$3,346.08	11 Nov 2019 09:28 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	CTPL, Co. Reg. No.: 199303821R								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHB4092C	Date of Loss:	08/11/2019 10:00 - :59 [49 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1908750	Policy/Cover Note No.:	MB010047 (Comprehensive) Coverage: 25/06/2019 - 25/06/2020						
Vehicle Reg. No. (Insured):	PZ1338T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>									
			View All	Compose Case Mail					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fiona Gan Bee Song

Date: 12 Nov 2019

## **Preliminary Advice**

Insured Vehicle No	: PZ1338T	Accident Date	: 08/11/2019
TP Vehicle No	: SHB4092C	Assignment Date	: 11/11/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 3.00
Date of Inspection	: 11/11/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front, o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,346.08
Revised Amount	:S\$	1,524.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,524.72

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2019 16:06
Date Of Accident	08/11/2019 10:40
Exact Location Of Accident	ORCHARD LINK TOWARDS ORCHARD RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB4092C
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

#### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

#### Driver

Name of Driver	TANG TIONG KIAT
NRIC No	S1355450A
Date Of Birth	05/10/1959
Occupation	OUTDOOR
Date Of Driving Pass	29/01/1977
Driving Experience	42 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96699167
Fax Number	
Contact Number	
Email Address	DRIVER7205@GMAIL.COM

Address	BLK 312 UBI AVENUE 1 #04-449
Postcode	400312
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PZ1338T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	TAN LYE YONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 08.11.2019  
@ 13:00 hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:


JC NO.: 305347762

CUSTOMER		REGN NO.: SHB4092C	MILEAGE
MR/MS	COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
CUSTOMER NO.	7010045	MODEL I-40	E ..... 1/2 .....
ADDRESS	383 SIN MING DRIVE Singapore SINGAPORE 575717	YR OF MANU 10.09.2015	DATE/TIME IN 08.11.2019 11:
TEL (R)	65508755 (O)	CHASSIS CODE KMHLB41UMGU077483	TARGET DATE
TEL (P)			COMPLETION DATE/TM
DISCOUNT CARD NO.			

Accident Date: 08.11.2019  
NATURE: 3P 08.11.2019

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:  
I/C No.:  
Vehicle No.: SHB4092C CHIANG

Vehicle No.: SHB4092C

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

#### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/11/2019
Vehicle Reg. No.:	SHB4092C	Driveable?	YES
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	10/09/2015
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDDU377391	Chassis No:	KMHLB41UMGU077483
Odometer:	565633 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	5

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

#### COST OF CLAIMS

	Amount
Parts	1,815.08
Miscellaneous Items	11.00
Labour	1,520.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,346.08</b>
<b>+ GST 7.00% (S\$)</b>	<b>234.23</b>
<b>Nett Amount (S\$)</b>	<b>3,580.31</b>

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHB4092C/08/11/2019 17:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER COVER X (R)	20.00	0.00	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET RH XHM	20.00	0.00	*24.60 FL
3	1		*FRONT FENDER RH BUC	20.00	0.00	*566.30 FL
4	1		*FRONT FENDER SHIELD RH XHM	20.00	0.00	*174.90 FL
5	1		*FRONT WHEEL HUB CAP RH SCR	20.00	0.00	*107.10 FL
6	1		*FRONT FENDER ADVERTISEMENT REC	0	0.00	*100.00 FS
7	1		*FRONT DOOR COMFORT LOGO REC	0	0.00	*75.00 FS
8	1		*FRONT DOOR ADVERTISEMENT REC	0	0.00	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 2,200.10

- List Item Discount on L Items (\$\$) 385.02

Total Parts (\$\$) 1,815.08

ComfortDelGro Engineering Pte Ltd/SHB4092C/08/11/2019 17:42. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

$$5673.4 \times 80\% = \$538.72$$

$$\$538.72 + 100 + 75 + 100 = \$813.72$$

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

## Estimates on Labour

No Particulars

Lab. Type

Amount

Labour Items

1 PANEL BEATING

New

600.00 ~~820~~

2 SPRAY PAINTING

New

750.00 ~~8400~~

3 TUFF KOTE

New

50.00 ~~820~~

4 FRT WHEEL ALIGNMENT

New

120.00 ~~240~~

Gross Labour Cost (\$\$)

1,520.00

ComfortDelGro Engineering Pte Ltd/SHB4092C/08/11/2019 17:42. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
  - To supply damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*[Handwritten Signature]*  
 12/11/19  
 Ram (LKK)  
 11/11/19 1130 hrs  
 \$1524.72  
 4/5 = \$1200  
 9ff repair photo  
 Paraman@lkkauto.com  
 886227284  
 3 repair days

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 17:36 <a href="#">Sendback Est</a>	08 Nov 2019 17:42 <b>S\$3,346.08</b>	11 Nov 2019 09:28 <a href="#">Edit Adj Rpt</a>	<b>S\$1,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHB4092C	Date of Loss:	08/11/2019 10:00 - :59 [49 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1908750	Policy/Cover Note No.:	MB010047 (Comprehensive) Coverage: 26/06/2019 - 25/06/2020
Vehicle Reg. No. (Insured):	PZ1338T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 20/11/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



## Claim Documents

SHB4092C (M1908750)

[PZ1338T]

TP

CTPL

Nov 8 2019 10:00AM

[CTPL]

ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
**View**
[View in Browser](#)

### Assessment Reports

 1 per page
 ☒

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	08/11/19 17:42	<b>Repairer Estimates</b>	1	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	11/11/19 09:28	<b>Accident Statement</b> From: SC - Reg. No: PZ1338T, Claimant: BIG S'HOLIDAY PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/11/19 13:33	<b>Adjuster Immediate Advice</b>	1	Load HTM	

### Photos/Images

 3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
22	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
23	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
24	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
25	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
26	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
27	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
28	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
29	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
30	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
31	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
32	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
33	12/11/19 09:28	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
34	14/11/19 11:37	Reinspection Photo	 Load JPG	✓
35	14/11/19 11:37	Reinspection Photo	 Load JPG	✓
36	14/11/19 11:37	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	20/11/19 10:15	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
2	20/11/19 15:11	SUPERCEDE LOD - LTA FEE	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	08/11/19 17:43	E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19019897/FQF3S2  
Date: 22/11/2019

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MB010047
Claimant Vehicle No :	SHB4092C	Insured Vehicle No :	PZ1338T
Date of Loss:	08/11/2019	Nature of Claim:	TP
		Claim No:	M1908750

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB4092C</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDDU377391
Reg. Date:	10/09/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU077483
Colour:	Blue	Odometer:	565633 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,815.08	813.72	1,001.36	55.17
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,520.00	700.00	820.00	53.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,346.08</b>	<b>1,524.72</b>	<b>1,821.36</b>	<b>54.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
(S\$)	3,346.08	1,200.00	2,146.08	64.14
<b>+ GST 7.00/7.00% (S\$)</b>	234.23	84.00	150.23	64.14
<b>Nett Amount (S\$)</b>	<b>3,580.31</b>	<b>1,284.00</b>	<b>2,296.31</b>	<b>64.14</b>

### INSPECTION

Date of Assignment:	11/11/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/11/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 22 Nov 2019)

**Parts:** 143    HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHB4092C)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	1,052.20 FL	*- FL
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	24.60 FL	*- FL
3	1		*FRONT FENDER RH	Buckled	566.30 FL	*566.30 FL
4	1		*FRONT FENDER SHIELD RH	Not Necessary	174.90 FL	*- FL
5	1		*FRONT WHEEL HUB CAP RH	Scratched	107.10 FL	*107.10 FL
6	1		*FRONT FENDER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
7	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
8	1		*FRONT DOOR ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,200.10</b>	<b>948.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	385.02	134.68
<b>Total Parts (S\$)</b>	<b>1,815.08</b>	<b>813.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAY PAINTING	New	750.00	400.00
3	TUFF KOTE	New	50.00	20.00
4	FRT WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,520.00	700.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;