

Page to Asher, Thanks



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/11/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1434K
Case Reference Number	BUS/10/19/1083
Registration Date	24/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Suvit See-Too
Type of Accident	Head to Rear
Accident Date and Time	30/10/2019 7:58 AM
Accident Reported Date and Time	30/10/2019 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104096
Special Instruction to ARC, if any	SMB1434K-REAR RIGHT PORTION SLR4975Z (TP) INSURED WITH AIG
Prepared Date and Time	31/10/2019 2:41 PM
Chassis Number	WMAA22ZZ0E7002151
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,080.00
Total Spray Cost	\$878.00	\$786.00
Total Spare Part Cost	\$2,441.16	\$2,441.16
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,644.16	\$4,287.16
Lump Sum Total	\$4,650.00	\$4,300.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	31/10/2019 2:49 PM	01/11/2019 3:18 PM
Signature		Sun
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/11/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$1,060.00
Total Labour	\$1,325.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	\$786.00
Total Spray Painting & Panel Beating	\$878.00	\$786.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	Replace
6010064	Body	F01001-CW274	BUMPER:REAR,CENTR E, FOR MAN A22 BUS	1.00	\$1,968.80	100.00	\$0.00	Repair	Repair
6009992	BODY RH	A01001-CW564	PANEL, SIDE:R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	Repair
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE:R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair
6010299	VE	88-25320-6006	LAMP,INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace
Total					\$7,234.50		\$3,051.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r} 877.23 \\ 1,027.53 \\ + 1,146.69 \\ \hline 3,051.45 \\ - 20\% \\ \hline 2,441.16 \end{array}$$

$$\begin{array}{r} 2,441.16 \\ 1,060.00 \\ + 786.00 \\ \hline 4,287.16 \end{array}$$

$$L/S = 4,300 @ 2 \text{ days}$$



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB1434K
Case Reference Number	BUS/10/19/1083
Registration Date	24/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Suvit Sae-Too
Type of Accident	Head to Rear
Accident Date and Time	30/10/2019 7:58 AM
Accident Reported Date and Time	30/10/2019 9:15 AM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1434K-REAR RIGHT PORTION SLR4975Z (TP) INSURED WITH AIG
Prepared Date and Time	31/10/2019 2:41 PM
Chassis Number	WMAA22Z20E7002151
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$876.00	\$0.00
Total Spare Part Cost	\$3,263.18	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,466.18	\$0.00
Lump Sum Total	\$5,450.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	31/10/2019 2:49 PM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655582
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/10/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1: Labour Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$1,325.00				1060			
Total Labour		\$1,325.00							
Part 2: Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$878.00				786			
Total Spray Painting & Panel Beating		\$878.00							
Part 3: Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4: Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010062	Body	F01001-CW273	COVER-REAR TAIL LAMP,RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	/ DD
6010298	VE	88-25225-6039	LAMP, STOP-LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	/ CRU.
6010064	Body	F01001-CW274	BUMPER-REAR, CENTR E, FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	X R
6009992	BODY RH	A01001-CW564	PANEL, SIDE-R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	X R
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE-R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	X R
6010299	VE	88-25320-6008	LAMP, INDICATOR-LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	/ SCR.
Total					\$7,234.50		\$4,078.98		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days.

Sun Pin (Lkk) sunpin@lkkquto.com

Lump Sum Repair

After print Photo

TP without prejudice.