

ASS. REC. BY:

REF:

CS3/MSG19019960/Mcf307

Special Instruction:

Survivor: Hock AnnASSIGNMENT (Office)From (Person): Kathrine Wong of MSG Date/Time: 11.11.19 16:57pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKX 37912 Insured: GBD 3993 Vat Workshop m/s Messrs CH Motor Tel: 68418841of 3019A vi road 1 #01-30Policy No: 29081320 Claim No: 611249

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9.11.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11.11.19 4:35pm Person Contacted: Joe H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBD 3993 V X</u>
	<u>SKX 37912 X</u>
	<u>Diamond: 13/11/2019</u>
	<u>After repair: 19/11/2019</u>

ASS. REC. BY:

H-ANN

REF: MS19

PRS

ASSIGNMENT

From:

Date:

12.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 37912

at Workshop m/s Messrs CH Motor

of 2019 A Ubi road 1 #01-30

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKX 37912

Yr Regn:

Jun / 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Lancer

C.C

1584

Colour:

yellow /

A/C:

Insured / Std / NI / NA

Sp. Reading

137589

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMY5N C53 A9000 4696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/45/R16

R:

205/45/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

pending G.A

D.O.I.

12/11/19

Survey held at

Messrs CH Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 2-3h
	repair days - 3 days
	MV - 34000
	PV - 28594
	NV - 5400

* SKX 37912

PRS case

* pending G.A report

* workshop work done

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

120

Transportation:

S + RS. \$

Photos

Others

11

TOTAL

131

Rep. Form:

PRS

Lump Sum / L.B. / C.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2019 13:57		11 Nov 2019 16:15 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Ching International Service Pte Ltd , Co. Reg. No.: 200909419G									
Main Claimant: NANTHAKUMAR THEVAR S/O PERIASAMY , ID: S8810136G									
Vehicle Reg. No.:	SKX3791Z	Date of Loss:	09/11/2019 14:00 - :59 [124 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 611249	Policy/Cover Note No.:	29081320 (Comprehensive) Coverage: 01/06/2018 - 31/12/2019						
Vehicle Reg. No. (Insured):	GBD3993U	Policy No. (Claimant):							
		Excess:							
Repairer: Messrs C H Motor Vehicle Repair Training (HQ) 3019A UBI ROAD 1, #01-30, 408713 Ubi - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 12/11/2019]									
Adj Asg. Remarks: on WP. Liab: NR. Disagree on SJE. Contact: Mr Joe @ 6841 8841 / 6748 8888.									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	136G
Vehicle Details	
Vehicle No.:	SKX3791Z
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Nov 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 GLX 5MT AIRBAG 2WD 4DR
Primary Colour:	Yellow
Manufacturing Year:	2009
Engine No.:	4G18KC6656
Chassis No.:	JMYSNCS3A9U004696
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,403.00
Original Registration Date:	25 Jun 2009
First Registration Date:	25 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$12,403.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$29,839.00
COE Rebate Amount:	\$28,594.00
Total Rebate Amount:	\$28,594.00

The information contained herein is correct as at 25 Nov 2019

OK



Tyres
Featuring
Control,
Response &...



Suzuki Short
Shifter For A
Faster Shift!



LTA
Compliant
Drift Racing
Exhaust Sys...



Used Alpine
DVD Player
In Mint
Condition

Mitsubishi Lancer 1.6A GLX

Price Range ▾

Depreciation ▾

Year Reg ▾

Vehicle Type ▾

Advanced Search

Home » Used Cars » Creative Auto » Mitsubishi Lancer 1.6A GLX Sports (COE till 04/2029)

Mitsubishi Lancer 1.6A GLX Sports (COE till 04/2029)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

CREATIVE AUTO

**Price**

\$36,800

Depreciation

\$3,940 /yr

Reg Date12-May-2009
(9yrs 4mths 3days COE left)**Mileage**

144,000 km (13.5k /yr)

Manufactured

2009

Road Tax

\$734 /yr

Transmission

Auto

Dereg Value

\$24,468 as of today (change)

OMV

\$14,027

COE

\$26,175

ARF

\$14,027

Engine Cap

1,584 cc

Power

79.0 kW (105 bhp)

Curb Weight

1,162 kg

No. of Owners

0

Type of Vehicle

Mid-Sized Sedan

Features

Reliable 1.6L Inline 4 Cylinders SOHC 16V Engine, Smooth 5 Speed CVT Auto Transmissions, ABS, EPS, Dual SRS Airbags, Immobiliser Remote Key Systems. View specs of the Mitsubishi Lancer (2006-2008)

Accessories

Sports Edition Lancer With Ralliart Full Bodykits/Spoiler/Sports Rims, Leather Seats, Sony AudioCD/USB Player, Reverse Sensors, Knockdown Rear Seats.

Description

Max Loan Amount Available As Advertised! Meticulously Well Maintained Unit With Low Mileage Done! Guaranteed Accident Free With No Repairs Needed! Non PHV Usage Car! Buy With Confidence And Assurance! Our Company Provide Loan Scheme! STA Or VICOM Evaluation Are Available! All Trade In Most Welcome! Hurry Contact Us Now For A Viewing Appointment Today Before It's Gone!

Category

COE Car

Status

Available

Resources**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

[Shortlist](#)[Compare](#)[Add note](#)[Report Error](#)[More Actions](#)**Seller Information****Creative Auto**

92 vehicles for sale. 74 sold in past 3 mths

61 Ubi Avenue 2 #04-02/03/18/19/20

Automobile Megamart

Search cars nearby

NEO

92222719

Alex Tan

97556887

[Used Car List](#) | [Company Profile](#)

Posted on: 21-Dec-2019 | Last Updated on: 27-Dec-2019

Upfront Payment

[more Financial info](#)

Tr

\$25

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2019 20:54
Date Of Accident	09/11/2019 14:40
Exact Location Of Accident	YISHUN AVENUE 7 AT BLOCK 173 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX3791Z
Insured/Policyholder	
Name Of Registered Owner	NANTHAKUMAR THEVAR S/O PERIASAMY
NRIC No	S8810136G
Email Address	SHANKERBOI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92378344
Alternative Phone No	OFFICE-92378344

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER 1.6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10923605
Cover Note Number	N.A.

Driver

Name of Driver	NANTHAKUMAR THEVAR S/O PERIASAMY
NRIC No	S8810136G
Date Of Birth	10/03/1988
Occupation	INDOOR
Date Of Driving Pass	22/05/2018
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92378344
Fax Number	
Contact Number	OFFICE-92378344
EEmail Address	SHANKERBOI@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER 1
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING AT 173 YISHUN AVE 7 CAR PARK . WHEN I DRIVING , I SAW VEHICLE B COMING OUT FROM MY RIGHT SIDE PARKING LOT . I STOPPED MY VEHICLE AND HORN . VEHICLE B DIDNOT STOP IN TIME AND COLLIDED ONTO RIGHT FRONT SIDE OF MY VEHICLE . I GOT 2 DAYS OF MC .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOADED INTO AVIVA FILE ZILLA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD3993U
Vehicle Make/Model/Colour	TOYOTA/DYNA 3.0 M
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAN KOK WENG THOMAS
NRIC/Passport Number	S7939055J
Contact Number	
Address	
Postcode	

- Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

NANTHAKUMAR THEVAR S/O PERIASAMY

Approximate Age

Injuries Sustain

GOT 2 DAYS OF MC

Injured person in which vehicle?

SKX3791Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


10/11/2019

Driver's Signature
(if driver is not the policyholder)
Date & Time:

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT**


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



173 YLHON

AVE 7



A: SKX3791Z

B. GBD39934

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

REFER TO ATTACHED STATEMENT.

DECLARATION

DECLARATION
 (We declare the foregoing particulars are true in every respect.)

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Common Statement

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING AT 173 YISHUN AVE 7 CAR PARK . WHEN I DRIVING , I SAW VEHICLE B COMING OUT FROM MY RIGHT SIDE PARKING LOT . I STOPPED MY VEHICLE AND HORN . VEHICLE B DIDN'T STOP IN TIME AND COLLIDED ONTO RIGHT FRONT SIDE OF MY VEHICLE . I GOT 2 DAYS OF MC .

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 November 2019 at 2:36 PM

Date/Time:

10 November 2019 at 2:36 PM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Nov 2019 13:57		11 Nov 2019 16:15 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

Ching International Service Pte Ltd, Co. Reg. No.: 200909419G

Main Claimant:

NANTHAKUMAR THEVAR S/O PERIASAMY, ID: S8810136G

Vehicle Reg. No.:

SKX3791Z

Date of Loss:

09/11/2019 14:00 - :59
[124 Months and 15 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 611249

Policy/Cover Note No.:

29081320 (Comprehensive)
Coverage: 01/06/2018 - 31/12/2019

Vehicle Reg. No. (Insured):

GBD3993U

Policy No. (Claimant):

Excess:

Repairer:

Messrs C H Motor Vehicle Repair Training (HQ) 3019A UBI ROAD 1, #01-30, 408713 Ubi - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 12/11/2019]

Adj Asg. Remarks:

on WP. Liab: NR. Disagree on SJE. Contact: Mr Joe @ 6841 8841 / 6748 8888.

[Created by insurer]

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)






























Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX3791Z (611249)
[GBD3993U]
TP
NANTHAKUMAR THEVAR S/O PERIASAMY
Nov 9 2019 2:00PM
[Ching International Service Pte Ltd]
Messrs C H Motor Vehicle Repair Training

Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/19 17:21	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	13/11/19 17:21	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	13/11/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/11/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/11/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/11/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
19	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
20	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
21	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
22	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
23	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
24	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
25	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
26	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
27	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
28	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
29	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
30	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
31	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
32	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
33	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
34	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
35	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
36	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
37	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
38	13/11/19 17:22	General View	Load JPG	<input checked="" type="checkbox"/>
39	13/11/19 17:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/11/19 17:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	13/11/19 17:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	13/11/19 17:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	13/11/19 17:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	13/11/19 17:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	21/11/19 09:47	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/11/19 13:58	PRI from Vision Law LLC	 Load PDF	
2	11/11/19 15:18	Disagree on SJE	 Load PDF	
3	14/11/19 10:34	TP SKX3791Z Gia Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19019960/HCF3E2

Date: 30/12/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29081320

Claimant**Vehicle No :** SKX3791Z**Insured Vehicle No :** GBD3993U

Date of Loss: 09/11/2019

Nature of Claim: TP

Claim No: 611249

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKX3791Z**Make & Model: MITSUBISHI LANCER, 1.6 GLX 5MT AIRBAG
2WD (M)

Engine No: 4G18KC6656

Reg. Date: 25/06/2009 (Man. Year: 2009)

Chassis No: JMYSNCS3A9U004696

Colour: Yellow

Odometer: 137587 km

Engine Capacity: 1584 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size:

205/45 R16

Front Left Side: Toyo 5 mm

Rear Left Side:

Toyo 5 mm

Front Right Side: Toyo 5 mm

Rear Right Side:

Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 12/11/2019 Inspected At:

Messrs C H Motor Vehicle Repair
Training (HQ)
3019A UBI ROAD 1, #01-30
Singapore 408713

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts:	143	MITSUBISHI LANCER 1.6 GLX 5MT AIRBAG 2WD (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX3791Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.	
Report was unsubmitted during this print-out.	

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >