

ASS. REC. BY:

REF:

CS/ALC/19019967/Alsd-302

Special Instructions:

Signature:

Tuph

ASSIGNMENT (Office)

From (Person):

Winnie Fern

of

ALC

Date/Time:

11/11/19 @ 2:56 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBI 88136

Insured:

at Workshop m/s

Site production

Tel:

6299 5177

of

610 Kensington Road

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/11/2019

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:20 pm 11/11/19

Person Contacted:

Wandy

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate 1

FBI 88136-x

12/11/19

@ 12:21 pm revised PA to AIG via email.

12/11/19

@ 12:24 pm mandate requested authorize repair to AIG via me: me

13/11/19

@ 17:29 pm mandate approved by Theddaens via me: me

13/11/19

@ 17:31 pm informed ch to Karen (repairs) via email.


Tan Kah

AG

# ASSIGNMENT

From: 11/1/19  
 Date: 11/1/19  
 Estimated Cost: CA TP WS TP RES OD RES EVA INV MV  
 To inspect Vehicle No: FBL 8813G  
 at Workshop n/s: Bike Production  
 of: 610 Seangoon Road  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: IBF \$1,300/-  
 (Client's Record)  
 Make of Veh:

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$25K  
 IDAC Accident Report: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: days Res: Yes or No  
 Luhn Sum: % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: Person Contacted: Vehicle: IN / OUT



Veh No: FBL 8813G Regn: 2017 / April  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha MT-10 SP c.c. 998  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 45287 T/Radio: Insured / Std / NI / NA  
 Eng/No:  
 C/No: JY ARN455000001370  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 120/70R17  
 R: 140/55R17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: 5 mm Rear: 5 mm  
 R/Bal: 5 mm L/Bal: 5 mm  
 D.O.A. D.O.L. 11/1/19  
 Survey held at: Bike Production  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Frt + O/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Tan Kah Confirmed L/S \$ 5,500/- @ 4 days with Kuan. <del>C \$ 4,900.60</del> Red - 47% <u>\$ 4,950.60</u>
	RECEIVED 21 FEB 2020
	12/2/2020

Date/Time, File Page 10? 21/02/20  
 1) Typ:sp  
 Date/Time, File Detail 10?  
 2)  
 Report Format:  
 Lump Sum / H/S: \$ 5,500/- L/S

☐ : Prel. Report  
☒ : Final Report

Days Of Repair: 4  
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp. (5)  
☐ : Interview (5)  
☐ : Tech. Insp. (5)  
☐ : Meet. Insp. (5)

Survey Fee: 200  
 Transportation: 3 + RS  
 1) 11  
 2) 21

- RE: NEW OD CLAIM - FBL8813G

From: AIG SGP, Claims-Survey

To:

Cc: Fong, Andy-SY

Sent: 11/11/2019 2:56:05 PM

Attachments: 20191110\_154812.jpg; FBL8813G DOA071119 AIG OD QWS.pdf

---

Hi LKE,

Kindly assist to survey, bike in.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-10 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you

-----Original Message-----

From: Sbk E [mailto:sbk5643@yahoo.com]

Sent: Sunday, November 10, 2019 6:53 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] RE: NEW OD CLAIM - FBL8813G

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. Thank you very much for your attention.

Regards,

Kuan S. H.

Director

Bike Production Pte Ltd

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 393H

**Vehicle Details**

Vehicle No.: FBL8813G

Vehicle to be Exported: No

Intended Deregistration  
Date: 12 Nov 2019

Vehicle Make: YAMAHA

Vehicle Model: MT-10 SP

Primary Colour: Black

Manufacturing Year: 2017

Engine No.: N530E008190

Chassis No.: JYARN455000001390

Maximum Power  
Output: -

Open Market Value: \$15,827.00

Original Registration  
Date: 22 Apr 2017

First Registration Date: 22 Apr 2017

Transfer Count: 1

Actual ARF Paid: \$2,375.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry  
Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 21 Apr 2027

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$6,354.00

COE Rebate Amount: \$4,728.00

**Total Rebate Amount: \$4,728.00**

The information contained herein is correct as at 12 Nov 2019

OK



(1)

Bike model

Type

Any

Price from

Any

Price to

Any

Class

Any

MORE SEARCH OPTIONS >

Q SEARCH

VIEW ALL LISTINGS/USED BIKES LISTINGS



REPORT ABUSE > | LISTING LISTING/USED BIKES LISTINGS | NEWS > | ADD TO WISHLIST

© 2019 SGBIKE.MART. ALL RIGHTS RESERVED. | TERMS & CONDITIONS | PRIVACY POLICY | CONTACT US

## Yamaha MT-10 SP

Listing Type	Part Ad
Brand	Yamaha (listing/usedbike/brand/yamaha/)
Model	Yamaha MT-10 SP (listing/usedbike/model/yamaha-mt-10-sp/)
Engine Capacity	998cc
Classification	Class 2 (listing/usedbike/model/motorcycle-for-sale/class/class-2/)
Registration Date	21/09/2017
COE Expiry Date	20/09/2027 (7 years 10 months left)
Mileage	30000km
No. of owners	1
Type of Vehicle	Street Bikes (listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: SGD\$27000

### DETAILS

Sep 2017 Yamaha MT-10 SP. Bike Fully Paid. For Refinancing Recommended Bike Shop Interest Rates 6%. Price include Transfer Fee \$1.2K. Exclude Insurance. Bike in Good Condition. Always Park Under Shelter. No Accident. Function is Similar With R1M. Bike Only Commute To Work. No Touring. Items Just Changed: Front And Rear Tyres, Engine Oil. Bike Fully Paid.

### Accessories

Street Legal Akrapovic Exhaust, Rissma Side Mirrors, Windshield, 10 Colour Displays, Adjustable Chain Suspension, Quick Shifter.

## Shirley Hiew (LKK Auto)

---

**From:** Sbk E <sbk5643e@yahoo.com>  
**Sent:** Thursday, 13 February 2020 9:12 am  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR  
**Subject:** Re: FBL 8813G OD Date of Loss: 07/11/2019

Dear Shirley,

I agree to your finalization. I will send you the invoice and DV soon. Thanks.

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

On Wednesday, February 12, 2020, 12:08:07 PM GMT+8, Shirley Hiew (LKK Auto) <shirleyhiew@lkkauto.com> wrote:

Dear All,

Please confirm lump sum of \$ 5,500.00 @ 4 days of repairs before excess \$ 1,300/- & GST.

Thank you.

Best Regards,

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Wednesday, 13 November 2019 5:36 pm  
**To:** Sbk E  
**Cc:** SUR  
**Subject:** FBL 8813G OD Date of Loss: 07/11/2019

Dear All,

As instructed by our client, please proceed to repair the insured vehicle **FBL 8813G (Excess \$ 1.300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Kindly refer to the below **AIG** comments.

Front shock absorber to be under repair basic.

To arrange photo taking for check, suppl & after repair.

Thanks

*Regards,*  
*Thaddaeus Ng*  
**AIG**  
*Motor Claims Surveyor*

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*FBL8813G (4431675816SG)**

OD

Nov 7 2019 6:00PM

[CHUA CHIEW WEI, JASON]

Bike Production

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 11/02/2020 21:19 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$6912.60) - FBL8813G - Claim Handler: Nadaraja, Deeban

Approved:6912.60:Front shock absorber to repair. To arrange photo taking for check, suppl & after repair. Engine Timing Cover replaced not require to used 4 ltrs engine oil to top-up to revise. After repair photo and front shock absorber & radi

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**\*FBL8813G (4431675816SG)**

OD

Nov 7 2019 6:00PM

[CHUA CHIEW WEI, JASON]

Bike Production

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 27/12/2019 08:08 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$6972.60) - FBL8813G - Claim Handler: Nadaraja, Deeban

Approved:6972.60:Front shock absorber to repair. To arrange photo taking for check, suppl & after repair. Engine Timing Cover replaced not require to used 4 ltrs engine oil to top-up to revise.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**\*FBL8813G (4431675816SG)**

OD

Nov 7 2019 6:00PM

[CHUA CHIEW WEI, JASON]

Bike Production

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 13/11/2019 17:29 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$7151.00) - FBL8813G - Claim Handler: Khoo, Kay-Eng

Approved:7151.00:Front shock absorber to repair. To arrange photo taking for check, suppl & after repair.

### DOCUMENTS SUMMARY

There are no documents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nadaraja, Deeban

Date: 30 Jan 2020

## Preliminary Advice

Vehicle No	: FBL8813G	Accident Date	: 07/11/2019
Make	: YAMAHA MT-10	Policy No.	: 1800023006
Assignment Date	: 12/11/2019	Excess	: S\$1,300.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 4 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,450.60 (inclusive supp)
Revised Amount	:S\$	6,912.60 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,912.60
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,272.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nadaraja, Deeban

Date: 17 Dec 2019

## Preliminary Advice

Vehicle No	: FBL8813G	Accident Date	: 07/11/2019
Make	: YAMAHA MT-10	Policy No.	: 1800023006
Assignment Date	: 12/11/2019	Excess	: S\$1,300.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 4 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,450.60 (inclusive supp)
Revised Amount	:S\$	6,972.60 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,972.60
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,272.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Supplementary amount is \$ 523.60.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 12 Nov 2019

**Preliminary Advice**

Vehicle No	: FBL8813G	Accident Date	: 07/11/2019
Make	: YAMAHA MT-10	Policy No.	: 1800023006-01
Assignment Date	: 12/11/2019	Excess	: S\$0.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 4 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,667.00
Revised Amount	:S\$	3,713.00
Check Items (Estimated)	:S\$	3,438.00
Total	:S\$	7,151.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,272.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2019 15:14
Date Of Accident	07/11/2019 18:40
Exact Location Of Accident	KPE TOWARDS TPE ENTRANCE FROM PIE (CHANGI)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL8813G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA CHIEW WEI, JASON
NRIC No	S8109393H
Email Address	OVERLOADED@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-93621352
Alternative Phone No	OFFICE-93621352

### Vehicle Particulars

Manufacturer	YAMAHA
Model	MT-10-998CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023006-01
Cover Note Number	

### Driver

Name of Driver	CHUA CHIEW WEI, JASON
NRIC No	S8109393H
Date Of Birth	03/04/1981
Occupation	INDOOR
Date Of Driving Pass	02/02/2018
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93621352
Fax Number	
Contact Number	OFFICE-93621352

Address	BLK 162B RIVERVALE CRESCENT #14-218
Postcode	542162
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MACPHERSON NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT AND POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM906U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	LAW SEE KIAT
NRIC/Passport Number	S7442142C
Contact Number	96282424
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Name  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

RIGHT LEG (SLIGHT SWELLING)  
FBL8813G

DETAILS OF INJURED PERSON 2

Name  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

FBM906U

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
 Date & Time:  
 8/11/19

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20191108/7063

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20191108/2063

Police Station Of Origin:  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

1 of 3

Report No. T/20191108/2063

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/11/2019 13:44		Vide Report No.:		Station Diary No.: 17	
<b>Informant's Particulars</b>					
Name of Informant: CHUA CHIEW WEI, JASON			Address: APT BLK 162B RIVERVALE CRESCENT #14-218 SINGAPORE 542162		
ID Type / ID No.: NRIC NO / S8109393H			Contact No.: Home/Office: Mobile: 93621352		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 03/04/1981	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: SWIMMING COACH			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/11/2019 18:40	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY  KPE > TPE INSIDE KPE ENTRANCE FROM PIE(CHANGI)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL8813G	Motorcycle	YAMAHA	MT-10 SP	Black	Slightly Damaged	0
FBM906U	Motorcycle					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20191108/2063

Police Station Of Origin:  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

2 of 3

Report No. T/20191108/2063

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBL8813G	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800023006-01	22/04/2019	21/04/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider:				
Name	CHUA CHIEW WEI, JASON		ID No.	S8109393H
Related Vehicle	FBL8813G (Motorcycle)		Contact No.	93621352
Hospital/Clinic	BOK FAMILY CLINIC PTE LTD		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	08/11/2019		Date Discharge	08/11/2019
No. of Days granted Medical Leave	03		Degree of Injury	Slight
Rider:				
Name	LAW SEE KIAT		ID No.	S7442142C
Related Vehicle	FBM906U (Motorcycle)		Contact No.	96282424
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 7/11/2019 at about 1840hrs while traveling on KPE towards TPE at the entrance from PIE(Changi). While travelling at about 40km when suddenly after passing one vehicle, one motorbike, FBM906U then came out of the front of the vehicle which I immediately engaged e-brake however was unable to stop in time, I tried to avoid the biker by swerving left however he then hit onto the right front portion of my motorbike causing damage to my radiator and front fork. We both stopped and exchanged particulars for insurance claims. I went to see a doctor on 8/11/2019 at Bok Family Clinic Pte Ltd and was given 3 days MC for pain on right leg area(slight swelling). I will be proceeding with insurance claims.



**SINGAPORE  
POLICE FORCE**



T/20191108/2063

Police Station Of Origin;  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

3 of 3

Report No. T/20191108/2063

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 SHAUN CHUA YONG QUAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/11/2019 13:44

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168

Classification Of Case:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2019 15:14
Date Of Accident	07/11/2019 18:40
Exact Location Of Accident	KPE TOWARDS TPE ENTRANCE FROM PIE (CHANGI)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL8813G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA CHIEW WEI, JASON
NRIC No	S8109393H
Email Address	OVERLOADED@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-93621352
Alternative Phone No	OFFICE-93621352

### Vehicle Particulars

Manufacturer	YAMAHA
Model	MT-10-998CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023006-01
Cover Note Number	

### Driver

Name of Driver	CHUA CHIEW WEI, JASON
NRIC No	S8109393H
Date Of Birth	03/04/1981
Occupation	INDOOR
Date Of Driving Pass	02/02/2018
Driving Experience	1 YEAR AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93621352
Fax Number	
Contact Number	OFFICE-93621352
EMail Address	OVERLOADED@ROCKETMAIL.COM

Address	BLK 162B RIVERVALE CRESCENT #14-218
Postcode	542162
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MACPHERSON NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT AND POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM906U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	LAW SEE KIAT
NRIC/Passport Number	S7442142C
Contact Number	96282424
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

RIGHT LEG (SLIGHT SWELLING)

Injured person in which vehicle?

FBL8813G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBM906U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

8/11/19

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20191108/2063

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
JNIC/TIN No.:



**SINGAPORE  
POLICE FORCE**



T/20191108/2083

1 of 3

Police Station Of Origin:  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

Report No: T/20191108/2083

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 08/11/2019 13:44	Vide Report No.:	Station Diary No.: 17
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: CHUA CHIEW WEI, JASON			Address: APT BLK 162B RIVERVALE CRESCENT #14-218 SINGAPORE 542162	
ID Type / ID No.: NRIC NO / S8109393H			Contact No.: Home/Office: Mobile: 93621352	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 38	Date of Birth: 03/04/1981	Type of Informant: Rider	
Race: Chinese			Language:	Institution / School Name:
Occupation: SWIMMING COACH			Driving Licence Information: Class: 2B, 2A, 2, 3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/11/2019 18:40	Type of Location: Straight Road
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY  KPE > TPE INSIDE KPE ENTRANCE FROM PIE(CHANGI)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL8813G	Motorcycle	YAMAHA	MT-10 SP	Black	Slightly Damaged	0
FBM906U	Motorcycle					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20191108/2063

2 of 3

Police Station Of Origin:  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

Report No. T/20191108/2063

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL8813G	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800023006-01	22/04/2019	21/04/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	CHUA CHIEW WEI, JASON		ID No.	S8109393H
Related Vehicle	FBL8813G (Motorcycle)		Contact No.	93621352
Hospital/Clinic	BOK FAMILY CLINIC PTE LTD		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	08/11/2019		Date Discharge	08/11/2019
No. of Days granted Medical Leave	03		Degree of Injury	Slight
Rider				
Name	LAW SEE KIAT		ID No.	S7442142C
Related Vehicle	FBM906U (Motorcycle)		Contact No.	96282424
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 7/11/2019 at about 1840hrs while traveling on KPE towards TPE at the entrance from PIE(Changi). While travelling at about 40km when suddenly after passing one vehicle, one motorbike, FBM906U then came out of the front of the vehicle which I immediately engaged e-brake however was unable to stop in time, I tried to avoid the biker by swerving left however he then hit onto the right front portion of my motorbike causing damage to my radiator and front fork. We both stopped and exchanged particulars for insurance claims. I went to see a doctor on 8/11/2019 at Bok Family Clinic Pte Ltd and was given 3 days MC for pain on right leg area(slight swelling). I will be proceeding with insurance claims.



**SINGAPORE  
POLICE FORCE**



T/20191108/2063

3 of 3

Report No. T/20191108/2063

Police Station Of Origin:  
MacPherson NPP  
54 Pipit Road #01-82/84 SINGAPORE  
370054  
Tel No: 1800-7449999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 SHAUN CHUA YONG QUAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/11/2019 13:44

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP158

Classification Of Case:



# CERTIFICATE OF INSURANCE

## MOTORCYCLE AUTOVANTAGE MOTORCYCLE

Name of Policyholder : CHUA CHIEW WEI, JASON (CAI ZHOUWEI, JASON)  
 Period of Insurance : 22 Apr 2019 To 21 Apr 2020  
 Engine No. : N530E008190  
 Chassis No. : JYARN455000001390

Vehicle No. : FBL8813G  
 Policy No. : 1800023006-01  
 Endorsement No. :  
 Issued Date : 03 Apr 2019

### ABOUT THE COVER

Make/Model : YAMAHA MT-10  
 Engine Capacity/Tonnage : 998.00 CC  
 Driver Restriction : Named Driver Basis  
 Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
 Off Peak Car : No

First Year of Registration : 2017  
 Insuring with COE/PAF : Yes

a) The Policyholder  
 b) Any person who is named as a "named driver" under this Policy.

Age Condition : Not Applicable  
 Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- 1) use for hire or reward;
- 2) use for driving tuition, driving test, racing, pace-making, reliability trial or speed testing;
- 3) use for the carriage of goods (other than samples) in connection with any trade or business; and
- 4) use for any purpose in connection with Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

Section 1  
 Fire - \$0 Own Damage - \$1300 Theft - \$0

Section 2  
 Property Damage - \$0

Windscreens : NA

Please note that the vehicle is insured by BIKE PRODUCTION PTE LTD. No transfer of endorsement is allowed unless with our written consent.

Named Driver and Excess (where applicable)

CHUA CHIEW WEI, JASON (CAI ZHOUWEI, JASON) - \$1300 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.  
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, You may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: BIKE PRODUCTION PTE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1999 (Malaysia).

BIKE PRODUCTION PTE LTD

Ce Reg No: 200007407G

610 Serangoon Road

Singapore 218216

Tel: 63922555 Fax: 62975400

0500656016

COWELL - BIKE PRODUCTION

8 BURN ROAD #09-09 TRIVEX

SINGAPORE 369977 ANSP-NONLIFE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Janile*

AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORISED REPRESENTATIVE

**BIKE PRODUCTION PTE LTD**  
610, Serangoon Road S(218216)  
Tel: 63922555, 62995177 Fax: 62975400  
ROC/ GST Reg No.: 200007407G

Date: 8 Nov 2019

**ASSESSMENT FOR REPAIR: YAMAHA MT-10 SP - FBL8813G**

Chassis No.: JYARN455000001390  
Engine No.: N530E008190

Taufik 44475747  
Revert, Not Authorise  
11/11/19 @ 520pm  
Exas: to be advise.  
Lumpsum -  
Resurvey after repair  
04 days.  
5 days

**Qty**

**Description**

**Estimate**

1 pc  
2 pcs  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc  
4 pcs  
1 pc  
1 pc  
1 pc  
1 pc  
1 pc

- Front right fork assy - photo new & old fork.
- Steering stem bearings
- Front right brake disk
- Front fork steering headcrown
- Front fork steering stem with bearing
- Front head fairing assembly
- Front right side air intake
- Yamaha logo
- Right side coolant cover
- Spare coolant tank
- Radiator assy
- Radiator hose
- Exhaust gasket
- Exhaust header assy
- Right engine cover
- Right engine cover gasket
- Brake pedal assy

\$1,990.00 1 add ✓  
~~\$110.00 X~~ X n  
\$490.00 ? X n  
~~\$550.00 X~~ n  
~~\$580.00 X~~ n  
\$480.00 cut ✓  
\$395.00 cut ✓  
\$75.00 cut ✓  
\$210.00 cut ✓  
~~\$220.00 X~~ n  
\$1,050.00 ? add ✓  
\$70.00 ? X n  
\$100.00 new ✓  
\$1,400.00 add ✓  
\$375.00 add ✓  
\$60.00 new ✓  
\$225.00 add ✓

Less discount 10%

\$8,380.00 6360.  
\$838.00  
\$7,542.00 5724

**Special nett items**

1 pc  
4 pcs

- Radiator coolant
- Fully synthetic engine oil @ \$30.00

\$55.00 new ✓  
\$120.00 new ✓ 60  
\$100.00 ? Towing new ✓

- 1) Towing charges
- Replace, realign and adjust above damaged parts, check wiring and lighting system
- 2) To replace and balance front wheel rim
- 3) To knock, straighten chassis & body balancing
- 4) To remove/refit, replace (if damage) check and straighten front fork tubes.
- 5) Spray painting
- 6) Spray painting

\$800.00 200  
~~\$120.00 X~~ n  
~~\$450.00 X~~ n  
\$180.00 120  
\$300.00 150

**Total Estimate**

\$9,667.00 665

**Note: The above estimate is subjected to the prevailing GST of 7%**

- Parts prices are subject to cost
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



For Bike Production Pte Ltd

Supp.

COOLANT CONNECTION

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
**ROC/ GST Reg No.: 200007407G**

Taufik 97495749  
 Report Not Authorise  
 11/11/19 2:52pm  
 Exam. to be advise.  
 Lumpsum -  
 Resurvey after repair  
 04 days.

Date: 8 Nov 2019

# ASSESSMENT FOR REPAIR: YAMAHA MT-10 SP - FBL8813G

Chassis No.: JYARN455000001390

Engine No.: N530E008190

Qty	Description	Estimate
1 pc	Front right fork assy	\$1,990.00 ?/dd
2 pcs	Steering stem bearings	\$110.00 x na
1 pc	Front right brake disk	\$490.00 ? x na
1 pc	Front fork steering headcrown	\$550.00 x na
1 pc	Front fork steering stem with bearing	\$580.00 x na
1 pc	Front head fairing assembly	\$480.00 cut
1 pc	Front right side air intake	\$395.00 cut
1 pc	Yamaha logo	\$75.00 cut
1 pc	Right side coolant cover	\$210.00 cut
1 pc	Spare coolant tank	\$220.00 ? x na
1 pc	Radiator assy	\$1,050.00 ?/dd
1 pc	Radiator hose	\$70.00 ? x na
4 pcs	Exhaust gasket	\$100.00 nec
1 pc	Exhaust header assy	\$1,400.00 dd
1 pc	Right engine cover	\$375.00 dd
1 pc	Right engine cover gasket	\$60.00 nec
1 pc	Brake pedal assy	\$225.00 dtv
		\$8,380.00
	Less discount 10%	\$838.00
		\$7,542.00
	<b>Special nett items</b>	
1 pc	Radiator coolant	\$55.00 nec
4 pcs	Fully synthetic engine oil @ \$30.00	\$120.00 nec 60
1)	Towing charges	\$100.00 80
	Repiece, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 200
	To replace and balance front wheel	
3)	rim	\$120.00 x na
	To knock, straighten chassis & body	
4)	balancing	\$450.00 x na
	To remove/refit, replace (if damage) check and	
5)	straighten front fork tubes.	\$180.00 120
6)	Spray painting	\$300.00 150
	<b>Total Estimate</b>	<b>\$9,667.00</b>

**Note: The above estimate is subjected to the prevailing GST of 7%**

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:

10490 60



For Bike Production Pte Ltd

Supp

COOLANT CONNUTOR

**BIKE PRODUCTION PTE LTD**  
 610, Serangoon Road S(218216)  
 Tel: 63922555, 62995177 Fax: 62975400  
 ROC/ GST Reg No.: 200007407G

Date: 8 Nov 2019

**ASSESSMENT FOR REPAIR: YAMAHA MT-10 SP - FBL8813G**

Chassis No.: JYARN455000001390

Engine No.: N530E008190

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Air intake cover 2	\$115.00 <i>nt</i>
1 pc	Spare coolant tank cover inner	\$145.00 <i>nt</i>
5 pcs	Engine cover screws @ \$10.00	\$50.00 <i>nt</i>
1 pc	U clip	\$15.00 <i>nt</i>
3 pcs	O rings @ \$13.00	\$39.00 <i>nt</i>
1 pc	Spare coolant elbow	\$40.00 <i>nt</i>
		<hr/>
		\$404.00
	Less discount 10%	\$40.40
		<hr/>
		\$363.60 ✓
1	Additional labour for suppl and unconfirmed items	\$300.00 <i>100</i>
2	Reset Meter	\$120.00 <i>60</i>
		<hr/>
	<b>Total Estimate</b>	<b>\$363.60</b> <i>\$783.60</i>

**Note: The above estimate is subjected to the prevailing GST of 7%**

For Bike Production Pte Ltd

*Tan Jiah*  
 16/12/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*6912-60*  
*455500*

# BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216  
Tel: 6392 2555 Fax: 6297 5400

## TAX INVOICE

Co. Registration No. 200007407G  
GST Reg. No: 200007407G  
GST Inclusive

No: 6238

Name: AIG ASIA PACIFIC INSURANCE Date: 12/2/20  
Address: 78, NEWTON WAY #02-16 C(079120)  
I/C No: \_\_\_\_\_ Occupation: \_\_\_\_\_ DOB: \_\_\_\_\_  
Tel: \_\_\_\_\_ Driving Licence: \_\_\_\_\_

Particulars		Amount
Reg. No: <u>FR88136</u>	Selling Price	<u>4494</u>
Make & Model: <u>YAMAHA MT-10</u>	+ Insurance	<u>0</u>
Engine No: <u>34AR N455000001390</u>	+ Retention	<u>0</u>
Chassis No: <u>N530E008190</u>	TOTAL PRICE	<u>4494</u>
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only		
Colour: <u>Lumpsum</u>	Downpayment	<u>5500</u>
		<u>1300</u>
Loan Amount _____	Interest rates _____ p.a.	<u>4200</u>
Terms: ( _____ )	Monthly Instalments of \$ <u>75</u>	<u>294</u>
N/R: _____	TEL: _____	<u>4494</u>
GTR: _____	TEL: _____	
COE NO: _____	TR	

### Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid.
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have full rights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

Chua Chiew Wei, Jason (Cai ZhouWei, Jason)  
Blk 162B Rivervale Crescent  
#14-218  
Singapore 542162

Date: 4 Jan 2020

To: Mr Kwan Say Hwee  
Bike Production Pte Ltd  
610, Serangoon Road  
Singapore 218216

Dear Sir,

**RE: ACKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION  
OF YAMAHA MT-10 SP VEHICLE NO.: FBL8813G**

I, Chua Chiew Wei, Jason (Cai ZhouWei, Jason), NRIC No.: 393H, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 4 / 1 / 2020 at 620pm.

Thank you very much for your attention.

Yours faithfully,



Chua Chiew Wei, Jason (Cai ZhouWei, Jason)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Nov 2019		12 Nov 2019 08:54 <a href="#">Edit Adj Rpt</a>	<b>S\$5,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  


















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	CHUA CHIEW WEI, JASON, ID: S8109393H, Tel: +6593621352, Email: overloaded@rocketmail.com								
Vehicle Reg. No.:	FBL8813G	Date of Loss:	07/11/2019 18:00 - :59 [30 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4431675816SG	Policy/Cover Note No.:	1800023006 (Comprehensive)						
		Excess:	S\$1,300.00						
Repairer:	Bike Production (HQ) No 610 Serangoon Road, 218216 Serangoon - Tel: 6299-5177								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban.nadaraja@aic.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/11/2019]								
Driver/Custodian:	CHUA CHIEW WEI, JASON (38 / Male), NRIC: S8109393H, Tel: +6593621352 Email: overloaded@rocketmail.com								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (11/02/2020): Alert - Adj Mandate Approved (S\$6912.60) - FBL8813G - Claim Handler: Nadaraja, D...</li> <li>AIG_SG (27/12/2019): Alert - Adj Mandate Approved (S\$6972.60) - FBL8813G - Claim Handler: Nadaraja, D...</li> <li>AIG_SG (13/11/2019): Alert - Adj Mandate Approved (S\$7151.00) - FBL8813G - Claim Handler: Khoo, Kay-E...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


## Claim Documents

\*FBL8813G (4431675816SG)  
OD  
Nov 7 2019 6:00PM  
[CHUA CHIEW WEI, JASON]  
Bike Production























<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/11/19 17:56	Video - Other	Load MP4	<input type="checkbox"/>
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 12:21	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	17/12/19 11:09	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
3	30/01/20 11:00	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
2	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
3	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
4	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
5	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
6	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
7	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
8	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
9	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
12	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
13	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
14	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
15	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
16	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
20	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
22	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
23	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
24	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
25	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
26	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
27	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
28	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
29	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>
30	12/11/19 12:23	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	12/11/19 12:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
81	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	17/12/19 10:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	30/01/20 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	30/01/20 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	30/01/20 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
116	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
117	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
118	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
119	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
120	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
121	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
122	12/02/20 09:39	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 12:21	FBL 8813G GIA.pdf	 Load PDF	
2	12/11/19 12:22	POLICE REPORT.pdf	 Load PDF	
3	12/11/19 12:22	CI & DRIVING.pdf	 Load PDF	
4	12/11/19 12:22	ESTIMATE.pdf	 Load PDF	
5	17/12/19 11:10	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
6	30/01/20 11:01	ESTIMATE & SUPP MARKED 1.pdf	 Load PDF	
7	21/02/20 15:08	Workshop Invoice	 Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
8	21/02/20 15:08	Discharge Voucher	 Load PDF	

## Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	06/12/19 19:15	Accident Statement	 Load HTM	
2	06/12/19 19:17	Accident Statement	 Load HTM	
3	06/12/19 19:17	Accident Statement	 Load HTM	
4	06/12/19 19:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	08/11/19 15:23	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	08/11/19 15:28	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	08/11/19 15:22	Identification Card , NRIC	 Load TIF	
2	08/11/19 15:22	Identification Card , NRIC	 Load TIF	
3	08/11/19 15:28	Sketch Plan	 Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG19019967/T1SD3E2

Date: 21/02/2020

### REFERENCE

Insured/Claimant: CHUA CHIEW WEI, JASON

Policy No: 1800023006

Date of Loss: 07/11/2019

Nature of Claim: OD

Claim No: 4431675816SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL8813G

Make &amp; Model: YAMAHA MT-10, 998cc

Engine No: N530E008190

Reg. Date: 22/04/2017 (Man. Year: 2017)

Chassis No: JYARN455000001390

Colour: Black

Odometer: 45287 km

Engine Capacity: 998 cc

Market Value/New Car Price: S\$25,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R17

Rear Tyre Size: 190/55 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,080.60	6,202.60	1,878.00	23.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	710.00	1,660.00	70.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,450.60</b>	<b>6,912.60</b>	<b>3,538.00</b>	<b>33.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	9,150.60	4,200.00	4,950.60	54.10
+ GST 7.00/7.00% (S\$)	640.54	294.00	346.54	54.10
<b>Nett Amount (S\$)</b>	<b>9,791.14</b>	<b>4,494.00</b>	<b>5,297.14</b>	<b>54.10</b>

### INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 11/11/2019

Inspected At:

Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218216

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT FORK ASSY	Dented	1,990.00 FL	*1,990.00 FL
2	2		*STEERING STEM BEARINGS	Not Necessary	110.00 FL	*- FL
3	1		*FRONT FORK STEERING HEADCROWN	Not Necessary	550.00 FL	*- FL
4	1		*FRONT FORK STEERING STEM WITH BEARING	Not Necessary	580.00 FL	*- FL
5	1		*FRONT HEAD FAIRING ASSEMBLY	Cut	480.00 FL	*480.00 FL
6	1		*FRONT RIGHT SIDE AIR INTAKE	Cut	395.00 FL	*395.00 FL
7	1		*YAMAHA LOGO	Cut	75.00 FL	*75.00 FL
8	1		*RIGHT SIDE COOLANT COVER	Cut	210.00 FL	*210.00 FL
9	1		*SPARE COOLANT TANK	Not Necessary	220.00 FL	*- FL
10	1		*RADIATOR ASSY	Dented	1,050.00 FL	*1,050.00 FL
11	1		*RADIATOR HOSE	Not Necessary	70.00 FL	*- FL
12	4		*EXHAUST GASKET	Necessary	100.00 FL	*100.00 FL
13	1		*EXHAUST HEADER ASSY	Dented	1,400.00 FL	*1,400.00 FL
14	1		*RIGHT ENGINE COVER	Dented	375.00 FL	*375.00 FL
15	1		*RIGHT ENGINE COVER GASKET	Necessary	60.00 FL	*60.00 FL
16	1		*BRAKE PEDAL ASSY	Bent	225.00 FL	*225.00 FL
17	1		*RADIATOR COOLANT	Necessary	55.00 FS	*55.00 FS
18	4		*FULLY SYNTHETIC ENGINE OIL	Necessary	120.00 FS	*60.00 FS
19	1		*AIR INTAKE COVER 2	Cut	115.00 FL	*115.00 FL
20	1		*SPARE COOLANT TANK COVER INNER	Cut	145.00 FL	*145.00 FL
21	5		*ENGINE COVER SCREWS	Necessary	50.00 FL	*50.00 FL
22	1		*U CLIP	Necessary	15.00 FL	*15.00 FL
23	3		*O RINGS	Necessary	39.00 FL	*39.00 FL
24	1		*SPARE COOLANT ELBOW	Cracked	40.00 FL	*40.00 FL
25	1		*FRONT RIGHT BRAKE DISK	Not Necessary	490.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,959.00</b>	<b>6,879.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>878.40</b>	<b>676.40</b>
<b>Total Parts (\$\$)</b>	<b>8,080.60</b>	<b>6,202.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGES	New	100.00	80.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	200.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	120.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	450.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	120.00
6	SPRAY PAINTING	New	300.00	150.00
7	ADDITIONAL LABOUR FOR SUPPL AND UNCONFIRMED ITEMS	New	300.00	100.00
8	RESET METER	New	120.00	60.00
Gross Labour Cost (S\$)			<b>2,370.00</b>	<b>710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >