

Marius

REF: es/EGT/19019968/Usd3m Special Instruction:

ASSIGNMENT (Office)

Person(s): Pauline Soh

at EGI

Date/Time: 11/11/19 @ 2:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G889075R

Insured:

GBC 5952 E

at Workshop m/s:

Muh Lian Motor

Tel:

G282 333 5

of

No. 38 Defu Lane 9

Policy No:

Claim No:

CDMCG19002079

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/11/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:30pm @ 11/11/19

Person Contacted:

Siti

Vehicle: IN / OUT

Date/Time

Action/Instruction

Inspected /

G889075R - X

GBC 5952 E - CS/MSG17007191/Kph360 DOA: 28/2/2017

ASS. REC. BY:

REF:

EPO/


: *maius*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: *6BB9075R*
 at Workshop m/s *maius*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: *10k.*
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *2* days Res.: Yes or No
 Lum Sum: *1.31* % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS *782N*

Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: *6BB9075R* Yr Regn: *9, 10*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(M)*
 Make: *Nissan cabstar* c.c. *2953*
 Colour: *silver* A/C: Insured / Std / NI / NA
 Sp. Reading: *392048* T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: *JN15C2F240801512*

Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *195 R 15*R: *165 R 13*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *green max*

Front: *6* mm R/Bal. *6/6* mm

L/Bal. *6/6* mm

D.O.A. *4/9/19* D.O.I. *11/11/19*

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*COE 12-9-2020 LHA250**please get OI G.A report & photo*

10/1/20 Confirmed final by #310 with S. hu;
(\$ 3,120.00 Red - 71%)

RECEIVED 16 JAN 2020

Date/Time, File Pass to?

*16/01/20*1) *Tyres*

Date/Time, File Return to?

2) _____

Request Format:

Lump Sum *(L.B.)**\$ 310.00 p/p*☐ : Preli. Report☒ : Final ReportDays Of Repair: *2*Resurvey No. of Trip: *1*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Wash and

Survey Fee:

Transportation:

S + RS \$

Photos

Other

Total

*250**11**261*

Nivitha (LKK Auto)

From: Pauline Soh <pauline.soh@ergo.com.sg>
Sent: Monday, 11 November 2019 2:09 PM
To: Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Ivy Yong; Phoebe Xie; 'Jacqueline Tan' (jactan@visionlawllc.com); ct-admin@visionlawllc.com
Subject: FW: Claims ref no. (P) CDMCG19002079
Attachments: 11112019140436-0001.pdf

Hi LKK,

Please conduct this survey request.
(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

*** NOTE: Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you

Date Classification : Confidential, C3

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five Singapore 038985
DID.: +65 6829 9194
pauline.soh@ergo.com.sg

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the

intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HOON
PAUL YAP TAI SAN
ANJALLI M MUMIANDY
AND KIM NOI DIANG
RAVENORA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHONG YUNHUI, CLARISSE
SONIA LIM WEI LID

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ **HEAD OFFICE**

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
(65) 65355905 (Litigation)

E-mail : jactan@visionlawllc.com**BRANCH**

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO **HEAD OFFICE** FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.112079.19 (sj)
Your Ref: CDMCG19002079

11 November 2019

ERGO INSURANCE PTE LTD
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Attention: Motor Claims Department

BY FAX: 6829 9247
claims@ergo.com.sg



Dear Sirs,

ACCIDENT INVOLVING GBB 9075 R & GBC 5952 E ON 04 NOVEMBER 2019 ALONG MARINA BAY SANDS LOADING BAY AT ABOUT 0840 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email 08 November 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor :
(Name & Signature)

2nd Survey on _____
Appointed surveyor
(Name & Signature)

3rd Survey on _____
Appointed Surveyor
(Name & signature)

cc: GBB 9075 R – By fax: 6289-3336 only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

View Sent Message

This mail is associated with :

***GBB9075R**
[GBC5952E]

TP

JIN DIING FOODSTUFF SUPPLIER PTE.LTD

Nov 4 2019 8:00AM

[-]

Mah Lian Motor Vehicle Repairer

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/11/2019 14:21 PM.
To pauline.soh@ergo.com.sg
CC sur@lkkauto.com
Subject GBB9075R [GBC5952E] TP

Dear Pauline,

Please be informed that we have inspected the vehicle GBB 9075R on 11/11/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

AVIVA

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Cheap Cheap



Accident Free & Cheapest In The Market & Yet Negotiable...
Ole Supercars [View Ad](#)

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Sort by Date Posted

5 vehicles

cabstar

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	cabstar		Any	Any	2010	Any	Any	Any
	Nissan Cabstar (New 5-yr COE)		\$21,800	\$4,360 /yr	26-Jan-2010	2,953 cc	150,000 km	Truck
	Fuel Type: Diesel Guaranteed Cheapest In The Market! Low Mileage! Excellent Condition. Low Fuel Consumption! Fast Loan Approval. High Trade In Available! KSL Automotive Pte Ltd Posted: 11-Nov-2019 Tags: 2010 Nissan Cabstar, 2010 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan							
	Nissan Cabstar		\$25,800	\$50,360 /yr	18-May-2010	2,953 cc	-	Truck
	Fuel Type: Diesel 05/09 New 5 Year COE Nissan Cabstar Box! Cheapest In Town & Super Reliable! Box With 2 Sliding Door And Rear Twin Swing Door. Tiptop Condition High Loan And High Trade-in Available, Drive Off With No Worries. Door Step Viewing Can Be Arrange. ABWIN (1994) Pte Ltd Posted: 11-Nov-2019 Tags: 2010 Nissan Cabstar, 2010 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan							
	Nissan Cabstar		\$12,800	\$14,240 /yr	06-Oct-2010	2,953 cc	-	Truck
	Fuel Type: Diesel Cheapest In Market! Immaculate Condition With Only A Single Owner! Genuine Low Mileage! Dashing Gun Metal Gray Paintwork Freshly Coated! Wear And Tear Replaced! Fuel-Efficient And Capable Of Carrying Heavy Load! Flexible Loan Scheme, Full Cash Welcome! Came... Car (S) Pte Ltd Posted: 09-Nov-2019 Tags: 2010 Nissan Cabstar, 2010 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan							
	Nissan Cabstar		\$9,800	\$14,540 /yr	16-Jul-2010	2,953 cc	-	Truck
	Fuel Type: Diesel New Paint, Well Kept. In House Loan Available. Posted: 01-Oct-2019 Tags: 2010 Nissan Cabstar, 2010 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan							

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	782N
Vehicle Details	
Vehicle No.:	GBB9075R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Nov 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	ZD30257184K
Chassis No.:	JN15C2F24Z0801512
Maximum Power Output:	-
Open Market Value:	\$27,204.00
Original Registration Date:	13 Sep 2010
First Registration Date:	13 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$1,361.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,601.00
COE Rebate Amount:	\$2,550.00
Total Rebate Amount:	\$2,550.00

The information contained herein is correct as at 12 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/11/2019 17:34
Date Of Accident	04/11/2019 08:40
Exact Location Of Accident	AT MARINA BAY SANDS LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB9075R
Insured/Policyholder	
Name Of Registered Owner	JIN DIING FOODSTUFF SUPPLIER PTE. LTD.
Co Reg No	201311782N
Email Address	JINDIINGORDER@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-86131166

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/18/VC00/102416
Cover Note Number	

Driver

Name of Driver	GUO CHUANGHONG
NRIC No	G2025526P
Date Of Birth	27/10/1975
Occupation	OUTDOOR
Date Of Driving Pass	15/08/2015
Driving Experience	4 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84553807
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance:	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC9075R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


**JIN DIING FOODSTUFF
SUPPLIER PTE. LTD.**

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 04/11/2019. OF 140 AM.

Accident Location: AT MARINA BAY SANDS LOADING BAY.

I was stationary at the above-mention location, unloading stocks with my colleague, vehicle B reversed & collided into the Rear (RH) portion of my door.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OD/TP)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**JIN DIING FOODSTUFF
SUPPLIER PTE. LTD.**

* IMPORTANT NOTE:

You have been advised by the workshop that in the event that you wish to claim against your own policy (Own Damage Claim), there is a FOURTEEN (14) days time bar whereby the claim must be made within the specified timeframe from the day of occurrence.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

G:\AR\NC\Inventory\Forms\ 9/3

Accident Photo



Accident Photo



Accident Photo



Accident Photo





LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19019968/USD3N2
Date: 20/01/2020

REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	GBB9075R	Insured Vehicle No :	GBC5952E
Date of Loss:	04/11/2019	Nature of Claim:	TP
		Claim No:	CDMCG19002079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB9075R		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A)	Engine No:	ZD30257184K
Reg. Date:	13/09/2010 (Man. Year: 2010)	Chassis No:	JN1SC2F24Z0801512
Colour:	Silver	Odometer:	392048 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	165R13 (D)
Front Left Side:	GREEN-MAX 6 mm	Rear Left Side:	GREEN-MAX 6/6 mm
Front Right Side:	GREEN-MAX 6 mm	Rear Right Side:	GREEN-MAX 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30.00	10.00	20.00	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	300.00	3,100.00	91.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,430.00	310.00	3,120.00	90.96
+ GST 7.00/7.00% (S\$)	240.10	21.70	218.40	90.96
Nett Amount (S\$)	3,670.10	331.70	3,338.40	90.96

INSPECTION

Date of Assignment:	11/11/2019	
Date Inspected:	11/11/2019	Inspected At: Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jan 2020)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD Turbo (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9075R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
						F=Franchise part. S=SpcNett.
Total Parts (S\$)					30.00	10.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR ALUMINIUM CANOPY BOX DOOR } (\$300)(50%)	New	1,800.00	150.00
2	TO JACK & DISMANTLE ALUMINIUM CANOPY FRAME STRUCTURE }	New	800.00	0.00
3	TO SPRAY & PAINTING WHOLE REAR BOX DOOR (\$300)(50%)	New	800.00	150.00
Gross Labour Cost (\$\$)			3,400.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >