

ASS. REC. BY:

REF:

C83/A16/14019971/Hqd30

Special Instruction:

Supervisor: AOUK Ann

ASSIGNMENT (Office)

From (Person): Winnie Fun

of

AIG

Date/Time:

11/11/2019 @ 8.10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 1742E

Insured:

GBG 2214B

at Workshop m/s

power Autocare

Tel:

81812212

of

1 kaki Bukit Ave 6 # 02-11 Autocare

Policy No:

Claim No:

046310279186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:41am @ 11/11/19

Person Contacted:

Gany

Vehicle IN / OUT

Date/Time	Action/Instruction
	Submitted ✓
	SJG 1742E - X
	GBG 2214B - X.
14/11/19	submit DAR.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2019 <a href="#">Edit Reg</a>		11 Nov 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	KWONG YONG CHEONG LAUNDRY & DRY CLEANING		
Main Claimant:	CHUA KOK KENG		
Vehicle Reg. No.:	SJG1742E	Date of Loss:	04/11/2019 00:00 - :59
Claim Type:	TP / 0463102791SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBG2214B	Policy No. (Claimant):	
		Excess:	
Repairer:	Power Auto Care - Kaki Bukit (HQ) 1 Kaki Bukit Road 6 #02-11 Autobay @ Kaki Bukit, 417883, Kaki Bukit - Tel: 8181 2212		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 20/11/2019]		
Claimant's Solicitor:	R.S. SOLOMON LLC - Tel: 68177498		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (13/11/2019): TP GIA report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.


**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE...**

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY

Sent: 11/11/2019 8:10:18 AM

Attachments:  2019.11.6-PRI letter to AIG for SJG1742E.PDF  2019.11.6-Our client's GIA Report SJG1742E.PDF

---

Hi LKK,

Kindly assist to survey.

**Winnie Fan**

**AIG**

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

Dear Yinrul,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyor.

In this respect, please arrange your surveyors to contact Mr. Gary Chen of Power Auto Care at mobile no. 8181 2212 for a pre-repair survey of our clients' vehicle located at 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Singapore 417883

**Please take note that our client's vehicle is available for Pre-repair survey on next Monday 11th November 2019 after 1.00 pm.**

Thank you and Best Regards

Lua Siew Hui | Legal Executive

**R. S. Solomon LLC | 正氣律师事务所**

**Advocates & Solicitors**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [lua\\_siewhui@rssolomon.com](mailto:lua_siewhui@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

---

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	683C
<b>Vehicle Details</b>	
Vehicle No.:	SJG1742E
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	MAZDA
Vehicle Model:	ROADSTER 2.0 A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	LF10437866
Chassis No.:	NCEC251032
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$20,026.00
Original Registration Date:	24 Jun 2008
First Registration Date:	24 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$20,026.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Apr 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$40,881.00
COE Rebate Amount:	\$34,601.00
<b>Total Rebate Amount:</b>	<b>\$34,601.00</b>

The information contained herein is correct as at 13 Nov 2019

OK

## IT'S NEVER TOO EARLY TO THINK ABOUT YOUR 2020 DRIVE

VISIT THE LEXUS SHOWCASE @  
TAMPINES 1 MALL FROM 8-14 NOVPost an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Porsche Panamera 3.6A PDK - Owner Migrating Overseas.

Low Mileage And Many Wear  
And Tear Parts Have Been  
Replaced This Year.  
Direct Owner. StarAd

**HIN LUNG AUTO**  
HoBee Group  
**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars

30 years of experience

Browse by Category

Sort by Date Posted

20 results/

Advanced Search

DOA = 4/11/19  
3 vehicles

MV - 64000  
PV - 34583  
NV - 29400

Search Selection

Mazda MX-5

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Mazda	MX-5	52000 + 2205 + 10013 64718	Any	2009	Any	Any	Any	Av

**Mazda MX-5 Roadster 2.0A  
RHT (COE till 07/2029)**

\$68,800

\$7,140 /yr

02-Jul-2009

1,998 cc

107,000 km

Sports

Av

1 Year In House Warranty, High Loan Available, Free 2 x Servicing, Warranty Not By 3rd Party Workshop, Company Renew COE Cars Based On Car Conditions, Price Stated Above Is Actual Selling Price, New Paintwork, Fully Refurbished, Accident Free, STA Or VICOM Ev...

Carway

Posted: 10-Nov-2019 Tags: 2009 Mazda MX-5, 2009 mazda MX5, Mazda MX-5, mazda MX5, Mazda, MX-5, MX5, Used Mazda

**Mazda MX-5 2.0A (COE till  
03/2029)**

\$69,800

\$7,440 /yr

23-Jul-2009

1,999 cc

100,280 km

Sports

Av

Enjoy A Legendary Roadster At A Sensible Price! This Bright Yellow MX-5 Is Super Fun To Drive But With Japanese Reliability And Low Depreciation, Original Mileage, Excellent Condition, Well Maintained, Serviced By Mazda, STA Inspection Welcome. Great Collectible Clas...

Posted: 01-Nov-2019 Tags: 2009 Mazda MX-5, 2009 mazda MX5, Mazda MX-5, mazda MX5, Mazda, MX-5, MX5, Used Mazda

**Mazda MX-5 Roadster 2.0A  
RHT (COE till 01/2029)**

\$63,888

\$6,960 /yr

15-Jan-2009

1,998 cc

120,000 km

Sports

Av

Fully Stock. Most Wear And Tear Parts Have Been Replaced. Buy Without Worry.

Posted: 17-Sep-2019 Tags: 2009 Mazda MX-5, 2009 mazda MX5, Mazda MX-5, mazda MX5, Mazda, MX-5, MX5, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
------	-------	-------	--------------	----------	---------	---------	----------	------

For old advertisements, view Expired ads

20 result

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpar insurance. Find buy used Mazda MX-5, Mazda MX-5 Singapore, used Mazda MX-5 Singapore, used Mazda MX-5, used vehicles Singapore or even buy used Mazda MX-5 Singapore. W car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our part job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

Compare

©2004-2019 sgCarMart. All rights reserved.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/11/2019 16:38
Date Of Accident	04/11/2019 19:20
Exact Location Of Accident	BLK 260 KIM KEAT LINK ( MSCP ) ROUNDABOUT PICK UP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG1742E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA KOK KENG
NRIC No	S8323683C
Email Address	PARANEOX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93396700
Alternative Phone No	OTHERS-93396700

### Vehicle Particulars

Manufacturer	MAZDA
Model	MX-5-ROADSTER 2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATRE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA334551
Cover Note Number	24/06/2019 - 23/06/2020

### Driver

Name of Driver	CHUA KOK KENG
NRIC No	S8323683C
Date Of Birth	08/08/1983
Occupation	INDOOR
Date Of Driving Pass	09/04/2013
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93396700
Fax Number	
Contact Number	OTHERS-93396700
Email Address	PARANEOX@GMAIL.COM



Address	BLK 246 KIM KEAT LINK #04-149
Postcode	310246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT AND SKETCH BY DRIVER

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2214B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE SEK CHOONG
NRIC/Passport Number	S6845030F
Contact Number	91060420
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**AH LIM MOTOR COMPANY**  
No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 SMK Autopoint Singapore 569047  
Tel: 6342 4444  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

Date of accident: 4<sup>th</sup> Nov 2019 Time: 7.20pm Location: Blk 260 Kim Kent Link (Multi-storey carpark)  
 My Vehicle A: SJG 1742E Vehicle B: GBC 2214 B Vehicle C: \_\_\_\_\_

## SKETCH PLAN



Roundabout  
Drop off  
Point

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving towards roundabout drop off point at multi-storey carpark 260 Kim Kent Link but as there were a few vehicles blocking the roundabout I ~~waited~~ waited behind vehicle B for them to move off. I noticed vehicle B GBC 2214 B was on the verge of moving off hence I kept half a car distance away from him. However, I noticed he started reversing at quite a high speed ~~hence~~ hence I gave a warning horn but he reversed all the way and his rear bumper hit my car. My front bumper was damaged hence I requested for his particulars and contact number. It was 7.20pm when the accident happened.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address : paraneox@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint Singapore 568047

Report to the Centre Person's Signature

Name:

NRIC/FIN No.:

AH LIM MOTOR COMPANY



redefining / insurance

AXA Insurance Pte Ltd  
 1800 880 4888 (Within Singapore)  
 (65) 6880 4888 (International)  
 (65) 6880 4740  
 customer.care@axa.com.sg  
 www.axa.com.sg

CHUA KOK KENG (CAI GUOQING)  
 BLK 246 KIM KEAT LINK  
 #04-19  
 SINGAPORE 310246

**Renewal**

date  
 07/06/2019

your servicing distributor  
 SPEEDO CAPITAL PTE LTD / 04139

your servicing distributor contact  
 6684 7757-YUKI

## Policy Schedule

### Your SmartDrive Comprehensive Peace

**Your policy snapshot**

Policyholder name	CHUA KOK KENG (CAI GUOQING)	Policy number	VA1 / GA334551
Cover	Comprehensive	FIN / NRIC	S8323683C
Period of Insurance	from 24/06/2019 to 23/06/2020 (both dates inclusive)		

**Premium breakdown**

Gross Premium after 20% NCD	SGD 1,713.45
Total Discounts	- SGD 182.06
7% GST	SGD 107.20
Final Premium	SGD 1,638.59

**Your benefits highlights**

(refer to Policy Wording for full terms and conditions)

**SmartDrive Comprehensive Peace Benefits**

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Loss of Personal Effects in Singapore up to \$3,000
- Delivery of repaired car to your preferred location
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

**Vehicle details**

Make & Model of Vehicle	MAZDA MX5 ROADSTER 2.0	Year of manufacture	2008
Vehicle registration number	SG1742E	Type of Use	Private use
Body type	CABRIO	Engine capacity (c.c.)	1998
Seating capacity (excl driver)	1	Engine number	LF10437866
Off-Peak car	No	Chassis number	NCEC251032

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	SPEEDO CAPITAL PTE LTD

**Excess applicable** (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 700.00
Windscreen Excess	SGD 100.00

AXA Insurance Pte Ltd (199903512M)  
 8 Shenton Way, #24-01, AXA Tower,  
 Singapore 068811  
 Customer Centre, #B1-01

1 of 2



**POLICYHOLDER ACKNOWLEDGEMENT FORM**

Date: 05/11/2017

To: Owner of Vehicle Number: STG 1742E

The following has been advised to you via your workshop, AH LIM MOTOR COMPANY through their staff, ZILA / EILEEN / MUI HONG.

Please tick the applicable box if you had been advised on any of the following:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☐ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- if fire damage and you claim under your own insurance, any applicable excess will be waived. However, there will be no recovery prospect and NCD will be affected.
  - if fire damage and you are claiming against the Third Party, your NCD will not be affected. However, the recovery is not guaranteed, and AXA will not be held responsible.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using any combination of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☒ Others claim TP of other workshop

Signed and acknowledged by:

[Signature]  
Name and signature of policyholder/ authorized driver\* and company stamp (where applicable)

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

No. 10 Ang Mo Kio Industrial Park  
#01-09 AMK Auto Centre Singapore 600047  
Tel: 6483 1244 Fax: 6483 8170

Name and signature of workshop personnel including company stamp





## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Nov 2019 <a href="#">Edit Reg</a>		11 Nov 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>	
Insured:	KWONG YONG CHEONG LAUNDRY & DRY CLEANING, Co. Reg. No.: -		
Main Claimant:	CHUA KOK KENG		
Vehicle Reg. No.:	SJG1742E	Date of Loss:	04/11/2019 00:00 - :59 [136 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0463102791SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBG2214B	Policy No. (Claimant):	
		Excess:	
Repairer:	Power Auto Care - Kaki Bukit (HQ) 1 Kaki Bukit Road 6 #02-11 Autobay @ Kaki Bukit, 417883. Kaki Bukit - Tel: 8181 2212		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 20/11/2019]		
Claimant's Solicitor:	R.S. SOLOMON LLC - Tel: 68177498		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (13/11/2019): TP GIA report</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Claim Documents

**\*SJG1742E (0463102791SG)  
[GBG2214B]**












































**TP**

**CHUA KOK KENG**










































**Nov 4 2019 12:00AM**

**[KWONG YONG CHEONG LAUNDRY & DRY CLEANING]**

**Power Auto Care - Kaki Bukit**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b>	<a href="#">View in Browser</a>
<b>Photos/Images</b>							<b>3 per page</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	14/11/19 09:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>			
2	14/11/19 09:21	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>			
3	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
4	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
5	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
6	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
7	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
8	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
9	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
10	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
11	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
12	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
13	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
14	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
15	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
16	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
17	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
18	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
19	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
20	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
21	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
22	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
23	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
24	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
25	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
26	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
27	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
28	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
29	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
30	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
31	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
32	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
33	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
34	14/11/19 09:22	General View	 Load JPG	<input checked="" type="checkbox"/>			
35	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
36	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
37	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
38	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
39	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
40	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
41	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
42	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			
43	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>			



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/11/19 09:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/11/19 09:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/11/19 09:02	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/11/19 15:56	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19019971/HQD3E2

Date: 18/11/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

## Claimant

Vehicle No : SJG1742E

Insured Vehicle No : GBG2214B

Date of Loss: 04/11/2019

Nature of Claim: TP

Claim No: 0463102791SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJG1742E**

Make &amp; Model: MAZDA MX-5, ROADSTER 2.0 (A)

Engine No: LF10437866

Reg. Date: 24/06/2008 (Man. Year: 2008)

Chassis No: NCEC251032

Colour: Red

Odometer: 154578 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 235/40Z R18

Front Left Side: Dunlop 5 mm Rear Left Side: Nexen 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Power Auto Care - Kaki Bukit (HQ)  
1 Kaki Bukit Road 6 #02-11 Autobay  
@ Kaki Bukit  
Singapore 417883.

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Crushed	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Crushed	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Crushed	0.00 F	*- F
4	1		*FRT BUMPER	Cracked	0.00 F	*- F
5	1		*SET FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*FRT BUMPER SIDE RETAINER R/H	Necessary	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
8	2		*FRT BUMPER TOW COVER	Crushed	0.00 F	*- F
9	1		*FRT BUMPER GRILLE LOWER	Cracked	0.00 F	*- F
10	1		*FRT BUMPER LOWER SPOILER	Repair	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Crushed	0.00 F	*- F
12	1		*FOG LAMP L/H	Cracked	0.00 F	*- F
F=Franchise part.						
				<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >