

ASS. REC. BY:

REF:

CS: III 9019973/Etd3

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): ~~minnen~~ Gabriel wee

of

TH

Date/Time: 8/11/19 @ 5:25pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBQ 4031X

Insured:

SHC 1135C

at Workshop m/s

Kemoce Motorcycles

Tel:

6475 0123

at

253 Alexandra Road #01-04

Policy No:

Claim No:

Sum Insured:

Excess:

D.O.A.

28/10/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:20am @ 11/11/19

Person Contacted:

Temy

Vehicle IN/OUT

Date/Time	Action/Instruction
	FBQ 4031X - X
	SHC 1135C - X. Submit unsafe total loss.
	Market Value: 29,000+
	LTA: 3558+
	NV: 50874+

Signature Steve


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR. Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F B Q 4031 X Yr Regn: 30/09/2019
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Harley Davidson XL 1200NS c.c. 1202
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: N/A T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 5H01LP3C6K C417447
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 100/90B19
 R: 150/80B16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. mm L/Bal. mm

D.O.A. 28/10/19 D.O.I. 11/11/19

Survey held at Komoco Motorcycles

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-29K *Total 1255
(unsafe to repair)

Check market value

14/12/2019

RECEIVED 15 NOV 2019

Date/Time, File Pass to?

☐ : Proli. Report

Days Of Repair: _____

1) 15/11/2019

☒ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee: 380

Transportation:

) \$ + RS. SI

) Priob

) Others

Report Format : TP

Lump Sum / I.B.I. (\$) _____

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

TOTAL

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 8 November 2019 5:25 PM
To: Chia Jia Rong; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: 'Ashley (Mr)'; Manivel Priyadarshini
Subject: RE: Pre Repair Inspection
Attachments: 08112019110257.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FBQ4031X
III INSURED VEHICLE NO. : SHC1135C
DATE OF LOSS : 28.10.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Priya.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street, #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chia Jia Rong [mailto:jiarong@roypartners.com.sg]
Sent: 08 November, 2019 4:49 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Ashley (Mr)' <ashley@roypartners.com.sg>
Subject: RE: Pre Repair Inspection

Dear Sirs,

My client is not agreeable to your list of surveyors hence they propose RT Appraisal as the Single joint Expert for the above Pre Repair Inspection.

With regards,

Chia Jia Rong

M/s Roy & Partners
133 New Bridge Road
#08-09

China Town Point

Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : jiarong@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Friday, 8 November, 2019 1:55 PM

To: Chia Jia Rong <jiarong@roypartners.com.sg>

Cc: 'Ashley (Mr)' <ashley@roypartners.com.sg>

Subject: RE: Pre Repair Inspection

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Chia Jia Rong [<mailto:jiarong@roypartners.com.sg>]

Sent: 08 November, 2019 11:05 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: 'Ashley (Mr)' <ashley@roypartners.com.sg>

Subject: Pre Repair Inspection

Your Insured: SHC 1135C

Our Ref: MKR/307/9300/2019/as.jr

Dear Sirs,

CLAIMANT: Van Hoorik Robbert Bastiaan (Owner FBQ 4031X)
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FBQ 4031X AND SHC 1135C ALONG
BUKIT BATOK WEST AVENUE 3 ON 28.10.2019 AT ABOUT 0540 HOURS.

We refer to the above matter.

We act for Van Hoorik Robbert Bastiaan, the owner of the motor vehicle No. **FBQ 4031X**.

We are instructed by our client to notify you of a road traffic accident on 28.10.2019 at about 0540 hours along **Bukit Batok West Avenue 3** between motor vehicle registration number **FBQ 4031X** and motor vehicle registration number **SHC 1135C** driven by your insured at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's motor vehicle **FBQ 4031X** been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor vehicle **FBQ 4031X** at our client's repairer workshop, Komoco Motorcycle Pte Ltd at 253 Alexander Road #01-04 Singapore 159936. Your said surveyor may contact Terry Mortimer at 6475 0123 to arrange the said inspection. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

With regards,

Chia Jia Rong

M/s Roy & Partners
133 New Bridge Road
#08-09

China Town Point
Singapore 059413

Tel : 6536 8466 Fax : 6536 1963

Email : jiarong@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby

notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2019 23:44
Date Of Accident	28/10/2019 05:30
Exact Location Of Accident	BUKIT BATOK WEST AVENUE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBQ4031X
Insured/Policyholder	
Name Of Registered Owner	VAN HOORIK ROBBERT BASTIAAN
NRIC No	S7668493F
Email Address	ROB.VAN.HOORIK@DAMEN.COM
Mobile Phone No	(LOCAL) +65-97108066
Alternative Phone No	OFFICE-97108066

Vehicle Particulars

Manufacturer	HARLEY-DAVIDSON
Model	XL1200NS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V13320
Cover Note Number	

Driver

Name of Driver	VAN HOORIK ROBBERT BASTIAAN
NRIC No	S7668493F
Date Of Birth	20/07/1976
Occupation	INDOOR
Date Of Driving Pass	09/09/2008
Driving Experience	11 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97108066
Fax Number	
Contact Number	OFFICE-97108066
Email Address	ROB.VAN.HOORIK@DAMEN.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	10 UBI AVENUE 3
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20191030/7012 LODGE AT 10 UBI AVENUE 3 Junction of BLK 446 Bukit Batok West ave 8 I was Travelling on Bukit Batok West Ave 3. Stop on red light. started riding when light turns green Comfort taxi (SHC1135) driven by Quek Keng Long (S112788D) came from the opposite side and made a right turn towards my direction and hit me.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1135C
Vehicle Make/Model/Colour	TOYOTA / PRIUS HYBRID 1.8 CVT
Details Of Properties	NA
Vehicle Category	TAXI
Name of Driver	QUEK KENG LONG
NRIC/Passport Number	S112788D
Contact Number	93841532
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 493F

Vehicle Details

Vehicle No.: FBQ4031X
Vehicle to be Exported: No
Intended Deregistration Date: 11 Nov 2019
Vehicle Make: HARLEY DAVIDSON
Vehicle Model: XL1200NS
Primary Colour: Black
Manufacturing Year: 2019
Engine No.: LP3K417447
Chassis No.: 5HD1LP3C6KC417447
Maximum Power Output: -
Open Market Value: \$9,350.00
Original Registration Date: 30 Sep 2019
First Registration Date: 30 Sep 2019
Transfer Count: 1
Actual ARF Paid: \$2,925.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2029
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$3,601.00
COE Rebate Amount: \$3,558.00
Total Rebate Amount: \$3,558.00

The information contained herein is correct as at 11 Nov 2019

OK



KOMOCO Motorcycles Pte Ltd
253, Alexandra Road, # 01-04. Singapore 159936
Tel: (65) 6475-0123 Fax: (65) 64728900

REPAIR ASSESSMENT

OWNER'S NAME : ROBERT VAN HOORIK
BIKE NO / MODEL: FBQ4031X / XL1200NS
VIN NO: 5HD1LP3C6KC417447

INSURANCE : LIBERTY
DATE : 4/11/2019

S/N	PART NO.	DESCRIPTION	QTY	AMOUNT
1	FRAME	RECOMEND TOTAL LOSS AS FRAME IS BENT	1	29900.00
2		FRONT DOWNWARD TUBES ARE BENT	ex. COE	
3		TOWARDS THE FRONT ENGINE CILINDER		
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25	Auto Consultants hence notify			
26	Repairer of the following:			
27	• To survey before/after spray painting			
28	• To display damaged part(s) during resurvey			
29	• Parts prices are subject to confirmation			
30	• Third party survey is on a "Without Prejudice" basis			
31	• Legal modification(s) is allowed			
32	• Supplementary item(s) must be resurveyed and			
33	is subject to final approval from Insurance Company			
34	Signed by Repairer			
35	Signature:			
36	Date:			

*** Estimation is based on visual inspection and should there be unforeseen additional damage found during repair,
*** supplementary parts may have to be ordered.
*** Prices are subject to change.

Steve (LKK)
8322 8813
steve@lkkad.com

wtl April 11/11/19, 11.33am
P/P
Total loss

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2019 11:19 Edit Reg		08 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: VAN HOORIK ROBBERT BASTIAAN , ID: S7668493F									
Main Claimant: -									
Vehicle Reg. No.: FBQ4031X		Date of Loss: 28/10/2019 00:00 - :59 [28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHC1135C		Policy No. (Claimant):							
		Excess:							
Repairer: KOMOCO MOTORCYCLE PTE LTD (HQ) 253 ALEXANDRA ROAD #01-04, 159936 Alexandra - Tel: 64750123									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 20/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





































*FBQ4031X
[SHC1135C]
TP
-






















Oct 28 2019 12:00AM
[VAN HOORIK ROBBERT BASTIAAN]
KOMOCO MOTORCYCLE PTE LTD

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/11/19 16:23	General View	 Load JPG	✓
2	15/11/19 16:23	General View	 Load JPG	✓
3	15/11/19 16:23	General View	 Load JPG	✓
4	15/11/19 16:23	General View	 Load JPG	✓
5	15/11/19 16:23	General View	 Load JPG	✓
6	15/11/19 16:23	General View	 Load JPG	✓
7	15/11/19 16:23	General View	 Load JPG	✓
8	15/11/19 16:23	General View	 Load JPG	✓
9	15/11/19 16:23	General View	 Load JPG	✓
10	15/11/19 16:23	General View	 Load JPG	✓
11	15/11/19 16:23	General View	 Load JPG	✓
12	15/11/19 16:23	General View	 Load JPG	✓
13	15/11/19 16:23	General View	 Load JPG	✓
14	15/11/19 16:23	General View	 Load JPG	✓
15	15/11/19 16:23	General View	 Load JPG	✓
16	15/11/19 16:23	General View	 Load JPG	✓
17	15/11/19 16:23	General View	 Load JPG	✓
18	15/11/19 16:23	General View	 Load JPG	✓
19	15/11/19 16:23	General View	 Load JPG	✓
20	15/11/19 16:23	General View	 Load JPG	✓
21	15/11/19 16:23	General View	 Load JPG	✓
22	15/11/19 16:23	General View	 Load JPG	✓
23	15/11/19 16:23	General View	 Load JPG	✓
24	15/11/19 16:23	General View	 Load JPG	✓
25	15/11/19 16:23	General View	 Load JPG	✓
26	15/11/19 16:23	General View	 Load JPG	✓
27	15/11/19 16:23	General View	 Load JPG	✓
28	15/11/19 16:23	General View	 Load JPG	✓
29	15/11/19 16:23	General View	 Load JPG	✓
30	15/11/19 16:23	General View	 Load JPG	✓
31	15/11/19 16:23	General View	 Load JPG	✓
32	15/11/19 16:23	General View	 Load JPG	✓
33	15/11/19 16:23	General View	 Load JPG	✓
34	15/11/19 16:23	General View	 Load JPG	✓
35	15/11/19 16:23	General View	 Load JPG	✓
36	15/11/19 16:23	General View	 Load JPG	✓
37	15/11/19 16:23	General View	Load JPG	✓
38	15/11/19 16:23	General View	Load JPG	✓
39	15/11/19 16:23	General View	Load JPG	✓
40	15/11/19 16:23	General View	Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	15/11/19 16:23	General View	 Load JPG	✓
42	15/11/19 16:23	General View	 Load JPG	✓
43	15/11/19 16:23	General View	 Load JPG	✓
44	15/11/19 16:23	General View	 Load JPG	✓
45	15/11/19 16:23	General View	 Load JPG	✓
46	15/11/19 16:23	General View	 Load JPG	✓
47	15/11/19 16:23	General View	 Load JPG	✓
48	15/11/19 16:23	General View	 Load JPG	✓
49	15/11/19 16:23	General View	 Load JPG	✓
50	15/11/19 16:23	General View	 Load JPG	✓
51	15/11/19 16:23	General View	 Load JPG	✓
52	15/11/19 16:23	General View	 Load JPG	✓
53	15/11/19 16:23	General View	 Load JPG	✓
54	15/11/19 16:23	General View	 Load JPG	✓
55	15/11/19 16:23	General View	 Load JPG	✓
56	15/11/19 16:23	General View	 Load JPG	✓
57	15/11/19 16:23	General View	 Load JPG	✓
58	15/11/19 16:23	General View	 Load JPG	✓
59	15/11/19 16:23	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/11/19 16:26	LTA REBATE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 08:31	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19019973/ETD3S2

Date: 15/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FBQ4031X

Insured Vehicle No : SHC1135C

Date of Loss: 28/10/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ4031X**

Make & Model: HARLEY-DAVIDSON XL 1200N, 1.2 (M)

Engine No: LP3K417447

Reg. Date: 30/09/2019 (Man. Year: 2019)

Chassis No: 5HD1LP3C6KC417447

Colour: Black

Odometer: 0 km

Engine Capacity: 1202 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 100/90 B19

Rear Tyre Size: 150/80 B16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/11/2019

Date Inspected: 11/11/2019 Inspected At:

KOMOCO MOTORCYCLE PTE LTD (HQ)

253 ALEXANDRA ROAD #01-04

Singapore 159936

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$29,000.00
OMV :	\$9,350.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$3,601.00
COE Rebate (2) :	\$3,558.00
Total Rebate (1) + (2) = :	\$3,558.00

The total amount incurred will be Market Value \$29,000.00 minus Total Rebate \$3,558.00 = \$25,442.00 before excess.

We are of the opinion that it would be unsafe to proceed with the repairs

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Nov 2019)	
Parts:	N/A	HARLEY-DAVIDSON XL 1200N 1.2 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ4031X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >