

ASS. REC. BY:

REF:

CS3/1A1/1019974/Gcd302

Special Instruction:

Surveyor:

Winnie Fan

ASSIGNMENT (Office)

From (Person):

Winnie Fan

of

ALC

Date/Time:

11/11/19 8:13am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 8713P

Insured:

SMP 4692M

at Workshop m/s

choon Hock Auto

Tel:

6453 0778.

of

BLK 176 Sin Ming #05-03

Policy No:

Claim No:

2407419410SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:44am 11/11/19

Person Contacted:

Jade

Vehicle

IN / OUT

Date/Time	Action/Instruction
	Example (X)
	SLH 8713P-X
	SMP 4692M-X
	Dismantle: 12/11/2019

ASS. REC. BY:

GIL

REF:

AIG

PRS

ASSIGNMENT

From:

Date:

11/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLH 8713P

at Workshop m/s

choon hock auto

of

176 Sin Ming Drive # 05-03

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

M/D

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 8713P

Yr Regn:

22 Nov 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel Astra 1.4 c.c

B399

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

76764

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WOLBE6EC 4H 000/802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11-11-19

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 NOV 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

180

Transportation:

S + RS: \$

Photos

Other:

TOTAL

191

Report Format:

DAR

Lump Sum / L.B.I.:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS								[Created by adjuster]	
Insured:									
Main Claimant:		-							
Vehicle Reg. No.:		SLH8713P		Date of Loss:		06/11/2019 00:00 - :59			
Claim Type:		TP / 2407419410SG		Policy/Cover Note No.:		(Comprehensive)			
Vehicle Reg. No. (Insured):		SMP4692M		Policy No. (Claimant):					
				Excess:					
Repairer:		Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721, 575721 Sin Ming - Tel: 64530778							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/11/2019]							
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
There are no mail for this case.									
ALL ASSOCIATED TASKS								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- 05#SMP4692M#027# RE: Re: Re: PRE-REPAIR INSPECTION - ACCIDENT IN...

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY

Sent: 11/11/2019 8:13:49 AM

Attachments:  SAS REPORT.PDF

Hi LKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Friday, November 08, 2019 3:30 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: [EXTERNAL] Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMP4692M AND SLH8713P ON 06/11/2019

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

CHOON HOCK AUTOCARE PTE LIMITED

Blk 176 Sin Ming Dr
#05-03 Sin Ming Autocare
Singapore (575721)
Tel: 6453 0778

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	096D
Vehicle No.:	SLH8713P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	OPEL
Vehicle Model:	ASTRA HB 1.4 AT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	B1162047GSGX0062
Chassis No.:	W0LBE6EC4HG001802
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$20,004.00
Original Registration Date:	22 Nov 2016
First Registration Date:	22 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$15,006.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$11,254.00
COE Expiry Date:	21 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,206.00
COE Rebate Amount:	\$39,500.00
Total Rebate Amount:	\$50,754.00

The information contained herein is correct as at 11 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 13:39
Date Of Accident	06/11/2019 20:35
Exact Location Of Accident	AIRPORT ROAD TOWARDS KPE ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH8713P
Insured/Policyholder	
Name Of Registered Owner	SEAH HOCK CHYE
NRIC No	S7107096D
Email Address	JUMMYSEAHHC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98719197
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA HB 1.4 AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE.
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01019240
Cover Note Number	22/11/2018 TO 21/11/2019

Driver

Name of Driver	SEAH HOCK CHYE
NRIC No	S7107096D
Date Of Birth	05/03/1971
Occupation	INDOOR
Date Of Driving Pass	25/03/1997
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98719197
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	JUMMYSEAHHC@GMAIL.COM

Address 2 PASIR RIS LINK
#08-01-
Postcode 518184
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : LEE LIN KIW
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SMP4692M
Vehicle Make/Model/Colour KIA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HEJIA
NRIC/Passport Number S8732159B
Contact Number 97533345
Address
Postcode
Insurance Company Name
Nature Of Damage

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 7/11/19/1PM


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: gerald
 NRIC/FIN No.: 7/11/2011



Sketch Plan Pg. 2

Date of accident: 06/11/19 Time: 20:34pm Location: AIRPORT ROAD TOWARDS KPE
 My Vehicle A: SLH 8713P Vehicle B: SMP 4692M Vehicle C:
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/11/19, I was driving along Airport Road toward KPE. Vehicle in front of me stopped and I also stop. My vehicle was stationary for a while and suddenly, vehicle B bang onto my vehicle A from behind. The owner of vehicle B alight her vehicle and apologise to me.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address : Jimmysehhic@gmail.com
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(0) (3)Check (0)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	CPA	✓	
1138	993627	Rear Number Plate Base	SCR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	Re	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	M.S	✓	
1146	992341	Rear Bumper Clips	REL	✓	
1147	992976	Rear Bumper Bracket	CPA	✓	
1148	993068	Rear Bumper Side Retainer	Re	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad Front Corner M.S			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CPA	✓	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Buc	✓	
1160	993339	Rear End Panel Top Garnish	CPA	✓	
1161	993333	Rear End Panel Inner Trim - Grille	CPA	✓	2
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	Repair		
1171	991328	Bootlid Emblem	REL	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

Vehicle No:

SUH8713P

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2019 Edit Reg		11 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TEE HE JIA SHERRAINE, ID: S8732159B		
Main Claimant:	SEAH HOCK CHYE, ID: S7107096D		
Vehicle Reg. No.:	SLH8713P	Date of Loss:	06/11/2019 00:00 - :59 [35 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2407419410SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SMP4692M	Policy No. (Claimant):	
		Excess:	
Repairer:	Choon Hock Autocare Pte Ltd (HQ) Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare Singapore 575721, 575721 Sin Ming - Tel: 64530778		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/11/2019]		
Claimant's Solicitor:	Kuru & Co		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)












































- AIG_SG (13/11/2019): TP GIA report





ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH8713P (2407419410SG)
[SMP4692M]
TP
SEAH HOCK CHYE
Nov 6 2019 12:00AM
[TEE HE JIA SHERRAINE]
Choon Hock Autocare Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
2	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
3	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
4	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
5	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
6	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
7	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
8	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
9	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
10	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
11	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
12	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
13	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
14	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
15	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
16	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
17	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
18	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
19	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
20	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
21	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
22	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
23	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
24	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
25	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
26	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
27	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
28	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
29	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
30	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
31	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
32	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
33	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
34	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
35	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
36	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
37	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
38	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
39	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
40	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
41	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
42	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	
43	13/11/19 09:38	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/11/19 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	13/11/19 09:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/11/19 16:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19019974/GCD3E2

Date: 14/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SLH8713P

Insured Vehicle No : SMP4692M

Date of Loss: 06/11/2019

Nature of Claim: TP

Claim No: 2407419410SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH8713P

Make & Model: OPEL ASTRA, 1.4 HB (A)

Engine No: B1162047GSGX0062

Reg. Date: 22/11/2016 (Man. Year: 2016)

Chassis No: W0LBE6EC4HG001802

Colour: Red

Odometer: 76764 km

Engine Capacity: 1399 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Choon Hock Autocare Pte Ltd (HQ)
Blk 176 Sin Ming Drive #05-03, Sin
Ming AutoCare Singapore 575721
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Scratched	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
6	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	1		*REAR BUMPER BRACKET	Cracked	0.00 F	*- F
8	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
9	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
10	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
11	1		*REAR END PANEL	Buckled	0.00 F	*- F
12	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
13	2		*REAR END PANEL INNER GRILLE	Cracked	0.00 F	*- F
14	1		*BOOTLID	Repair	0.00 F	*- F
15	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >