

ASSIGNED BY:

File No:

CE3/MSG 190 19995/4f302

MS14/

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLV 72710

at Workshop m/s

SL.

Insured:

SKZ 256L

Policy No.

A28666716ANW

Claims No.

611265

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

24

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6020

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV 72710

Yr Regn:

1 of

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CRV

c.c 2354

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

85.711

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHLRE 48508C203807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/60 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

mm

Rear

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/11/19

D.O.I.

11/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3yrs. Data

LTA 16693 we until 22-1-2023

Dep 2500 per year next 7307 low mileage

SLV 72710 X

SLV - 2661-X

RECEIVED 19 NOV 2019

17/11/19 1:35pm sent email GHA report.

18/11/19 L/S 7300 confirmed with AHA (Red: 18532.40; 71%)

Date/Time: File Pass 1/7

Prell. Report

Days Of Repair:

5

19/11/2019

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 18 Nov 2019

Preliminary Advice

Insured Vehicle No	: SKZ256L	Accident Date	: 09/11/2019
TP Vehicle No	: SLV7271E	Assignment Date	: 12/11/2019
Make	: HONDA CR-V	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/11/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,832.40
Revised Amount	:S\$	10,905.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,905.12
Lump Sum Repair	:S\$	7,300.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 12 November 2019 1:35 PM
To: 'motorsurvey@sg.msiga-asia.com'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 09/11/2019, SLV 7271E (TP VEHICLE), SKZ 256L (OI VEHICLE)
Attachments: SLV 7271E GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLV 7271E at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SAVE \$S ON UR CAR

INSURANCE RENEWAL



Compare 10+ Insurers

CLICK HERE >

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal Cost Toyota A81s 1.6A



2.0PFA, 1.6A, 90 Down, 90 Down
Recently from JMB, 2 years
Automatic Engine, Gold
100-AD

Republic Auto

CERTIFIED PRE-OWNED
MERCEDES BENZ



VIEW OUR CARS

Browse by Category

1 vehicles

Honda CR-V

Sort by Date Posted 40 results/page

Advanced Search

Search Selection

Honda CR-V

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



Honda CR-V 2.0A (COE till
04/2024)

\$25,800

\$5,770 /yr

08-Sep-1999

1,972 cc

-

SUV

Available

Rare Unit, New 5 Years COE, New Timing Belt, Very Well Maintained. See To Believe. Sunroof, Trade In Welcome.

Posted: 09-Nov-2019 Tags: 1999 Honda CR-V, 1999 honda CRV, Honda CR-V, honda CRV, Honda, CR-V, CRV, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Avg Cost Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

40 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda CR-V, Honda CR-V Singapore, used Honda CR-V Singapore, used Honda CR-V, used vehicles Singapore or even buy used Honda CR-V Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 602D

Vehicle Details

Vehicle No.: SLV7271E

Vehicle to be Exported: No

Intended Deregistration Date: 12 Nov 2019

Vehicle Make: HONDA

Vehicle Model: HONDA CRV 2.4L AT

Primary Colour: Black

Manufacturing Year: 2007

Engine No.: K24Z12745071

Chassis No.: JHLRE48508C203807

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$29,637.00

Original Registration Date: 23 Jan 2008

First Registration Date: 23 Jan 2008

Transfer Count: 1

Actual ARF Paid: \$32,601.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Jan 2023

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$26,136.00

COE Rebate Amount: \$16,693.00

Total Rebate Amount: \$16,693.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Nov 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 14:42
Date Of Accident	09/11/2019 18:15
Exact Location Of Accident	TELOK BLANGAH ROAD TOWARDS PASIR PANJANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV7271E
Insured/Policyholder	
Name Of Registered Owner	BAVANESWARY D/O MAAHNEKHAM
NRIC No	S8236602D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83641626
Alternative Phone No	OFFICE-83641626

Vehicle Particulars

Manufacturer	HONDA
Model	CR-V-2.4 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00563745
Cover Note Number	

Driver

Name of Driver	SIVA KUMAR S/O SUNTHAN TEVAN
NRIC No	S8000753A
Date Of Birth	12/01/1980
Occupation	INDOOR
Date Of Driving Pass	01/12/1999
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81623004
Fax Number	
Contact Number	OFFICE-81623004
Email Address	NOEMAIL

Address	BLK 666B PUNGGOL DRIVE #15-564
Postcode	822666
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT NO: T/20191110/2056

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ256L
Vehicle Make/Model/Colour	VOLKSWAGEN / SPORTSVAN 1.4 AT AM13HZ CL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG SIANG KIAT
NRIC/Passport Number	S9246322B
Contact Number	96211359
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	SIVA KUMAR S/O SUNTHAN TEVAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLV7271E
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 666B PUNGGOL DRIVE #15-564
Postcode	822666

Date of Accident : 09/11/19 Accident Time: 6:15pm (24-HR-Format)
Accident Place : Telok Blangah Rd. Towards Pasir Panjang
Vehicle No. (Car Plate No.) : SLV 7271E Make/Model: Honda CRY 2.4L
Insurance Company : Direct Asa. Policy No: MT/0058545
Owner or Company Name / IC No. : 882366020 Ravansury. D/o Maath^h netkum
Owner or Company Contact No. : 83641626 Owner's Hp Company Tel
DRIVER'S Name / IC No. : 882366020 Siva Kumar S/o Sathyan Tevan
DRIVER'S Date Of Birth : 12/01/1980 DRIVER'S License Pass Date 01/12/1999
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others:
DRIVER'S Address : Blk 666B Punggol Drive # 15-564 S222666
DRIVER'S Contact No./ Alt No. : 1) 81623004, 2)
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address :
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): * Driver No. only
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: <u>SKZ 256L</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

☐ I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Bukit Chermín Road

Telok Blangah Road

Bus stop A

Bus stop B

on 09/11/2019 I was travelling ^{straight} along Telok Blangah Rd.
vehicle B was making right turn into Bulevar Chermin Rd.
We - vehicle B's driver did not checked traffic and dashed.
we collided.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20191110/2056

1 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191110/2056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/11/2019 13:53	Vide Report No.:	Station Diary No.: 66
--	------------------	--------------------------

Informant's Particulars

Name of Informant: SIVA KUMAR S/O SUNTHAN TEVAN			Address: APT BLK 666B PUNGGOL DRIVE #15-564 SINGAPORE 822666		
ID Type / ID No.: NRIC NO / S8000753A			Contact No.: Home/Office: Mobile: 81623004		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 12/01/1980	Type of Informant: Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: PROJECT MANAGER			Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/11/2019 18:15	Type of Location:
Location: Along Road 1 PASIR PANJANG ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKZ256L	Car					0
SLV7271E	Car	HONDA	CRV	Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191110/2056

CONTINUATION OF REPORT

Driver			
Name	CHONG SIANG KIAT	ID No.	S9246322B
Related Vehicle	SKZ256L (Car)	Contact No.	96211359
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SIVA KUMAR S/O SUNTHAN TEVAN	ID No.	S8000753A
Related Vehicle	SLV7271E (Car)	Contact No.	81623004
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	10/11/2019	Date Discharge	10/11/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 09.11.2019 at about 6.15pm, I was driving my car (SLV7271E) along the extreme left lane heading towards Pasir Panjang Road when another car (SKZ256L) suddenly came out from my right to turn in to Bukit Chermin Road which was on my left. I was not able to stop in time as such the front of my car collided with the left rear side of the other car.

Both drivers stopped and exited our cars to make a check. At that time my right thumb was injured however there was no need for any Ambulance. There was also no government properties damaged and no Police were at scene.

I discovered damages to mostly the front portion of my car. I do not have any in car camera.

There were no passengers in my vehicle at that time. Today I felt some pain on my neck and back area as such I decided to go to Mount Alvernia Hospital where I was given 5 days of MC.

I am lodging this report for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20191110/2056

3 of 3

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20191110/2056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 REEMA KAUR SANDHU

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:

10/11/2019 13:53

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Link Auto Co. warrants these parts
to be free of the following:
1. Defects in material or workmanship
2. Damage caused by accident, fire, flood, theft, or other causes
3. Damage caused by misuse or improper installation
4. Damage caused by use of parts not approved by Link Auto Co.
5. Damage caused by use of parts not approved by Link Auto Co.
6. Damage caused by use of parts not approved by Link Auto Co.
7. Damage caused by use of parts not approved by Link Auto Co.
8. Damage caused by use of parts not approved by Link Auto Co.
9. Damage caused by use of parts not approved by Link Auto Co.
10. Damage caused by use of parts not approved by Link Auto Co.

Acknowledged by Receiver:
Signature: _____
Date: _____

VEHICLE NO: SLV 7271E

QTY	PARTICULAR
1 PCS	BONNET
2 PCS	BONNET HINGES @\$85.00
1 PCS	FRONT GRILLE
1 PCS	FRONT GRILLE 'H' LOGO
1 PCS	FRONT GRILLE LOWER GARNISH
1 PCS	FRONT BUMPER TOP 440.10
1 PCS	FRONT BUMPER LOWER 366.20
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE 195.30
1 PCS	FRONT BUMPER FOG LAMP N/S 267.40
1 PCS	FRONT BUMPER FOG LAMP CHROME N/S
1 PCS	FRONT BUMPER BEAM 233.70
1 PCS	FRONT BUMPER SIDE RETAINER N/S
1 SET	FRONT BUMPER CLIPS
2 PCS	HEADLAMP ASSY @\$1065.5 911.40 X 2 = 1822.80
2 PCS	HEADLAMP LOWER BRACKETS @\$86.50 25.00
1 PCS	AIR CON CONDENSER 843.80
1 PCS	RADIATOR 1418.00
1 PCS	RADIATOR FAN ASSY
1 PCS	FRONT SUPPORT PANEL
1 PCS	FRONT SUPPORT PANEL TOP GARNISH
1 PCS	FRONT FENDER N/S
1 PCS	FRONT FENDER INNERSHIELD N/S
1 PCS	DRIVER AIR BAG 1425.30
1 PCS	DRIVER AIR BAG SPIRAL SENSOR 181.20
1 PCS	PASSENGER AIR BAG 2055.30
2 PCS	SEATBELTS @\$750.00 485.50 X 2 = 971.00
2 PCS	SEATBELT BUCKLES @\$150.00
1 PCS	AIR BAG ECU 650.00
1 PCS	FRONT WINDSCREEN
1 PCS	FRONT LICENCE PLATE GARNISH 50.80
1 PCS	FRONT LICENCE PLATE W/HOLDER

LABOUR CHARGES

TO CHECK WIRING
TO REFILL AIR CON GAS
TO DISMANTLE & REFIX FRONT WINDSCREEN
TO DISMANTLE & REPLACING AIR BAG
TO SPRAY RUST PROOFING
TO REPROGRAMME & RESET AIRBAG SYSTEM
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

not Allowed
11/11/18
7300/
d/s
take up after repair
sdy.

2	\$1,066.20	X
11	\$170.00	X
one	\$245.50	✓
ner	\$30.80	✓
one	\$266.20	✓
one	\$766.30	✓
one	\$755.20	✓
one	\$298.50	✓
one	\$285.30	✓
11	\$105.00	X
one	\$366.20	✓
one	\$25.50	✓
one	\$30.00	✓
one	\$2,131.00	✓
one	\$133.00	1pc
one	\$1,022.30	✓
one	\$1,488.50	✓
11	\$650.00	X
11	\$641.20	X
11	\$305.50	X
11	\$671.10	X
11	\$122.30	X
Activity	\$2,882.30	✓
Activity	\$243.50	✓
Activity	\$3,113.20	✓
Activity	\$1,500.00	✓
11	\$300.00	X
Activity	\$866.20	✓
one	\$1,455.30	X
one	\$106.30	✓
one	\$50.00	✓
	\$22,092.40	

	\$50.00	30
	\$120.00	100
11	\$150.00	X
11	\$380.00	300
11	\$80.00	X
11	\$380.00	X
	\$1,080.00	520
	\$1,500.00	680
TOTAL	\$25,832.40	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19019995/UTF3N2

Date: 21/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28666716AVW
Claimant Vehicle No :	SLV7271E	Insured Vehicle No :	SKZ256L
Date of Loss:	09/11/2019	Nature of Claim:	TP
		Claim No:	611265

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7271E	Engine No:	K24Z12745071
Make & Model:	HONDA CR-V, 2.4 L (A)	Chassis No:	JHLRE48508C203807
Reg. Date:	23/01/2008 (Man. Year: 2007)	Odometer:	85711 km
Colour:	Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60R18	Rear Tyre Size:	225/60R18
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	22,092.40	9,275.12	12,817.28	58.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,630.00	2,110.00	56.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,832.40	10,905.12	14,927.28	57.79
Approved Total (Overridden) (\$\$)		7,300.00		
(\$\$)	25,832.40	7,300.00	18,532.40	71.74
+ GST 7.00/7.00% (\$\$)	1,808.27	511.00	1,297.27	71.74
Nett Amount (\$\$)	27,640.67	7,811.00	19,829.67	71.74

INSPECTION

Date of Assignment:	12/11/2019	
Date Inspected:	11/11/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts: M1-SUV	HONDA CR-V 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV7271E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,066.20 F	*- FL
2	2		*BONNET HINGES	Not Necessary	170.00 F	*- FL
3	1		*FRONT GRILLE	Cracked	245.50 F	*245.50 FL
4	1		*FRONT GRILLE H LOGO	Necessary	30.80 F	*30.80 FL
5	1		*FRONT GRILLE LOWER GARNISH	Cracked	266.20 F	*266.20 FL
6	1		*FRONT BUMPER TOP	Distorted	766.30 F	*440.10 FL
7	1		*FRONT BUMPER LOWER	Distorted	755.20 F	*366.20 FL
8	1		*FRONT BUMPER LOWER CENTRE GRILLE	Torn	298.50 F	*195.30 FL
9	1		*FRONT BUMPER FOG LAMP N/S	Cracked	285.30 F	*267.40 FL
10	1		*FRONT BUMPER FOG LAMP CHROME N/S	Not Necessary	105.00 F	*- FL
11	1		*FRONT BUMPER BEAM	Bent	366.20 F	*233.70 FL
12	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	25.50 F	*25.50 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
14	2		*HEADLAMP ASSY	Cracked	2,131.00 F	*1,822.80 FL
15	1		*HEADLAMP LOWER BRACKETS	N/s Cracked	133.00 F	*25.00 FL
16	1		*AIR CON CONDENSER	Bent/Punctured	1,022.30 F	*843.80 FL
17	1		*RADIATOR	Bent/Punctured	1,488.50 F	*1,418.00 FL
18	1		*RADIATOR FAN ASSY	Not Necessary	650.00 F	*- FL
19	1		*FRONT SUPPORT PANEL	Repair	641.20 F	*- FL
20	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	305.50 F	*- FL
21	1		*FRONT FENDER N/S	Repair	671.10 F	*- FL
22	1		*FRONT FENDER INNERSHIELD N/S	Not Necessary	122.30 F	*- FL
23	1		*DRIVER AIR BAG	Activated	2,882.30 F	*1,425.30 FL
24	1		*DRIVER AIR BAG SPIRAL SENSOR	Activated	243.50 F	*181.20 FL
25	1		*PASSENGER AIR BAG	Activated	3,113.20 F	*2,055.30 FL
26	2		*SEATBELTS	Activated	1,500.00 F	*971.00 FL
27	2		*SEATBELTS BUCKLES	Not Necessary	300.00 F	*- FL
28	1		*AIR BAG ECU	Activated	866.20 F	*650.00 FL
29	1		*FRONT WINDSCREEN	Serviceable	1,455.30 F	*- FL
30	1		*FRONT LICENCE PLATE GARNISH	Distorted	106.30 F	*50.80 FL
31	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 F	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	22,092.40	11,593.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,318.78
Total Parts (\$\$)	22,092.40	9,275.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
4	TO DISMANTLE & REPLACING AIR BAG }	New	380.00	300.00
5	TO REPROGRAMME & RESET AIRBAG SYSTEM }	New	380.00	0.00
6	TO SPRAY RUST PROOFING	New	80.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	520.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	680.00
Gross Labour Cost (S\$)			3,740.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >