Weel and 15

TOTAL

161

Lump Sum / LEJ: / :

### Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Tuesday, 12 November 2019 2:05 PM

To:

motorsurvey@sg.msig-asia.com

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP SMRT AUTOMOTIVE SERVICES PTE

LTD, DOA: 05/11/2019, SG 6071T (TP VEHICLE), GBE 5952U (OI VEHICLE)

Attachments:

SG 6071T EST.pdf; SG 6071T GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SG 6071T at M/s SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 on 08/11/2019

Enclosed herewith a copy of TP's GIA and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	200000000000000000000000000000000000000
Owner ID Type:	Company
Owner ID: Vehicle Details	292D
Vehicle No.:	SG6071T
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	MAN
Vehicle Model:	A95
Primary Colour:	Multicolor
Manufacturing Year:	2018
Engine No.:	50351900665185
Chassis No.:	WMAA95ZZXKF008635
Maximum Power Output:	
Open Market Value:	\$417,622.00
Original Registration Date:	14 Jan 2019
First Registration Date:	14 Jan 2019
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$0.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 11 Nov 2019

OK

### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Mobile Number

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aroresara.	
	ACCIDENT STATEMENT
Date Of Report	07/11/2019 09:03
Date Of Accident	05/11/2019 11:10
Exact Location Of Accident	BKE TOWARDS PIE AFT DAIRY FARM RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SG6071T
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MAN
Model	MAN A95
Exact Purpose for which vehicle was being used at time of accident	t .
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	
Driver	
Name of Driver	ISPARAN A/L G MUNUSAMY
Passport No/FIN	F0568329R
Date Of Birth	27/01/1965
Occupation	OUTDOOR
Date Of Driving Pass	04/10/2010
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE

(LOCAL) +65-80000000

NOEMAIL

Address

NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

### General Information of the Accident

Type Of Accident Weather Conditions SIDE SWIPE

RAINING

Road Surface

WET

### Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

2

NO

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

18

### **Details of Police Action**

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

Police Report No 1/20191105/7022 I was driving a SMRT double decker bus (service number 966) along BKE lane 3 towards PIE, when a motorcycle with a pillion overtake my bus and collided with a lorry that was already stationary along the expressway road shoulder. The pillion of the motorcycle flew out of the motorcycle and landed onto the lane 3, which is the lane that am driving on. Because of this, I immediately did an emergency brake and did not run over the pillion rider who flew out onto the lane. Then, I went to check my passengers if they are okay, and no one mentioned that they are injured. I wanted to continue driving as no one was injured, but this time, I realised another pick up had hit the right side of my bus. I discover this only after I finished checking my passengers and wanted to move off.

### Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

PENDING DOWNLOAD

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

GBE5952U

Vehicle Make/Model/Colour

**Details Of Properties** 

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

LI GUANDE

NRIC/Passport Number

Page 2 of 5

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

MSIG INSURANCE (SINGAPORE) PTE. LTD.

# SKETCH PLAN

Eus/11/19/1011 81=xxd 29 60717

IMPORTANT NOTICE

This Form must be sampleted by the Policyholder and/or the Authorised Driver.

1. Please report correctly the details of the accident to speed up the claims process.

- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudlate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance

# Any false reporting may be referred to the Police for investigation.

- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insurer vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use
- processing, handling and/or dealing with my daims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;

Sketch Plan Pg. 1

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and 9
- agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes. my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or (0)
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
  - - the information so collected under (d) above may be shared / disclosed:

(0)

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.




(If driver is not the palicyhoider) Date & Time:

Name: NRIC/FIN No.:

Reporting Centri

Page 4 of 5

### Sketch Plan Pg. 2





SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4. Singapore 757705

1 . -

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 08/11/2019

User ID : BoonChewTay

and the literature of the second	Section A - Accident	Details		
Registration Number	SG6071T			
Case Reference Number	BUS/11/19/1011			
Registration Date	14/1/2019			
Company Type	SMRT Buses Ltd			
Make	A95 MAN E6			
Model	A95 MAN E6			
Name of Driver	Isparan A/L G Munusamy			
Type of Accident	Side Swipe			
Accident Date and Time	5/11/2019 11:10 AM			
Accident Reported Date and Time	6/11/2019 3:28 PM			
Is Surveyor Required?	No			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number				
Special Instruction to ARC,if any	SG6071T-RIGHT FRONT PORTI GBE5952U (TP) INSURED WITH	ON H MSIG		
Prepared Date and Time	8/11/2019 1:13 PM			
Chassis Number	WMAA95ZZXKF008635	WMAA95ZZXKF008635		
Mileage				
Work Shop				
	Section B - Summary of Rep	air Estimates		
	Section B - Summary of Rep	air Estimates  Adjusted by Surveyor, if applicable		
Summary of Repair Estimates  Total Labour Cost	Quotation from ARC	Adjusted by Surveyor, if applicable		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost	Quotation from ARC \$795,00	Adjusted by Surveyor, if app#cable \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Part Cost	Quotation from ARC \$795,00 \$602,00	Adjusted by Surveyor, if app#cable \$0,00 \$0,00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost	Quotation from ARC \$795,00 \$602,00 \$0.00	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST	Quotation from ARC \$795,00 \$602,00 \$0.00 \$0.00	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00		
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spraye Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days	Quotation from ARC \$795,00 \$602,00 \$0.00 \$1,397.00	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days	Quotation from ARC \$795,00 \$602,00 \$0.00 \$0.00 \$1,397,00 \$0.00	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total	Quotation from ARC \$795,00 \$602,00 \$0.00 \$0.00 \$1,397,00 \$0.00 3.0	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By	Quotation from ARC \$795,00 \$602,00 \$0.00 \$0.00 \$1,397,00 \$0.00 3.0 ARC Manager Team	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date	\$795,00 \$602,00 \$0.00 \$0.00 \$1,397.00 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	\$795,00 \$602,00 \$0.00 \$0.00 \$1,397.00 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by Surveyor, if app#cable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	\$795,00 \$602,00 \$0.00 \$0.00 \$1,397.00 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Sprae Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature  Remarks	Quotation from ARC \$795,00 \$602,00 \$0.00 \$0.00 \$1,397.00 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00  \$0.00		
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00 \$1.397.00 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00		



SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

Date Generated: 08/11/2019 : BoonChewTay

			Sec	tion D - Deta	alls of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope				Quotation f	rom AR	PLANT.		Adjusted by Surveyo	r, if applicable
TO REPAIR FR	ONT RH PORT	TION		\$795.00				530	
Total Labour		11315		\$795.00					
Part 2 - Spray	y Painting & F	Panel Beating Rela	ited Works			8 1			
Job Scope				Quotation f	rom ARC	I V		Adjusted by Surveyo	or, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			ND RESPRAY ABOVE	\$602,00				432.	
Total Spray Pa	inting & Panel	Beating		\$602,00					
Part 3 - Other	Costs - Acci	dent and Acciden	Repair Related Expe	nse					
Job Scope			Victoria de la constanta de la	Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Co	sts								
Part 4 - Spare	Parts / Mate	rial Usage	- F - La			The state of			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off	des en			l de la		MINIST
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Sun Pm (Lkk)

Lump Sum P/P Repuir.

After spray photo.

TP without Prejudice.

149X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 12/11/2019

User ID : CatherineLee

	Section A - Accident	Details
		事を言う。 <u>学、型ので、</u> 書のは、III A 1982 日本
Registration Number	SG6071T	
Case Reference Number	BUS/11/19/1011	
Registration Date	14/1/2019	
Company Type	SMRT Buses Ltd	
Make	A95 MAN E6	
Model	A95 MAN E6	
Name of Driver	Isparan A/L G Munusamy	
Type of Accident	Side Swipe	
Accident Date and Time	5/11/2019 11:10 AM	
Accident Reported Date and Time	6/11/2019 3:28 PM	
is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number	24104249	
Special Instruction to ARC, if any	SG6071T-RIGHT FRONT PORTI GBE5952U (TP) INSURED WIT	ION H MSIG
Prepared Date and Time	8/11/2019 1:13 PM	
Chassis Number	WMAA95ZZXKF008635	
Mileage		
SWEET SPECIFICATION	Section B - Summary of Rep	pair Estimates
Repair Completion Date and Time		
Repair Completion Date and Time  Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost	Quotation from ARC \$795.00	Adjusted by Surveyor, if applicable \$530.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost	Quotation from ARC \$795.00 \$602.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Cost  Total Spare Part Cost	Quotation from ARC \$795.00 \$602.00 \$0.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00 \$1,397.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00 \$962.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST	Quotation from ARC   \$795.00   \$602.00   \$0.00   \$0.00   \$1,397.00   \$0.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00 \$1,397.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00 2.0
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days	Quotation from ARC   \$795.00   \$602.00   \$0.00   \$0.00   \$1,397.00   \$0.00	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00
Work Shop Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost  TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC   \$795.00   \$602.00   \$0.00   \$0.00   \$1,397.00   \$0.00   3.0	Adjusted by Surveyor, if applicable \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00 2.0
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By	Quotation from ARC   \$795.00   \$602.00   \$0.00   \$0.00   \$1,397.00   \$0.00   3.0   Boon Chew Tay	Adjusted by Surveyor, if applicable  \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00 2.0 Sun Pin (LKK)
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date	Quotation from ARC     \$795.00     \$602.00     \$0.00     \$1,397.00     \$0.00     \$3.0     Boon Chew Tay     \$08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable  \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00 2.0 Sun Pin (LKK)
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	Quotation from ARC     \$795.00     \$602.00     \$0.00     \$1,397.00     \$0.00     \$3.0     Boon Chew Tay     \$08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$530,00 \$432,00 \$0.00 \$0.00 \$962,00 \$0.00 2.0 Sun Pin (LKK) 08/11/2019 3:36 PM
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature  Remarks	Quotation from ARC     \$795.00     \$602.00     \$0.00     \$0.00     \$0.00     \$3.0     Boon Chew Tay     \$08/11/2019 1:18 PM     \$08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable \$530,00 \$432,00 \$0.00 \$0.00 \$962,00 \$0.00 2.0 Sun Pin (LKK) 08/11/2019 3:36 PM
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	Quotation from ARC     \$795.00     \$602.00     \$0.00     \$0.00     \$0.00     \$3.0     Boon Chew Tay     \$08/11/2019 1:18 PM     \$08/11/2019 1:18 PM	Adjusted by Surveyor, if applicable  \$530.00 \$432.00 \$0.00 \$0.00 \$962.00 \$0.00 2.0 Sun Pin (LKK) 08/11/2019 3:36 PM



SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number : 68662672

Date Generated : 12/11/2019

User ID : CatherineLee

OUR DATE LA			Sec	tion D - Deta	ils of Repair E	stimates		ALL STANDARDS TO	THE PLANTS
Part 1 - Labor	ır Works					- 45 10			
Job Scope				Quotation fo	rom AR			Adjusted by Surveyo	or, if applicable
TO REPAIR FR	ONT RH PORT	TION	AND DESCRIPTION OF THE PERSON	\$795.00				\$530.00	
Total Labour				\$795.00				\$530.00	
Part 2 - Spray	Painting & P	Panel Beating Rela	ited Works					A STATE OF	THE TABLE
Job Scope				Quotation f	rom ARC			Adjusted by Surveyo	or, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$602.00				\$432.00	
Total Spray Pa		Beating		\$602.00				\$432.00	
Part 3 - Other	Costs - Acci	dent and Acciden	t Repair Related Expe	nse			ST VIVE	THE PARTY OF THE	
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Co	sts								
Part 4 - Spare	Parts / Mater	rial Usage		Marian I		A BANDE			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off						uping beri
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total	100								
OCT (COLOR )									+



SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number: 68652623

Accident Reporting Number : 68552572

Date Generalod : 08/11/2019

User D : BoonChewTay

MATERIAL SEPTIMES AND	Section A - Accide	nt Details	
Registration Number	SG6071T	THE PERSON NAMED AND ADDRESS OF THE PERSON	AND THE PROPERTY OF THE PROPER
Case Reference Number	BUS/11/19/1011		
Registration Date	14/1/2019		
Company Type	SMRT Buses Ltd		
Make	A95 MAN E6		
Model	A95 MAN E6		
Name of Driver	Isparan A/L G Munusamy		
Type of Accident	Side Swipe		
Accident Date and Time	5/11/2019 11:10 AM		
Accident Reported Date and Time	5/11/2019 3:28 PM		
Is Surveyor Required?	No		W-10-10-10-10-10-10-10-10-10-10-10-10-10-
Survey by			
Vehicle is Towed Back?	No		XIII 7
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC/II any	SG6071T-RIGHT FRONT PO GBE5952U (TP) INSURED I	RTION WITH MSIG	
Prepared Date and Time	8/11/2019 1:13 PM		
Chassis Number	WMAA95ZZXKF008535		
Miloage			
Repair Completion Date and Time	Section B - Summary of F		
Repair Completion Date and Time	Section B - Summary of F	企業的企業的 1	
Repair Completion Date and Time	Quotation from ARC	Adjusted by S	1.18K-0.7 起來意思"你,例
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost	Quotation from ARC \$785,00	Adjusted by S	1.18K-0.7 起來意思"你,例
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cost Total Spray Cost	Quotation from ARC \$795,00 \$602,00	Adjusted by S \$0,00 \$0,00	1.18K-0.7 起來無疑"你,例
Repair Completion Date and Time Summary of Repair Estimates Total Labour Cosl Total Spray Cost Total Spare Part Cost	Quotation from ARC \$785,00 \$602,00 \$0.00	Adjusted by S \$0.00 \$0.00 \$0.00	1186人。广泛水道是"在"的
Repair Completion Date and Time Summary of Repair Estimatos  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost	Quotation from ARC \$785,00 \$602,00 \$0.00 \$0.00	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00	1.18K-0.7 起來無疑"你,例
Repair Completion Date and Time Summary of Repair Estimatos  Total Labour Cosl Total Spray Cost Total Spare Part Cost Total Other Cosl TOTAL COST	Quotation from ARC \$795,09 \$602,00 \$0.00 \$0,00 \$1,397,08	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	1.18K-0.7 起來無疑"你,例
Repair Completion Date and Time Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00 \$1,397.06 \$6.00	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00	1.18K-0.7 起來無疑"你,例
Repair Completion Date and Time Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days	Quotation from ARC \$795.00 \$602.00 \$0.00 \$0.00 \$1,397.00 \$6.00 3.9	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	1.18K-0.7 起來無疑"你,例
Repair Completion Date and Time Summary of Repair Estimates  Total Labour Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepaced / Adjusted By	Quotation from ARC \$795.00 \$602.00 \$0.00 \$1,397.00 \$6,00 3.0 ARC Manager Team	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	1186人。广泛水道是"在"的
Repair Completion Date and Time Summary of Repair Estimates  Total Labour Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$795,09 \$602,00 \$0.00 \$0.00 \$1,397.09 \$6,00 3.9 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	1186人。广泛水道是"在"的
Repair Completion Date and Time Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepaced / Adjusted By	Quotation from ARC \$795.00 \$602.00 \$0.00 \$1,397.00 \$6,00 3.0 ARC Manager Team	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	1.186人。广泛水流域。12.30
Summary of Repair Estimates  Total Labour Cosl Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepaced / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$795,09 \$602,00 \$0.00 \$0.00 \$1,397.09 \$6,00 3.9 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	计输入分类外距离 "在"
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prapaced / Adjusted By  ARC / Surveyor Sign Off Date  Signature  Remarks	Quotation from ARC \$785.00 \$602.00 \$50.00 \$0.00 \$1,397.08 \$0.00 3.0 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Surveyor, II app@cable
Repair Completion Date and Time  Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spray Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prapaced / Adjusted By  ARC / Surveyor Sign Off Date  Signature  Remarks	Quotation from ARC  \$795,00 \$602,00 \$0,00 \$0,00 \$1,397,00 \$60,00 3.9 ARC Manager Team 08/11/2019 1:18 PM	Adjusted by S \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Surveyor, II applicable



SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singspore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623

Date Generaled : 08/11/2019

A THE			Sec	tion D - Deta	ils of Repair E	stimates	SULP CAR		And the Annual Con-	
art 1 - Labou	r Works	DESCRIPTION OF								
Job Scope	-51511			Quotation fr	om AR	E 1931A		Adjusted by Surveyo	r, if applicable	
TO REPAIR FR	ONT RH PORT	ION	AND THE REAL PROPERTY.	\$795.00				530	HON	
Total Labour				\$795.00					NAT ALL	
Part 2 - Spray	Painting & P	anel Beating Rela	ted Works		A STATE OF THE STA		HEAR		FEBRUAR VIII	
Job Scope				Quotation fr	om ARC			Adjusted by Surveyo	r, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$602.00				432.		
Total Spray Pa		Beating		5602,00						
Part 3 - Other	Costs - Acci	dent and Accident	Repair Related Expe	nse	ATT A STA		5 20		30000=17) ) = (	
Job Scope	0 3 0 5 15	C I COSA ESS		Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Co	sts			1						
Part 4 - Spare	Parts / Mater	rial Usage	ON THE RESERVE		THE RESERVE	SHEET PARTY			CACHETER AND	
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
Total										
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off	NO CONTESS	1000		W. Carlotte		1	
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total	100000		polyment that the same				-			

Repair days - 2 days.

Sun Pm (Lkk)

Lump Sum P/P Repuir.

Before spray photo.

TP without Prejudice.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	9	Adj Submitted	Ins Auth'ed	Status	
Main	06 Nov 2019		13 Nov 2019 09:39 Edit Adj Rpt	S\$962.00 Edit Estin	1	S\$962.00 View Rpt		Pending fo Report Cancel Case	
,	Main	R	eference	Cla	sim Detai	ls	Documents		Show All
CLAIM SUI	BFOLDER DE	TAILS				[Created	by insurer]		
Insured:	FOOD FR	ESH PTE LTD, C	o. Reg. No.: 201422	2538E, Ema	il: hello@f	oodfresh.com.s	sg		
Main Claimant:	SMRT BU	SES LTD, Co. R	eg. No.: 198202292	D					
Vehicle Reg. No.:	SG6071	т			Date of Lo		19 11:00 - :59 and <b>22</b> Days From	LTA Reg Date (	Man Yr)]
Claim Type:	TP / 610	663			Policy/Cov Note No.:		MKC (Comprehensi 25/01/2019 - 24/0		
Vehicle Reg. No. (Insured):		GBE5952U				Policy No. (Claimant):			
					Excess:	S\$500.00			
Repairer:	SMRT Aut	tomotive Service	s Pte Ltd (Woodla	ands) 60 Woo	odlands In	dustrial Park E	4, 757705 Woodlan	ds - Tel: 686626	28
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 6	827 7888	[Handled by	Irene Tan Gek I	<b>ng</b> - 6594 2541]	
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel: 62	56-3561 [	Handled b	y OI SUN PIN	] [Imm.Advi	ce due 14/11,	/2019]
Driver/Custo dian (Insured):	LI GUANG	DE () , NRIC: G	8049002Q, Tel: +	6587404012	Email:				
Adj Asg. Remarks:	Liab: uncle	ear. Direct Survey	by LKK Auto Consu	Itants on 08/	11/2019.				
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w All Compo	se Case Ma
There are no	o mail for this	case.							
ALL ASSO	CIATED TAS	iks =				View All	Search Tasks C	reate New Task	Complet
Due Date	Priority	Type Task	Group Subject	ct Handle	r As	signed By	Completed On	Created O	n Done

### Claim Documents

\*SG6071T (610663) [GBE5952U] TP SMRT BUSES LTD Nov 5 2019 11:00AM [FOOD FRESH PTE LTD] **SMRT Automotive Services Pte Ltd** 

Pho	tos/Images		3 per pa	age V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/19 17:06	General View	0	Load JPG	$\mathbf{V}$
2	15/11/19 17:06	General View	0	Load JPG	V
3	15/11/19 17:06	General View	0	Load JPG	V
4	15/11/19 17:06	General View	6	Load JPG	$\mathbf{Z}$
5	15/11/19 17:06	General View	0	Load JPG	V
6	15/11/19 17:06	General View	0	Load JPG	V
7	15/11/19 17:06	General View	0	Load JPG	V
8	15/11/19 17:06	General View	0	Load JPG	V
9	15/11/19 17:06	General View	0	Load JPG	V
10	15/11/19 17:06	General View	0	Load JPG	V
11	15/11/19 17:06	General View	0	Load JPG	V
12	15/11/19 17:06	General View	0	Load JPG	V
13	15/11/19 17:06	General View	0	Load JPG	V
14	15/11/19 17:06	General View	0	Load JPG	V
15	15/11/19 17:06	General View	0	Load JPG	V
16	15/11/19 17:06	General View	0	Load JPG	V
17	15/11/19 17:06	General View	0	Load JPG	V
18	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
19	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
20	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
21	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
22	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
23	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
24	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
25	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
26	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
27	15/11/19 17:07	Reinspection Photo	0	Load JPG	V
	,,,,,,,,,,	1			
Doc	cumentation		1 per p	age 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/11/19 09:33	REPAIR EST	0	Load PDF	

### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19020002/QTF3E2

Date:

20/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29069258MKC

Claimant Vehicle No :

SG6071T

Insured Vehicle No:

GBE5952U

Date of Loss:

05/11/2019

Nature of Claim:

TP

Claim No: 610663

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SG6071T

Make & Model:

MAN A95, 10.5 D (A)

Engine No:

50351900665185

Reg. Date:

14/01/2019 (Man. Year: 2018) Multi-colour Chassis No:

WMAA95ZZXKF008635

Colour: Engine Capacity:

10518 cc

Odometer:

109288 km

Market Value/New Co

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

tion:

Pre-accident Condition:

....

CONDITION OF TYRES

Front Tyre Size:

275/70 R22.5

Rear Tyre Size:

275/70 R22.5

Front Left Side: Front Right Side: Firenza 5 mm

Rear Left Side: Rear Right Side: Firenza 5 mm Firenza 5 mm

Front Right Side: Firenza 5 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,397.00	962.00	435.00	31.14
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	1,397.00	962.00	435.00	31.14

INSPECTION

Date of Assignment:

13/11/2019

Date Inspected:

08/11/2019 Inspected At:

SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair:

2.0 days

Adjuster: OI SUN PIN Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 20 Nov 2019)

Parts:

N/A

MAN A95 10.5 D (A) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SG6071T)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPAIR FRONT RH PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	602.00	432.00
	Gross Lab	Gross Labour Cost (S\$)		962.00
	Report was unsubmitted du	uring this print-out		

< END OF ESTIMATES >