

ASS. REC. BY: Sun Pin

REF:

NTUC
NS/INC 1902006/Q5F327

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of


Insured: SMN 4054RPolicy No. 511702263 (07/08/2019 - 06/08/2020)Claims No. MT/1070567-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG1733AYr Regn: 01/Sep/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

10518Make: MAN NL 320F (A2-2)c.c. 10988Colour: Multicolour

A/C: Insured / Std / NI / NA

Sp. Reading 288368

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WMAA22223F7062906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275 / 70 R22.5R: 275 / 70 R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenz9

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 07/11/2019D.O.I. 08/11/2019

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front Left

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMN 4054R : X

SG1 1733A : X

(\$541.00 Red - 44%)

Confirm with Catherine

\$700 @ 1 days

L/S Repair

Date/Time, File Pass to?

06/12/19☐ : Prell. Report☒ : Final Report1) Typist

Date/Time, File Return to?

2)

Days Of Repair: 1Resurvey No. of Trip: 1

Survey Fee:

160

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

160Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Rep. Format :

Lump Sum / L.P. / L.C.

\$700/- 45

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5111702263		ONESTO LEASING PTE LTD	201814843R	GPC	drive CLASSIC	SMN4054R	SMN4054R	07/08/2019	06/08/2020

TP Claims against NTUC Income: Follow-Through Survey

Date : 05/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1029721-002	SMRT TAXIS PTE LTD	SHC 4115R	SHC 6728J	26/01/2019	23:00	\$ 24,955.87	\$ 8,900.00
2	MT/1070567-002	SMRT BUSES PTE LTD	SG 1733A	SMN 4054R	07/11/2019	10:45	\$ 1,241.00	\$ 700.00

Claim received from LKK Auto

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SG1733A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2015
Engine No.:	50340971954086
Chassis No.:	WMAA22ZZ3F7002906
Maximum Power Output:	-
Open Market Value:	\$238,661.00
Original Registration Date:	01 Sep 2016
First Registration Date:	01 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 11 Nov 2019

OK

Shirley Hiew (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Monday, 2 December 2019 10:14 am
To: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: RE: Finalisation - SG1733A (BUS/11/19/1015) - NTUC

Dear Catherine,

Confirm the finalize amount \$700 @ 1 Repair day under lump sum repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [<mailto:catherineleesc@smrt.com.sg>]
Sent: Tuesday, 26 November, 2019 10:59 AM
To: Oi Sun Pin (LKK Auto); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: Finalisation - SG1733A (BUS/11/19/1015) - NTUC

Hi Sun Pin,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$700/- @ 1 working day under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2019 13:13
Date Of Accident	07/11/2019 10:45
Exact Location Of Accident	ALONG CTE BEF BALESTIER RD EXIT (TOWARDS SHENTON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG1733A
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN NL320F (A22)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	MUHAMAD NASRAN BIN JAFAR
NRIC No	S8008758F
Date Of Birth	26/03/1980
Occupation	OUTDOOR
Date Of Driving Pass	24/06/2015
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	11

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was traveling straight at the left most lane of CTE. Suddenly a private car (SMN4054R) came out from the slip road without stopping and cut into my lane. I could not stop my bus in time and the left front portion of the bus had collided into the right rear portion of the private car. No injuries reported. That's all..

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN4054R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NENA CHUA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

SKETCH PLAN

SG 1733 H
PAX-11
6/4/19/1015

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information to collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulator's, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre/Workshop's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

Along CTE bel. Celestial Rd
and Edwards Street (just
Terminal) :

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.DECLARATION US

I/We declare ^{that} the foregoing particulars are true in every respect.

Policyholder's Signature: _____
Date & Time: _____

Driver's Signature _____
(if driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature _____
Name: _____
NARC/PTM No.: _____



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 08/11/2019

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG1733A
Case Reference Number	BUS/11/19/1015
Registration Date	1/9/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Muhamad Nasran Bin Jafar
Type of Accident	Side Swipe
Accident Date and Time	7/11/2019 10:45 AM
Accident Reported Date and Time	7/11/2019 1:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1733A-LEFT REAR PORTION SMN4054R (TP) INSURED WITH NTUC
Prepared Date and Time	8/11/2019 1:29 PM
Chassis Number	WMAA22ZZ3F7002906
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,241.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	08/11/2019 1:32 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/11/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00	354
Total Spray Painting & Panel Beating	\$446.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER, HEADLAMP: FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
Total					\$974.70		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

[Signature]
12/11/19 Repair days - 1 day.

Sun Pin (446)

TP without prejudice.

Lump Sum Repair.

Take After spray photo.

2719.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Date:

530
+ 354
884

884
- 20%
707.2

4/5 = 700

Section A - Accident Details	
Registration Number	SG1733A
Case Reference Number	BUS/11/19/1015
Registration Date	1/9/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Muhamad Nasran Bin Jafar
Type of Accident	Side Swipe
Accident Date and Time	7/11/2019 10:45 AM
Accident Reported Date and Time	7/11/2019 1:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104278
Special Instruction to ARC, if any	SG1733A-LEFT FRONT PORTION SMN4054R (TP) INSURED WITH NTUC
Prepared Date and Time	8/11/2019 1:29 PM
Chassis Number	WMAA22Z23F7002906
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$446.00	\$354.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	-\$176.80
TOTAL COST	\$1,241.00	\$707.20
Lump Sum Total	\$0.00	\$700.00
Number of Repair Days	2	1
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	08/11/2019 1:32 PM	08/11/2019 3:38 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$795.00			\$530.00				
Total Labour		\$795.00			\$530.00				
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$446.00			\$354.00				
Total Spray Painting & Panel Beating		\$446.00			\$354.00				
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Lump Sum Adjustment by Surveyor		\$0.00			-\$176.80				
Total Other Costs		\$0.00			(\$176.80)				
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW284	COVER HEADLAMP FRT.L 1.00	1.00	\$974.70	100.00	\$0.00	Repair	Repair
H.FOR MAN A22 BUS					\$974.70		\$0.00		
Total					\$974.70		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19020006/Qsf3e2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 06-12-2019	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMN 4054R	Veh. Inspected	SG 1733A
Policy No.	5111702263	Coverage (\$)	0.00
Claim No.	MT/1070567-002	Excess (\$)	0.00
Assign From		Assign Date	08/11/2019
2. Vehicle Particulars & Condition			
Make & Model	MAN NL 320F (A22)	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA22ZZ3F7002906	Colour	MULTI COLOUR
Odometer	288368	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
R/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
L/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/11/2019	Inspection Date	08/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1733A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	COVER, HEADLAMP:FRT, LH, FOR MAN A22 BUS		974.70	-
			974.70	-
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, HEADLAMP:FRT, LH, FOR MAN A22 BUS.		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		446.00	354.00
			1,241.00	884.00
GRAND TOTAL			2,215.70	884.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				700.00

Report Ref No. NS/INC19020006/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.