

22/03/2002

ASS. REC. BY:

REF:

CS3/C7119020018/HCF322

Special Instruction:

Surveyor: Hock Dnn

ASSIGNMENT (Office)

From (Person):

Chong Dnn Sn

of

C71

Date/Time:

11.11.19 3:47p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 3338B

Insured:

SGA 7227U

at Workshop m/s

Nio Auto

Tel:

of

53 Ubi Ave 1 #05-44

Policy No:

Claim No:

SNM19D 205132

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29.10.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

12.11.19 11:16 am

Person Contacted:

MS N20

Vehicle IN OUT

Date/Time

Action/Instruction

(X) Estimate

SGA 7227U NSA/INC13014745/21 DCA 28/06/2015

SLL 3338B X

Dismantle: 13/11/2019

ASS. REC. BY:

REF:

C71

PRS

## ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SLL 3338 B

Yr Regn: 22/05/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL 3338 B

at Workshop m/s

NEO Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Tyre Size:

F:

245/35/R19

R:

275/30/R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

HAB/LEAD

R/Bal.

5 mm

700

R/Bal.

5 mm

L/Bal.

5 mm

700

L/Bal.

5 mm

D.O.A.

29/10/19

D.O.I.

12/11/19

Survey held at

NEO Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Page 76 - 75K 3-4K

\* SLL 3338 B

PRS use

MV - 87000

PV - 2825

NV - 58100

27/12/2019

Date/Time, File, Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

RECEIVED 31 DEC 2019

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

190

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

190

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wheel and (\$

Rep. Form:

PRS

Lump Sum / L.P. / C.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		23 Dec 2019 10:41 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:									
Main Claimant:	<b>SEE TERNG HUEI</b> , ID: S8838155F								
Vehicle Reg. No.:	<b>SLL3338B</b>	Date of Loss:	29/10/2019 13:00 - :59						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SGQ7227U</b>	Policy No. (Claimant):	GA273282						
		Excess:	S\$0.00						
Repairer:	<b>Neo Automotive Pte Ltd (HQ)</b> 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6880 4888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 03/01/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 11 November 2019 3:47 PM  
**To:** Jeffrey Tay; pamela@yoga-legal.com  
**Cc:** 'assignments'  
**Subject:** RE: OUR REF: SNM19D205132-SGQ7227U-CBS- PRS Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019 @ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI  
**Sent:** Monday, November 11, 2019 3:33 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; pamela@yoga-legal.com  
**Cc:** Chee So Chow <sochow.chee@sg.cntaiping.com>  
**Subject:** OUR REF: SNM19D205132-SGQ7227U-CBS- PRS Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019 @ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

Dear Boon Sen,

Please conduct PRS for SLL3338B.

Note : officer in charge – Boon Sen 63896171.

Neo Automotive  
53 Ubi Ave 1  
#05-40

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Pamela Pamela [<mailto:pamela@yoga-legal.com>]  
**Sent:** Monday, 11 November, 2019 12:31 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Winnie Phee <[winnie@yoga-legal.com](mailto:winnie@yoga-legal.com)>  
**Subject:** Pre-repair inspection for Non Injury Motor Accident Cases Road Traffic Accident Involving Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019 @ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

Dear Sir/Mdm,

We enclosed herewith our letter (Pre-repair Inspection) dated 11 November 2019 for your attention and information.

Thank you.

Regards,

Pamela

**M/s C. YOGARAJAH LLC**

883 North Bridge Road

#11-03 Southbank

Singapore 198785

Tel : (65) 6292 5838

Fax : (65) 6292 5938

(UEN No. 201333127N) (GST Reg No. 201333127N)

**Important Note:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this

message and its attachments immediately and contact us at (65) 6292 5838, if you have received this message in error. Thank you.

---












This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>








---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 11 November 2019 4:19 PM  
**To:** Admin-D (LKKAuto); Jeffrey Tay  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D205132-SGQ7227U-CBS- PRS Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019 @ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

PRI - SLL3338B.pdf - Adobe Acrobat

File Edit View Window Help

Create ▾ |           

1 / 6 |      90.1% ▾ |  

Too

**Ong Yen Ping Jenny**  
**c/o China Taiping Insurance (Singapore) Pte Ltd**  
(Motor Claims Department)  
3 Anson Rd  
#16-00 Springleaf Tower  
Singapore 079909

[By Email](#)

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT INVOLVING ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLL 3338B & SGQ 7227U ON 29.10.2019 @ 13:10HRS ALONG PUNGGOL DRIVE CARPARK BLOCK 638 ENTRANCE**


We are instructed by See Terng Huei to notify you of a road traffic accident on 29.10.2019 at 13:10hrs along location involving our client's customer's vehicle registration number SLL 3338B & SGQ 7227U driven by you at the material time. A copy of accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client repairs the damaged vehicle, please let us know within 2 working days of your receipt whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive your response within the stipulated timeline, our client shall proceed to repair the vehicle at their reference to you.

At the same time, our proposed list of surveyors is appended as below:-

1. Lee Kok Weng
2. Seah Kwang Boon
3. Amas Ong Poh Meng
4. Louis Ng

Yours faithfully,

  
**C. Yogarajah LLC**  
Enc

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Admin-D (LKKAuto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]

**Sent:** Monday, November 11, 2019 3:56 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>

**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** RE: OUR REF: SNM19D205132-SGQ7227U-CBS- PRS Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019  
@ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

Dear Boon Sen,

Thank you for the assignment.

Kindly assist to provide the workshop detail.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Monday, 11 November, 2019 3:47 PM

**To:** Jeffrey Tay <[Jeffrey.Tay@sg.cntaiping.com](mailto:Jeffrey.Tay@sg.cntaiping.com)>; [pamela@yoga-legal.com](mailto:pamela@yoga-legal.com)

**Cc:** 'assignments' <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** RE: OUR REF: SNM19D205132-SGQ7227U-CBS- PRS Motor Vehicles SLL 3338B & SGQ 7227U On 29.10.2019  
@ 13:10hrs along Punggol Drive Carpark Block 638 Entrance

**WITHOUT PREJUDICE**

**SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	155F
Vehicle Details	
Vehicle No.:	SLL3338B
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	335I A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	N54B30A08506437
Chassis No.:	WBAWB72070P052241
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$48,027.00
Original Registration Date:	22 May 2007
First Registration Date:	20 Oct 2008
Transfer Count:	4
Actual ARF Paid:	\$48,027.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$28,825.00
<b>Total Rebate Amount:</b>	<b>\$28,825.00</b>

The information contained herein is correct as at 14 Nov 2019

OK



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



bmw 335

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼



Home » Used Cars » Direct Owners » BMW 3 Series 335i (COE till 07/2029)

## BMW 3 Series 335i (COE till 07/2029)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT

<b>Price</b>	\$90,888		
<b>Depreciation</b> ⓘ	\$9,360 /yr	<b>Reg Date</b>	31-Jul-2009 (9yrs 8mths 16days COE left)
<b>Mileage</b>	68,000 km (6.6k /yr)	<b>Manufactured</b> ⓘ	2009
<b>Road Tax</b> ⓘ	\$2,362 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$41,663 as of today (change)	<b>OMV</b> ⓘ	\$49,018
<b>COE</b> ⓘ	\$42,885	<b>ARF</b> ⓘ	\$49,018
<b>Engine Cap</b>	2,979 cc	<b>Power</b>	225.0 kW (301 bhp)
<b>Curb Weight</b> ⓘ	1,825 kg	<b>No. of Owners</b> ⓘ	More than 6
<b>Type of Vehicle</b>	Luxury Sedan		

100% I  
PAPERW  
SUPPORT  
BOTH B  
& SELLE

Preferred Viewing Area

## Features

View specs of the BMW 3 Series Convertible (2007-2013)

## Category

COE Car, Direct Owner Sale, Low Mileage Car

## Status

Available

## Resources



## Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



## Car Valuation - Free

Find out the market value of your existing car for free. Get started

DOA 29/10/19

mv - 87000  
pv - 28225  
NL - 58175

Subaru → 94k  
Mazda → 8700  
8700 in = 725  
87000

Shortlist

Compare

Add nc

Report Error

More Actions


Posted on: 11-Nov-2019 | Last Updated on: 11-Nov-2019

## Upfront Payment

<b>Transfer Fee</b> ⓘ	\$25	
<b>Down Payment</b> ⓘ	\$27,266 (change)	Maximum 70% Loan
<b>1st Instalment</b> ⓘ	\$956	Based on 3.75% interest rate
<b>Insurance</b>	\$662 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & POGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	
<b>Tot</b>	\$28,909	Check with seller for exact figure

» more Financial info

Powered by



## Seller Information

<b>Contact Person(s)</b>	Tony
<b>Contact No.</b>	81387987
<b>Enquiry</b>	<input checked="" type="checkbox"/> Contact Seller

## ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer

GET HELP WITH  
PAPERWORK

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agree and we'll help with **Car Loans, Insurance, Pay & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/10/2019 15:55
Date Of Accident	29/10/2019 13:10
Exact Location Of Accident	PUNGGOL DR C/P BLK 638 ENTRANCE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3338B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEE TERNG HUEI
NRIC No	S8838155F
Email Address	TERNGHUEI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-83823368
Alternative Phone No	OTHERS-83823368

### Vehicle Particulars

Manufacturer	BMW
Model	335I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA273282
Cover Note Number	

### Driver

Name of Driver	SEE TERNG HUEI
NRIC No	S8838155F
Date Of Birth	08/10/1988
Occupation	INDOOR
Date Of Driving Pass	19/01/2007
Driving Experience	12 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83823368
Fax Number	
Contact Number	OTHERS-83823368
EMail Address	TERNGHUEI@HOTMAIL.COM

Address	BLK 102 SIMEI ST 1 #09-908
Postcode	520102
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI N.P.C
Police Station Address	ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ7227U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name SEE TERNG HUEI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLL3338B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

30/10/19.

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

SKETCH PLAN *outside*

*inside*

*Carpark entrance -*

**Vehicle**  
A - SL23338 B  
B - SGQ7227U

**Legend**  
 Vehicle  
 Motorcycle

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When exiting the carpark and in my lane, the B car directly accelerated into the carpark and bang into my car.

I was stationary at the moment when the B car bang into me. I saw the B car accelerating into the carpark straight ahead therefore i stopped my car but seconds later, the B car just bang into me. After the bang, we got out of the car to the photos.

She admitted that it was her fault and said that she was blinded by the brightness of the sun and when she entered the carpark, she could not see.

She mentioned if private settlement was possible but i suggested for insurance claim as the amount might be more than what she could offer.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

30/10/19.

## Common Statement

ternghuei@hotmail.com

## ACCIDENT STATEMENT (Part I)

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims

Entrance

1 Date of accident Time 29/10/19 13:00 2 Exact location of accident Punggol Pr C/P B1K 638

3 Injuries even if slight No ☒ Yes ☐

4 Material damage To vehicles other than vehicles A and B No ☐ Yes ☐ To objects other than vehicles No ☐ Yes ☐

5 Witness' name, address and tel no. (to be underlined if he/she is passenger in vehicle A or vehicle B)

Vehicle Video Camera Available No ☒ Yes ☐

Registration No. (VEHICLE A) SLL3338B

6 Insured / policyholder (see insurance cert.)

Name SLL Terng Huei

Address B/102 Simet St #09-902 (500102)

NRIC / Passport no. S0838155

Tel no. (from 9am till 5pm) 8382 3368

HP 8382 3368

7 Vehicle Make, type BMW 335i

8 Insurance company AXA ☒ C ☐ TPFT ☐ TPO

Does the policy cover damage to vehicle A? No ☐ Yes ☒

Policy No. GA573202

9 Driver ☒ State as Owner

Name (capital letters)

NRIC / Passport no.

Class of licence

HP

Gender Male ☐ Female ☐

## 12 CIRCUMSTANCES

Put a cross (X) in each of the relevant boxes applicable to your vehicle

- ☐ Clean Collision  
☐ Collided into Bicycle  
☐ Collided into Motorcycle  
☐ Collided into Parked Vehicle  
☐ Collided into Pedestrian  
☐ Collided into Property  
☐ Collision - Change/Cross Lane  
☐ Collision - Cross Junction  
☐ Collision - Head on Collision  
☐ Collision - Head to Rear  
☐ Collision - Major/Minor Hit  
☐ Collision - Opening Door of Vehicle  
☐ Collision - Roundabout  
☐ Collision - U-Turn  
☐ Drunk Driving / Drug Influence  
☐ Fire, Explosion or Lightning  
☐ Flood  
☐ Hit and Run / Violation / Damaged whilst Parked  
☐ Hit by Fallen Tree / Other Objects  
☐ No Collision  
☐ Side Swipe  
☐ Theft

Registration No. (VEHICLE B) JGQ 7227

6 Insured / policyholder (see insurance cert.)

Name

Address

NRIC / Passport no.

Tel no. (from 9am till 5pm)

HP

7 Vehicle Make, type

8 Insurance company ☐ C ☐ TPFT ☐ TPO

Does the policy cover damage to vehicle B? No ☐ Yes ☐

Policy No. (if available)

9 Driver (See driving licence) (if different from insured B above)

Name (capital letters)

NRIC / Passport no.


Class of licence

HP

Gender Male ☐ Female ☐

State TOTAL number of boxes marked with a cross

10 Indicate the point of initial impact with an arrow (→)




13 Sketch of accident when impact occurred

Please indicate: 1. layout of the road - 2. the direction of vehicles A and B with arrows - 3. their positions at the time of impact - 4. the road signs - 5. names of the streets or roads

REFER TO ATTACHED

10 Indicate the point of initial impact with an arrow (→)



11 Visible damage to vehicle A

11 Visible damage to vehicle B

14 My remarks

15 Signatures of drivers

14 My remarks

A

B

In the event of injuries or in the event of damage to property other than to vehicles A and B, give information overleaf

Do not alter anything in the statement after signing. Subsequently, each driver should take one copy.

For insured's individual statement (Part II) see overleaf →

## Police report



**SINGAPORE  
POLICE FORCE**



T/20191030/2176

1 of 3

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No. T/20191030/2176

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/10/2019 19:52		Vide Report No.:		Station Diary No.: 185	
<b>Informant's Particulars</b>					
Name of Informant: SEE TERNG HUEI			Address: APT BLK 102 SIMEI STREET 1 #09-908 SINGAPORE 520102		
ID Type / ID No.: NRIC NO / S8838155F			Contact No.: Home/Office Mobile 83823368		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 08/10/1988	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: CONSTRUCTION SECTOR			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/10/2019 13:10	Type of Location Car Park
Location: Along Road 1 PUNGOL DRIVE  MSCP OF BLK 638 PUNGOL DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGQ7227U	Car	TOYOTA	PRIUS ALPHA HYBRID 1.8S CVT		Slightly Damaged	0
SLL3338B	Car	BMW	335I A	Grey	Slightly Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

Police report



**SINGAPORE  
POLICE FORCE**



T/20191030/2176

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 3

Report No. T/20191030/2176

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLL3338B	AXA INSURANCE SINGAPORE PTE LTD	GA273282	20/10/2019	19/10/2020

**Brief Details.**

On 29/10/2019 at about 1310hrs, I was driving my vehicle (SLL3338B) out of the MSCP located at Blk 638 Punggol Drive. I spotted one incoming vehicle (SGQ7227U) driving into the MSCP hence my vehicle came to a complete stop.

Out of a sudden, one vehicle (SGQ7227U) accelerated into the entrance of the MSCP. The vehicle cut into the exit lane that my vehicle came to a complete stop and hit head on to my vehicle.

Both of us came out of our vehicle and exchanged particulars. The driver is namely Ong Yen Ping Jenny (S7504902A). She admitted that it's her mistake.

On 30/10/2019 afternoon, I felt pain on my neck and shoulder. I went to see a doctor at Well Family Clinic & Surgery and was given 3 days of medical leave. The doc tor told me that I suffered minor sprain on my neck.

There is in-car camera installed in my vehicle but it's not recording.

Police report



**SINGAPORE  
POLICE FORCE**



T/20191030/2176

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

3 of 3

Report No. T/20191030/2176

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report. D / Sgt 3 TAN WEN HONG	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/10/2019 19:52
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	



































## ...CLAIM SUBFOLDER...(Pending for Survey Report)




















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2020 12:08		23 Dec 2019 10:41 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>SEE TERNG HUEI</b> , ID: S8838155F								
Vehicle Reg. No.:	<b>SLL3338B</b>	Date of Loss:	29/10/2019 13:00 - :59 [149 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SGQ7227U</b>	Policy No. (Claimant):	GA273282						
		Excess:	S\$0.00						
Repairer:	<b>Neo Automotive Pte Ltd (HQ)</b> 53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL PARK, 408934 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6880 4888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>LEE HOCK ANN</b> ] ... <b>[Final Rpt due 03/01/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents










\*SLL3338B  
[SGQ7227U]  
TP  
SEE TERNG HUEI  
Oct 29 2019 1:00PM  
[-]  
Neo Automotive Pte Ltd

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 14:05	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	30/10/19 15:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/12/19 18:31	General View	Load JPG	<input checked="" type="checkbox"/>
28	24/12/19 18:31	General View	Load JPG	<input checked="" type="checkbox"/>
29	24/12/19 18:31	General View	Load JPG	<input checked="" type="checkbox"/>








Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
30	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/12/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/12/19 18:32	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 16:08	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 16:08	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 16:08	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 16:08	Individual Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 16:08	AXA letter [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	31/10/19 14:05	Police report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	31/10/19 14:05	Police report [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
8	31/10/19 14:05	<b>Police report</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>









## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 14:05	<b>Addendum Sheet</b>	 Load JPG	<input checked="" type="checkbox"/>
2	06/12/19 19:10	<b>Accident Statement</b>	 Load HTM	
3	06/12/19 19:12	<b>Accident Statement</b>	 Load HTM	
4	06/12/19 19:12	<b>Accident Statement</b>	 Load HTM	
5	06/12/19 19:16	<b>Accident Statement</b>	 Load HTM	
6	06/12/19 19:17	<b>Accident Statement</b>	 Load HTM	
7	06/12/19 19:19	<b>Accident Statement</b>	 Load HTM	
8	06/12/19 19:23	<b>Accident Statement</b>	 Load HTM	
9	06/12/19 19:23	<b>Accident Statement</b>	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
7	30/10/19 15:59	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	30/10/19 16:08	<b>Sketch Plan</b>	 Load JPG	<input checked="" type="checkbox"/>
2	30/10/19 16:08	<b>Sketch Plan #2</b>	 Load JPG	<input checked="" type="checkbox"/>
3	30/10/19 16:08	<b>Common Statement</b>	 Load JPG	<input checked="" type="checkbox"/>
4	30/10/19 16:08	<b>Individual Statement</b>	 Load JPG	<input checked="" type="checkbox"/>
5	30/10/19 16:08	<b>AXA letter</b>	 Load JPG	<input checked="" type="checkbox"/>
6	31/10/19 14:05	<b>Police report</b>	 Load JPG	<input checked="" type="checkbox"/>
7	31/10/19 14:05	<b>Police report</b>	 Load JPG	<input checked="" type="checkbox"/>
8	31/10/19 14:05	<b>Police report</b>	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19020018/HCF3E2

Date: 02/01/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:

Claimant Vehicle No : SLL3338B Insured Vehicle No : SGQ7227U

Date of Loss: 29/10/2019 Nature of Claim: TP Claim No: SNM19D205132

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL3338B

Make & Model: BMW 335i, 3.0 (A) Engine No: N54B30A08506437

Reg. Date: 22/05/2007 (Man. Year: 2007) Chassis No: WBAWB72070P052241

Colour: Grey Odometer: 262454 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 275/30 R19

Front Left Side: Goodyear 5 mm Rear Left Side: Habilead 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 12/11/2019 Inspected At:

Neo Automotive Pte Ltd (HQ)  
53 UBI AVE 1, #05-44 PAYA UBI  
INDUSTRIAL PARK  
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2020)
<b>Parts:</b>	143	BMW 335I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLL3338B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >