

ASS. REC. BY:

REF:

CS/CTZ 19D2004/0453 22

Special Instruction:

Surveyor:

marcus

ASSIGNMENT (Office)

From (Person):

Tan Kah Leang

of

CTZ

Date/Time:

11.11.19 1734p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 6897E

Insured:

SMG 1464Y

at Workshop with:

RICO 60

Tel:

62866060

of

B Kaka Butik no 4 102-2x

Policy No:

DMP/CSN 30299418000

Claim No:

SNM 9102533462

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

9.11.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12.11.19 10.10am

Person Contacted:

Gls

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMG 1464Y NA 1221/01/19/06/19 DEN 01/11/2019
	SMA 6897E NA 1221/01/19/06/19 DEN 01/11/2019

Marcus
a.k

ASS. FNO. BY:

Wkt:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SMA 6PP7 E
 at Workshop m/s: RICO 60
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GR / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 6PP7 E Yr Regn: 6 18
 Type: M 2 / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA

Make: Hyundai Elantra C.C. 1591

Colour: Beige A/C: Insured / Std / NI / NA

Sp. Reading: 23910 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body & 15

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

net 23810

27/12/19

LTA 40190 Syre. 7.2716

1/5 @ 17.300 confirmed with John. (Red \$20840.00, 54%)

RECEIVED 30 DEC 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

30/12/19 Typist

Days Of Repair: 14

Resurvey No. of Trip: 3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wash and (\$

Survey Fee:

Transportation:

\$ + RS \$

Phone

Other

Print

270

270

People Form:

Lump Sum / E.J.: \$17300f

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		11 Nov 2019 17:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: HO LAI LIN , ID: S0171572J									
Vehicle Reg. No.: SMA6897E		Date of Loss:	09/11/2019 17:00 - :59						
Claim Type: TP / SNM19D205334C02		Policy/Cover Note No.:	DMPCSN30799418000						
Vehicle Reg. No. (Insured): SMG1464Y		Policy No. (Claimant):	D19MPC0003005						
		Excess:	S\$1,000.00						
Repairer: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 11 November 2019 5:30 PM
To: Rico 60; assignments
Subject: RE: OUR REF :SNM19D205334-SMG1464Y-TKL- PRI Arrangement for SMA 6897E
Attachments: PRI Arrangement.pdf

WITHOUT PREJUDICE

Dear John,

We refer to your email dated 06.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rico 60 [mailto:claims@rico60.com]
Sent: Monday, November 11, 2019 4:49 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF :SNM19D205334-SMG1464Y-TKL- PRI Arrangement for SMA 6897E

Dear Sir,

Please have Marcus survey the said vehicle.

Thank you.

Best Regards,
John Ong



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 8811 2101 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: claims@rico60.com

From: Tan Kah Leong

Sent: Monday, 11 November 2019 4:10 PM

To: claims@rico60.com

Subject: RE: OUR REF :SNM19D205334-SMG1464Y-TKL- PRI Arrangement for SMA 6897E

Without Prejudice

Dear Shanelle,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, November 11, 2019 3:55 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow

<sochow.chee@sg.cntaiping.com>; claims@rico60.com

Subject: OUR REF :SNM19D205334-SMG1464Y-TKL- PRI Arrangement for SMA 6897 E

Dear Kah Leong,

Please conduct PRS for SMA6897E.

Note : officer in charge – Kah leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Enquiry [mailto:claims@rico60.com]
Sent: Monday, 11 November, 2019 1:52 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: PRI Arrangement for SMA 6897 E

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SMA 6897 E
Your Insured – SMG 1464 Y
DOA – 09/11/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: enquiry@rico60.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24

Singapore 415875 | Email: enquiry@rico60.com

Tel: +65 6286 6060 | Fax: +65 6286 7060

PRI ARRANGEMENT

Date: 11/11/19

To: China Taiping

ATTN: Motor Claims Department

RE: Accident involving motor vehicle nos. SMA6897E, SMG1464Y, SJT6593S & SJA2997G
along 67 Sims Place, Greentops (carpark) on 9/11/19 @ 17:00hrs.

We refer to the above matter.

We are instructed by Ho Lai Lin
to notify you of a road traffic accident on 9/11/19 at about 17:00hrs
along 67 Sims Place, Greentops (carpark)
involving our client's vehicle no. SMA6897E and vehicle no. SMG1464Y
driven by you at the stated time.

Due to the above-mentioned accident, our client's vehicle has been damaged. Before our client/we proceed with the repair(s) of the damaged vehicle, please kindly let us know within 2 working days of your receipt of this notice, whether you or your insurer would like to conduct pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to the repair work(s) of the vehicle without further reference to you.

Thank you.

Signature

Name: Shanelle Lim

Mobile No.: 9187 8064

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 14:20
Date Of Accident	09/11/2019 17:00
Exact Location Of Accident	63 SIMS PLACE GREENTOPS (CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA6897E
Insured/Policyholder	
Name Of Registered Owner	HO LAI LIN
NRIC No	S0171572J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96316937
Alternative Phone No	OFFICE-96316937

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MPC0003005
Cover Note Number	

Driver

Name of Driver	HO LAI LIN
NRIC No	S0171572J
Date Of Birth	04/06/1952
Occupation	INDOOR
Date Of Driving Pass	06/09/1979
Driving Experience	40 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96316937
Fax Number	
Contact Number	OFFICE-96316937
Email Address	NOEMAIL

Address	BLK 63 SIMS PLACE #15-209
Postcode	380063
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20191110/7004

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG1464Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJT6593S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLA3997G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. This report is **strictly confidential** to the accident involved and the claims process.
2. The report must be completed by the **Policyholder** and/or the **Authorized Driver**.
3. Information provided must be as **correct and accurate as possible** and without misrepresentation or withholding of material facts that may affect insurance coverage or **invalidate policy benefits**.
4. The facts and accident description form of insurance companies is not an admission of liability benefits on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my co-insurer and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiry by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

Accident Sketch Plan

A = 57462897E C = 57462893E
B = 57461464Y D = 57462897G

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

*****for company vehicle only*****
I _____ is the _____ of
company _____ and I am using the
vehicle _____ for work/private purpose

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRC/RN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20191110/7004

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20191110/7004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/11/2019 09:45	Vide Report No.: G/20191109/0163	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: HO LAI LIN			Address: APT BLK 63 SIMS PLACE #15-209 SINGAPORE 380063		
ID Type / ID No.: NRIC NO / S0171572J			Contact No.: Home/Office:		Mobile: 96316937
Nationality: SINGAPORE CITIZEN			Email: colleenho@yahoo.com		
Sex: Female	Age: 67	Date of Birth: 04/06/1952	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Administration manager			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/11/2019 17:00	Type of Location: Car Park
Location: SIMS PLACE				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 20 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: MOVING VEHICLES AGAINST KERB/SIGNAGE/CARS				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJT6593S	Car			Blue	Seriously Damaged	0
SLA3997G	Car	HONDA	CITY	Black	Seriously Damaged	0
SMA6897E	Car	HYUNDAI	ELANTRA	Beige	Seriously Damaged	0
SMG1464Y	Car	MERCEDES BENZ	E300	Black	Seriously Damaged	0

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20191119/7004

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No: T/20191119/7004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	HO LAI LIN	ID No.	S0171572J
Related Vehicle	NIL	Contact No.	96316937
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details:

THIS MORNING, AT APPROXIMATELY 06:40AM, I WENT DOWN TO THE CAR PARK READY TO DRIVE MY CAR OUT FOR MY EXERCISE LESSON. HOWEVER WHEN I ARRIVED TO MY VEHICLE, I WAS IN STATE OF SHOCK WHEN I SAW THE 4 DOORS AND BOTH SIDE MIRROR, ESPECIALLY THE LEFT SIDE MIRROR WAS BADLY DAMAGED.

A NEIGHBOUR HAPPENED TO PASS BY, TOLD ME THE ACCIDENT OCCURED YESTERDAY AT ABOUT 5PM, AND ALSO SENT ME THE ACCIDENT PHOTOS.

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20191110/7004

3 of 3

Report No: T/20191110/7004

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
MARIAH BINTE ZAKARIA
Contact No.: 65476433

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
10/11/2019 09:45

Classification Of Case:

> Back to OneMotoring

Angus

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	572J
Vehicle Details	
Vehicle No.:	SMA6897E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Beige
Manufacturing Year:	2018
Engine No.:	G4FGJU185593
Chassis No.:	KMHD841CMJU685513
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,819.00
Original Registration Date:	18 Jun 2018
First Registration Date:	18 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$11,819.00 <i>5909</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2028
PARF Rebate Amount:	\$8,864.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,426.00
COE Rebate Amount:	\$31,326.00
Total Rebate Amount:	\$40,190.00

The information contained herein is correct as at 11 Nov 2019

11

OK

Get a Google Nest
Hub for just \$129.Get it today at store.google.com

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Toyota R3 Cruiser



Auction Buy Now Sell Now

Newest

Direct Owner



« Back (1 2) Next »

Sort by Date Posted

20 results/page

31 vehicles

HYUNDAI ELANTRA

Basic Search



Price Any price **Depre** Any depre **Reg Date** 2018 to 2018 **Eng Cap** Any **Veh Type** All types
Fuel Any fuel **Mileage** Any **OMV** Any **Gear** Any Gear **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer **Location** Any **Status** Available



Make & Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
 Hyundai Elantra 1.6A GLS S Hyundai Komoco Unit, Full Agent Maintained, Metallic Silver Exterior With Black Interior, Manufacture Warranty Till May 2023, Popular Sedan For Daily Usage, Spacious Leg Room With Large Boot Space, Attractive Interest Rate From 1.99% Please Call Our Sales Consulta... Incscape Pre-Owned Posted: 11-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$70,668	\$7,650 /yr	03-May-2018	1,591 cc	38,418 km	Sedan	Available
 Hyundai Elantra 1.6A GLS S 1 Owner, Fully Agent Serviced And Maintained, Face Lifted Model, Keyless Entry And Push/Start, Low Depreciation, Flexible Loan Available. Posted: 11-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$67,800	\$7,020 /yr	15-Aug-2018	1,591 cc	20,000 km	Sedan	Available
 Hyundai Elantra 1.6A GLS S 100% Full Loan Available, 1 Owner! 5 Yrs Warranty From Agent, Car In Tip Top Condition, Kindly Contact Us For An Appointment Or Visit Us At Our Showrooms Today, Where Quality Service Really Matters. 1axis Posted: 11-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$66,800	\$7,150 /yr	19-May-2018	1,591 cc	33,662 km	Sedan	Available
 Hyundai Elantra 1.6A GLS Lowest Depreciation Below \$7k Per Annual! 1 Owner, Low Mileage, 5 Years/100,000km Agent Warranty, Accident Free, Always Under Shelter Parking, Tip-Top Well Maintained, Even Some Factory Protection Sticker Still Not Yet Remove. Free 6 Months Road Tax Till May 2... Posted: 10-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$68,500	\$6,990 /yr	17-Nov-2018	1,591 cc	22,045 km	Sedan	Available
 Hyundai Head Rest Pillow Hyundai Head Rest Pillow More info about this product:							
 Hyundai Elantra 1.6A GLS S (OPC) 1 Owner, Well Maintained By Agent, High Loan With High Trade In Available, Price Negotiable, Call Now Or Visit Our Showroom Today. Posted: 05-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$56,800	\$6,150 /yr	24-Feb-2018	1,591 cc	28,000 km	Sedan	Available
 Hyundai Elantra 1.6A Elite Don't Miss Then Regret! Unbelievable Low Mileage Done Of 14466km Only! As Good As Brand New, Serviced At Komoco Motors With All Proof/Warranty, 1 Lady Owner, New Michelin Tyres, Road Tax Till Feb 20, 100% Accident Free, Highest Specs, Elite Model, Call Now! Lake View Credit Pte Ltd Posted: 09-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai	\$66,800	\$7,250 /yr	20-Feb-2018	1,591 cc	14,466 km	Sedan	Available

Compare

36 elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra



Hyundai Elantra 1.6A GLS \$65,800 \$7,250 /yr 29-Mar-2018 1,591 cc 39,000 km Sedan Available

Meticulously Well Kept By 1 Fussy Owner. Fully Maintained By (Komoco Motors) And Still Under Agent 5 Years Warranty. Low Depreciation! Guaranteed Accident Free! Buy With A Peace! Our Company Provide Loan Scheme! All Trade In Most Welcome! Hurry Con...

Creative Auto

Posted: 08-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$57,800 \$5,710 /yr 16-Nov-2018 1,591 cc 7,681 km Sedan Available

Full Loan Available, 1 Owner, Super Low Mileage 7681km Plus Only, Cheapest In The Whole 2016 Elantra Page, Very Well Kept By 1 Fussy Owner. Low Mileage. Still Under Agent Warranty. Avoid Disappointment Book Now To View. High Loan And High Trade In Available. Call...

taxis

Posted: 08-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$70,800 \$7,250 /yr 03-Oct-2018 1,591 cc 31,000 km Sedan Available

High Spec S Model With Keyless Push Start Button. Best Sedan Car To Own. \$7.1K Yearly. 5 Years Agent Warranty. Flexible Loan 100% Loan Available. View Now.

Hua Yang Credit Pte Ltd

Posted: 08-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$70,800 \$7,250 /yr 13-Nov-2018 1,591 cc 10,180 km Sedan Available

1 Owner 2018 Newest Model Hyundai Elantra 1.6A GLS AT (AMS) Clock With Genuine Lowest Mileage 10180km In Stock Now! Under Warranty! Pristine Condition! Sporty Red With Black Interior! Flexible Loan, Tenures And Down Payment Available! Come View And We...

Posted: 07-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Find the right car through consignment.

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!



Hyundai Elantra 1.6A GLS \$71,800 \$7,460 /yr 03-Oct-2018 1,591 cc 3,500 km Sedan Available

Sporty White 1 Owner, Excellent Fuel Efficiency, Spacious Cabin, Easy Maintenance, Buy With Peace Of Mind With Agent Warranty, Call Now To Find Out More.

Posted: 07-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS Elite \$73,800 \$7,650 /yr 24-Jul-2018 1,591 cc 10,500 km Sedan Available

Elite Spec. Very Good Condition. Sheltered Park. Fully Agent Serviced With 5 Years Agent (Komoco) Warranty. Excellent Condition. 100% Accident Free. Highest Trade In, Bank Loan, Balloon Loan, In House Loan, 100% Loan Available. Test Drive Today.

Posted: 06-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$69,900 \$7,310 /yr 01-Sep-2018 1,591 cc 35,000 km Sedan Available

1 Owner. Serviced By Agent. As Good As New Condition. Well Taken Care By Previous Owner. Trade In Welcome! Full Loan Available! Hurry Call Or Visit Us Now For Further Details.

Alimotoring.sg

Posted: 06-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$70,800 \$7,320 /yr 01-Sep-2018 1,591 cc 6,800 km Sedan Available

100% Full Loan Available, 1 Owner! 5 Yrs Warranty From Agent. Car In Tip Top Condition, Kindly Contact Us For An Appointment Or Visit Us At Our Showrooms Today, Where Quality Service Really Matters.

taxis

Posted: 06-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$66,800 \$7,310 /yr 21-Apr-2018 1,591 cc 24,200 km Sedan Available

Graded **A** by **STR**

Flexible Bank, In House Loan And Full Loan Available! 1 Owner Only, Genuine Low Mileage, Still Under Agent Warranty, Fully Service By Komoco, New Car Condition With Plastics Still In Tact! Fuel Efficient, Trade In Welcome! Make Your Appointment With Us Today!

SKL Automobile Pte Ltd

Posted: 04-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS \$71,500 \$7,340 /yr 28-Sep-2018 1,591 cc 15,000 km Sedan Available

Elantra S Model, Not The Basic Model. Direct Owner, \$7% Plus Only Depre Yearly Bank Interest Rate.

Posted: 03-Nov-2019 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

Compare

Hyundai Elantra 1.6A GLS 7,250 /yr 27-Mar-2018 1,591 cc 43,000 km Sedan Available



1 Owner Only, Agent Service And Still Under Warranty By Komoco, Reliable And Fuel Economic, 100% Loan Approval, Bank/In House Flexible Loan Available. Please Call Or Visit Us Now For Further Details.

Pure Motors Pte Ltd

Posted: 02-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$66,800 \$7,170 /yr 15-May-2018 1,591 cc 30,700 km Sedan Available

Attractive Loan Packages, Enquirer To Know More! 1 Owner Only Stunning Gun Metal Elantra "S" Model! Keyless And Push Start Function! Fully Maintained By Komoco Since Day 1! Free Agent Servicing Up To 100k Km! 5 Years Unlimited Agent Warranty! 100% Loa...

Posted: 01-Nov-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS (OPC) \$55,800 \$5,740 /yr 21-Aug-2018 1,591 cc 6,100 km Sedan Available

OPC Unit, Option To Convert To Normal Plate At Top Up. 5 Years Warranty From Agent. Almost New, Rarely Driven. In House Loan Available. Instant In House Loan Approval, Immediate Transfer Of Ownership Upon Collection, Hassle Free Transaction! Call Now To En...

Hui Hua Credit Pte Ltd

Posted: 21-Oct-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Hyundai Elantra 1.6A GLS S \$58,800 \$5,990 /yr 23-Aug-2018 1,591 cc 6,079 km Sedan Available

Special Promotion 1.5% Interest Rate! 1 Owner OPC Unit, Agent Maintained With Valid Agent Warranty Till Aug 2023. Sport White Well Maintained With Almost New Showroom Condition, Excellent Fuel Efficiency, Spacious Cabin, Easy Maintenance, Don't Miss! Call/Watsapp...

Republic Auto

Posted: 29-Oct-2018 Tags: 2018 Hyundai Elantra, 2018 hyundai elantra, Hyundai Elantra, hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used HYUNDAI ELANTRA, HYUNDAI ELANTRA Singapore, used HYUNDAI ELANTRA Singapore, used HYUNDAI ELANTRA, used vehicles Singapore or even buy used HYUNDAI ELANTRA Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Customer:

Date:

12/11/2019 12:05 PM

Company:

VIN

License No:

SMA6897E


Technician:

Odometer:

Order No.:

Graphic Alignment Report

HYUNDAI, ELANTRA, 2013-2013, (JK) Coupé



Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 4 December 2019 9:30 AM
To: Yvonne Wong (LKK Auto)
Subject: FW: HELP CHECK PART PRICE

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Asyraf Noor Azman <muhammad.asyraf@hyundaimotors.com.sg>
Sent: Wednesday, 4 December 2019 8:53 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: HELP CHECK PART PRICE

86510-F2000	COVER ASSY-FR BUMPER	474.4
71110-F2A01	PANEL ASSY-PILLAR OUTER,LH	3919.2
<u>76003-F2000</u>	PANEL ASSY-FRONT DOOR,LH	1831.1
87610-F2210	MIRROR ASSY-OUTSIDE RR VIEW,LH	638.6
81310-F2010	LATCH ASSY-FRONT DOOR,LH	191.5
82471-F2030	PANEL ASSY-FRONT DR MODULE,LH	250.4
82450-F2000	MOTOR ASSY-FRONT POWER WDW,LH	297.8
82305-F2AR0UTE	PANEL ASSY-FRONT DOOR TRIM,LH	756.9
<u>77003-F2000</u>	PANEL ASSY-REAR DOOR,LH	1775.2
83305-F2040UTE	PANEL ASSY-REAR DOOR TRIM,LH	497.9
71503-F2C01	PANEL ASSY-QUARTER OUTER,LH	1768.3
<u>92401-F2000</u>	LAMP ASSY-REAR COMB OUTSIDE,LH	362.6

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]
Sent: Monday, December 02, 2019 4:44 PM
To: Muhammad Asyraf Noor Azman
Subject: HELP CHECK PART PRICE

Dear Sir,

Can help me check part price please

SMA 6897E
Hyundai Elantra 2018
KMH0841CMJU 685513



Rico 60 Auto Services Pte Ltd, Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SMA 6897 E
HYUNDAI ELANTRA

Not Allocated
1/53
14dy
12/11/19

Take photo of damage

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	FRONT WINDSCREEN MOULDING <i>new</i>	1	
	2	HEADLAMP (L+R) <i>11 X</i>	2	
	3	HEADLAMP BRACKET (L+R) <i>11 X</i>	2	
	4	FRONT BUMPER <i>11 X</i>	1	
	5	FRONT BUMPER RETAINER (L+R) <i>11 X</i>	2	
	6	FRONT BUMPER REINFORCEMENT BAR <i>11 X</i>	1	
	7	FRONT BUMPER BRACKET (L+R) <i>11 X</i>	2	
	8	FRONT BUMPER BEAM <i>11 X</i>	1	
	9	FRONT BUMPER SPONGE <i>11 X</i>	1	
	10	FRONT BUMPER TOP SEAL <i>11 X</i>	1	
	11	FRONT BUMPER GRILLE <i>11 X</i>	1	
	12	FRONT BUMPER GRILLE BASE <i>11 X</i>	1	
	13	FRONT BUMPER FOG LAMP (L+R) <i>11 X</i>	2	
	14	FRONT BUMPER FOG LAMP TOP LAMP (L+R) <i>11 X</i>	2	
	15	FRONT BUMPER FOG LAMP GARNISH (L+R) <i>11 X</i>	2	
	16	FRONT BUMPER FOG LAMP GARNISH CHROME (L+R) <i>11 X</i>	2	
	17	FRONT BUMPER UNDERCOVER <i>11 X</i>	1	
	18	FRONT FENDER (L+R) <i>MSD 015 R 1PC</i>	2	
	19	FRONT FENDER QUARTER GARNISH (L+R) <i>11 X</i>	2	
	20	FRONT FENDER INNER PANEL (L+R) <i>11 X</i>	2	
	21	FRONT FENDER COWLING (L+R) <i>11 X</i>	2	
	22	FRONT FENDER MUDFLAP (L+R) <i>11 X</i>	2	
	23	A PILLAR (L+R) <i>MSR 015 R 1PC</i>	2	
	24	FRONT DOOR (L+R) <i>MSD 015 R 1PC</i>	2	
	25	FRONT DOOR SIDE MIRROR ASSY (L+R) <i>CR9/407</i>	2	
	26	FRONT DOOR SIDE MIRROR COVER (L+R) <i>MSR 015 R 1PC</i>	2	
	27	FRONT DOOR SIDE MIRROR SIGNAL LAMP (L+R) <i>11 X</i>	2	
	28	FRONT DOOR HANDLE (L+R) <i>MSR 015 R 1PC</i>	2	
	29	FRONT DOOR HANDLE END CAP (L+R) <i>015 R 1PC</i>	2	
	30	FRONT DOOR LOCK CYLINDER (L+R) <i>11 X</i>	2	
	31	FRONT DOOR LOCK SWITCH (L+R) <i>015 R 1PC</i>	2	
	32	FRONT DOOR WINDOW MOULDING (L+R) <i>015 R 1PC</i>	2	
	33	FRONT DOOR INNER LOCK (L+R) <i>? 015</i>	2	
	34	FRONT DOOR INNER LOCK CATCH (L+R) <i>11 X</i>	2	
	35	FRONT DOOR INNER BOARD (L+R) <i>?</i>	2	
	36	FRONT DOOR INNER BOARD SWITCH (L+R) <i>11 X</i>	2	
	37	FRONT DOOR POWER WINDOW MOTOR (L+R) <i>7 015</i>	2	
	38	FRONT DOOR WINDOW REGULATOR (L+R) <i>015 ?</i>	2	
	39	FRONT DOOR HINGE (UPPER & LOWER) (L+R) <i>015 ?</i>	4	
	40	FRONT DOOR CHECKER (L+R) <i>015 ?</i>	2	

41	FRONT DOOR WEATHERSTRIP (L+R)	new /	2
42	FRONT DOOR INNER WEATHERSTRIP (L+R)	new /	2
43	CENTER PILLAR (L+R)	0/5 ?	2
44	REAR DOOR (L+R)	Body / new /	2
45	REAR DOOR HANDLE (L+R)	11 X	2
46	REAR DOOR HANDLE END CAP (L+R)	17 X	2
47	REAR DOOR WINDOW MOULDING (L+R)	17 X	2
48	REAR DOOR INNER LOCK (L+R)	N/S ?	2
49	REAR DOOR INNER LOCK CATCH (L+R)	17 X	2
50	REAR DOOR INNER BOARD (L+R)	?	2
51	REAR DOOR INNER BOARD SWITCH (L+R)	17 X	2
52	REAR DOOR POWER WINDOW MOTOR (L+R)	new 0/5 ?	2
53	REAR DOOR REGULATOR (L+R)	0/5 ?	2
54	REAR DOOR HINGE (UPPER & LOWER) (L+R)	0/5 ?	4
55	REAR DOOR CHECKER (L+R)	0/5 ?	2
56	REAR DOOR WEATHERSTRIP (L+R)	new /	2
57	REAR DOOR INNER WEATHERSTRIP (L+R)	new /	2
58	ROCKER PANEL (L+R)	2 X	2
59	ROCKER PANEL GARNISH (L+R)	NS X	2
60	REAR FENDER (L+R)	N/S and 50 / 100	2
61	REAR FENDER PETROL COVER (LH)	Body /	1
62	REAR FENDER INNER TRIM (L+R)	17 X	2
63	REAR FENDER QUARTER GARNISH (L+R)	17 X	2
64	REAR FENDER COWLING (L+R)	17 X	2
65	REAR FENDER MUDFLAP (L+R)	17 X	2
66	TAIL LAMP (L+R)	N/S ?	2
67	TAIL LAMP PANEL (L+R)	17 X	2
68	BOOTLID	11 X	1
69	BOOTLID LOGO (HYUNDAI)	17 X	1
70	BOOTLID EMBLEM (ELANTRA)	17 X	1
71	BOOTLID EMBLEM (S)	17 X	1
72	BOOTLID LAMP (L+R)	17 X	2
73	BOOTLID HANDLE	17 X	1
74	BOOTLID CARPLATE LAMP (L+R)	17 X	2
75	BOOTLID INNER LOCK	17 X	1
76	BOOTLID INNER LOCK COVER	17 X	1
77	BOOTLID INNER LOCK CATCH	17 X	1
78	BOOTLID INNER TRIM	17 X	1
79	BOOTLID HINGE (L+R)	17 X	2
80	BOOTLID STOPPER (L+R)	17 X	2
81	BOOTLID WEATHER STRIP	17 X	1
82	REAR BUMPER	2 X	1
83	REAR BUMPER RETAINER (L+R)	17 X	2
84	REAR BUMPER REINFORCEMENT BAR	17 X	1
85	REAR BUMPER BRACKET (L+R)	17 X	2
86	REAR BUMPER BEAM	17 X	1
87	REAR BUMPER SPONGE	17 X	1
88	REAR BUMPER REVERSE SENSOR SET	17 X	2

[illegible]

23	REAR BUMPER CLIPS	✓ 1X	10	\$	100.00
24	REAR W. nd screen Sealant	see 40	1	\$	120.00
25	REAR FENDER INNER TRIM CLIPS (L+R)	✓ 1X	20	\$	200.00
26	REAR FENDER COWLING CLIPS (L+R)	✓ 1X	20	\$	200.00
27	REAR FENDER MUDFLAP CLIPS (L+R)	✓ 1X	10	\$	100.00
28	FRONT TYRE SET	see 4	2	\$	1,600.00
29	FRONT RIM SET	nd 147 170 H50	2	\$	3,000.00
30	REAR TYRE SET	see 4	2	\$	1,600.00
31	REAR RIM SET	nd 147 170 H50 170	2	\$	3,000.00
				SPECIAL NETT TOTAL	\$ 13,200.00
LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1800	1	\$	9,300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	1	\$	5,700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	120	1	\$	250.00
4	TO RNR FRONT WINDSCREEN	120	1	\$	400.00
4	TO RNR REAR WINDSCREEN	120	1	\$	400.00
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	80	1	\$	400.00
6	TO RNR DOOR MECHANISM FRONT & BACK	100	1	\$	800.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	11X	1	\$	120.00
8	TO RNR UNDERCARRIAGE SYSTEM	11X	1	\$	250.00
9	TO CHECK WHEEL ALIGNMENT	60	1	\$	250.00
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	\$	150.00
11	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	11X	1	\$	150.00
12	TO CHECK WIRING LAYOUT AND FOG LAMP TOP LAMP FUNCTION	11X	1	\$	150.00
13	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	11X	1	\$	150.00
14	TO RNR TYRE AND WHEEL BALANCING	11X	1	\$	250.00
15	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	1	\$	400.00
16	TO DO WATER LEAK TEST .	11X	1	\$	80.00
17	TO RNR FUEL TANK TO ASSIST WORK LOAD	60	1	\$	250.00
				TOTAL	\$ 19,450.00
				GRAND TOTAL COST	\$ 32,650.00

LRR Auto Consultants hence notify
 the Receiver of the following:
 • To conduct an immediate safety audit
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance
 • To ensure that the vehicle is in compliance

Authorised by Receiver

Signature

Date



Rico 6674400 Sclwices Pte Ltd, Bldg 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico.sg.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM: SMA 6897 E
MAKE & MODEL: HYUNDAI ELANTRA
MILEAGE:
TYRE:
CHASSIS NUM:

Not Allocated
1/5th 17,300
14th
18/11/19

Take for. H. H. H.

ITEM	DESCRIPTION	QTY	PRICE
1	FRONT WINDSCREEN MOULDING	1	\$197.70
2	HEADLAMP (L+R)	2	\$1954.80
3	HEADLAMP BRACKET (L+R)	2	\$247.20
4	FRONT BUMPER	1	\$495.90
5	FRONT BUMPER RETAINER (L+R)	2	\$136.00
6	FRONT BUMPER REINFORCEMENT BAR	1	\$512.00
7	FRONT BUMPER BRACKET (L+R)	2	\$176.00
8	FRONT BUMPER BEAM	1	NIL
9	FRONT BUMPER SPONGE	1	\$321.00
10	FRONT BUMPER TOP SEAL	1	\$142.10
11	FRONT BUMPER GRILLE	1	\$498.00
12	FRONT BUMPER GRILLE BASE	1	\$412.00
13	FRONT BUMPER FOG LAMP (L+R)	2	\$830.00
14	FRONT BUMPER FOG LAMP TOP LAMP (L+R)	2	\$376.40
15	FRONT BUMPER FOG LAMP GARNISH (L+R)	2	\$410.00
16	FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	2	\$593.60
17	FRONT BUMPER UNDERCOVER	1	\$289.70
18	FRONT FENDER (L+R)	2	\$1795.00
19	FRONT FENDER QUARTER GARNISH (L+R)	2	\$160.00
20	FRONT FENDER INNER PANEL (L+R)	2	\$2031.80
21	FRONT FENDER COWLING (L+R)	2	\$197.40
22	FRONT FENDER MUDFLAP (L+R)	2	\$170.80
23	A PILLAR (L+R)	2	\$2483.80
24	FRONT DOOR (L+R)	2	\$2508.80
25	FRONT DOOR SIDE MIRROR ASSY (L+R)	2	\$1378.40
26	FRONT DOOR SIDE MIRROR COVER (L+R)	2	\$408.20
27	FRONT DOOR SIDE MIRROR SIGNAL LAMP (L+R)	2	\$347.00
28	FRONT DOOR HANDLE (L+R)	2	\$510.80
29	FRONT DOOR HANDLE END CAP (L+R)	2	\$181.80
30	FRONT DOOR LOCK CYLINDER (L+R)	2	\$687.40
31	FRONT DOOR LOCK SWITCH (L+R)	2	\$480.20
32	FRONT DOOR WINDOW MOULDING (L+R)	2	\$274.60
33	FRONT DOOR INNER LOCK (L+R)	2	\$835.00
34	FRONT DOOR INNER LOCK CATCH (L+R)	2	\$186.00
35	FRONT DOOR INNER BOARD (L+R)	2	\$1431.60
36	FRONT DOOR INNER BOARD SWITCH (L+R)	2	\$1360.00
37	FRONT DOOR POWER WINDOW MOTOR (L+R)	2	\$567.80
38	FRONT DOOR WINDOW REGULATOR (L+R)	2	\$4948.60
39	FRONT DOOR HINGE (UPPER & LOWER) (L+R)	2	\$376.80
40	FRONT DOOR CHECKER (L+R)	2	\$157.20

9463.48

2704130

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
41	FRONT DOOR WEATHERSTRIP (L+R)	2	198.00	396.00	✓
42	FRONT DOOR INNER WEATHERSTRIP (L+R)	2	160.00	320.00	✓
43	CENTER PILLAR (L+R)	2	198.00	396.00	1P C
44	REAR DOOR (L+R)	2	2090.00	4180.00	✓
45	REAR DOOR HANDLE (L+R)	2	323.20	646.40	X
46	REAR DOOR HANDLE END CAP (L+R)	2	181.60	363.20	X
47	REAR DOOR WINDOW MOULDING (L+R)	2	274.60	549.20	X
48	REAR DOOR INNER LOCK (L+R)	2	417.50	835.00	1P C
49	REAR DOOR INNER LOCK CATCH (L+R)	2	186.00	372.00	X
50	REAR DOOR INNER BOARD (L+R)	2	135.60	271.20	✓
51	REAR DOOR INNER BOARD SWITCH (L+R)	2	1206.30	2412.60	X
52	REAR DOOR POWER WINDOW MOTOR (L+R)	2	567.80	1135.60	1P C
53	REAR DOOR REGULATOR (L+R)	2	998.60	1997.20	1P C
54	REAR DOOR HINGE (UPPER & LOWER) (L+R)	4	366.80	1467.20	1P C
55	REAR DOOR CHECKER (L+R)	2	138.20	276.40	1P C
56	REAR DOOR WEATHERSTRIP (L+R)	2	375.20	750.40	✓
57	REAR DOOR INNER WEATHERSTRIP (L+R)	2	370.00	740.00	✓
58	ROCKER PANEL (L+R)	2	2445.20	4890.40	X
59	ROCKER PANEL GARNISH (L+R)	2	751.40	1502.80	X
60	REAR FENDER (L+R)	2	3614.40	7228.80	1P C
61	REAR FENDER PETROL COVER (LH)	1	109.20	109.20	✓
62	REAR FENDER INNER TRIM (L+R)	2	692.00	1384.00	X
63	REAR FENDER QUARTER GARNISH (L+R)	2	160.00	320.00	X
64	REAR FENDER COWLING (L+R)	2	197.40	394.80	X
65	REAR FENDER MUDFLAP (L+R)	2	170.80	341.60	X
66	TAIL LAMP (L+R)	2	916.00	1832.00	1P C
67	TAIL LAMP PANEL (L+R)	2	451.80	903.60	X
68	BOOTLID	1	1085.60	1085.60	X
69	BOOTLID LOGO (HYUNDAI)	1	70.00	70.00	X
70	BOOTLID EMBLEM (ELANTRA)	1	68.60	68.60	X
71	BOOTLID EMBLEM (S)	1	65.50	65.50	X
72	BOOTLID LAMP (L+R)	2	650.00	1300.00	X
73	BOOTLID HANDLE	1	211.80	211.80	X
74	BOOTLID CARPLATE LAMP (L+R)	2	186.20	372.40	X
75	BOOTLID INNER LOCK	1	487.00	487.00	X
76	BOOTLID INNER LOCK COVER	1	60.00	60.00	X
77	BOOTLID INNER LOCK CATCH	1	79.00	79.00	X
78	BOOTLID INNER TRIM	1	548.00	548.00	X
79	BOOTLID HINGE (L+R)	2	264.00	528.00	X
80	BOOTLID STOPPER (L+R)	2	36.00	72.00	X
81	BOOTLID WEATHER STRIP	1	254.00	254.00	X
82	REAR BUMPER	1	895.50	895.50	X
83	REAR BUMPER RETAINER (L+R)	2	119.00	238.00	X
84	REAR BUMPER REINFORCEMENT BAR	1	475.00	475.00	X
85	REAR BUMPER BRACKET (L+R)	2	126.00	252.00	X
86	REAR BUMPER BEAM	1	0.00	0.00	X
87	REAR BUMPER SPONGE	1	0.00	0.00	X
88	REAR BUMPER REVERSE SENSOR SET	2	624.00	1248.00	X

89	REAR BUMPER REFLECTOR (L+R)	11 X	2	\$ 240.00	X
90	REAR BUMPER LOWER	11 X	1	\$ 321.60	X
91	REAR BUMPER UNDERCOVER	11 X	1	\$ 248.70	X
92	FRONT ABSORBER (L+R)	11 X	2	\$ 974.60	X
93	FRONT LOWER ARM (L+R)	11 X	2	\$ 875.20	X
94	FRONT KNUCKLE (L+R)	11 X	2	\$ 1089.20	X
95	FRONT KNUCKLE BEARING (L+R)	11 X	2	\$ 370.80	X
96	FRONT BEARING HUB (L+R)	11 X	2	\$ 300.20	X
97	FRONT CROSSMEMBER	11 X	1	\$ 1254.00	X
98	FRONT STEERING RACK AND PINION ASSY	11 X	1	\$ 2450.90	X
99	FRONT DRIVE SHAFT (L+R)	11 X	1	\$ 1254.90	X
100	FRONT TIE ROD (L+R)	11 X	2	\$ 360.00	X
101	FRONT TIE ROD END (L+R)	11 X	2	\$ 290.00	X
102	FRONT STABILIZER BAR	11 X	1	\$ 762.10	X
103	FRONT STABILIZER LINK (L+R)	11 X	2	\$ 291.20	X
104	REAR ABSORBER (L+R)	11 X	2	\$ 526.00	X
105	REAR LOWER ARM (L+R)	11 X	2	\$ 530.00	X
106	REAR KNUCKLE (L+R)	11 X	2	\$ 692.80	X
107	REAR KNUCKLE BEARING (L+R)	11 X	2	\$ 794.00	X
108	REAR BEARING HUB (L+R)	11 X	2	\$ 794.00	X
109	REAR AXLE	11 X	1	\$ 1825.00	X

SUBTOTAL

\$ -

73244.7

LESS 20%

\$ -

14648.9

PARTS TOTAL

\$ -

58595.8

SPECIAL NETT

QTY

PRICE

1	FRONT WINDSCREEN SEALANT	11 X	1	\$ 120.00	40
2	FRONT BUMPER CLIPS	11 X	10	\$ 100.00	X
3	FRONT CARPLATE	11 X	1	\$ 120.00	X
4	FRONT CARPLATE FRAME	11 X	1	\$ 120.00	X
5	FRONT FENDER INNER PANEL SEALANT	11 X	1	\$ 120.00	X
6	FRONT FENDER COWLING CLIPS (L+R)	11 X	20	\$ 200.00	X
7	FRONT FENDER MUDFLAP CLIPS (L+R)	11 X	10	\$ 100.00	X
8	A PILLAR SEALANT	11 X	1	\$ 120.00	X
9	FRONT DOOR INNER BOARD CLIPS	11 X	10	\$ 100.00	50
10	FRONT DOOR VISOR (L+R)	11 X	2	\$ 300.00	100
11	FRONT DOOR VISOR CHROME STRIP (L+R)	11 X	2	\$ 300.00	X
12	CENTER PILLAR SEALANT	11 X	1	\$ 120.00	X
13	REAR DOOR INNER BOARD CLIPS	11 X	10	\$ 100.00	50
14	REAR DOOR VISOR (L+R)	11 X	2	\$ 300.00	100
15	REAR DOOR VISOR CHROME STRIP (L+R)	11 X	2	\$ 300.00	X
16	ROCKER PANEL SEALANT	11 X	1	\$ 120.00	X
17	ROCKER PANEL GARNISH CLIPS	11 X	10	\$ 100.00	X
18	REAR WINDSCREEN MOULDING SEALANT	11 X	1	\$ 120.00	X
19	TAIL LAMP CLIPS (L+R)	11 X	4	\$ 80.00	X
20	BOOTLID INNER TRIM CLIPS	11 X	10	\$ 100.00	X
21	REAR CARPLATE	11 X	1	\$ 120.00	X
22	REAR CARPLATE FRAME	11 X	1	\$ 120.00	X

23	REAR BUMPER CLIPS	11 X	10	\$	100.00	X
24	REAR w. nd screen Sealant	see 40	1	\$	120.00	40
25	REAR FENDER INNER TRIM CLIPS (L+R)	11 X	20	\$	200.00	X
26	REAR FENDER COWLING CLIPS (L+R)	11 X	20	\$	200.00	X
27	REAR FENDER MUDFLAP CLIPS (L+R)	11 X	10	\$	100.00	X
28	FRONT TYRE SET	see 4	2	\$	1,600.00	X
29	FRONT RIM SET	MS cut 1/2 450	2	\$	3,000.00	450
30	REAR TYRE SET	see 4	2	\$	1,600.00	X
31	REAR RIM SET	MS cut 450 pc	2	\$	3,000.00	450
				SPECIAL NETT TOTAL		\$ 13,200.00
LABOUR			QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1800	1	\$	9,300.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	1	\$	5,700.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA	120	1	\$	250.00	
4	TO RNR FRONT WINDSCREEN	120	1	\$	400.00	
4	TO RNR REAR WINDSCREEN	120	1	\$	400.00	
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	80	1	\$	400.00	
6	TO RNR DOOR MECHANISM FRONT & BACK	100	1	\$	800.00	
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	11 X	1	\$	120.00	
8	TO RNR UNDERCARRIAGE SYSTEM	11 X	1	\$	250.00	
9	TO CHECK WHEEL ALIGNMENT	60	1	\$	250.00	
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	20	1	\$	150.00	
11	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	11 X	1	\$	150.00	
12	TO CHECK WIRING LAYOUT AND FOG LAMP TOP LAMP FUNCTION	11 X	1	\$	150.00	
13	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	11 X	1	\$	150.00	
14	TO RNR TYRE AND WHEEL BALANCING	11 X	1	\$	250.00	
15	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11 X	1	\$	400.00	
16	TO DO WATER LEAK TEST .	11 X	1	\$	80.00	
17	TO RNR FUEL TANK TO ASSIST WORK LOAD	60	1	\$	250.00	
				TOTAL		\$ 19,450.00
				GRAND TOTAL COST		\$ 32,650.00

\$ 21,675.50
 - 20%
 17,340.40

99797 82

P-20144.38
20%
P-16115.50
S.N-1280.00
L-4280.00
21675.50
17340.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		11 Nov 2019 17:34 Edit Adj Rpt	S\$17,300.00 Edit Estimates	S\$17,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HO LAI LIN , ID: S0171572J									
Vehicle Reg. No.: SMA6897E		Date of Loss: 09/11/2019 17:00 - :59 [16 Months and 22 Days From LTA Reg. Date (Man Yr)]							
Claim Type: TP / SNM19D205334C02		Policy/Cover Note No.: DMPCSN30799418000							
Vehicle Reg. No. (Insured): 5MG1464Y		Policy No. (Claimant): D19MPC0003005							
		Excess: S\$1,000.00							
Repairer: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMA6897E (SNM19D205334C02)
[SMG1464Y]
TP
HO LAI LIN
Nov 9 2019 5:00PM
[-]
RICO 60 AUTO SERVICES PTE LTD

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	30/12/19 09:46	General View							 Load JPG	☒		
2	30/12/19 09:46	General View							 Load JPG	☒		
3	30/12/19 09:46	General View							 Load JPG	☒		
4	30/12/19 09:46	General View							 Load JPG	☒		
5	30/12/19 09:46	General View							 Load JPG	☒		
6	30/12/19 09:46	General View							 Load JPG	☒		
7	30/12/19 09:46	General View							 Load JPG	☒		
8	30/12/19 09:46	General View							 Load JPG	☒		
9	30/12/19 09:47	General View							 Load JPG	☒		
10	30/12/19 09:47	General View							 Load JPG	☒		
11	30/12/19 09:47	General View							 Load JPG	☒		
12	30/12/19 09:47	General View							 Load JPG	☒		
13	30/12/19 09:47	General View							 Load JPG	☒		
14	30/12/19 09:47	General View							 Load JPG	☒		
15	30/12/19 09:47	General View							 Load JPG	☒		
16	30/12/19 09:47	General View							 Load JPG	☒		
17	30/12/19 09:47	General View							 Load JPG	☒		
18	30/12/19 09:47	General View							 Load JPG	☒		
19	30/12/19 09:47	General View							 Load JPG	☒		
20	30/12/19 09:47	General View							 Load JPG	☒		
21	30/12/19 09:47	General View							 Load JPG	☒		
22	30/12/19 09:47	General View							 Load JPG	☒		
23	30/12/19 09:47	General View							 Load JPG	☒		
24	30/12/19 09:47	General View							 Load JPG	☒		
25	30/12/19 09:47	General View							 Load JPG	☒		
26	30/12/19 09:47	General View							 Load JPG	☒		
27	30/12/19 09:47	General View							 Load JPG	☒		
28	30/12/19 09:47	General View							 Load JPG	☒		
29	30/12/19 09:47	General View							 Load JPG	☒		
30	30/12/19 09:47	General View							 Load JPG	☒		
31	30/12/19 09:47	General View							 Load JPG	☒		
32	30/12/19 09:47	General View							 Load JPG	☒		
33	30/12/19 09:47	General View							 Load JPG	☒		
34	30/12/19 09:47	General View							 Load JPG	☒		
35	30/12/19 09:47	General View							 Load JPG	☒		
36	30/12/19 09:47	General View							 Load JPG	☒		
37	30/12/19 09:47	General View							 Load JPG	☒		
38	30/12/19 09:47	General View							 Load JPG	☒		
39	30/12/19 09:47	General View							 Load JPG	☒		
40	30/12/19 09:47	General View							 Load JPG	☒		
41	30/12/19 09:47	General View							 Load JPG	☒		
42	30/12/19 09:47	General View							 Load JPG	☒		
43	30/12/19 09:47	General View							 Load JPG	☒		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	30/12/19 09:47	General View	 Load JPG	☒
45	30/12/19 09:47	General View	 Load JPG	☒
46	30/12/19 09:47	General View	 Load JPG	☒
47	30/12/19 09:47	General View	 Load JPG	☒
48	30/12/19 09:47	General View	 Load JPG	☒
49	30/12/19 09:47	General View	 Load JPG	☒
50	30/12/19 09:47	General View	 Load JPG	☒
51	30/12/19 09:47	General View	 Load JPG	☒
52	30/12/19 09:47	General View	 Load JPG	☒
53	30/12/19 09:47	General View	 Load JPG	☒
54	30/12/19 09:47	General View	 Load JPG	☒
55	30/12/19 09:47	General View	 Load JPG	☒
56	30/12/19 09:47	General View	 Load JPG	☒
57	30/12/19 09:47	General View	 Load JPG	☒
58	30/12/19 09:47	General View	 Load JPG	☒
59	30/12/19 09:47	General View	 Load JPG	☒
60	30/12/19 09:47	General View	 Load JPG	☒
61	30/12/19 09:47	General View	 Load JPG	☒
62	30/12/19 09:47	General View	 Load JPG	☒
63	30/12/19 09:47	General View	 Load JPG	☒
64	30/12/19 09:47	General View	 Load JPG	☒
65	30/12/19 09:47	General View	 Load JPG	☒
66	30/12/19 09:47	General View	 Load JPG	☒
67	30/12/19 09:47	General View	 Load JPG	☒
68	30/12/19 09:47	General View	 Load JPG	☒
69	30/12/19 09:47	General View	 Load JPG	☒
70	30/12/19 09:47	General View	 Load JPG	☒
71	30/12/19 09:47	General View	 Load JPG	☒
72	30/12/19 09:47	General View	 Load JPG	☒
73	30/12/19 09:47	General View	 Load JPG	☒
74	30/12/19 09:47	General View	 Load JPG	☒
75	30/12/19 09:47	General View	 Load JPG	☒
76	30/12/19 09:47	General View	 Load JPG	☒
77	30/12/19 09:47	General View	 Load JPG	☒
78	30/12/19 09:47	General View	 Load JPG	☒
79	30/12/19 09:47	General View	 Load JPG	☒
80	30/12/19 09:47	General View	 Load JPG	☒
81	30/12/19 09:47	General View	 Load JPG	☒
82	30/12/19 09:47	General View	 Load JPG	☒
83	30/12/19 09:47	General View	 Load JPG	☒
84	30/12/19 09:47	General View	 Load JPG	☒
85	30/12/19 09:47	General View	 Load JPG	☒
86	30/12/19 09:47	General View	 Load JPG	☒
87	30/12/19 09:47	General View	 Load JPG	☒
88	30/12/19 09:47	General View	 Load JPG	☒
89	30/12/19 09:47	General View	 Load JPG	☒
90	30/12/19 09:47	General View	 Load JPG	☒
91	30/12/19 09:47	General View	 Load JPG	☒
92	30/12/19 09:47	General View	 Load JPG	☒
93	30/12/19 09:47	General View	 Load JPG	☒
94	30/12/19 09:47	General View	 Load JPG	☒
95	30/12/19 09:47	General View	 Load JPG	☒
96	30/12/19 09:47	General View	 Load JPG	☒
97	30/12/19 09:49	Reinspection Photo	 Load JPG	☒
98	30/12/19 09:49	Reinspection Photo	Load JPG	☒
99	30/12/19 09:49	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	30/12/19 09:49	Reinspection Photo		☒
101	30/12/19 09:49	Reinspection Photo		☒
102	30/12/19 09:49	Reinspection Photo		☒
103	30/12/19 09:49	Reinspection Photo		☒
104	30/12/19 09:49	Reinspection Photo		☒
105	30/12/19 09:49	Reinspection Photo		☒
106	30/12/19 09:49	Reinspection Photo		☒
107	30/12/19 09:49	Reinspection Photo		☒
108	30/12/19 09:49	Reinspection Photo		☒
109	30/12/19 09:49	Reinspection Photo		☒
110	30/12/19 09:49	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 10:11	Supplementary		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	06/12/19 18:58	Accident Statement		☐
2	06/12/19 18:59	Accident Statement		☐
3	06/12/19 18:59	Accident Statement		☐
4	06/12/19 19:01	Accident Statement		☐
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	11/11/19 15:39	Accident Photo		☒
2	11/11/19 15:39	Accident Photo		☒
3	11/11/19 15:39	Accident Photo		☒
4	11/11/19 15:39	Accident Photo		☒
5	11/11/19 15:39	Accident Photo		☒
6	11/11/19 15:39	Accident Photo		☒
7	11/11/19 15:39	Accident Photo		☒
8	11/11/19 15:39	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	11/11/19 15:35	Accident Sketch Plan		☒
2	11/11/19 15:35	Accident Sketch Plan		☒
3	11/11/19 15:36	POLICE REPORT		☒
4	11/11/19 15:36	POLICE REPORT		☒
5	11/11/19 15:36	POLICE REPORT		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020021/UYF3E2

Date: 17/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30799418000
 Claimant Vehicle No: SMA6897E Insured Vehicle No: SMG1464Y
 Date of Loss: 09/11/2019 Nature of Claim: TP Claim No: SNM19D205334C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA6897E
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU185593
 Reg. Date: 18/06/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU685513
 Colour: Beige Odometer: 23910 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	75,947.82	17,395.50	58,552.32	77.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,850.00	4,280.00	15,570.00	78.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	95,797.82	21,675.50	74,122.32	77.37
Approved Total (Overridden) (S\$)		17,300.00		
(S\$)	95,797.82	17,300.00	78,497.82	81.94
+ GST 7.00/7.00% (S\$)	6,705.85	1,211.00	5,494.85	81.94
Nett Amount (S\$)	102,503.67	18,511.00	83,992.67	81.94

INSPECTION

Date of Assignment: 11/11/2019
 Date Inspected: 12/11/2019 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
 8, KAKI BUKIT AVENUE 4, #02-24,
 PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2020)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6897E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN MOULDING	Necessary	197.70 FL	*121.20 FL
2	2		*HEADLAMP (L+R)	Not Necessary	1,954.80 FL	*- FL
3	2		*HEADLAMP BRACKET (L+R)	Not Necessary	247.20 FL	*- FL
4	1		*FRONT BUMPER	Deformed / Torn	895.90 FL	*474.40 FL
5	2		*FRONT BUMPER RETAINER (L+R)	Not Necessary	136.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	512.00 FL	*- FL
7	2		*FRONT BUMPER BRACKET (L+R)	Not Necessary	176.00 FL	*- FL
8	1		*FRONT BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	321.00 FL	*- FL
10	1		*FRONT BUMPER TOP SEAL	Not Necessary	142.10 FL	*- FL
11	1		*FRONT BUMPER GRILLE	Not Necessary	498.00 FL	*- FL
12	1		*FRONT BUMPER GRILLE BASE	Not Necessary	412.00 FL	*- FL
13	2		*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	830.00 FL	*- FL
14	2		*FRONT BUMPER FOG LAMP TOP LAMP (L+R)	Not Necessary	876.40 FL	*- FL
15	2		*FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	410.00 FL	*- FL
16	2		*FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	Not Necessary	593.60 FL	*- FL
17	1		*FRONT BUMPER UNDERCOVER	Not Necessary	289.70 FL	*- FL
18	1		*FRONT FENDER (L+R)	N/S Dented / O/S Repair	1,795.00 FL	*487.20 FL
19	2		*FRONT FENDER QUARTER GARNISH (L+R)	Not Necessary	160.00 FL	*- FL
20	2		*FRONT FENDER INNER PANEL (L+R)	Repair	2,031.80 FL	*- FL
21	2		*FRONT FENDER COWLING (L+R)	Not Necessary	197.40 FL	*- FL
22	2		*FRONT FENDER MUDFLAP (L+R)	Not Necessary	170.80 FL	*- FL
23	1		*A PILLAR (L+R)	N/S Repair / O/S Dented	2,483.80 FL	*1,242.90 FL
24	2		*FRONT DOOR (L+R)	Badly Dented	2,508.80 FL	*2,508.80 FL
25	2		*FRONT DOOR SIDE MIRROR ASSY (L+R)	Cracked / Cut	1,378.40 FL	*1,277.20 FL
26	1		*FRONT DOOR SIDE MIRROR COVER (L+R)	N/S Cracked	408.20 FL	*105.00 FL
27	2		*FRONT DOOR SIDE MIRROR SIGNAL LAMP (L+R)	Not Necessary	347.00 FL	*- FL
28	2		*FRONT DOOR HANDLE (L+R)	N/S Scratched / O/S Broken	510.80 FL	*410.00 FL
29	1		*FRONT DOOR HANDLE END CAP (L+R)	O/S Broken	181.80 FL	*35.00 FL
30	2		*FRONT DOOR LOCK CYLINDER (L+R)	Not Necessary	687.80 FL	*- FL
31	1		*FRONT DOOR LOCK SWITCH (L+R)	O/S Broken	400.20 FL	*200.10 FL
32	1		*FRONT DOOR WINDOW MOULDING (L+R)	O/S Bent	274.60 FL	*101.00 FL
33	1		*FRONT DOOR INNER LOCK (L+R)	O/S Twisted / Jammed	835.00 FL	*191.50 FL
34	2		*FRONT DOOR INNER LOCK CATCH (L+R)	Not Necessary	186.00 FL	*- FL
35	2		*FRONT DOOR INNER BOARD (L+R)	Deformed / Cracked	1,431.68 FL	*1,431.68 FL
36	2		*FRONT DOOR INNER BOARD SWITCH (L+R)	Not Necessary	1,360.00 FL	*- FL
37	1		*FRONT DOOR POWER WINDOW MOTOR (L+R)	O/S Jammed	567.80 FL	*283.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT DOOR WINDOW REGULATOR (L+R)	O/S Bent	998.60 FL	*385.00 FL
39	1		*FRONT DOOR HINGE (UPPER & LOWER) (L+R) (4PCS)	O/S Bent (2pcs only)	378.80 FL	*130.00 FL
40	1		*FRONT DOOR CHECKER (L+R)	O/S Twisted	157.20 FL	*78.60 FL
41	2		*FRONT DOOR WEATHERSTRIP (L+R)	Necessary	395.20 FL	*296.40 FL
42	2		*FRONT DOOR INNER WEATHERSTRIP (L+R)	Necessary	399.80 FL	*160.00 FL
43	1		*CENTER PILLAR (L+R)	O/S Badly Dented	3,960.00 FL	*1,480.00 FL
44	2		*REAR DOOR (L+R)	Badly Dented / Bent	2,090.00 FL	*2,090.00 FL
45	2		*REAR DOOR HANDLE (L+R)	Not Necessary	323.20 FL	*- FL
46	2		*REAR DOOR HANDLE END CAP (L+R)	Not Necessary	181.60 FL	*- FL
47	2		*REAR DOOR WINDOW MOULDING (L+R)	Not Necessary	274.60 FL	*- FL
48	1		*REAR DOOR INNER LOCK (L+R)	N/S Twisted	835.00 FL	*191.50 FL
49	2		*REAR DOOR INNER LOCK CATCH (L+R)	Not Necessary	186.00 FL	*- FL
50	2		*REAR DOOR INNER BOARD (L+R)	Deformed / Cracked	1,255.60 FL	*1,255.60 FL
51	2		*REAR DOOR INNER BOARD SWITCH (L+R)	Not Necessary	1,206.30 FL	*- FL
52	1		*REAR DOOR POWER WINDOW MOTOR (L+R)	O/S Jammed	567.80 FL	*283.90 FL
53	1		*REAR DOOR REGULATOR (L+R)	O/S Bent	998.60 FL	*385.00 FL
54	1		*REAR DOOR HINGE (UPPER & LOWER) (L+R)	O/S Twisted	366.80 FL	*65.00 FL
55	1		*REAR DOOR CHECKER (L+R)	O/S Twisted	138.80 FL	*69.40 FL
56	2		*REAR DOOR WEATHERSTRIP (L+R)	Necessary	375.20 FL	*266.00 FL
57	2		*REAR DOOR INNER WEATHERSTRIP (L+R)	Necessary	370.00 FL	*160.00 FL
58	2		*ROCKER PANEL (L+R)	Repair	2,445.20 FL	*- FL
59	2		*ROCKER PANEL GARNISH (L+R)	No such part	751.40 FL	*- FL
60	1		*REAR FENDER (L+R)	N/S Badly Dented	3,614.40 FL	*1,768.30 FL
61	1		*REAR FENDER PETROL COVER (LH)	Bent	107.20 FL	*107.20 FL
62	2		*REAR FENDER INNER TRIM (L+R)	Not Necessary	692.00 FL	*- FL
63	2		*REAR FENDER QUARTER GARNISH (L+R)	Not Necessary	160.00 FL	*- FL
64	2		*REAR FENDER COWLING (L+R)	Not Necessary	197.40 FL	*- FL
65	2		*REAR FENDER MUDFLAP (L+R)	Not Necessary	170.80 FL	*- FL
66	1		*TAIL LAMP (L+R)	N/S Cracked	916.00 FL	*362.60 FL
67	2		*TAIL LAMP PANEL (L+R)	Not Necessary	451.80 FL	*- FL
68	1		*BOOTLID	Not Necessary	1,085.60 FL	*- FL
69	1		*BOOTLID LOGO (HYUNDAI)	Not Necessary	70.00 FL	*- FL
70	1		*BOOTLID EMBLEM (ELANTRA)	Not Necessary	68.60 FL	*- FL
71	1		*BOOTLID EMBLEM (S)	Not Necessary	65.50 FL	*- FL
72	2		*BOOTLID LAMP (L+R)	Not Necessary	650.00 FL	*- FL
73	1		*BOOTLID HANDLE	Not Necessary	211.80 FL	*- FL
74	2		*BOOTLID CARPLATE LAMP (L+R)	Not Necessary	186.20 FL	*- FL
75	1		*BOOTLID INNER LOCK	Not Necessary	487.00 FL	*- FL
76	1		*BOOTLID INNER LOCK COVER	Not Necessary	60.00 FL	*- FL
77	1		*BOOTLID INNER LOCK CATCH	Not Necessary	79.00 FL	*- FL
78	1		*BOOTLID INNER TRIM	Not Necessary	548.00 FL	*- FL
79	2		*BOOTLID HINGE (L+R)	Not Necessary	264.00 FL	*- FL
80	2		*BOOTLID STOPPER (L+R)	Not Necessary	36.00 FL	*- FL
81	1		*BOOTLID WEATHER STRIP	Not Necessary	254.00 FL	*- FL
82	1		*REAR BUMPER	Repair	895.50 FL	*- FL
83	2		*REAR BUMPER RETAINER (L+R)	Not Necessary	119.00 FL	*- FL
84	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	475.00 FL	*- FL
85	2		*REAR BUMPER BRACKET (L+R)	Not Necessary	126.00 FL	*- FL
86	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
87	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
88	2		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	624.00 FL	*- FL
89	2		*REAR BUMPER REFLECTOR (L+R)	Not Necessary	240.80 FL	*- FL
90	1		*REAR BUMPER LOWER	Not Necessary	321.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*REAR BUMPER UNDERCOVER	Not Necessary	243.70 FL	*- FL
92	2		*FRONT ABSORBER (L+R)	Not Necessary	974.60 FL	*- FL
93	2		*FRONT LOWER ARM (L+R)	Not Necessary	875.20 FL	*- FL
94	2		*FRONT KNUCKLE (L+R)	Not Necessary	1,089.20 FL	*- FL
95	2		*FRONT KNUCKLE BEARING (L+R)	Not Necessary	370.80 FL	*- FL
96	2		*FRONT BEARING HUB (L+R)	Not Necessary	300.20 FL	*- FL
97	1		*FRONT CROSSMEMBER	Not Necessary	1,254.00 FL	*- FL
98	1		*FRONT STEERING RACK AND PINION ASSY	Not Necessary	2,450.90 FL	*- FL
99	1		*FRONT DRIVE SHAFT	Not Necessary	1,254.90 FL	*- FL
100	2		*FRONT TIE ROD (L+R)	Not Necessary	860.00 FL	*- FL
101	2		*FRONT TIE ROD END (L+R)	Not Necessary	290.00 FL	*- FL
102	1		*FRONT STABILIZER BAR	Not Necessary	762.10 FL	*- FL
103	2		*FRONT STABILIZER LINK (L+R)	Not Necessary	291.20 FL	*- FL
104	2		*REAR ABSORBER (L+R)	Not Necessary	586.00 FL	*- FL
105	2		*REAR LOWER ARM (L+R)	Not Necessary	530.00 FL	*- FL
106	2		*REAR KNUCKLE (L+R)	Not Necessary	692.80 FL	*- FL
107	2		*REAR KNUCKLE BEARING (L+R) }	Not Necessary	794.00 FL	*- FL
108	2		*REAR BEARING HUB (L+R) }	Not Necessary	0.00 FL	*- FL
109	1		*REAR AXLE	Not Necessary	1,385.00 FL	*- FL
110	2		*FRONT DOOR STEP GARNISH (L+R)	Not Necessary	380.00 FL	*- FL
111	2		*FRONT DOOR INNER TRIM (L+R) (NPA)	Repeated	0.00 FL	*- FL
112	2		*FRONT DOOR INNER HANDLE (L+R)	Cracked	967.40 FL	*490.00 FL
113	2		*REAR DOOR STEP GARNISH (L+R)	Deformed	380.00 FL	*136.00 FL
114	2		*REAR DOOR INNER TRIM (L+R) (NPA)	Repeated	0.00 FL	*- FL
115	1		*REAR DOOR INNER HANDLE (L+R)	Cracked (1pc only)	959.80 FL	*245.00 FL
116	1		*FRONT DOOR FRAME INNER TRIM (RH)	Repeated	519.60 FL	*- FL
117	1		*CENTER PILLAR INNER TRIM UPPER (RH)	Deformed / Twisted	416.70 FL	*325.30 FL
118	1		*CENTER PILLAR INNER TRIM LOWER (RH)	Deformed / Twisted	499.10 FL	*288.50 FL
119	1		*REAR DOOR FRAME INNER TRIM (RH)	Twisted	567.40 FL	*255.20 FL
120	1		*FRONT WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
121	10		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
122	1		*FRONT CARPLATE	Not Necessary	120.00 FS	*- FS
123	1		*FRONT CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
124	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
125	20		*FRONT FENDER COWLING CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
126	10		*FRONT FENDER MUDFLAP CLIPS (L+R)	Not Necessary	100.00 FS	*- FS
127	1		*A PILLAR SEALANT	Not Necessary	120.00 FS	*- FS
128	10		*FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*50.00 FS
129	2		*FRONT DOOR VISOR (L+R)	Necessary	300.00 FS	*100.00 FS
130	2		*FRONT DOOR VISOR CHROME STRIP (L+R)	Not Necessary	300.00 FS	*- FS
131	1		*CENTER PILLAR SEALANT	Not Necessary	120.00 FS	*- FS
132	10		*REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*50.00 FS
133	2		*REAR DOOR VISOR (L+R)	Necessary	300.00 FS	*100.00 FS
134	2		*REAR DOOR VISOR CHROME STRIP (L+R)	Not Necessary	300.00 FS	*- FS
135	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
136	10		*ROCKER PANEL GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
137	1		*REAR WINDSCREEN MOULDING SEALANT	Not Necessary	120.00 FS	*- FS
138	4		*TAIL LAMP CLIPS (L+R)	Not Necessary	80.00 FS	*- FS
139	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
140	1		*REAR CARPLATE	Not Necessary	120.00 FS	*- FS
141	1		*REAR CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
142	10		*REAR BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
143	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
144	20		*REAR FENDER INNER TRIM CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
145	20		*REAR FENDER COWLING CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
146	10		*REAR FENDER MUDFLAP CLIPS (L+R)	Not Necessary	100.00 FS	*- FS
147	2		*SET FRONT TYRE	Serviceable	1,600.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
148	1		*SET FRONT RIM	N/S Cut	3,000.00 FS	*450.00 FS
149	2		*SET REAR TYRE	Serviceable	1,600.00 FS	*- FS
150	1		*SET REAR RIM	N/S Cut	3,000.00 FS	*450.00 FS
151	10		*FRONT DOOR FRAME INNER TRIM CLIPS (RH)	Not Necessary	100.00 FS	*- FS
152	10		*CENTER PILLAR INNER TRIM UPPER CLIPS (RH)	Not Necessary	100.00 FS	*- FS
153	10		*CENTER PILLAR INNER TRIM LOWER CLIPS (RH)	Not Necessary	100.00 FS	*- FS
154	10		*REAR DOOR FRAME INNER TRIM CLIPS (RH)	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	91,534.78	21,424.38
- List Item Discount on L Items 20.00/20.00% (S\$)	15,586.96	4,028.88

Total Parts (S\$)	75,947.82	17,395.50
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	New	9,300.00	1,800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	5,700.00	1,800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	120.00
4	TO RNR FRONT WINDSCREEN	New	400.00	120.00
5	TO RNR REAR WINDSCREEN	New	400.00	120.00
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	New	400.00	80.00
7	TO RNR DOOR MECHANISM FRONT & BACK	New	800.00	100.00
8	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	120.00	0.00
9	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
10	TO CHECK WHEEL ALIGNMENT	New	250.00	60.00
11	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	150.00	20.00
12	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	New	150.00	0.00
13	TO CHECK WIRING LAYOUT AND FOG LAMP TOP LAMP FUNCTION	New	150.00	0.00
14	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	0.00
15	TO RNR TYRE AND WHEEL BALANCING	New	250.00	0.00
16	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	400.00	0.00
17	TO DO WATER LEAK TEST	New	80.00	0.00
18	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	60.00
19	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS. (REPEATED)	New	400.00	0.00
Gross Labour Cost (\$\$)			19,850.00	4,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >