

ASS. REC. BY:

REF:

CS3/C12/19020050/Hof302

Special Instruction:

Surveyor: Hock Ann**ASSIGNMENT (Office)**From (Person): Chong Eon Sen of C12 Date/Time: 12.11.19 11.40a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMP 9360M Insured: SDF 108 Uat Workshop m/s Goblin Group Tel: 95280092of 25 Kaki Bukit Rd 4 #03-32 SynergyPolicy No: DMPLEN30049019000 Claim No: SNMM16205337 C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 12.11.19 2.53p.m Person Contacted: Bobo H.O.D. Endorsement: _____
Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SDF 108 U : X
	SMP 9360M : X
	After repair: 13/11/2019

ASS. REC. BY:

H. ADIV
PRS

REF:

C11

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smp 9360m

Yr Regn:

23/10/19.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

H. FREED HYAMO c.c. 1498

Colour:

Atta Gray

A/C: Insured / Std / NI / NA

Sp. Reading

006344

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB71090719

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65/R15

R:

185/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or 8

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

2/11/19

D.O.I.

12/11/19

Survey held at

Goblin Group

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

* Smp 9360m
PRS use

Date / Time

Action / Instruction

Range 1-11.5K

MV - 90000

PV - 50293

NV - 39700

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Rep. Format:

PRS

Lump Sum / L.E.I. /

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019		23 Dec 2019 10:35 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: GOBLIN GROUP PTE. LTD., Co. Reg. No.: 201921619G									
Vehicle Reg. No.: SMP9360M		Date of Loss: 02/11/2019 21:00 - :59							
Claim Type: TP / SNM19D205337C02		Policy/Cover Note No.: DMPCSN30049019000							
Vehicle Reg. No. (Insured): SDF108U		Policy No. (Claimant): 5112041349							
		Excess: S\$0.00							
Repairer: Goblin Group Pte Ltd (HQ) Goblin Group Pte Ltd, 417800 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 12 November 2019 11:40 AM
To: Accident@kscgp.com; Jeffrey Tay
Cc: assignments
Subject: RE: OUR REF: SNM19D205337-SDF108U-CBS- 1st Notice to conduct pre-repair survey (Your Ref: SDF 108U; Our Ref: SMP 9360M/OAC/hk)

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Monday, November 11, 2019 5:43 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205337-SDF108U-CBS- 1st Notice to conduct pre-repair survey (Your Ref: SDF 108U; Our Ref: SMP 9360M/OAC/hk)

Dear Sirs,

John

We refer to the matter above and your email of even date.

Please see enclosed our 2nd Notice to Conduct Pre-Repair Survey. Our client is not agreeable to your proposed motor surveyors as a Single Joint Expert.

The workshop details are as follows:

Goblin Group Pte Ltd

25 Kaki Bukit Road 4,

#03-32 Synergy @ Kaki Bukit,

Singapore 417800

Contact person: Ms Bobo (9328 0092)

Thank you.

Regards,
Hong Kuin
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

To: Jeffrey.Tay@sg.cntaiping.com, Accident@kscgp.com

Sent: Mon, 11 Nov 2019 09:21:32 +0000

Subject:

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, November 11, 2019 5:11 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>;
Accident@kscgp.com

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D205337-SDF108U-CBS- 1st Notice to conduct pre-repair survey (Your Ref: SDF 108U; Our Ref: SMP 9360M/OAC/hk)

Dear Boon Sen,

Please conduct PRS for SMP9360M.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Monday, 11 November, 2019 2:27 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: 1st Notice to conduct pre-repair survey (Your Ref: SDF 108U; Our Ref: SMP 9360M/OAC/hk)

Dear Sirs,

We enclose herewith our 1st Notice to conduct pre-repair survey for your necessary action.

Thank you.

Regards,
Hong Kuin

for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	619G
Vehicle Details	
Vehicle No.:	SMP9360M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	LEB5629491
Chassis No.:	GB71090719
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,671.00
Original Registration Date:	23 Oct 2019
First Registration Date:	23 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$19,340.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2029
PARF Rebate Amount:	\$14,505.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$35,788.00
Total Rebate Amount:	\$50,293.00

The information contained herein is correct as at 13 Nov 2019

OK



Honda Min Price to No Max Depreciation Vehicle Type Category

Home » New Cars » New Car Brands » Honda » Honda Freed Hybrid

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Featured Merchants

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.
Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?
Click here to see all Auspicious Numbers!

Related Articles



5 most established Parallel Importers in the East



New Honda Freed to arrive in Singapore



Honda unveils the Insight Sports Modulo concept



Compare

Honda Freed Hybrid (Parallel Imported)

Select Another Make Select The Make

Overview Pricing Photos Research Reviews Specs Features Similar Accessories Pron

Add to Shortlist

Submit a Review

Report Error

Share



USER RATINGS:

(3 reviews)

Details

Sold by 47 dealers » Show full list
Built in Japan (launched 2016)
Variants 6 submodel(s) » Show pricelist
Predecessor Honda Freed Hybrid (2014-2015)
Promotion \$109,999 Honda Sensing Model! "C" Package! Guaran COE Without Up! Full Accessories, CASETRUST SVTA Accredited!

» View 1 promotions for Freed Hybrid

Add to Shortlist

We have some dealers currently running very good deals on the Honda Freed Hybrid. Get them to contact you directly with more info.

Name*

Contact No*



I'm not a robot

reCAPTCHA
Privacy Terms

Submit

Submodel	Price	Depreciation	ECO	Power	Detailed
1.5 G (A) <input checked="" type="checkbox"/>	\$106,000 Pricelist	-	25km/L	135bhp	Specs Fei
1.5 G Honda Sensing (A) <input checked="" type="checkbox"/>	\$108,000 Pricelist	-	25km/L	135bhp	Specs Fei
1.5 G C Package Honda Sensing (A)	\$110,000 Pricelist	-	25km/L	135bhp	Specs Fei
1.5 G Dual Power Sliding Doors (A)	\$110,000 Pricelist	-	25km/L	135bhp	Specs Fei
1.5 G Honda Sensing Dual Power Sliding Doors (A)	\$112,000 Pricelist	-	25km/L	135bhp	Specs Fei
1.5 G Welcab (A)	\$130,000 Pricelist	-	26.6km/L	135bhp	Specs Fei

☒ Verified Ready Stocks are vehicles that have cleared all LTA paperwork and ready to be registered immediately. This is verified by sgCarMart with the VITAS Approval Code (VAC) issued by LTA.

» View all the Honda Freed Hybrid that are Ready Stock.

Showing 9 out of 47 dealers selling this vehicle

Miracle Automobile
Tel: 91352273

Speedo Motoring
☒ This Dealer has Ready Stocks
Tel: 67697757 / 86887883

Car Pulse
Tel: 97616452

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 18:22
Date Of Accident	02/11/2019 21:05
Exact Location Of Accident	ALONG VICTORIA STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP9360M
Insured/Policyholder	
Name Of Registered Owner	GOBLIN GROUP PTE. LTD.
Co Reg No	201921619G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93280092

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5112041349
Cover Note Number	

Driver

Name of Driver	IBRAHIM BIN MOHD
NRIC No	S1562165F
Date Of Birth	02/09/1962
Occupation	OUTDOOR
Date Of Driving Pass	19/02/1991
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90501239
Fax Number	
Contact Number	
EMail Address	IBRAHIMMOHD161923@GMAIL.COM

Address BLK 209 BOON LAY DRIVE #01-293

Postcode 640209

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name JURONG WEST NPC

Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/20191103/2009;

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WITH OWNER/DRIVER

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDF108U

Vehicle Make/Model/Colour B.M.W. / 740LI AT SR HID DSC NAV HUD INT A/STR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]


IDAC KAKI BUKIT (YAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@vicom.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Accident Sketch Plan

A-SMP9360M

B- QDE108V

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vacb@vicom.com.sg

Reporting Centre Personnel's Signature

Name

NRIC/FIN No



**SINGAPORE
POLICE FORCE**



T/20191103/2009

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20191103/2009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/11/2019 03:10		Vide Report No.:		Station Diary No.: 9	
Name of Informant: IBRAHIM BIN MOHD					
Address: APT BLK 209 BOON LAY PLACE #01-293 SINGAPORE 640209					
ID Type / ID No.: NRIC NO / S1582165F		Contact No.: Home/Office: Mobile: 90501239			
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 57	Date of Birth: 02/09/1962	Type of Informant: Driver		
Race: Malay		Language: English		Institution / School Name:	
Occupation: GRAB DRIVER		Driving Licence Information: Class: 2B,3 Date of Expiry:			

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 02/11/2019 21:05	Type of Location: X-Junction
Location: Along Road 1 VICTORIA STREET				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDF108U						0
SMP9360M	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191103/2009

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20191103/2009

CONTINUATION OF REPORT


Name	IBRAHIM BIN MOHD	ID No.	S1562165F
Related Vehicle	NIL	Contact No.	90501239
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/11/2019 at about 2105hrs, I was travelling along Victoria Street when suddenly, I heard a Sound and felt a slight impact. I was not sure of what had happened and check my mirrors for anything out of the norm. However, I did not notice anything but I decided to stop and make a check on my vehicle. I checked and discovered damage to the rear right bumper of my vehicle. I checked the in car camera and discovered a vehicle had hit onto the rear right portion of my vehicle and drove off quickly. The incident is recorded in my in car camera. Thus, I made a Police report. No one was injured from this incident.



**SINGAPORE
POLICE FORCE**



T/20191103/2009

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20191103/2009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: SN 126 J / Sgt 2 MUHAMMAD ADNAN BIN MOHAMED IBRAHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/11/2019 03:10
Officer In Charge Of Case: TP / HRT / Staff Sgt MUHAMMAD KHAIRIL BIN KAMAL Contact No. 65476131	Classification Of Case:

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019		23 Dec 2019 10:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	GOBLIN GROUP PTE. LTD., Co. Reg. No.: 201921619G								
Vehicle Reg. No.:	SMP9360M	Date of Loss: 02/11/2019 21:00 - :59 [10 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D205337C02	Policy/Cover Note No.: DMPCSN30049019000							
Vehicle Reg. No. (Insured):	SDF108U	Policy No. (Claimant): 5112041349							
		Excess: S\$0.00							
Repairer:	Goblin Group Pte Ltd (HQ) Goblin Group Pte Ltd, 417800 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 03/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMP9360M (SNM19D205337C02)

[SDF108U]

TP








GOBLIN GROUP PTE. LTD.

Nov 2 2019 9:00PM



















[-]

Goblin Group Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>		
No	Finalized On	VAC (Kaki Bukit)		Thumbnail		Print							
1	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
2	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
3	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
4	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
5	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
6	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
7	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
8	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
9	04/11/19 18:30	Accident Photo [Linked Accident Report Documents]		Load JPG		<input checked="" type="checkbox"/>							
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail		Print							
1	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
2	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
3	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
4	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
5	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
6	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
7	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
8	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
9	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
10	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
11	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
12	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
13	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
14	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
15	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
16	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
17	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
18	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
19	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
20	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
21	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
22	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
23	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
24	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
25	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
26	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
27	24/12/19 18:25	General View		Load JPG		<input checked="" type="checkbox"/>							
28	24/12/19 18:25	After Repair Photo		Load JPG		<input checked="" type="checkbox"/>							
29	24/12/19 18:25	After Repair Photo		Load JPG		<input checked="" type="checkbox"/>							
30	24/12/19 18:25	After Repair Photo		Load JPG		<input checked="" type="checkbox"/>							

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
31	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
32	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
33	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
34	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
36	24/12/19 18:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	04/11/19 18:30	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 18:30	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 18:30	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 18:30	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 18:30	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/12/19 19:25	Accident Statement	 Load HTM	
2	06/12/19 19:27	Accident Statement	 Load HTM	
3	06/12/19 19:33	Accident Statement	 Load HTM	
4	06/12/19 19:34	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/11/19 18:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	04/11/19 18:30	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	04/11/19 18:30	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	04/11/19 18:30	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
4	04/11/19 18:30	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
5	04/11/19 18:30	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19020050/HCF3E2

Date: 26/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30049019000
Claimant Vehicle No :	SMP9360M	Insured Vehicle No :	SDF108U
Date of Loss:	02/11/2019	Nature of Claim: TP	Claim No: SNM19D205337C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP9360M		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5629491
Reg. Date:	23/10/2019 (Man. Year: 2019)	Chassis No:	GB71090719
Colour:	Grey	Odometer:	6344 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/12/2019	
Date Inspected:	12/11/2019 Inspected At:	Goblin Group Pte Ltd (HQ) 25 Kaki Bukit Road 4 # 03-32 Synergy Singapore 417800
Estimated Period of Repair:	2.0 days	

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 - \$1,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2019)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP9360M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >