





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/11/2019

User ID : JeongCH

Section A - Accident Details		
Registration Number	SG5574R	
Case Reference Number	BUS/10/18/5050	
Registration Date	8/31/2016	
Company Type	SMRT Buses Ltd	
Make	VOLVO B9TL DD	
Model	B9TL	
Name of Driver	Safwan Bin Aspan	
Type of Accident	Side Swipe	
Accident Date and Time	10/28/2018 6:18 PM	
Accident Reported Date and Time	11/7/2018 3:31 PM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle Issued?	No	
Job Card Number	24104202	
Special Instruction to ARC, if any	RIGHT CENTER PORTION DAMAGED SLK8045T - TP INSURED WITH AIG - LEFT FRONT PORTION DAMAGED	
Prepared Date and Time	11/6/2019 1:59 PM	
Chassis Number	YV3S4P927GA179444	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,132.00</b>	<b>\$697.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	1.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	STEVE CHEN
ARC / Surveyor Sign Off Date	06/11/2019 2:02 PM	06/11/2019 6:28 PM
Signature		
Remarks	Photo after paint	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/11/2019

User ID : JeongCH

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION CENTER	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$602.00	\$432.00
Total Spray Painting & Panel Beating	\$602.00	\$432.00

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 1 days.

Sun Pin (Ukk)

TP without Prejudice.

Lump Sum Repair.

After Repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: