

Past to Asher, Thanks



### SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 13/11/2019

User ID : CatherineLee

| Section A - Accident Details       |   |
|------------------------------------|---|
| Registration Number                | SG5574R   |
| Case Reference Number              | BUS/10/18/5050  |
| Registration Date                  | 31/8/2016   |
| Company Type                       | SMRT Buses Ltd  |
| Make                               | VOLVO B9TL DD   |
| Model                              | B9TL  |
| Name of Driver                     | Safwan Bin Aspan  |
| Type of Accident                   | Side Swipe  |
| Accident Date and Time             | 28/10/2018 6:18 PM  |
| Accident Reported Date and Time    | 7/11/2018 3:31 PM   |
| Is Surveyor Required?              | Yes   |
| Survey by                          |   |
| Vehicle is Towed Back?             | No  |
| Towed Back Date and Time           |   |
| Replacement Vehicle issued?        | No  |
| Job Card Number                    | 24104202  |
| Special Instruction to ARC, if any | RIGHT CENTER PORTION DAMAGED<br>SLK8045T - TP INSURED WITH AIG - LEFT FRONT PORTION DAMAGED |
| Prepared Date and Time             | 6/11/2019 1:59 PM   |
| Chassis Number                     | YV3S4P927GA179444   |
| Mileage                            |   |
| Work Shop                          |   |
| Repair Completion Date and Time    |   |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| Section B - Summary of Repair Estimates |                    |                                     |
|---|--------------------|-------------------------------------|
| Summary of Repair Estimates             |                    |                                     |
|   | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Labour Cost                       | \$530.00           | \$265.00                            |
| Total Spray Cost                        | \$602.00           | \$432.00                            |
| Total Spare Part Cost                   | \$0.00             | \$0.00                              |
| Total Other Cost                        | \$0.00             | \$0.00                              |
| <b>TOTAL COST</b>                       | <b>\$1,132.00</b>  | <b>\$697.00</b>                     |
| Lump Sum Total                          | \$0.00             | \$0.00                              |
| Number of Repair Days                   | 1.0                | 1.0                                 |
| Prepared / Adjusted By                  | Jeong Choon Hwee   | Sun Pin (LKK)                       |
| ARC / Surveyor Sign Off Date            | 06/11/2019 2:02 PM | 06/11/2019 6:28 PM                  |
| Signature                               |                    |                                     |
| Remarks                                 |                    | Photo after paint                   |

| Section C - Quotation and Accident Invoice Details |  |                |  |
|--|--|----------------|--|
| Quotation Number                                   |  | Invoice Number |  |
| Quotation Date                                     |  | Invoice Date   |  |
| Invoice Amount                                     |  | Prepared Date  |  |



## SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 13/11/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

| Job Scope                   | Quotation from AR | Adjusted by Surveyor, if applicable |
|-----------------------------|-------------------|-------------------------------------|
| TO REPAIR RH PORTION CENTER | \$530.00          | \$265.00                            |
| Total Labour                | \$530.00          | \$265.00                            |

#### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO PUTTY & RESPRAY                   | \$602.00           | \$432.00                            |
| Total Spray Painting & Panel Beating | \$602.00           | \$432.00                            |

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope         | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------|--------------------|-------------------------------------|
| Total Other Costs |                    |                                     |

#### Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|-----------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Total       |         |              |           |          |                 |              |                  |                    |                   |

#### Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|-----------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |                 |              |                  |           |                |





## SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 80 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63665592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 07/11/2019

User ID : JeongCH

| Section A: Accident Details        |   |
|------------------------------------|---|
| Registration Number                | SG5574R   |
| Case Reference Number              | BUS/10/18/5050  |
| Registration Date                  | 8/31/2018   |
| Company Type                       | SMRT Buses Ltd  |
| Make                               | VOLVO B9TL DD   |
| Model                              | B9TL  |
| Name of Driver                     | Sefwan Bin Aspari   |
| Type of Accident                   | Side Swipe  |
| Accident Date and Time             | 10/28/2018 6:18 PM  |
| Accident Reported Date and Time    | 11/7/2018 3:31 PM   |
| Is Surveyor Required?              | Yes   |
| Survey by                          |   |
| Vehicle is Towed Back?             | No  |
| Towed Back Date and Time           |   |
| Replacement Vehicle Issued?        | No  |
| Job Card Number                    | 24104202  |
| Special Instruction to ARC, if any | RIGHT CENTER PORTION DAMAGED<br>SLK8045T - TP INSURED WITH AIG - LEFT FRONT PORTION DAMAGED |
| Prepared Date and Time             | 11/6/2019 1:59 PM   |
| Chassis Number                     | YV3S4P927GA179444   |
| Mileage                            |   |
| Work Shop                          |   |
| Repair Completion Date and Time    |   |

| Section B: Summary of Repair Estimates |   |   |
|--|---|---|
| Summary of Repair Estimates            |   |   |
|  | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost                      | \$530.00  | \$265.00  |
| Total Spray Cost                       | \$602.00  | \$432.00  |
| Total Spare Part Cost                  | \$0.00  | \$0.00  |
| Total Other Cost                       | \$0.00  | \$0.00  |
| TOTAL COST                             | \$1,132.00  | \$697.00  |
| Lump Sum Total                         | \$0.00  | \$0.00  |
| Number of Repair Days                  | 1.0   | 1.0   |
| Prepared / Adjusted By                 | Jeong Choon Hwee  | STEVE CHEN  |
| ARC / Surveyor Sign Off Date           | 06/11/2019 2:02 PM  | 06/11/2019 6:28 PM  |
| Signature                              |  |  |
| Remarks                                |   | Photo after paint   |

| Section C: Quotation and Accident Invoice Details |  |                |  |
|---|--|----------------|--|
| Quotation Number                                  |  | Invoice Number |  |
| Quotation Date                                    |  | Invoice Date   |  |
| Invoice Amount                                    |  | Prepared Date  |  |



# SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 50 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 07/11/2019

User ID : JeongCH

| Section D: Details of Repair Estimates                                    |         |                    |           |          |                 |                                     |                  |                    |                   |
|---|---------|--------------------|-----------|----------|-----------------|-------------------------------------|------------------|--------------------|-------------------|
| <b>Part 1: Labour Works</b>   |         |                    |           |          |                 |                                     |                  |                    |                   |
| Job Scope   |         | Quotation from ARC |           |          |                 | Adjusted by Surveyor, if applicable |                  |                    |                   |
| TO REPAIR RH PORTION CENTER   |         | \$530.00           |           |          |                 | \$265.00                            |                  |                    |                   |
| Total Labour  |         | \$530.00           |           |          |                 | \$265.00                            |                  |                    |                   |
| <b>Part 2: Spray Painting &amp; Panel Beating Related Works</b>           |         |                    |           |          |                 |                                     |                  |                    |                   |
| Job Scope   |         | Quotation from ARC |           |          |                 | Adjusted by Surveyor, if applicable |                  |                    |                   |
| TO PUTTY & RESPRAY  |         | \$602.00           |           |          |                 | \$432.00                            |                  |                    |                   |
| Total Spray Painting & Panel Beating                                      |         | \$602.00           |           |          |                 | \$432.00                            |                  |                    |                   |
| <b>Part 3: Other Costs - Accident and Accident Repair Related Expense</b> |         |                    |           |          |                 |                                     |                  |                    |                   |
| Job Scope   |         | Quotation from ARC |           |          |                 | Adjusted by Surveyor, if applicable |                  |                    |                   |
| Total Other Costs   |         |                    |           |          |                 |                                     |                  |                    |                   |
| <b>Part 4: Spare Parts / Material Usage</b>                               |         |                    |           |          |                 |                                     |                  |                    |                   |
| Part Number   | Portion | Stock Number       | Part Name | Quantity | List Price (\$) | Discount (%)                        | Final Price (\$) | Estimator Approved | Surveyor Approved |
| Total   |         |                    |           |          |                 |                                     |                  |                    |                   |
| <b>Added Spare Parts / Material Usage After Surveyor Signed off</b>       |         |                    |           |          |                 |                                     |                  |                    |                   |
| Part Number   | Portion | Stock Number       | Part Name | Quantity | List Price (\$) | Discount (%)                        | Final Price (\$) | ARC Check          | Surveyor Check    |
| Total   |         |                    |           |          |                 |                                     |                  |                    |                   |

Repair day - 1 days.

Sun Pin (Uchi)

TP without Projudice.

Lump Sum Repair.

After Repair photo.

265  
432  
697.