

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
DAMAGE ASSESSMENT REPORT					
NTUC INCOME INSURANCE CO-OPERATIVE LTD Re			Ref: CS/INC19020113/Evd3s2		
10 Bit to Brief till to the			Date: 22-11-2019		
#05-0 1895		UNION HOUSESINGAPORE			
1TTA	N: AZHARI		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGG 1021M	Veh. Inspected	FBH 4158L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1071002-001	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	13/11/2019	
2. Vehicle Particulars & Condition					
	Make & Model	KAWASAKI NINJA 400R	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	ER400BA07170	Colour	GREEN	
	Odometer	55560 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60 ZR17	METZELER	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60 ZR17	METZELER	5 mm	
	L/H Rear Tyre			mm	
4.	1. Description of Damages				
	THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION.  REPAIR CONDITION SEE DETAILS.				
<b>-</b>	. General Information				
5.	Accident Date 23/06/2019 Inspect Date / Time 13/11/2019 ( 01:42 PM )				
	Survey held at	HKL LIM TEAM MOTORSPORT	•	13/11/2019 (01.42 FW)	
	Survey neid at	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	1				

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: