

ASS REC BY:

REF: esline19020116/Gtd3n2

Special Instructions:

Owner: Steve

ASSIGNMENT (Office)

From (Person): Herzalya B Ibrahim of INC

Date/Time: 13/11/1979 9:47am

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 4511Y Insured: GBJ 5365M

at Workshop m/s C/h02 Tel: 8822 8334

of 30 Bukit Batok Crescent

Policy No: _____ Claim No: MT/1065746-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:48am @ 13/11/14 Person Contacted: Mr. Lee Vehicle: N/A

Date/Time	Action/Instruction
	SLX 4511 Y-X

NEF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bail. or Market Value:	_____		
IDAC Accident Rpt:	_____	Consistent? :	Yes or No
GIA / PR Seen:	_____	Consistent? :	Yes or No
Est. Repairs:	_____ days	Res.:	Yes or No
Lum Sum:	_____ %	3 Val.:	Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vch No: SLX 4511Y Yr Regn: 28/3/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Nissan Sylphy c.c. 1598
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp.Reading: 28696 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MINTQDAB172 0039939
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 7/19/19

Survey held at ETH92 2:15pm

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 12/11/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-79K 21/11/19 Finalize confim \$2732.76 , 4 chgs (Mr Lee)
	(Red: 1556.58) 36%
	RECEIVED 21 NOV 2019

RECEIVED 21 NOV 2013

Date/Time, File Pass to?

☐ : Prel. Report
☒ : Final Report

02/11 Typist
Date/Time. File Return to?

24

References

Long Run / 11/3 = 2732.76

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Interview	(\$
-----------	-----

Tech. Invs (3)

☐ Weekend (9)

Survey Fee:

Transportation

3) Ethanol

CONCLUSIONS

1974-1975

190

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Thursday, 14 November 2019 8:49 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR; Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Re-send with complete details.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 14 November 2019 7:41 AM
To: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear Hazalya,

Kindly assist to provide us the complete details of the below assignment.

Best Regards

G.NIVTTHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim (mailto:hazalya.ibrahim@income.com.sg)

Sent: Wednesday, 13 November 2019 9:47 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Azhari	MT/1071002-001	FBH4158L	HKL LIM TEAM MOTORSPT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim (Keong) / 6275-6656		SGG1021M	23/06/19	6275-6566
2	Chryllis Quah	MT/1070958-001	SCR233P	MAXIMUS RACING PTE LTD	MR PERFORMANCE CENTRE 7 SOON LEE STREET #05-05 USPACE SINGAPORE 627608	Ary Seah / 8858 3131	12:00-16:00	SKT7763A	11/11/19	9638 2477
3	Jared Liu	MT/1071048-001	SLL3226R	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	14:00-16:00	GBJ9737V	11/11/19	Driver waiting
4	Eric Tang	MT/1070984-001	SLR4815C	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	10:30-16:00	XD3747D	12/11/19	

5	Muhammad Airwan	MT/1070829-002	SMD474SH	TRANS EUROKARS PTE LTD	27A TANIONG PERJURU SINGAPORE 609042	Samuel Ng /	15:00-16:00	SJA3340A	11/11/19	
6	Jeff Lin	MT/1071063-001	SMH5296J	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01-75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481		SKJ1748L	08/11/19	
7	Muhammad Airwan	MT/1068445-002	SMH4477K	AUTO INSURE PTE LTD	6 MARSLING LANE	Mr Sam Goh / 31572628		SLJ4787S	21/10/19	9743 6363
8	Charlotte Chew	MT/1067845-002	SML3246X	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Kevin Leong / 81680997	10:00-12:00	SKW4924G	19/10/19	6568 4501
9	Fiona Shen	MT/1055123-002	SLR758K	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Edwin Caina / 91819978	10:00-12:00	FBH1536Z	25/07/19	6568 4501
10	Helena Tan	MT/1070771-002	EM1175U	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	GO CHEE HAN / 9181 7717		SHD1108B	10/11/19	6771 4336
11	Jared Liu	MT/1065746-002	SLX4511Y	ETHOZ AUTOMOTIVE SOLUTIONS LTD	30 BUKIT BATOK CRESCENT SINGAPORE 658075	Lee Chen Sin / 8822 8339		GBJ5365M	07/10/19	6654 7520
12	Jeff Lin	MT/1071022-001	SGG5504K	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131		XE1549S	08/11/19	63161151

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL....

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Steve Chen (LKK Auto)

From: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Sent: Thursday, November 21, 2019 8:30 AM
To: Steve Chen (LKK Auto)
Subject: RE: FINALIZATION REPORT OF SLX-4511-Y NISSAN SYLPHY (TP)(NTUC)

Hi Steve,

Finalize amount confirm and accept.
Please close the case.
Thank you.

Warmest Regards,
Lee Chen Sin

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Wednesday, November 20, 2019 5:20 PM
To: Lee Chen Sin <ChenSin.Lee@ethozgroup.com>
Subject: FINALIZATION REPORT OF SLX-4511-Y NISSAN SYLPHY (TP)(NTUC)

Dear Mr Lee,

Kindly follow up the finalize at below.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Chen (LKK Auto)
Sent: Tuesday, November 19, 2019 5:06 PM
To: Lee Chen Sin
Subject: FINALIZATION REPORT OF SLX-4511-Y NISSAN SYLPHY (TP)(NTUC)

Dear Mr Lee,

Kindly inform that. Revise the finalize \$2732.76 (P/P, before GST). 4 repair days.

Kindly confirm.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	531H
Vehicle Details	
Vehicle No.:	SLX4511Y
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	HR16917295C
Chassis No.:	MNTBBAB17Z0030939
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,792.00
Original Registration Date:	28 Mar 2018
First Registration Date:	28 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$16,792.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2028
PARF Rebate Amount:	\$12,594.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$31,977.00
Total Rebate Amount:	\$44,571.00

The information contained herein is correct as at 13 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 17:25
Date Of Accident	07/10/2019 10:50
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX4511Y
Insured/Policyholder	
Name Of Registered Owner	ETHOZ GROUP LTD
Co Reg No	198104531H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66547777

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.6 CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D19MTRENT000051
Cover Note Number	28/03/2019-27/03/2020

Driver

Name of Driver	SHINICHIRO TAGAMI
NRIC No	G3840244M
Date Of Birth	23/09/1982
Occupation	INDOOR
Date Of Driving Pass	26/02/2007
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86666315
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	37 TUAS VIEW CRESCENT JOTUN SERVICE CENTRE
Postcode	637236
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5365M
Vehicle Make/Model/Colour	NISSAN NV200
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JASECA
NRIC/Passport Number	
Contact Number	63861815
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGU3794D
-----------------------------	----------

Vehicle Make/Model/Colour	SUZUKI SX4
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Rakeswaran Arund
NRIC/IN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I used to drive along the PIE towards Changi.
Suddenly the vehicle in front Vehicle E applied the emergency brake and hit the vehicle E. Vehicle (SGV3794) also jammed brake and hit the Vehicle D. I also cannot manage to stop on time and hit front Vehicle (SGV3794). These another vehicle also (GBJ5365M) hit me on rear.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature
Date & Time

Driver's Signature
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Pate Swaran Arind
Nric/Fin No.

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 12/11/2019

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000051

Accident Date : 07/10/2019

Vehicle No : SLX-4511-Y

Make & Model : NISSAN SYLPHY 1.6 L PREMIUM (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	FRONT BUMPER X R	RESTORE	
1	FRONT NUMBER PLATE BASE / OR	142.20	127.80 ✓
1	REAR BOOTLID X R	RESTORE	
1	REAR BOOTLID EMBLEM CENTRE / MC	52.30	✓
1	REAR BOOTLID EMBLEM "SYLPHY" / MC	98.50	62 ✓
1	REAR BUMPER / 00	652.50	✓
10	REAR BUMPER CLIP / MC	50.00	30 ✓
1	REAR BUMPER SIDE RETAINER LH / OR	38.20	✓
1	REAR BUMPER SIDE RETAINER RH / OR	38.20	✓

Date : 12/11/2019

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000051

Accident Date : 07/10/2019

Vehicle No : SLX-4511-Y

Make & Model : NISSAN SYLPHY 1.6 L PREMIUM (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER INNER BRACKET LH X NN	49.90	
1	REAR BUMPER INNER BRACKET RH X NN	49.90	
1	REAR BUMPER REFLECTOR LH X NN	61.90	
1	REAR BUMPER REFLECTOR RH X NN	61.90	
1	REAR BUMPER FOAM (CENTRE) ? / OR	38.60	/
1	REAR BUMPER FOAM (LH) ? / OR	96.80	/
1	REAR BUMPER FOAM (RH) ? X NN	145.30	
1	REAR END PANEL X R	454.30	
1	REAR END PANEL TOP GARNISH X NN	102.10	

1136.40
- 10%
1022.76

Date : 12/11/2019
 To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D19MTRENT000051 Accident Date : 07/10/2019
 Vehicle No : SLX-4511-Y Make & Model : NISSAN SYLPHY 1.6 L PREMIUM (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	2132.60	
	Discount 10% On Parts	(213.26)	
	<u>Special Nett Item</u>		
1	FRT NUMBER PLATE ✓ OT	35.00 ✓	
1	END PANEL SEALANT x NN	50.00	
1	REVERSE SENSOR ✓ SL	220.00	
	Sub Total	305.00	235
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT FRONT REPAIR	150 200.00	
	TO SPRAY PAINTING ON FRONT AFFECTED AREA	200 250.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ETHOZ

Date : 12/11/2019

To : NTUC INCOME INSURANCE CO-OPERATIVE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000051

Accident Date : 07/10/2019

Vehicle No : SLX-4511-Y

Make & Model : NISSAN SYLPHY 1.6 L PREMIUM (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	LABOUR TO CARRY OUT REAR REPAIR	400 700.00	
	TO SPRAY PAINTING ON REAR AFFECTED AREA	600.00	/
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	/
	SPRAY RUST PROOF ON AFFECTED AREA	30 40.00	
	TO DETACH & RENEW REVERSE SENSOR	30 200.00	
	TO REMOVE & RE-INSTALL SPARE COMPARTMENT TRIMS	30 40.00	
	Sub Total	2065.00	1475
	P- 1072.76		
	N- 235		
	L- 1475		

Remarks:

p/p — 2732.76

4,289.34

SUB TOTAL

GST 7.0 % 300.25

TOTAL 4,589.59

Surveyor's name:

Steve (LKK) 8322 8813 steve@lkkaut.com

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

13/11/19, 2.30pm
4 days
P/P, R, B, L, S, J
14/11/19

PAGE 4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020116/Eld3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 22-11-2019



ATTN: JARED LIU

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 5365M	Veh. Inspected	SLX 4511Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1065746-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	13/11/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MNTBBAB17Z0030939	Colour	GREY
Odometer	28696 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	5 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/10/2019	Inspect Date / Time	13/11/2019 (02:15 PM)
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 4511Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (NPA)(N)	TO REPAIR SEE LABOUR	-	-
1	FRONT NUMBER PLATE BASE (N)	BROKEN	142.20	127.80
1	REAR BOOTLID (NPA)(N)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOTLID EMBLEM CENTRE (N)	NECESSARY	52.30	52.30
1	REAR BOOTLID EMBLEM "SYLPHY" (N)	NECESSARY	98.50	62.00
1	REAR BUMPER (N)	DENTED	652.50	652.50
10	REAR BUMPER CLIP (N)	NECESSARY	50.00	30.00
1	REAR BUMPER SIDE RETAINER LH (N)	BROKEN	38.20	38.20
1	REAR BUMPER SIDE RETAINER RH (N)	BROKEN	38.20	38.20
1	REAR BUMPER INNER BRACKET LH (N)	NOT NECESSARY	49.90	-
1	REAR BUMPER INNER BRACKET RH (N)	NOT NECESSARY	49.90	-
1	REAR BUMPER REFLECTOR LH (N)	NOT NECESSARY	61.90	-
1	REAR BUMPER REFLECTOR RH (N)	NOT NECESSARY	61.90	-
1	REAR BUMPER FOAM (CENTRE)(N)	BROKEN	38.60	38.60
1	REAR BUMPER FOAM (LH)(N)	BROKEN	96.80	96.80
1	REAR BUMPER FOAM (RH)(N)	NOT NECESSARY	145.30	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	454.30	-
1	REAR END PANEL TOP GARNISH (N)	NOT NECESSARY	102.10	-
LESS 10% DISCOUNT			-213.26	-113.64
			1,919.34	1,022.76
SPECIAL NETT ITEMS				
1	FRT NUMBER PLATE (SN)	BENT	35.00	35.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			305.00	235.00
LABOUR				
LABOUR TO CARRY OUT FRONT REPAIR.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.			200.00	150.00

Report Ref No. CS/INC19020116/Etd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON FRONT AFFECTED AREA.		250.00	200.00
	LABOUR TO CARRY OUT REAR REPAIR.INCLUSIVE OF THE REPAIR OF REAR BOOTLID END REAR END PANEL.		700.00	400.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA.		600.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	35.00
	SPRAY RUST PROOF ON AFFECTED AREA.		40.00	30.00
	TO DETACH & RENEW REVERSE SENSOR.		200.00	30.00
	TO REMOVE & RE-INSTALL SPARE COMPARTMENT TRIMS.		40.00	30.00
			2,065.00	1,475.00
GRAND TOTAL			4,289.34	2,732.76

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,732.76
--	--	--	-----------------

Report Ref No. CS/INC19020116/Etd3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.