

ASS. REC. BY:

Steve

REF:

Asm (AXA)

ASSIGNMENT

From:

Date: 13.11.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLK 355B

at Workshop m/s

Alexandra village Industrial Estate

of

B1K1010 Bukit Merah Lane 3 #01-119

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

"Virtual" WP Survey Do not finalized

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X	X
N/S	O/S	

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"mp"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK 355B

Yr Regn:

2/2/1996

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ferrari F355 Spider

c.c. 3496

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

73626

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFF PR48C 000104364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40ZR18

R:

C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

17/9/19

D.O.A.

13/11/19

Survey held at

Exquisite Marques

Des. of Damages: (Frt) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Do Not Finalise

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / L.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL