

SYSTEM

ASS. REC. BY:

Surveyor: Kamith

REP:

081CT119020205/K9d3ⁿ²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Ben Tong

of CTI

Date/Time: 13/11/19 9:49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMQ 23724

Insured:

SJQ 2039T

at Workshop w/s

CarTimes Audolution

Tel:

6471 5111

of

160 Bin Ming Drive # 02-04

Policy No:

PMHCIN 19155919000

Claim No:

SNM19020533/02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

7/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:30am 14/11/19

Person Contacted:

Yulci

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>SMQ 23724 - X</u>
	<u>SJQ 2039T - X</u>
<u>18/11</u>	<u>81323.25 email & cal from (led @ 7076.75, 84%)</u>

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s Car Times
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1.51 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMA 2370U Yr Regn: 11, 19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A) Wagon
 Make: Toy Noah c.c. 1797
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 1751 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZWR 80 . 0386513
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD. A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 9 mm Rear R/Bal. 9 mm
 L/Bal. 9 mm L/Bal. 9 mm
 D.O.A. 7/11/19 D.O.I. 13/11/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear N/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

Date/Time, File Return to?
 2) _____

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Fuel: _____
 Others: _____
 TOTAL: 220

Report Format: NET-TP
 Lump Sum / I.B.I. (\$) 1323.75

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 13 November 2019 9:49 AM
To: assignments@lkkauto.com
Subject: RE: OUR REF :sNM19D205331-SJQ2039T-THL- SMQ 2372 U (D.O.A 07/11/2019) - (YOUR REF: SJQ 2039 T) - PRI

Dear LKK

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMQ 2372U.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: claims@cartimes.com.sg <claims@cartimes.com.sg>
Sent: Tuesday, November 12, 2019 9:03 AM
To: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>
Subject: Re: ****SPAM**** RE: OUR REF :sNM19D205331-SJQ2039T-THL- SMQ 2372 U (D.O.A 07/11/2019) -(YOUR REF: SJQ 2039 T) - PRI

Dear Mr Tang,

Kindly appoint kenneth as the surveyor. Thanks.

Regards,

Yuki Peck

CarTimes Autolution Pte Ltd

160 Sin Ming Drive AutoCity #02-04 Singapore 575722

Tel 6471 5111

www.cartimes.com.sg

Journey Together

On 2019-11-11 13:39, Tang Hock Lye wrote:

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 11.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING
6. KENNETH KONG
2. Kelvin Ang
7. SIMON HO
3. SEE CHEW SENG
8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN
9. MARCUS CHUA
5. XING QUO QIANG
10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the

repair is completed.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com [1] | FB:

www.facebook.com/chinataipingsg/ [2] | WECHAT: 太平獅城

Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

FROM: Claims Dept of CTI

SENT: Monday, November 11, 2019 1:17 PM

TO: Tang Hock Lye <hocklye.tang@sg.cntaiping.com>; Jeffrey Tay <Jeffrey.Tay@sg.cntaiping.com>; claims@cartimes.com.sg

SUBJECT: OUR REF :sNM19D205331-SJQ2039T-THL- SMQ 2372 U (D.O.A 07/11/2019) -(YOUR REF: SJQ 2039 T) - PRI

Dear Ben,

Please conduct PRS for SMQ2372U.

Note : officer in charge - Ben Tang 63896175.

Regards,

Claims Department

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com [1] | FB:

www.facebook.com/chinataipingsg/ [2] | WECHAT: 太平獅城

Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

FROM: claims@cartimes.com.sg [mailto:claims@cartimes.com.sg]

SENT: Monday, 11 November, 2019 9:42 AM

TO: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
CC: Don <don@cartimes.com.sg>
SUBJECT: RE: SMQ 2372 U (D.O.A 07/11/2019) -(YOUR REF: SJQ 2039 T) -
PRI

Dear Claims,

Attached is the PRI for vehicle SMQ 2372 U. Kindly arrange surveyor.
Thanks.

Regards,

Yuki Peck

Links:

- [1] <http://www.sg.cntaiping.com/>
[2] <http://www.facebook.com/chinataipingsg/>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 17:22
Date Of Accident	07/11/2019 13:00
Exact Location Of Accident	FERNVALE LINK FILTER LEFT TO SENGGKENG WEST AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ2372U
Insured/Policyholder	
Name Of Registered Owner	CARTIMES AUTO RENT PTE LTD
Co Reg No	201633634W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97321089
Alternative Phone No	OFFICE-64715111

Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH HYBRID-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	SEE TOH WENG FAI
NRIC No	S7737767J
Date Of Birth	19/12/1977
Occupation	OUTDOOR
Date Of Driving Pass	11/01/2003
Driving Experience	16 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97321089
Fax Number	
Contact Number	
Email Address	AMOSSETOH@GMAIL.COM

Address	BLK 602C PUNGGOL CENTRAL #08-648
Postcode	823602
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM CHOON MENG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ2039T
Vehicle Make/Model/Colour	TOYOTA ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/11/19 around 11:00am, I was travelling along Sengkang East Ave towards Sengkang West Ave. I wait for an coming car to pass. suddenly vehicle B from the rear hit my rear portion of my car.

DECLARATION

I/We declare that the above particulars are true to my/our best knowledge.


 Police Station Seal
 Date & Time


 Driver's Signature
 (If driver is not the witness/observer)
 Date & Time


 Reporting Control Personnel's Signature
 Name: TENG
 NRCCN No: 273457660

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repeal policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agencies/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim involving the settlement of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (b) complying with applicable law in administering, processing, handling and/or dealing with my claim collectively the "Purposes";
- (c) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (d) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (e) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (f) the information so collected under (d) above may be stored / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, committing or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: THO TAN
NRIC No: 87347704D

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel: 6471 5111
 Email: claims@cartimes.com.sg



Vehicle No. SMQ2372U

Car Model : TOYOTA NOAH

DESCRIPTION	REPAIRER ESTIMATE(S\$)	
LIST ITEM		
REAR TAILGATE	\$ R 2,355.00	X
REAR TAILGATE INNER TRIM	\$ Lu 751.00	X
REAR BUMPER <i>751.00</i>	\$ Bu 951.00	✓
REAR BUMPER SIDE RETAINNER LH	\$ Lu 180.00	X
REAR BUMPER SIDE RETAINNER RH	\$ Lu 180.00	X
REAR END PANEL	\$ R 955.00	X
REAR END PANEL TOP GARNISH	\$ Lu 245.00	X
REAR SPARE TYRE PANEL	\$ R 855.00	X
SPARE PANEL TOP COVER	\$ Lu 1,088.00	X
	\$ 7,560.00	
	25%	
	\$ 1,890.00	
	\$ 5,670.00	
Special Nett items		
REVERSE SENSOR	\$ Short 200.00	✓
REVERSE CAMERA	\$ Lu 380.00	X
REAR BUMPER CLIP	\$ Lu 60.00	✓
REAR TAILGATE INNER TRIM CLIP	\$ Lu 30.00	X
REAR WINDSCREEN SEALANT	\$ Lu 30.00	X
	\$ 700.00	
	\$ 6,370.00	

*Not included
 Reverse Bypass*

1323-25

2 days

Auto Consultant/ Vendor notify the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged parts being resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal interference is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Vehicle No. SMQ2372U Car Model : TOYOTA NOAH

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,000.00	2000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 800.00	2500
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ~ 50.00	X
4	To remove & replace reverse camera reverse sensor check for proper function	\$ 60.00	500
5	To remove and refix rear windscreen	\$ ~ 120.00	X
	Labour Total :	\$ 2,030.00	
	TOTAL (PARTS & LABOUR):	8,400	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020205/KQD3N2

Date: 29/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN19155919000
Claimant Vehicle No :	SMQ2372U	Insured Vehicle No :	SJQ2039T
Date of Loss:	07/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205331C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ2372U	Engine No:	2ZR0D64124
Make & Model:	TOYOTA NOAH, 1.8 (A)	Chassis No:	ZWR800386513
Reg. Date:	04/11/2019 (Man. Year: 2019)	Odometer:	1751 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 9 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Goodyear 9 mm	Rear Right Side:	Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,370.00	823.25	5,546.75	87.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	500.00	1,530.00	75.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,400.00	1,323.25	7,076.75	84.25

INSPECTION

Date of Assignment:	26/11/2019		
Date Inspected:	13/11/2019	Inspected At:	Cartimes Autolution Pte Ltd 160 Sin Ming Drive #02-04 Autocity, Singapore 575722
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2019)
Parts: M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMQ2372U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	2,355.00 FL	*- FL
2	1		*REAR TAILGATE INNER TRIM	Serviceable	751.00 FL	*- FL
3	1		*REAR BUMPER	Buckled	951.00 FL	*751.00 FL
4	1		*REAR BUMPER SIDE RETAINNER LH	Serviceable	180.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINNER RH	Serviceable	180.00 FL	*- FL
6	1		*REAR END PANEL	Repair	955.00 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Serviceable	245.00 FL	*- FL
8	1		*REAR SPARE TYRE PANEL	Repair	855.00 FL	*- FL
9	1		*SPARE PANEL TOP COVER	Serviceable	1,088.00 FL	*- FL
10	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
11	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
12	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
13	1		*REAR TAILGATE INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,260.00	1,011.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,890.00	187.75
Total Parts (\$\$)	6,370.00	823.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	1,000.00	200.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	250.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	50.00	0.00
4	TO REMOVE & REPLACE REVERSE CAMERA REVERSE SENSOR CHECK FOR PROPER FUNCTION	New	60.00	50.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
Gross Labour Cost (S\$)			2,030.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >