

22/03/2003

ASS. REC. BY:

REF:

03/CTI/9020242/H036

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Beng Tung of CTI Date/Time: 14/11/19 @ 11.29am

Estimated Cost: Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBP 3785R Insured: SLH 6416K

at Workshop m/s HP MOTO Tel: 8110 3563

of 8 kaki Bukit Avenue 4 #04-32 premier

Policy No: Claim No: SNM/9D205227

Sum Insured: Excess:

Make of Veh: D.O.A. 21/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 12.40pm 14/11/19 Person Contacted: AH DI Vehicle IN/OUT

Date/Time	Action/Instruction	Exchanged (x)
	FBP 3785R - NA/CTI/9019403/h4	DOA: 2/11/19
	SLH 6416K - NA/CTI/9019403/h4	DOA: 2/11/19
	Dismantle: 27/11/2019.	
	After paint 11	workshop updated now complete, waiting parts & painting

ASS. REC. BY: H-ANN

REF: 171

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

FBP 3785R

Yr Regn:

06/06/201

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBP 3785R

at Workshop m/s

HP motor

of

8 kalis Bukit Avela 04-32

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Front

R/Bal.

mm

L/Bal.

mm

D.O.A.

2/11/19

Rear

R/Bal.

5 mm

L/Bal.

mm

D.O.I.

14/11/19

Survey held at

HP motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 5 - 6.5k

repair days - 4 days

* FBP 3785R

PRS cum

mv - 29000

pv - 3618

nv - 25300

RECEIVED 03 JAN 2020

AG 01 - 8110 3563

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

190

Transportation:

S + RS, SI

Phone

Others

TOTAL

190

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Rep. Format:

PRS

Lump Sum / L.E.I. /

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		26 Nov 2019 15:26 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: MUHAMMAD ALFALAH BIN AZNI									
Vehicle Reg. No.: FBP3785R		Date of Loss: 02/11/2019 20:00 - :59							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SLH6416K		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Hp Moto (HQ) 8 KAKI BUKIT AVENUE 4, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 05/12/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Thursday, 14 November 2019 11:29 AM
To: Prestina
Cc: Claims Dept of CTI; General; assignments@lkkauto.com
Subject: RE: OUR REF: SNM19D205227/SLH6416K/BEN - & YOUR REF: FBP3785R - PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K

WITHOUT PREJUDICE

Dear Sirs

We refer to your email below.

We noted that you are not agreeable to our proposed list of surveyors. We will assign our panel surveyor M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please arrange for the survey.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Prestina <prestina@jklc.com.sg>
Sent: Thursday, November 14, 2019 10:46 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; General <general@jklc.com.sg>
Subject: RE: OUR REF: SNM19D205227/SLH6416K/BEN - & YOUR REF: FBP3785R - PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K

WITHOUT PREJUDICE
OUR REF: JK.

Dear Sir/Mdm,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

TAKE NOTICE that we object to all your surveyors sated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose appointment as Single Joint Expert the following surveyors for your consideration:

1. Amos Ong

Please reply within 2 working days

*****OUR FAX LINE IS TEMPORARILY DOWN. KINDLY REPLY VIA EMAIL ONLY.*****

Regards,
Prestina
Legal Executive



UEN No. 53394571B
6A Shenton Way
#04-02 to 08
OUE Downtown Gallery
Singapore 068815

Tel: 6914 2682
Fax: 6429 1048
Email: prestina@jklc.com.sg

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Thursday, November 14, 2019 10:14 AM
To: Prestina <prestina@jklc.com.sg>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205227/SLH6416K/BEN - & YOUR REF: FBP3785R - PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K

WITHOUT PREJUDICE

Dear Sirs

We refer to your email of 13.11.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

Without admission of liability, please provide our surveyor with repair estimates to facilitate direct settlement.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Thursday, November 14, 2019 9:36 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; prestina@jklc.com.sg
Subject: OUR REF: SNM19D205227/SLH6416K/BEN - & YOUR REF: FBP3785R - PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K

Dear Ben,

Please conduct PRS –FBP3785R soonest possible

File with officer-in-charge –Ben Tang - DID 6389 6175

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Prestina [<mailto:prestina@jklc.com.sg>]
Sent: Wednesday, November 13, 2019 5:11 PM
To: Claims Dept of CTI
Cc: Angie Foo; Alfred Toh; Chee So Chow; Ong Chin Kiat
Subject: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE
OUR REF: JK.19.FBP 3785R

Dear Sir/Mdm,

We are instructed by **MUHAMMAD ALFALAH BIN AZNI** to notify you of a road traffic accident on **02.11.2019 at about 2000 hours along Compassvale Crescent** involving our client's vehicle registration number **FBP 3785R** and vehicle registration number **SLH 6416K** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not received any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Prestina
Legal Executive



UEN No. 53394571B
6A Shenton Way
#04-02 to 08
OUE Downtown Gallery
Singapore 068815

Tel: 6914 2682
Fax: 6429 1048

Email: prestina@jklc.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Prestina <prestina@jklc.com.sg>
Sent: Thursday, 14 November 2019 12:02 PM
To: Ben Tang; assignments@lkkauto.com; sur@lkkauto.com
Cc: Claims Dept of CTI; General
Subject: RE: OUR REF: SNM19D205227/SLH6416K/BEN - & YOUR REF: FBP3785R - PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 02.11.2019 at about 2000 hours along Compassvale Crescent involving FBP 3785R and SLH 6416K

WITHOUT PREJUDICE
OUR REF: JK.19. FBP 3785R

Dear Sir/Mdm,

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: HP MOTO
8 KAKI BUKIT AVENUE 4
#04-32 PREMIER@KAKI BUKIT
SINGAPORE 415875
Contact No: 8110 3563 – AH DI (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,
Prestina
Legal Executive



UEN No. 53394571B
6A Shenton Way
#04-02 to 08
OUE Downtown Gallery
Singapore 068815

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair Inspection:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	934B
Vehicle Details	
Vehicle No.:	FBP3785R
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	R1200GS ADVENTURE MANUAL
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	122EN10150855
Chassis No.:	WB10A0206FZ218908
Maximum Power Output:	-
Open Market Value:	\$24,891.00
Original Registration Date:	06 Jun 2015
First Registration Date:	06 Jun 2015
Transfer Count:	4
Actual ARF Paid:	\$3,734.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,512.00
COE Rebate Amount:	\$3,618.00
Total Rebate Amount:	\$3,618.00

The information contained herein is correct as at 15 Nov 2019

OK

Advertisement

Home ▾ Motorbikes ▾ Motorbikes for Sale ▾ Class 2



Advertisement



Chat

Make Offer

Share 50

S\$32,900

BMW R1200GS ADV LC

Fajar Shopping Centre

Mailing - Meetup

Used

Under Utilise Nov 2015 BMW R1200GS ADV LC
 Non TFT Display
 Keyless
 PML Unit
 Mint Condition
 Accident Free
 Sheltered Parking

Mileage 39,400km

Most Recent (All <1000KM)

- 40,000km servicing done at PML
- Changed Skyrich Lithium Battery
- Bridgestone A41 Front & Rear

Wunderlich Parts

- Headlight Protector
- Foglight Protector
- Clutch & Brake Reservoir Protector
- Radiator Guard
- Brake Caliper Protector
- Side Stand Big Foot
- Windshield Reinforcement
- etc

Others

- Powder Coated Crash Bars
- Ceramic Coated
- Protective Stickers
- Bar Riser
- Tourex Foglights

Negotiable

Selling due to family commitment
 Number plate will be retained

3 weeks ago in Class 2

BMW

Adventure

Meet-up

Fajar Shopping Centre

Shipping

Listed by cinimod87

Very Responsive

Verified

Check seller profile

Reviews for cinimod87



whatisusernamee
 2019 Oct

Seller was very chill and friendly, item was perfect. Would recommend others to deal with him :)

Read all 18 reviews ★★★★★

MV - 29600
 PV - 3618
 NV - 25300

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 16:55
Date Of Accident	02/11/2019 20:00
Exact Location Of Accident	COMPASSVALE CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP3785R
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ALFALAH BIN AZNI
NRIC No	S8742934B
Email Address	FALAH.HSE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90295111
Alternative Phone No	OFFICE-90295111

Vehicle Particulars

Manufacturer	BMW
Model	R1200GS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMMPHQ19-000449
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ALFALAH BIN AZNI
NRIC No	S8742934B
Date Of Birth	22/12/1987
Occupation	INDOOR
Date Of Driving Pass	14/06/2013
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90295111
Fax Number	
Contact Number	OFFICE-90295111
EEmail Address	FALAH.HSE@GMAIL.COM

Address	BLK 272 YISHUN ST 22 #03-110
Postcode	760272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20191103/2001.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH6416K
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD ALFALAH BIN AZNI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBP3785R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191103/2001

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

1 of 3

Report No. T/20191103/2001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/11/2019 00:19	Vide Report No.: F/20191102/0155	Station Diary No.: 5
--	-------------------------------------	-------------------------

Informant's Particulars				
Name of Informant: MUHAMMAD ALFALAH BIN AZNI			Address: APT BLK 272 YISHUN STREET 22 #03-110 SINGAPORE 760272	
ID Type / ID No.: NRIC NO / S8742934B			Contact No.: Home/Office: Mobile: 90295111	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 31	Date of Birth: 22/12/1987	Type of Informant: Rider	
Race: Malay			Language:	Institution / School Name:
Occupation: OPERATION TECHNICIAN			Driving Licence Information: Class: 2B,2A,2,3A Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/11/2019 20:00	Type of Location: Straight Road
Location: Along Road 1 COMPASSVALE CRESCENT Along Compassvale Crescent, just beside Blk 293A Compassvale Crescent				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP3785R	Motorcycle	BMW	R1200GS ADVENTUR E MANUAL	Blue		0
SLH6416K	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20191103/2001

2 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20191103/2001

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBP3785R	EQ INSURANCE COMPANY LTD.	DMMPHQ19-000449	13/04/2019	12/04/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD ALFALAH BIN AZNI	ID No.	S8742934B
Related Vehicle	FBP3785R (Motorcycle)	Contact No.	90295111
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3A Date of Expiry: NIL
Date Treatment	02/11/2019	Date Discharge	02/11/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 2nd November 2019 at about 2000hrs, I just turned left from Compassvale Street into Compassvale Crescent. Just then on the opposite lane, there was one car (SLH6416K). which was turning right into the estate (Blk 293A) on my left, I was going straight then. The said car initially slowed down and I carried on my route, but as I got nearer, the said car suddenly moved and collided me on my right, I fell onto the ground. The car driver and the passers by came and attended to me. I then called for the Police.

Moments later, Traffic Police and Ambulance came. I was then conveyed to Sengkang General hospital by the Ambulance as I complained of right shoulder pain and I have abrasion on my left knee. When I was at the hospital, the doctor did a xray on me and assessed there is nothing wrong with me. I was then given 04 days MC from 2nd Nov 2019 to 5th Nov 2019. The said car driver is a Female Chinese with a China accent. She was accompanied by a female passenger. Both of them are not injured.

The Traffic Police attended to me, gave my friend who was at the scene, the report number (F/20191102/0155). I was advised to lodge this Traffic Accident report. TP IO Hidayah Tel: 65476331/87112464.



**SINGAPORE
POLICE FORCE**



T/20191103/2001

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 3

Report No. T/20191103/2001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J /
Sgt 3 LUCAS KOH PEI SONG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
03/11/2019 00:19

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SYED ZAYID MUHAMMAD BIN
SYED ABDUL WAHID ALHINDUAN

Classification Of Case:

Authentication Stamp
NP168
SIGNATURE

13. Apr. 2019 10:26

BHH Office

No. 5083 P. 1

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1995 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

MOTORCYCLE**Comprehensive****Certificate No. : DMMPHQ19-000449**

Form: MY1
Excess: S\$1250.00

1. Index Mark and Registration Number of Vehicles
FBP3785R

2. Name of Policyholder
MUHAMMAD ALFALAH BIN AZNI

3. Effective Date of the Commencement of Insurance for the purpose of the Act
13/04/2019

4. Date of Expiry of Insurance
12/04/2020

5. Person or Classes of persons entitled to drive*
Restricted to Named Drivers Only
1) The Policyholder / Insured
2) WAN FIRDAUS BIN WAN ABDULLAH

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*
LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and in connection with the Policyholder's business or profession

THE POLICY DOES NOT COVER:

- (1) Use for hire or reward
- (2) Use for racing pace-making reliability trial or speed-testing
- (3) Use for the carriage of goods (other than samples) in connection with any trade or business
- (4) Use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase : Yew Heng Credit Enterprise Pte Ltd

A000338/Ban Hock Hin Co. Pte Ltd
Date of Issue : 13/04/2019 10:25

Authorised Signatory
EQ Insurance Company Limited

...CLAIM SUBFOLDER...(Pending for Survey Report)

























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2020 17:10		26 Nov 2019 15:26 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case














































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MUHAMMAD ALFALAH BIN AZNI								
Vehicle Reg. No.:	FBP3785R	Date of Loss:	02/11/2019 20:00 - :59 [52 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLH6416K	Policy No. (Claimant):							
		Excess:	\$0.00						
Repairer:	Hp Moto (HQ) 8 KAKI BUKIT AVENUE 4, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 05/12/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBP3785R
[SLH6416K]
TP
MUHAMMAD ALFALAH BIN AZNI
Nov 2 2019 8:00PM
[-]
Hp Moto

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
2	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
3	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
4	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
5	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
6	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
7	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
8	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
9	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
10	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
11	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
12	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
13	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
14	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
15	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
16	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
17	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
18	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
19	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
20	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
21	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
22	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
23	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
24	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
25	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
26	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
27	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
28	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
29	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
30	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
31	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
32	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
33	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
34	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
35	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
36	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
37	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
38	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
39	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
40	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
41	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
42	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>
43	26/11/19 16:52	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/11/19 16:52	General View	 Load JPG	<input checked="" type="checkbox"/>
76	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	29/11/19 08:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	29/11/19 08:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19020242/HCD3E2

Date: 07/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant FBP3785R

Insured Vehicle No : SLH6416K

Vehicle No : FBP3785R

Date of Loss: 02/11/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBP3785R

Make & Model: BMW R1200GS, 1.2 (M)

Engine No: 122EN10150855

Reg. Date: 06/06/2015 (Man. Year: 2015)

Chassis No: WB10A0206FZ218908

Colour: Blue

Odometer: 83071 km

Engine Capacity: 1170 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17

Rear Tyre Size: 170/60Z R17

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/11/2019

Date Inspected: 14/11/2019 Inspected At:

Hp Moto (HQ)
8 KAKI BUKIT AVENUE 4
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,500.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Jan 2020)	
Parts:	N/A	BMW R1200GS 1.2 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP3785R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >