



Estimate No. : **b1 53432**
Date Estimated : **13/11/2019**
Prepared By : **Chua Kee Sin**

Yang Fei Jonathan
3 Berwick Drive

Singapore
Singapore 559894

- ACCOUNT - 45912
EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU8256	28/02/2018	318i	0

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (LINES)	1,178.85	1.00	0	1,178.85
SET MOUNTING PDC/PIA SENSOR REAR	67.30	1.00	0	67.30
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05

Total Labour :	2,014.00
Total Parts :	1,299.20
Total Labour & Parts :	3,313.20
GST @7%:	231.92
Grand Total :	3,545.12

TO	TO PARTY	DATE	NO.
FROM	Steve LKR	13/14/19	3
TO			
FROM			
TO			
FROM			
TO			
FROM			
TO			
FROM			

CAR RENTAL = \$300.00 (3 DAYS)
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W/ GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53432**
Date Estimated : **13/11/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Yang Fei Jonathan
3 Berwick Drive

Singapore
Singapore 559894

- ACCOUNT - 45912

EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBA8E36020NU8256	28/02/2018	318i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# (DG/SL) ADHESIVE SET K6 <i>mc</i>	53.05	1.00	0	53.05

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	53.05
Total Labour & Parts :	53.05

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



2/Atas
Sung & rep
minin

GST REG. NO : M2 - 0020081 - X

13 NOV 2019

E S T I M A T E

Estimate No. : b1 53432
Date Estimated : 13/11/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Yang Fei Jonathan
3 Berwick Drive

Singapore
Singapore 559894

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBABE36020NU82564	28/02/2018	318i	0

DESCRIPTION

Replace rear bumper include remove attachment etc and
repair on accident area

850 1,275.00

Spray painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80 / ? 80.00

Total Labour 1: **2,570.00**

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT ? X NAI
REAR BUMPER CENTRE GUIDE ? X NAI
REAR BUMPER CARRIER (ECE) ? X NAI
REAR BUMPER TOWING EYE COVER PRIMED X NAI
TRIM STRIP CHROME ? X NAI
REAR BUMPER PANEL PRIMED (LINES) ? X NAI
(S/L) LH PROTECTION FOIL ? X NAI
(S/L) RH PROTECTION FOIL ? X NAI
SET MOUNTING PDC/PMA SENSOR REAR ? / REC
DECOUPLING RING PDC TORQUE CONVERTE ? X NAI
ULTRASONIC SENSOR (JATоба MET) ? X NAI

QTY	PRIC	VALUE
1	72.85	72.85
1	55.75	55.75
1	470.25	470.25
1	43.50	43.50
1	133.85	133.85
1	1,178.85	1,178.85
1	10.70	10.70
1	10.70	10.70
1	67.30	67.30
4	5.10	20.40
4	370.00	1,480.00

Total Parts : **3,543.95**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53432 Page No. : 2 of 5
Date Estimated : 13/11/2019
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ929K	WBABE36020NU82564	28/02/2018	318i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 2/12/19, 11.39am Excess S\$ _____
 Surveyor's Name SEK (LKK) Sign _____
 Surveyor's Tel _____ Authorised Yes / No _____
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
 Surveyor's E-mail _____
 No. of Working Days Recommend _____

WHL MRL
PIP
By Del sy
3 days

Labour 1	:	2,570.00
Parts	:	3,543.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	427.98
Grand Total	:	6,541.93

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **