

ASS. REC. BY:

REF:

A19

20/11/19

ASSIGNMENT

From:

Date:

20/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLS 4176 H

at Workshop m/s

Volkswagen

of

1 Kempung Ampat Macpherson

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3:30 pm (waiting)
Steven

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLS 4176 H

Yr Regn:

24 Aug 2017

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf c.c 1395

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

18572

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888AUZH W119316

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225 / 45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

20-11-19

Survey held at

w/s

3:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wheel end (\$

Report Format:

Lump Sum / L.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	755A
Vehicle Details	
Vehicle No.:	SLS4176H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CZC161756
Chassis No.:	WWWZZZAUZHW119316
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,460.00
Original Registration Date:	24 Aug 2017
First Registration Date:	24 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$10,644.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2027
PARF Rebate Amount:	\$7,983.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$36,290.00
Total Rebate Amount:	\$44,273.00

The information contained herein is correct as at 20 Nov 2019

OK