

ASS. REC. BY:

KLE:

CS/FCI 19020322/K14 d3

Special Instruction:

Survey: Kasu

ASSIGNMENT (Office)

From (Person): Karen Tun

of FCI

Date/Time: 2:30pm 15/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

8KT 2921T

Insured:

SHA 2406A

at Workshop m/s

cycle & Carriage Kig

Tel:

65684501

of

209 Penden Gardens

Policy No:

Claim No:

D19007199MF47

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/11/2019

CA / REV / REP. / REV 24 HRS 1DS?

H.O.D. Endorsement:

Date/Time: 3:10pm 15/11/19

Person Contacted:

Don

Vehicle IN/OUT

Date/Time

Action/Instruction

10/11/19

8KT 2921T - X

SHA 2406A - CS/6W1701/417/H1/b52

Don 7/6/17

27/11 - 4:22pm - Pensed via email pre-advise

confirm \$7713, 7days Cred: 9026, 53%

ASSIGNMENT

From

Date:

26/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKT2921T

at Workshop m/s

cycle & carriage

of

209 pondon Gardens

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

11am (waiting)
Don Bong

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKT2921T

Yr Regn:

2015 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA SORENTO 2.4 A

c.c 2359

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp.Reading

30128

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAPH 813MF 5083692

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Order~~ / Jammed / Leaked / Burnt orBrake: ~~Order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/352R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rondine

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/11/19

D.O.I.

26/11/19

Survey held at

CBC CPN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Prel. Report



Final Report

Date/Time, File Return to?

3

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Wheel and (\$

Survey Fee:

Transportation:

S + PS \$

Flare

Others

TOTAL

6x15= 90

170+90

50

50

56

416

Report Format:

TP

Lump Sum / IE:

FH3



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007199MFSH

Date: 27/11/2019

Our Ref: CS/FCI19020322/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 2921T

Please be informed that we had conducted the inspection of the abovementioned vehicle 21/11/2019 at the premises of M/s Cycle and Carriage have the following to report: -

Workshop Estimate Amount	: S\$ <u>16,610.00</u>
Revised Estimate Amount	: S\$ <u>6,640.00</u>
"Check" Items Amount	: S\$ <u>5,888.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-11-2019	Our Ref No. D19007199MFSH
Accident Date	12-11-2019	Claim Type. Third Party
Insured Vehicle	SHA2406A	Third Party Vehicle. SKT2921T
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684555/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 27 November 2019 4:22 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007199MFSH/1
Attachments: PRELI ADVISED OF SKT 2921T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKT 2921T**
Number of days (estimated) : 7 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 15 November 2019 3:12 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007199MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 15 November 2019 2:30 PM
To: ASSIGNMENTS@LKKAUTO.COM

Nivitha (LKK Auto)

From: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Sent: Friday, 15 November 2019 5:49 PM
To: 'admin-a@lkkauto.com'; assignments@lkkauto.com; sur@lkkauto.com; Admin-D (LKKAuto)
Cc: Andre Chow En De; Coco Lu Ting; Edwin Abcede Caina; Kevin Leong Wai Kit
Subject: FW: SURVEYOR APPOINTED; OUR REF : D19007199MFSH ; YOUR REF: SKT2921T
Importance: High

Hi Officer in Charge,

Please assist to arrange survey on following next **Tuesday 26/11 Time 11 am** .

Thanks

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • H: +65 91865202 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 15 November 2019 2:30 PM
To: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: SURVEYOR APPOINTED; OUR REF : D19007199MFSH ; YOUR REF: SKT2921T

This email was sent from outside of your organisation

Dear Sir/Madam

PRI Request For **SKT2921T** Accident Involving **SHA2406A** On 12-11-2019 AT 14:15:00HRS.

Please find below details for your reference

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2019 10:19
Date Of Accident	12/11/2019 14:10
Exact Location Of Accident	ALONG MOULMEIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT2921T
Insured/Policyholder	
Name Of Registered Owner	TAO RANYI
Passport No/FIN	G5362284X
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92360884
Alternative Phone No	OTHERS-92360884

Vehicle Particulars

Manufacturer	KIA
Model	SORENTO 2.4 A GDI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100414305
Cover Note Number	

Driver

Name of Driver	QIU HUI
Passport No/FIN	G5373593U
Date Of Birth	24/12/1974
Occupation	INDOOR
Date Of Driving Pass	30/03/2015
Driving Experience	4 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92360884
Fax Number	
Contact Number	
Email Address	QIUHUIANGEL@YAHOO.COM

Address	50 NEWTON ROAD #20-02
Postcode	307991
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : MAYA GAL GENDER: : FEMALE
Passenger 2	NAME: : XIAOLONG HU GENDER: : FEMALE
Passenger 3	NAME: : LINGBAI QIU GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2406A
Vehicle Make/Model/Colour	HYUNDAI/I40/BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	MUHAMMAD HAIRY BIN MANSHOR
NRIC/Passport Number	
Contact Number	93384717

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. ~~The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.~~
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 13/11/19 09:00


Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/11/19 09:00


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Moulmein Rd

A SKT 2921T

B SHA 2406A

Rear right side of the vehicle has been bumped and damaged.

1/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Tao Ranyi
Period of Insurance : 29 May 2019 To 28 May 2020
Engine No. : G4KJFA646907
Chassis No. : KNAPH813MF5083692

Vehicle No. : SKT2921T
Policy No. : 2100414305-04
Endorsement No. :
Issued Date : 22 Apr 2019

ABOUT THE COVER

Make/Model : KIA SORENTO 2.4 A GDI
Engine Capacity/Tonnage : 2,359.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PAF : Yes

a) This Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1800cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Tao Ranyi - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Bin Ming Ave Singapore 575733 69928000
2. Cycle & Carriage Body & Paint Centre Add: 208 Pandan Gardens Singapore 609339 65684601
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408960 67481000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0500709910

CYCLE & CARRIAGE - KEENG(KIA)
 239 ALEXANDRA ROAD
 SINGAPORE 159930 ANSP-MOTOR
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

10037141506WAC24

88093-V



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tao Ranyi	Cust No/Name /Tao Ranyi
50 Newton Rd	Reg No/Reg Date SKT2921T / 29/05/201
#20-02 Newton Gens	Date In/Mileage / 0
Singapore 307991	Chassis No KNAPH813MF5083692
Contact No Mobile: 97257797	Engine No G4KJFA646907
	Make/Model KIA/SORENTO UM 2.4 A GDI W/SR
	Colour/Trim MY3 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	13/11/2019/ 15:55	QUD	247 / DonBong	61840
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, CUT/WELD REAR END PANEL, REPAIR BOTH REAR FENDER				2750.00
E PNT88000	REMOVE AND REPLACE REAR WINDSCREEN GLASS				1650 -
E PNT88000	REMOVE AND INSTALL REAR TRIM, SIDE TRIM AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK				240 300.00
E PNT88000	REMOVE AND INSTALL PARKING ASSIST				250 300.00
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT				80 100.00
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR TAILGATE, REAR BUMPER, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION				80 80.00
M SUNDRY	SUPPLY BODY SEALANT				126 2520.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				80 240.00
M SUNDRY	PERFORM RUST PREVENTION				30 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				80 240.00
M SUNDRY	RE-APPLY ZERTONA BODY COATING				200.00
M SUNDRY	SUNDRIES				240.00
M PANEL ASSY-TAIL GATE		1.00	1445.00	00.00	1445.00
M GLASS ASSY-TAIL GATE		1.00	690.00	00.00	690.00
M EMBLEM-SORENTO		1.00	32.00	00.00	32.00
M LOGO ASSY-KIA SUB		1.00	69.00	00.00	69.00
M EMBLEM-G.D.I		1.00	37.00	00.00	37.00
Confirm & accepted by					
Authorized signatory and company stamp					

LRT Auto Consultants hence notify the Repairer of the following:

- To remedy before/after spray painting
- To display damaged part(s) during remedy
- To ensure work is subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No legal action(s) is allowed
- Supplementary items must be re-surveyed and be subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tao Ranyi	Cust No/Name /Tao Ranyi
50 Newton Rd	Reg No/Reg Date SKT2921T / 29/05/201
#20-02 Newton Gems	Date In/Mileage / 0
Singapore 307991	Chassis No KNAPH813MF5083692
Contact No Mobile: 97257797	Engine No G4KJFA646907
	Make/Model KIA/SORENTO UM 2.4 A GDI W/SR
	Colour/Trim MY3 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	13/11/2019/ 15:55	QUD	247 / DonBong	61840

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-BACK repair ? x sue	1.00	526.00	00.00	526.00
M TRIM ASSY-RR TRANSVERSE ? x sue	1.00	59.00	00.00	59.00
M TRIM ASSY-LUGG FLR BOX ? x sue	1.00	571.00	00.00	571.00
M BRACKET ASSY-RR BUMPER SIDE, LH ac	1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE, RH ac	1.00	25.00	00.00	25.00
M BRACKET-RR BUMPER SIDE LWR, LH ac	1.00	18.00	00.00	18.00
M BRACKET-RR BUMPER SIDE LWR, RH ac	1.00	18.00	00.00	18.00
M ANTENNA ASSY-SMARTKEY ? x sue	1.00	53.00	00.00	53.00
M RAIL ASSY-REAR BUMPER ? x sue	1.00	392.00	00.00	392.00
M WIRING HARNESS-RR BUMPER ? cut	1.00	248.00	00.00	248.00
M RETAINER ASSY-BUMPER COVER MTG ? x sue	10.00	2.00	00.00	20.00
M BRACKET-RR BPR SIDE REINF, LH ? x sue	1.00	18.00	00.00	18.00
M BRACKET-RR BPR SIDE REINF, RH ? x sue	1.00	18.00	00.00	18.00
M COVER-RR BUMPER, UPR ? x sue	1.00	696.00	00.00	696.00
M RETAINER-BUMPER MTG ? x sue	2.00	2.00	00.00	4.00
M COVER-RR BUMPER LWR ? x sue	1.00	650.00	00.00	650.00
M SKID PLATE-RR BUMPER ? x sue	1.00	111.00	00.00	111.00
M COVER ASSY-RR BPR UNDER ?	1.00	88.00	00.00	88.00
M ULTRASONIC SENSOR-S.P.A.S } ? x sue	1.00	215.00	00.00	215.00
M ULTRASONIC SENSOR-S.P.A.S }	1.00	215.00	00.00	215.00
M ULTRASONIC SENSOR-S.P.A.S }	1.00	215.00	00.00	215.00
M ULTRASONIC SENSOR-S.P.A.S }	1.00	215.00	00.00	215.00
M ULTRASONIC SENSOR-S.P.A.S }	1.00	215.00	00.00	215.00
M ULTRASONIC SENSOR-S.P.A.S }	1.00	215.00	00.00	215.00
M MUFFLER ASSY-REAR ?	1.00	892.00	00.00	892.00
M MUFFLER COMPLETE-CENTER ?	1.00	1545.00	00.00	1545.00

SURVEYOR NAME: Rasul

SURVEYOR SIGNATURE: [Signature]

DATE: 26/11/19 @ 1120

REMARKS: 7 days

Confirm & accepted by

Rany before print

Nett 16,610.00
7% GST on 16610.00 1162.70

Total Payable 17,772.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



TP CLAIM
FIRST CAPITAL
Rasul

VEHICLE NO : SKT2921T

MODEL : KIA/SORENTO UM 2.4 A

WIP : 61840

Material	:	\$	<u>3,503.00</u>
Labour	:	\$	<u>4,210.00</u>
Sub-Total	:	\$	<u>7,713.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>7,713.00</u>
GST 7%	:	\$	<u>539.91</u>
Grand Total	:	\$	<u>8,252.91</u>

Finalise By/Date : Lenny on 17/02/20

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (weekend)

* TP VEHICLE No: SHA2406A

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K


THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tao Ranyi	Cust No/Name /Mr Tao Ranyi
50 Newton Rd	Reg No/Reg Date SKT2921T / 29/05/2015
#20-02 Newton Gens	Date In/Mileage 04/02/2020/ 31455
Singapore 307991	Chassis/Package KNAPH813MF5083692 /KC17P
Contact No Mobile: 97257797	Engine No G4KJFA646907
04/02/2020	Make/Model KIA/SORENTO UM 2.4 A GDI W/SR
	Colour/Trim MY3 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	17/02/2020/ 18:59	TLD	884 / Lauro Songcuan	61840
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, REPAIR REAR END PANEL					1650.00 ✓
E PNT88000 REMOVE AND REPLACE REAR WINDSCREEN GLASS					240.00 ✓
E PNT88000 REMOVE AND INSTALL REAR TRIM, SIDE TRIM AND OTHER ATTACHMENT TO FACILITATE REPAIR					250.00 ✓
E PNT88000 REMOVE AND INSTALL PARKING ASSIST					80.00 ✓
M SUNDRY SUPPLY REAR WINDSCREEN SEALANT					80.00 ✓
E PNT98000 SPRAY PAINT REAR END PANEL, REAR TAILGATE, REAR BUMPER AND AFFECTED PORTIONS					1260.00 ✓
M SUNDRY SUPPLY BODY SEALANT ON AFFECTED AREAS					80.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					30.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS					80.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					200.00 ✓
M SUNDRY RE-APPLY ZERTONA BODY COATING					240.00 ✓
M SUNDRY SUNDRIES					20.00 ✓
X PANEL ASSY-TAIL GATE ✓		1.00	1445.00	00.00	1445.00 ✓
X EMBLEM-SORENTO ✓		1.00	32.00	00.00	32.00 ✓
X LOGO ASSY-KIA SUB ✓		1.00	69.00	00.00	69.00 ✓
X EMBLEM-G.D.I ✓		1.00	37.00	00.00	37.00 ✓
X BRACKET ASSY-RR BUMPER SIDE,LH ✓		1.00	25.00	00.00	25.00 ✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tao Ranyl	Cust No/Name /Mr Tao Ranyl
50 Newton Rd	Reg No/Reg Date SKT2921T / 29/05/2015
#20-02 Newton Gens	Date In/Mileage 04/02/2020/ 31455
Singapore 307991	Chassis/Package KNAPH813MF50B3692 /KC17P
Contact No Mobile: 97257797	Engine No G4KJFA646907
04/02/2020	Make/Model KIA/SORENTO UM 2.4 A GDI W/SR
	Colour/Trim MY3 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	17/02/2020/ 18:59	TLD	884 / Lauro Songcuan	61840

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BRACKET ASSY-RR BUMPER SIDE,RH ✓	1.00	25.00	00.00	25.00 ✓
X BRACKET-RR BUMPER SIDE LWR,LH ✓	1.00	18.00	00.00	18.00 ✓
X BRACKET-RR BUMPER SIDE LWR,RH ✓	1.00	18.00	00.00	18.00 ✓
X WIRING HARNESS-RR BUMPER ?	1.00	248.00	00.00	248.00 ?
X COVER-RR BUMPER,UPR ✓	1.00	696.00	00.00	696.00 ✓
X COVER-RR BUMPER LWR ✓	1.00	650.00	00.00	650.00 ✓
X SKID PLATE-RR BUMPER ✓	1.00	111.00	00.00	111.00 ✓
X LAMP ASSY-REAR FOG,RH → sup	1.00	129.00	00.00	129.00 X

Z TEXT

FIRST CAPITAL TP CLAIM - SHA2406A

DOA: 12/11/2019

SURVEYOR: RASUL LKK 26/11/19

07 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,503.00		Nett	7,713.00
Labour	3,710.00	7% GST on	7713.00	539.91
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	8,252.91
Sundry/Others	500.00			
Total(w/o GST)	7,713.00			

This is not an official tax invoice.

This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: FIRST CAPITAL

Supplementary For Registration No.: SKT 2921 T

Materials

1 Lamp Assy- Rear Fog, RH *CR ✓*

7% GST

Total

Cost (\$)

129.00

9.03

138.03

Thank You,

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE

TEL: 6568 4658

FAX: 6567 5258

16739



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020322/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-02-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 2406A	Veh. Inspected	SKT 2921T
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19007199MFSH	Excess (\$)	0.00
	Assign From	KARENT	Assign Date	15/11/2019
2. Vehicle Particulars & Condition				
	Make & Model	KIA SORENTO 2.4A	c.c	2359
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KNAPH813MF5083692	Colour	BROWN
	Odometer	30128	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 ZR19	ROADSTONE	6 mm
	L/H Front Tyre	235/55 ZR19	ROADSTONE	6 mm
	R/H Rear Tyre	235/55 ZR19	ROADSTONE	6 mm
	L/H Rear Tyre	235/55 ZR19	ROADSTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/11/2019	Inspection Date	26/11/2019
	Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2921T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL ASSY-TAIL GATE (SN)	BENT	1,445.00	1,445.00
1	GLASS ASSY-TAIL GATE (SN)	SERVICEABLE	690.00	-
1	EMBLEM-SORENTO (SN)	NECESSARY	32.00	32.00
1	LOGO ASSY-KIA SUB (SN)	NECESSARY	69.00	69.00
1	EMBLEM-G.D.I (SN)	NECESSARY	37.00	37.00
1	PANEL ASSY-BACK (SN)	TO REPAIR SEE LABOUR	526.00	-
1	TRIM ASSY-RR TRANSVERSE (SN)	SERVICEABLE	59.00	-
1	TRIM ASSY-LUGG FLR BOX (SN)	SERVICEABLE	571.00	-
1	BRACKET ASSY-RR BUMPER SIDE,LH (SN)	NECESSARY	25.00	25.00
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	NECESSARY	25.00	25.00
1	BRACKET-RR BUMPER SIDE LWR,LH (SN)	NECESSARY	18.00	18.00
1	BRACKET-RR BUMPER SIDE LWR,RH (SN)	NECESSARY	18.00	18.00
1	ANTENNA ASSY-SMARTKEY (SN)	SERVICEABLE	53.00	-
1	RAIL ASSY-REAR BUMPER (SN)	SERVICEABLE	392.00	-
1	WIRING HARNESS-RR BUMPER (SN)	CUT	248.00	248.00
10	RETAINER ASSY-BUMPER COVER MTG (SN)	SERVICEABLE	20.00	-
1	BRACKET-RR BPR SIDE REINF,LH (SN)	SERVICEABLE	18.00	-
1	BRACKET-RR BPR SIDE REINF,RH (SN)	SERVICEABLE	18.00	-
1	COVER-RR BUMPER,UPR (SN)	TORN	696.00	696.00
2	RETAINER-BUMPER MTG (SN)	SERVICEABLE	4.00	-
1	COVER-RR BUMPER LWR (SN)	TORN	650.00	650.00
1	SKID PLATE-RR BUMPER (SN)	SCRATCHED	111.00	111.00
1	COVER ASSY-RR BPR UNDER (SN)	SERVICEABLE	88.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	ULTRASONIC SENSOR-S.P.A.S (SN)	SERVICEABLE	215.00	-
1	MUFFLER ASSY-REAR (SN)	SERVICEABLE	892.00	-

Report Ref No. CS/FCI19020322/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MUFFLER COMPLETE-CENTER (SN)	SERVICEABLE	1,545.00	-
1	LAMP ASSY-REAR FOG,RH (ADDITIONAL)(SN)	CRACKED	129.00	129.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
			9,799.00	3,603.00
	LABOUR			
	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE,REAR BUMPER FACE,CUT/WELD REAR END PANEL,REPAIR BOTH REAR FENDER.INCLUSIVE OF THE REPAIR OF PANEL ASSY-BACK.		2,750.00	1,650.00
	REMOVE AND REPLACE REAR WINDSCREEN GLASS.		300.00	240.00
	REMOVE AND INSTALL REAR TRIM,SIDE TRIM AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK.		300.00	250.00
	REMOVE AND INSTALL PARKING ASSIST.		100.00	80.00
	PAINT WORK SPRAY REAR END PANEL,REAR TAILGATE,REAR BUMPER,RH REAR FENDER,LH REAR FENDER AND AFFECTED PORTION.		2,520.00	1,260.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	PERFORM RUST PREVENTION.		240.00	80.00
	SUPPLY BODY SEALANT.		240.00	80.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	RE-APPLY ZERTONA BODY COATING.		240.00	240.00
			6,940.00	4,110.00
	GRAND TOTAL		16,739.00	7,713.00
	RECOMMENDED COST OF REPAIRS			7,713.00

Report Ref No. CS/FCI19020322/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.