

ASS. REC. BY:

REF:

@INC19020359/Gld3m4

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person):

Hazalysa Bt Ibrahim

INC

Date/Time: 18/11/19 @ 10:02am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

8MD1010P

Insured:

SDL 7722T

at Workshop n/a

Weelmes Automotive

Tel:

9818 7217

of

249 Alexandra Road

Policy No:

Claim No:

MT/1068626-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:40am @ 18/11/19

Person Contacted:

Derek

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Estimated ✓

8MD1010P - x

SDL 7722T - x

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

ul _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMD 1010PYr Regn: 29/4/19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo XC40 TS R-dyn c.c. 1969Colour: White A/C: Insured / Std / NI / NASp. Reading: 12489 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV IX 216 ACK 2125.742Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/50R19R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 25/10/19

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 18/11/19Survey held at Wesley's

2.13pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-160K27/11/19 Finalize Confil \$4396.23, 3 days (Richmond) (Red: \$6763.17; 60%)

RECEIVED 27 NOV 2019

27/11/2019

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

S + RS. \$

Photos

Others

TOTAL

250

Rep. Form:

Emp. No. / TP 4396.23

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Monday, 18 November 2019 10:02 AM
To: Admin-D (LKKAuto); assignments
Cc: Susan Ting; Hazalya Binte Ibrahim
Subject: TP CASES FARMED OUT TO LKK ON 18/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071241-002	CB7507M	CT AUTO PTE LTD	10 BUKOH STREET #01-31 WEST CONNECT BUILDING SINGAPORE 627564	Daniel Tan/Cady Lee / 9353 3333	13:00-14:30	SJH362P	08/11/19	owner waiting/6266-6727
2	Eng Huey Huey	MT/1071557-001	SFE222D	HIN LUNG WORKSHOP	BLK 1008 #01-20 BUKIT MERAH LANE 3 SINGAPORE 159722	Anna / 6858 3000	10:00-12:00	FV1933P	13/11/19	
3	Helena Tan	MT/1070807-002	GBD2836Y	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642		PC5664X	10/11/19	
4	Chryllis Quah	MT/1071066-002	GBE9864P	SIN SHENG ENGINEERING SERVICES	NO 8 TUAS AVENUE 18, #05-00 SINGAPORE 638892	Susan / 68639595		YM7508S	07/11/19	68636477
5	Azhari	MT/1069720-002	SLT5498S	WEARINES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	SLB2908	02/11/19	6430 4895
6	Helena Tan	MT/1068626-002	SMMD1010P	WEARINES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	SDL7722T	25/10/19	6430 4895

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	844C

Vehicle Details

Vehicle No.:	SMD1010P
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	VOLVO
Vehicle Model:	XC40 T5 R-DESIGN
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	B4204T182991665
Chassis No.:	YV1XZ16ACK2125742
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$30,366.00
Original Registration Date:	29 Apr 2019
First Registration Date:	29 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$34,513.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2029
PARF Rebate Amount:	\$25,884.00

Intended COE Rebate Details

COE Expiry Date:	28 Apr 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$45,333.00
Total Rebate Amount:	\$71,217.00

The information contained herein is correct as at 18 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2019 11:53
Date Of Accident	25/10/2019 07:30
Exact Location Of Accident	JALAN EUNOS RD TWDS STILL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD1010P
Insured/Policyholder	
Name Of Registered Owner	LIM CHIN SIANG KEVIN
NRIC No	S7922844C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97503938
Alternative Phone No	OTHERS-97503938

Vehicle Particulars

Manufacturer	VOLVO
Model	XC40-2.0 T5 R-DESIGN (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900092089
Cover Note Number	

Driver

Name of Driver	LIM CHIN SIANG KEVIN
NRIC No	S7922844C
Date Of Birth	06/08/1979
Occupation	INDOOR
Date Of Driving Pass	15/11/1999
Driving Experience	19 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97503938
Fax Number	
Contact Number	OTHERS-97503938
Email Address	NOEMAIL

Address	65 PUNGGOL CENTRAL #10-10
Postcode	828842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JASMINE KOH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDL7722T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 25/10/14
9:30 am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

On 25/10/19, I was driving along Jln Ewas towards still road ^{at} after the PIE flyover when my vehicle was rear ended by another vehicle with the registration number SPK 7722 T. Prior to the impact, the traffic in front of me came to a stop and I braked and stopped in time. Within seconds after I came to a complete stop, I felt a big impact from the rear of the vehicle. The time is 7.27 am. The weather is clear, no rain, the road is dry. Videos and photos attached.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

 25/10/19
Policyholder's Signature / Date & Time
9.30 am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Lim Chin Siang, Kevin
65 Punggol Central
#10-10

Singapore 828842

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 29/10/2019

WIP No. : 44450

Veh.In/Out: 25/10/2019

*Tel.No. : Mobile: 97503938

Reg.No. : SMD1010P

Reg.date : 29/04/2019

Mileage : 0

Chassis No: YV1XZ16ACK2125742

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Lim Chin Siang, K

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SKID PLATE, REAR SENSOR, ETC	800	0	2400.00	0	2,400.00 S	1200
-----	---	-----	---	---------	---	------------	------

800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	700	0	1400.00	0	1,400.00 S	700
-----	--	-----	---	---------	---	------------	-----

R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	0	60.00	0	60.00 S	X
-----	---	---	---	-------	---	---------	---

280	TO CHECK WIRING INCLUDE RESTTING OF ALL ELECTRICAL MODULES	0	0	480.00	0	480.00 S	/
-----	--	---	---	--------	---	----------	---

BUMPER COVER REAR AL	✓ CUT	1.0	EA	1169.90		1,169.90 S	1051.91
BUMPER PAD REAR LH A	✓ OR	1.0	EA	497.80		497.80 S	448.02
BUMPER PAD REAR RH A	✓ NM	1.0	EA	497.80		497.80 S	
BUMPER BRACKET REAR	✓ x NM	1.0	EA	40.90		40.90 S	
BUMPER BRACKET REAR	✓ x NM	1.0	EA	40.90		40.90 S	
SCREW	✓ x NM	10.0	EA	2.70		27.00 S	
TOW COVER REAR XC40	✓ NM	1.0	EA	73.90		73.90 S	

Steve (LKK) ML ML 18/11/19, 2.30pm
3 day
P/P
By Bel spy

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Lim Chin Siang, Kevin
 65 Punggol Central
 #10-10

Singapore 828842

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date. : 29/10/2019
 WIP No. : 44450
 Veh.In/Out: 25/10/2019
 *Tel.No. : Mobile: 97503938
 Reg.No. : SMD1010P
 Reg.date. : 29/04/2019
 Mileage : 0
 Chassis No: YV1XZ16ACK2125742

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Lim Chin Siang, K

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	PROTECTING PLATE REA / <i>CNT</i>	1.0 EA	443.55			443.55 S	399.70
	BUMPER CLIP GREEN S6 / <i>nk</i>	10.0 EA	4.80			48.00 S	43.20
	SPRING NUT ST4 8*1 X <i>X</i> AI <i>NN</i>	10.0 EA	2.60			26.00 S	
	SIX PT SOCKET SCREW / <i>nk</i>	10.0 EA	2.70			27.00 S	74.30
	SIX POINT SOCKET SCR <i>X</i> AI <i>NN</i>	10.0 EA	2.60			26.00 S	
	EXPANDING NUT XC40 1 / <i>nk</i>	10.0 EA	5.40			54.00 S	48.60
	BUMPER REFLECTOR RH <i>X</i> <i>NAI</i>	1.0 EA	79.30			79.30 S	
	BUMPER REFLECTOR LH <i>X</i> <i>NN</i>	1.0 EA	79.30			79.30 S	
	BUMPER RAIL (BEAM) R <i>?</i> <i>X</i> <i>NN</i>	1.0 EA	1022.30			1,022.30 S	
	CROSS MEMBER REAR XC <i>?</i> <i>X</i> <i>NAI</i>	1.0 EA	220.10			220.10 S	
	GUIDE MOULDING REAR <i>?</i> <i>X</i> <i>NAI</i>	1.0 EA	74.20			74.20 S	
	INNER PANEL BRACKET <i>?</i> <i>X</i> <i>NN</i>	2.0 EA	42.60			85.20 S	
	REINFORCEMENT <i>?</i> <i>X</i> <i>NN</i>	1.0 EA	47.70			47.70 S	
	REINFORCEMENT <i>?</i> <i>X</i> <i>NN</i>	1.0 EA	47.70			47.70 S	
	REAR SECTION <i>X</i> <i>R</i>	1.0 EA	723.40			723.40 S	
	PROTECTING PLATE REA <i>X</i> <i>Replaced</i>	1.0 EA	443.55			443.55 S	
	END PIPE LH R-D XC40 <i>X</i> <i>NN</i>	1.0 EA	369.75			369.75 S	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Lim Chin Siang, Kevin
65 Punggol Central
#10-10

Singapore 828842

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 29/10/2019

WIP No. . : 44450

Veh.In/Out: 25/10/2019

*Tel.No. . : Mobile: 97503938

Reg.No. . : SMD1010P

Reg.date. : 29/04/2019

Mileage . : 0

Chassis No: YV1XZ16ACK2125742

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Lim Chin Siang, K

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	END PIPE RH R-D XC40	X	1.0	EA	369.75		369.75	S
	EXTERIOR ADHESIVE GL	X	2.0	EA	142.20		284.40	S

Gross Total. 11,159.40

Labour Total 4,340.00
Parts Total 6,819.40
Package Total 0.00

Net..... 11,159.40
GST @ 7.0% 781.16
Total..... 11,940.55
Paid..... 0.00
Please Pay.. 11,940.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - N00001	SL: NTUC INCOME INSURANCE CO-OPERATIVE	GST Reg.No:M28920628X
NTUC INCOME INSURANCE CO-OPERATIVE		
73 Bras Basah	Inv.No. : B&P	0 Page 1
#05-01	Inv.date. : 26/11/2019	
NTUC Trade Union House	WIP No. : 44450	
Singapore 189556	Veh.In/Out: 18/11/2019 22/11/2019	
	*Tel.No. :	
	Reg.No. : SMD1010P	
Closed by : Richmond Ho	Reg.date : 29/04/2019	
Svc Consultant : ACC	Mileage : 12,489	
Remarks : Mr Lim Chin Siang, K	Chassis No: YV1XZ16ACK2125742	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR BRACKET,REAR LOWER SPOILER, REAR SKID PLATE,REAR SENSOR,ETC	0	1200.00	0		1,200.00	S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC	0	700.00	0		700.00	S
280	TO CHECK WIRING INCLUDE RESTING OF ALL ELECTRICAL MODULES	0	480.00	0		480.00	S
	BUMPER COVER REAR AL (1)	1.0 EA	1169.90	10		1,052.91	S/
	BUMPER PAD REAR LH A (2)	1.0 EA	497.80	10		448.02	S/
	PROTECTING PLATE REA (8)	1.0 EA	443.55	10		399.20	S/
	BUMPER CLIP GREEN S6 (4)	10.0 EA	4.80	10		43.20	S/
	SIX PT SOCKET SCREW (4)	10.0 EA	2.70	10		24.30	S/
	EXPANDING NUT XC40 1 (3)	10.0 EA	5.40	10		48.60	S/

Gross Total. 4,396.23

Labour Total 2,380.00
 Parts Total 2,016.23
 Package Total 0.00

Net..... 4,396.23
 GST @ 7.0% 307.74
 Total..... 4,703.97
 Paid..... 0.00
 Please Pay.. 4,703.97

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020359/Etd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 28-11-2019



ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDL 7722T	Veh. Inspected	SMD 1010P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1068626-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	18/11/2019

2. Vehicle Particulars & Condition

Make & Model	VOLVO XC40 T5 R-DESIGN	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	YV1XZ16ACK2125742	Colour	WHITE
Odometer	12489 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R19	PIRELLI	6 mm
L/H Front Tyre	235/50 R19	PIRELLI	6 mm
R/H Rear Tyre	235/50 R19	PIRELLI	6 mm
L/H Rear Tyre	235/50 R19	PIRELLI	6 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	25/10/2019	Inspect Date / Time	18/11/2019 (02:13 PM)
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1010P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR AL (SN)	CUT	1,169.90	1,052.91
1	BUMPER PAD REAR LH A (SN)	BROKEN	497.80	448.02
1	BUMPER PAD REAR RH A (SN)	NOT NECESSARY	497.80	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	40.90	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	40.90	-
10	SCREW (SN)	NOT NECESSARY	27.00	-
1	TOW COVER REAR XC40 (SN)	NOT NECESSARY	73.90	-
1	PROTECTING PLATE REA (SN)	CUT	443.55	399.20
10	BUMPER CLIP GREEN S6 (SN)	NECESSARY	48.00	43.20
10	SPRING NUT ST4 8*1 X (SN)	NOT NECESSARY	26.00	-
10	SIX PT SOCKET SCREW (SN)	NECESSARY	27.00	24.30
10	SIX POINT SOCKET SCR (SN)	NOT NECESSARY	26.00	-
10	EXPANDING NUT XC40 1 (SN)	NECESSARY	54.00	48.60
1	BUMPER REFLECTOR RH (SN)	NOT NECESSARY	79.30	-
1	BUMPER REFLECTOR LH (SN)	NOT NECESSARY	79.30	-
1	BUMPER RAIL (BEAM) R (SN)	NOT NECESSARY	1,022.30	-
1	CROSS MEMBER REAR XC (SN)	NOT NECESSARY	220.10	-
1	GUIDE MOULDING REAR (SN)	NOT NECESSARY	74.20	-
2	INNER PANEL BRACKET (SN)	NOT NECESSARY	85.20	-
1	REINFORCEMENT (SN)	NOT NECESSARY	47.70	-
1	REINFORCEMENT (SN)	NOT NECESSARY	47.70	-
1	REAR SECTION (SN)	TO REPAIR SEE LABOUR	723.40	-
1	PROTECTING PLATE REA (SN)	REPEATED	443.55	-
1	END PIPE LH R-D XC40 (SN)	NOT NECESSARY	369.75	-
1	END PIPE RH R-D XC40 (SN)	NOT NECESSARY	369.75	-
1	EXTERIOR ADHESIVE GL (SN)	NOT NECESSARY	284.40	-
			6,819.40	2,016.23



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SKID PLATE, REAR SENSOR, ETC. INCLUSIVE OF THE REPAIR OF REAR SECTION.		2,400.00	1,200.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC.		1,400.00	700.00
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		480.00	480.00
			4,340.00	2,380.00
	GRAND TOTAL		11,159.40	4,396.23
RECOMMENDED COST OF REPAIRS				4,396.23

Report Ref No. CS/INC19020359/Etd3n2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.