S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Our Reference: TP/019/0140SK
Your Reference: TBA

Date: 20/6/2019

TO: SUNNY RECOVERY PTE LTD
c/o ACE Autolution Pte Ltd
13 Kaki Bukit Road 4 #03-29
Bartley Biz Centre
Singapore 417807

Assessment of Vehicle No : YP 7085D
Date of Accident : 10/04/2019
Date of Inspection : 20/04/2019

We have carried out a physical assessment of YP 7085D at Ace Autolution Pte Ltd according to your instructions on 20/04/2019 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	YP 7085D
Make & Model	:	ISUZU NHR85AUE
Year of Registration	:	2017
Engine Capacity (cc)	:	2999
Chassis No.	:	JAANHR85EH7100273
Engine No.	:	4JJ13B2211
Colour	:	Green
Mileage (km)	:	60962

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	Ohtsu 195R15 - 80%
LH Make/Size	:	Ohtsu 195R15 - 80%

Rear

RH Make/Size	:	Falken 185R14C - 80%
LH Make/Size	:	Falken 185R14C - 80%

Note: % denotes the remaining percentage of the tyre

Our Reference TP/019/0140SK
Vehicle No. YP 7085D

4.DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Front and Rear portion
Badly damaged
Please see attached schedule for details.



Estimated Amount : S$52,088.29
Adjusted Amount : S$40,000/-
Estimated Repair Days : 20 days

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a **"Without Prejudice"** basis.

If we are not notified of anything to the contrary within **14 Days** from the date hereof, this report shall be treated as correct

Disclaimer
This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **S K AUTO CONSULTANTS** for any reliance on this report by any third party.