

\*ASS. REC. BY:

REF:

CS/AIG/19020389/19030

Special Instruction:

Senior: Nqz  
Mentor

ASSIGNMENT (Office) ✓

From (Person): Andy Fong of AIG Date/Time: 18/11/19 @ 8:20am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 2832X Insured: \_\_\_\_\_at Workshop m/s Bike Production Tel: 6 299 5177of 610 Serangoon RoadPolicy No: 180017469 Claim No: 547798052696Sum Insured: \_\_\_\_\_ Excess: TBA 300Make of Veh: \_\_\_\_\_ D.O.A. 5/11/2019  
(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:18am @ 18/11/19 Person Contacted: Wendy Vehicle IN/OUT: OUT

Date/Time	Action/Instruction	Submit ✓
	<u>FBK 2832X - CS/AIG/18020490/Nqz352</u>	<u>D.O.A: 13/11/18</u>
<u>21/11/19 @ 1:22pm</u>	<u>revert to Andy Fong via Messenger.</u>	
<u>21/11/19 @ 2:15pm</u>	<u>Victor informed C/A via Messenger.</u>	
<u>21/11/19 @ 4:16pm</u>	<u>informed Mr Kwan &amp; Wendy C/A not move than US \$4200 LEX:</u>	
<u>19/12/19 @ 8:55am</u>	<u>2nd revert to Andy Fong via Messenger (T/L)</u>	<u>6305</u>

Supervisor: N/A

REF:

A16

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop refs: \_\_\_\_\_

at \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Swm Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Name of Vch: \_\_\_\_\_

(Prey Condition)

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Remark: The vch had commenced its repair at the time of inspection.

Est. or Market Value: 7.5K

IAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

CI / IPR Score: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: 4 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Veh No: FBK 2832X Yr Regn: 16 JUN 2015

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Troller or

Make: YAMAHA YZF-R3 ABJ cc: 321

Colour: BLUE A/C: Insured / Std / Nil / NA

Sp. Reading: 78,625 T/Radiq: Insured / Std / Nil / NA

Eng No: \_\_\_\_\_

CANo: MH3RHO7100003537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Lacked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SIR / STD / AIR / or

Tyre Size: F: \_\_\_\_\_ R: 100/80 R17

R: 150/60 R17

BSI / DUH / EXHOVA / GY / FS / IZA / MIC / OHSU / PRX / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Rat: 4 mm R/Rat: 4 mm

L/Rat: \_\_\_\_\_ mm L/Rat: \_\_\_\_\_ mm

D.O.A. 5/11/19 U.O.A. 20/11/19

Survey held at: BIKE PRODUCTION

Dist. of Damages: Frt / Rear / O/S / M/S / UIC / Rostop or

The UIC / Chassis Frame / Body Structure affected due to damage

A16 / US

Date / Time Action / Instruction

MV:

COE Rebate: \$3,231.00

Repair Limit: \$4K

RECEIVED 29 DEC 2019

16/12/19 Steering stem damage, hitting onto body frame. Unsafe to repair. Recommend total loss.

23/12/19 Submit Unconditional total loss report / unsafe.

Qualify, Fit Pass?  : Profit Report

23/12 Pass  : Final Report

Qualify, Fit Repair?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

700

Transportation

Fuel

11

Repair Format: MER-1/L-Unsafe

Lump Sum: T.B.I. IS

Add Fee:  : Site Insp (\$

: Interview (\$

: Techn. Insp (\$

: Weekend (\$

211

**- RE: NEW OD CLAIM - FBK2832X**

From: AIG SGP, Claims-Survey

To:

Cc: Fong, Andy-SY

Sent: 11/18/2019 8:12:14 AM

Attachments:  20191113\_145449.jpg  20191113\_145453.jpg  FBK2832X GIA.pdf

---

Hi LKK,

Kindly assist to survey, bike in.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**From:** Sbk E [mailto:sbk5643e@yahoo.com]

**Sent:** Sunday, November 17, 2019 3:46 PM

**To:** AIG SGP, Claims-Survey

**Subject:** [EXTERNAL] RE: NEW OD CLAIM - FBK2832X

**This message is from an external sender; be cautious with links and attachments.**

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. The bike is in. Thank you very much for your attention.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 19 Dec 2019

**Preliminary Advice**

Vehicle No	: FBK2832X	Accident Date	: 05/11/2019
Make	: YAMAHA YZF-R3	Policy No.	: 1800117469
Assignment Date	: 18/11/2019	Excess	: S\$300.00
Date of Inspection	: 20/11/2019	Est. Duration of Repair	: 4.00
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion, o/s &amp; n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,423.00
Revised Amount	:S\$	7,396.00
Check Items (Estimated)	:S\$	2,232.00
Total	:S\$	9,628.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,500.00
COE / PARF Rebate	:S\$	3,231.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,269.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :  
According to the repairer, while dismantling, the steering stem was found to be damaged and hitting onto the body frame. It is unsafe to repair. If repaired, the bike may not be safe to ride at high speed & cornering and stability is affected.

Therefore, our surveyor has recommended this motorbike written off as total loss due to the reason above.

## View Sent Message

This mail is associated with :

**\*FBK2832X (5477980526SG)**  
OD  
Nov 5 2019 3:00PM  
[ABDUL RAHMAN BIN AHMAD]  
Bike Production

Resend View Recipients Print Message Delete Message Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 17/12/2019 10:58 AM.  
**To** Victor\_KohCK  
**CC** PriscillaSim; sur@lkkauto.com  
**Subject** OD VEHICLE FBK 2832X (YOUR REF: 5477980526SG)

Dear Sir/Madam,

According to the repairer, while dismantling, the steering stem was found to be damaged and hitting onto the body frame. It is unsafe to repair. If repaired, the bike may not be safe to ride at high speed & cornering and stability is affected.

Therefore, our surveyor has recommended this motorbike written off as total loss due to the reason above.

**Best Wishes for Merry Christmas & Happy New Year 2020**

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd

### DOCUMENTS SUMMARY

There are no documents.

## Shiau Chan (LKKAUTO)

---

**From:** Sbk E <sbk5643e@yahoo.com>  
**Sent:** Saturday, 14 December 2019 8:05 AM  
**To:** Naz (LKKAUTO)  
**Cc:** Shiau Chan (LKKAUTO); SUR  
**Subject:** Re: REPAIR LIMIT FOR FBK2832X

Dear Shiau Chan and Naz,

As discussed with Naz, the vehicle may not be safe to ride at high speed and or cornering after repair. Please advise if total loss is a good option for this case. Please advise and also the claim officer for this matter. Thanks.

Regards,  
Kwan S. H.  
Director  
Bike Production Pte Ltd

*While dismantling, the steering stem was found to be damaged and hitting onto the body frame. It is unsafe to repair. If repaired, the bike may not be safe to ride at high speed & cornering. Therefore our surveyor has recommended this vehicle to be written off as total loss due to*

On Friday, December 13, 2019, 6:11:20 AM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote: *the reason above.*

Dear Naz,

Thank you very much for your confirmation. I will work based on the repair limit. Thanks.

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

*And ~~with~~ stability is affected.*

On Thursday, December 12, 2019, 6:06:49 PM GMT+8, Naz (LKKAUTO) <naz@lkkauto.com> wrote:

Dear Mr Kwan,

The repair limit as revised, should not exceed more than \$4200.00 on lump sum basis.

Thank you.

**"Best Wishes for Merry Christmas & Happy New Year 2020"**

Best Regards,

**Naz** | Technical Investigator

**LKK Auto Consultants**

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Sbk E <sbk5643e@yahoo.com>  
**Sent:** Wednesday, 4 December 2019 4:28 AM  
**To:** Naz (LKKAUTO) <Naz@lkkauto.com>

## Shiau Chan (LKKAuto)

---

**From:** Sbk E <sbk5643e@yahoo.com>  
**Sent:** Wednesday, 4 December 2019 10:01 AM  
**To:** Naz (LKKAuto); SUR; Shiau Chan (LKKAuto)  
**Subject:** \$4,200.00 Re: REPAIR LIMIT FOR FBK2832X

Dear Shiau Chan,

Good Day. Please confirm that the amount is \$4,200.00 from the last Whatsapp conversation with the surveyor.  
Thanks.

Regards,

Kwan S. H.  
Director  
Bike Production Pte Ltd

On Wednesday, December 4, 2019, 9:00:09 AM GMT+8, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Mr Kwan,

According to our surveyor's record, the repair limit is not more than \$4,000.00 on Lump Sum basis.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 4 December 2019 7:46 AM  
**To:** Sbk E <sbk5643e@yahoo.com>; Naz (LKKAuto) <Naz@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: REPAIR LIMIT FOR FBK2832X

Dear Mr Kwan,

Thank you for the email.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 21 November 2019 4:16 PM  
**To:** Sbk E  
**Cc:** SUR  
**Subject:** OD VEHICLE FBK 2832X (DOA: 05/11/2019)

Dear Mr Kwan and Wendy,

Instructed by our client, please proceed to repair the insured vehicle **FBK 2832X** at repair cost not more than Lump Sum **\$4,200.00 (Excess \$300)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	14 Nov 2019 11:24	<b>Cim Veh Model Changed</b>		[ ] Merimen Administrator
2	14 Nov 2019 11:24	<b>Cim Created</b>	Reg No: FBK2832X, Policy No: 1800117469, Acct Date: 2019/11/05, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Cr eated from SAS:MCD519149708	[1] Merimen Administrator
3	18 Nov 2019 16:10	<b>Cim Registration Modified</b>	Setl.Type:3->0, Claim Type:SC->OD.	[ ] Nivitha Govindasamy
4	18 Nov 2019 16:10	<b>Adj Cim Retrieved</b>	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] Nivitha Govindasamy
5	18 Nov 2019 16:10	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	18 Nov 2019 16:10	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/11/27	[A] Nivitha Govindasamy
7	18 Nov 2019 16:10	<b>Adj Mandate Set</b>	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	18 Nov 2019 16:10	<b>Cim Registration Modified</b>	Rep:1137->202620.	[A] Nivitha Govindasamy
9	18 Nov 2019 16:10	<b>Cim Veh Model Changed</b>	(204720) YAMAHA YZF-R3 321cc ABS.	[A] Nivitha Govindasamy
10	18 Nov 2019 16:11	<b>Adj Adjuster Assigned</b>	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	19 Nov 2019 10:32	<b>Cim Registration Modified</b>	Acct Time:15:30:00->15:00:00. Init.Est.->4,000 - 5,000.	[1] Azlan, Syazairdina
12	19 Nov 2019 11:26	<b>Cim Registration Modified</b>	Excess: -> 300.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[1] Azlan, Syazairdina
13	19 Nov 2019 11:26	<b>Label Added</b>	(20226):Coverage Confirmed.	[A] Merimen Administrator
14	21 Nov 2019 08:56	<b>Adj Adjuster Assigned</b>	MOHD TAUFIKH BIN HAMID -> Muhammad Nazri Bin Abdullah	[A] Nivitha Govindasamy
15	21 Nov 2019 13:14	<b>Adj Rpt Initiated</b>		[A] SHIAU CHAN
16	21 Nov 2019 13:14	<b>Cim Dtl Modified</b>	JPJ Reg. Date: -> 2015/06/16.	[A] SHIAU CHAN
17	21 Nov 2019 13:14	<b>Cim Details Notified</b>		[A] SHIAU CHAN
18	21 Nov 2019 13:19	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2019/11/27	[A] SHIAU CHAN
19	21 Nov 2019 13:22	<b>Adj Mandate Request</b>	Cur.Reg:4269.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. REPAIRER ABLE TO REPAIR THE MOTORBIKE AT \$4200. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	21 Nov 2019 14:18	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2019/11/27. Mandate Remarks: Repair limit at \$4200. 00. Re-inspection to be done for damage check and supplementary items / labour.	[1] Koh, Victor-CK
21	21 Nov 2019 14:18	<b>Adj Mandate Set</b>	Approved:4200.00:Repair limit at \$4200.00. Re-inspection to be done for damage c heck and supplementary items / labour. Reinsp:Yes.	[1] Koh, Victor-CK

Date From     Date To     Audit Type

### ACTIVITY

[18/11/2019 16:11] Nivitha Govindasamy:  
Please be informed that vehicle is not in the workshop, repairer arrange on 19/11/2019.

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2352518	21 Nov 2019 13:14:33	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	FBK2832X		11.77

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 21 Nov 2019

**Preliminary Advice**

Vehicle No	: FBK2832X	Accident Date	: 05/11/2019
Make	: YAMAHA YZF-R3	Policy No.	: 1800117469
Assignment Date	: 18/11/2019	Excess	: S\$300.00
Date of Inspection	: 20/11/2019	Est. Duration of Repair	: 4.00
Inspection At	: BIKE PRODUCTION (HQ) NO 610 SERANGOON ROAD SINGAPORE 218216		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion, o/s &amp; n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,423.00
Revised Amount	:S\$	7,396.00
Check Items (Estimated)	:S\$	2,232.00
Total	:S\$	9,628.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,500.00
COE / PARF Rebate	:S\$	3,231.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,269.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO REPAIR THE MOTORBIKE AT \$4,200.00.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	227B
Vehicle Details	
Vehicle No.:	FBK2832X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R3 ABS
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	H402E0010078
Chassis No.:	MH3RH071000003537
Maximum Power Output:	-
Open Market Value:	\$4,972.00
Original Registration Date:	16 Jun 2015
First Registration Date:	16 Jun 2015
Transfer Count:	3
Actual ARF Paid:	\$746.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,800.00
COE Rebate Amount:	\$3,231.00
<b>Total Rebate Amount:</b>	<b>\$3,231.00</b>

The information contained herein is correct as at 20 Nov 2019

OK

## Enquire Vehicle Transfer Fee

### Vehicle Details

Vehicle No.  
**FBK2832X**

Make / Model  
**YAMAHA / YZF-R3 ABS**

Vehicle Type :  
**P00 - Passenger Motorcycle/Autocycle/Moped**

Vehicle Scheme :  
**Normal**

Propellant :  
**Petrol**

Motor No. :  
-

Power Rating :  
-

Maximum Laden Weight :  
**329 kg**

Year Of Manufacture :  
**2015**

Lifespan Expiry Date :  
-

Quota Premium :  
**\$5,800.00**

Road Tax Expiry Date :  
**15 Dec 2019**

Inspection Due Date :  
**15 Jun 2020**

CO2 Emission :  
-

CO Emission :  
-

NOx Emission :  
-

Vehicle Attachment 1 :  
**No Attachment**

Chassis No. :  
**MH3RH071000003537**

Engine No. :  
**H402E0010078**

Engine Capacity :  
**321 cc**

Maximum Power Output :  
-

Unladen Weight :  
**169 kg**

Original Registration Date :  
**16 Jun 2015**

COE Category :  
**D - Motorcycle**

COE Expiry Date :  
**15 Jun 2025**

PARF Eligibility Expiry Date :  
-

Intended Transfer Date :  
**20 Nov 2019**

CEV/VES Rebate Utilised Amount :  
-

HC Emission :  
-

PM Emission :  
-



SGD **\$8800**

Reg : 10/10/2016

Type: **Sport Bikes**

321cc

1007km

Ergonomics Supersport Bike. Owner Upgrading. 2016 Yamaha Yzf-r3 Abs Matte Grey Color. Accident Free. Showroom Condition With Genuine Mileages Of 1,007Km Only. View To Believe And Apprecia...

Ideal Motoring Provide Trade-in And Loan Package.

Posted on : 12/11/2019

**PAID AD** **DEALER AD**

[COMPARE](#)

[DETAILS](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/11/2019 14:52
Date Of Accident	05/11/2019 15:30
Exact Location Of Accident	WOODLANDS AVE 9 TOWARDS WOODLANDS LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK2832X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ABDUL RAHMAN BIN AHMAD
NRIC No	S8107227B
Email Address	LYNN.BMT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92322360
Alternative Phone No	OTHERS-92322360

### Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R3 ABS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800117469
Cover Note Number	

### Driver

Name of Driver	ABDUL RAHMAN BIN AHMAD
NRIC No	S8107227B
Date Of Birth	27/02/1981
Occupation	INDOOR
Date Of Driving Pass	26/07/2011
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92322360
Fax Number	
Contact Number	OTHERS-92322360

Address	BLK 854 WOODLANDS ST 83 #02-80
Postcode	730854
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT PANJANG NORTH NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED .

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	TRAILER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Name	ABDUL RAHMAN BIN AHMAD BAJURI
Approximate Age	38
Injuries Sustain	BOTH ARM INJURED AND BROKEN LH FORARM ,LH HIP BONE CHIP,ARASION ON LIP ,BACK AND BOTH LEG
Injured person in which vehicle?	FBK2832X
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**SINGAPORE  
POLICE FORCE**



T/20191110/2062

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

2 of 3

Report No. T/20191110/2062

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	ABDUL RAHMAN BIN AHMAD BAJURI	ID No.	S8107227B
Related Vehicle	FBK2832X (Motorcycle)	Contact No.	92322360
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 05/11/2019 at around 1530hrs, I was travelling along Woodlands Avenue 9 towards Woodlands Link near to Woodlands Spectrum 1 and I got into an accident. It is a two lane road and I was travelling on the right lane and a trailer is travelling on the left lane and suddenly making a u turn. I tried to brake however could not stop on time and hit onto the trailer. I then fell to the ground and subsequently, I was conveyed by the ambulance. Traffic Police also came to scene. The trailer was making a u turn at a lane that should not be u turn. I was injured during the accident.

I wish to state that the trailer move his vehicle slightly after the accident.



**SINGAPORE  
POLICE FORCE**



T/20191110/2062

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

3 of 3

Report No. T/20191110/2062

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: SN 127 L/ Sgt 1 TEO KAI XUN  Signature:	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 10/11/2019 14:26
Officer In Charge Of Case: TP / GIT /  Contact No.:	Classification Of Case:

Authentication Stamp  
NP168



**CERTIFICATE OF INSURANCE**

**MOTORCYCLE AUTOVANTAGE MOTORCYCLE**

Name of Policyholder	: ABDUL RAHMAN BIN AHMAD SAJURI	Vehicle No.	: FDK26327
Period of Insurance	: 01 Oct 2018 To 15 Dec 2019	Policy No.	: 1602117409
Engine No.	: H402E0010078	Endorsement No.	: 00000000284266
Chassis No.	: MH3R94071000000537	Issued Date	: 14 Jun 2019

**ABOUT THE COVER**

Make/Model	YAMAHA YZF-R3 ABS		
Engine Capacity/Tonnage	321.00 CC	Burn Insured	Market Value
Driver Restriction	Named Driver Basis	Off Peak Car	No
Person or Classes of Persons Entitled to Drive*		First Year of Registration	2015
		Insuring with COE/PAFF	Yes

\* The Policyholder  
or any person who is named as a 'named driver' under this Policy.

Age Condition : Not Applicable

**Limitation as to use\***

Use only for social, domestic, and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- 1. Use for hire or reward.
- 2. Use for driving tuition, driving test, racing, public-holding, liability test or speed testing.
- 3. Use for the transport of goods (other than services in connection with any trade or business) and
- 4. Use for any purpose in connection with Motor Vehicle.

\* Limitation imposed in accordance with Section 8 of the Motor Vehicle (Third Party Rules and Compensation) Act (Cap. 186) and Section 15 of the Road Transport Act, 1987 (Malaysia); see note to be included under Road Usage.

**EXCESS**

Section 1  
Fire - \$0 (Over Damage) - \$500 (Theft) - \$2

Section 2  
Theft - \$0

Windscreen : NA

**Named Driver and Excess (where applicable)**

ADD: SAUDAH BINTI AHMAD SAJURI - \$200 (Over Damage), MURAHMAD ZUFRU BIN AHMAD SAJURI - \$100 (Over Damage)

**APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)**

Any accident repairs to the vehicle must be carried out by one of our Authorised Repairers, within the first 3 years of the first registration of the vehicle in Singapore. You have the option of having the accident repairs carried out at the Site Agent's workshop.  
For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at 165 8228 2200. Alternatively, You may refer to the website [www.aig.com.sg](http://www.aig.com.sg) or AIG 3G Mobile App. Simply search and download AIG 3G from iTunes or Google Play.

**IMPORTANT NOTES**

First Purchase Company/Employer's Loan: BIKE PRODUCTION PTE LTD

This policy is valid only for the period in which the Certificate of Insurance remains in force. It is subject to the provisions of the Motor Vehicle (Third Party Rules and Compensation) Act (Cap. 186), Part 15 of the Road Transport Act, 1987 (Malaysia) and Motor Vehicle (Third Party Rules, Rules, 1987 (Malaysia).

050000014

*Signature*

# BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 12 Nov 2019

## ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 ABS - FBK2832X

Chassis No.: MH3RH071000003537

Engine No.: H402E0010078

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$195.00 / CRK
1 pc	Front wheel axle	\$85.00 ?
1 pc	Left fork assy	\$850.00 / BF
1 pc	Right fork assy	\$850.00 / BR
1 pc	Front brake disk	\$220.00 ?
1 pc	Front ABS disk rotor	\$115.00 X SVL
1 pc	Front ABS sensor	\$185.00 X SVL
1 pc	Headlamp assy	\$395.00 / SCR
1 pc	Front windshield	\$135.00 / CLK
1 pc	Front cowling	\$275.00 / CRK
1 pc	Right mirror	\$135.00 / SCR
1 pc	Right black cover	\$185.00 / CRK
1 pc	Right handle bar	\$185.00 ?
1 pc	Right balancer	\$45.00 / SCR
1 pc	Brake lever	\$75.00 / BR
1 pc	Steering bridge	\$295.00 ?
2 pcs	Steering bearing @ \$45.00	\$90.00 ?
1 pc	Steering stem	\$335.00 ?
1 pc	Left fairing assy	\$325.00 / SCR
1 pc	Left fairing emblem	\$75.00 / NEC
1 pc	Right fairing	\$325.00 / CRK
1 pc	Right fairing inner black	\$175.00 ?
1 pc	Right fairing emblem	\$75.00 / NEC
1 pc	Radiator assembly	\$595.00 ?
1 pc	Radiator Fan	\$295.00 ?
1 pc	Right slider	\$105.00 / BR
1 pc	Right lower cover	\$205.00 ?
1 pc	Right footrest front	\$95.00 / BR
1 pc	Right footrest holder front	\$175.00 / SCR
1 pc	Brake pedal	\$105.00 / BF
1 pc	Front seat	\$220.00 / TN
1 pc	Exhaust assembly	\$1,650.00 / DEF
1 pc	Rear right cover	\$305.00 / SCR
1 pc	Rear left cover	\$305.00 / SCR
1 pc	Rear footrest holder right	\$205.00 / SCR
1 pc	Rear footrest right	\$85.00 / SCR
		<hr/>
		\$6,940.00 9970
	Less discount 10%	\$694.00 997
		<hr/>
		\$6,246.00 8973
	<b>Special nett items</b>	
1 pc	Front sport rim	\$480.00 X SVL
1 pc	Front number plate	15 \$20.00 / NEC
1 pc	Rear number plate	\$30.00 X NN
1)	Towing charges	\$100.00 80

2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	<del>\$700.00</del> 400
3)	To replace and balance front and rear wheel rim	<del>\$120.00</del> 30 ✓ FRONT ONLY
4)	To knock, straighten chassis & body balancing	<del>\$450.00</del> 100
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 100
6)	Spray painting	<del>\$250.00</del> 200
7)	Reset meter	\$120.00 x NN
<b>Total Estimate</b>		<u>\$8,696.00</u> 11423

Note: The above estimate is subjected to the prevailing GST of 7%

NAZ LKK  
20/11/19 1130  
LIS

*[Signature]*  
21/11/19



For Bike Production Pte Ltd

4 DAYS  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2019		18 Nov 2019 16:10 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	ABDUL RAHMAN BIN AHMAD, ID: S8107227B, Tel: +6592322360, Email: lynn.bmt@gmail.com		
Vehicle Reg. No.:	FBK2832X	Date of Loss:	05/11/2019 15:00 - :59 [52 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 5477980526SG	Policy/Cover Note No.:	1800117469 (Comprehensive)
		Excess:	S\$300.00
Repairer:	Bike Production (HQ) No 610 Serangoon Road, 218216 Serangoon - Tel: 6299-5177		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Sim, Priscilla-LK - 6419 1755] Priscilla-lk.sim@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 27/11/2019]		
Driver/Custodian:	ABDUL RAHMAN BIN AHMAD (38 / Male), NRIC: S8107227B, Tel: +6592322360 Email: lynn.bmt@gmail.com		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (21/11/2019): Alert - Adj Mandate Approved (S\$4200.00) - FBK2832X - Claim Handler: Azlan, Syaz...</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

## Claim Documents

\*FBK2832X (54779805265G)  
 OD  
 Nov 5 2019 3:00PM  
 [ABDUL RAHMAN BIN AHMAD]  
 Bike Production

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View	View in Browser
<b>Assessment Reports</b>															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	21/11/19 13:19	Adjuster Immediate Advice											Load HTM			
2	19/12/19 08:54	Adjuster Immediate Advice											Load HTM			
<b>Photos/Images</b>															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
2	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
3	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
4	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
5	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
6	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
7	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
8	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
9	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
10	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
11	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
12	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
13	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
14	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
15	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
16	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
17	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
18	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
19	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
20	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
21	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
22	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
23	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
24	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
25	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
26	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
27	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
28	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
29	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
30	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
31	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
32	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
33	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
34	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
35	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
36	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
37	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
38	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
39	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		
40	20/11/19 17:17	General View											Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
42	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
43	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
44	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
45	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
46	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
47	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
48	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
49	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
50	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
51	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
52	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
53	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
54	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
55	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
56	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
57	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
58	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
59	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
60	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
61	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
62	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
63	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
64	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
65	20/11/19 17:17	General View		<input checked="" type="checkbox"/>
66	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
67	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
68	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
69	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
70	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
71	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
72	16/12/19 10:37	Dismantled Parts		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/19 13:03	Log card (if available)		<input type="checkbox"/>
2	21/11/19 13:03	ESTIMATE		<input type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	06/12/19 19:14	Accident Statement		<input type="checkbox"/>
2	06/12/19 19:18	Accident Statement		<input type="checkbox"/>
3	06/12/19 19:18	Accident Statement		<input type="checkbox"/>
4	06/12/19 19:18	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
2	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
3	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
4	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
5	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
6	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
7	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>
8	12/11/19 17:08	Accident Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
9	12/11/19 17:08	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 17:08	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 17:08	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	12/11/19 15:05	<b>Identification Card</b> POLICY HOLDER	 Load TIF	
2	12/11/19 15:05	<b>Driving License</b> POLICY HOLDER	 Load TIF	
3	13/11/19 15:47	<b>Sketch Plan</b>	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CS/AIG19020389/NQD3E2

**Date:** 06/01/2020

#### REFERENCE

Insured/Claimant: ABDUL RAHMAN BIN AHMAD Policy No: 1800117469  
Date of Loss: 05/11/2019 Nature of Claim: OD Claim No: 5477980526SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK2832X**  
Make & Model: YAMAHA YZF-R3, 321cc ABS Engine No: H402E0010078  
Reg. Date: 16/06/2015 (Man. Year: 2015) Chassis No: MH3RH071000003537  
Colour: Blue Odometer: 78625 km  
Engine Capacity: 321 cc  
Market Value/New Car Price: S\$7,500.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 150/60 R17  
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>-300.00</b>	<b>-300.00</b>	<b>0.00</b>	<b>0.00</b>

#### INSPECTION

Date of Assignment: 18/11/2019  
Date Inspected: 20/11/2019 Inspected At: Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218216

Estimated Period of Repair: 0.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value : \$7,500.00  
OMV : \$4,972.00  
PARF Rebate (1) : \$ 0.00  
Quota Premium Paid : \$5,800.00  
COE Rebate (2) : \$3,231.00  
Total Rebate (1) + (2) = : \$3,231.00

The total amount incurred will be Market Value \$7,500.00 minus Total Rebate \$3,231.00 = \$4,269.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >