

ASS. REC. BY:

Tampin

REF:

III

20290 / 11(1)

ASSIGNMENT

From:

Date:

20/11/19

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 4456L

at Workshop m/s

Mora Automotive

of

Blk 1008 Blk Merah Lane 3 #01-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

after 11am

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(14)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SME 4456L

Yr Regn:

2018 / Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Town

c.c

1390

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

14416

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WV 9227 IT ZJW/20877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

C

mm

L/Bal.

6

mm

L/Bal.

C

mm

D.O.A.

D.O.I.

20/11/19

Survey held at

Mora Bm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format:

Lump Sum / L.B.J. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Week end (\$

Survey Fee:

Transportation:

S + PS, SI

Photos

Others

TOTAL