VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue Singapore 639176

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: SABRINA GWENDOLYN KHOO MEI YUN 7 PEMIMPIN DRIVE #11-04 Singapore 576150

Page Document no. 11-11-2019 Document date 5211043795 Customer no. Customer GST-ID 201009404M Dealer 39999 Job order number 2019002616/1 Job order date 11-11-2019 PEARLYN CHEONG Service Advisor

1/1

License plate	Model code	First registration	VIN	Model Passat Comfortline 1.8 I TSI 132kW DSG	Mileage
SLX9898Z	3G24JZ	29-01-2019	WVWZZZ3CZKE019824		111

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 🛠	#1	280.00	299.60
3G2857508FJ9B9	Rear View Mirror Housing / CMT	1	pcs.	603.41	#1	603.41	645.65
3G0857538H GRU	Mirror Cap Primed X	1	pcs.	131.26	#1	131.26	140.45
	LABOUR	2	pcs.	840.00 300	#1	1,680.00	1,797.60
	Spray Painting	2	pcs.	800.00 ×	#1	1,600.00	1,712.00

Quotation valid till 18-11-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	4,014.67	7%	334.23	4,774.67	5,108.90
Total	760.00	4,014.67	THE STATE OF THE S	334.23	4,774.67	5,108.90

Customer Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions) .--

to Consultants hence notify pairer of the following: urvey before/after spray painting play damaged part(s) during resurvey prices are subject to confirmation party survey is on a "Without Prejudice" basis egal modification(s) is allowed plementary item(s) must be resurveyed and ubject to final approval from Insurance Company

knowledged by Repairer gn**ature:**

Steric (LI(K) with Arrit 15/11/19, 10-39 am

I day

Shence notify
Illowing:
spray painting
(s) during resurvey
to confirmation

Late: