

ASS. REC. BY Ram

REF CC3/TMI19020441/fyd302

### ASSIGNMENT

Front  
Estimated Cost  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No:  
at Workshop no:  
of  
Insured: **SLZ 597 R**  
Policy No  
Claims No  
Sum Insured: Excess:  
(Client's Record)  
Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date Person Contacted:

Vehicle IN / OUT

Veh No: **SH 8434L**  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai i40**

Colour: **blue**

Sp. Reading: **109458**

Eng/No: -

C/No: **KMHL B41UMSU089891**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: **205/60 R16**

R: **205/60 R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

**Westlake**

Front

Rear

R/Bal. **5** mm

R/Bal. **6** mm

L/Bal. **5** mm

L/Bal. **6** mm

D.O.A. **16/11/19**

D.O.A. **18/11/19**

Survey held at: **comfort delgro (coyang)**

Des. of Damages: Fnt / Rear / **6/S** / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**SH 8434L - CC4 / III 18019828 / P109342**

DOA: 29/10/18

**SLZ 597R - X**

**L/S**

**25/11/19 Send preli revised via merimen**

**12/12/19 Confirm L/S \$1800/- (Real \$1767.56, 49%)**

**TOKIOMARINE**

RECEIVED 13 DEC 2019

Date/Time File Pass to?

☐ : Preli. Report

Days Of Repair: **3**

1)

☐ : Final Report

Resurvey No. of Trip: **1**

Date/Time, File Return to?

**12/12/19 Typist**

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format:

Lump Sum I.B.I.: (\$ **\$1800/-**

Survey Fee:

Transportation

9 x 10. 24

Photo:

Others:

11/18

**290**

**11**

**261**

Photo O.K

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	Tokio Marine Insurance Singapore Ltd 20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Dillen Senthilan so Selvarajoo	Date:	25 Nov 2019
-------	--------------------------------	-------	-------------

**Preliminary Advice**

Insured Vehicle No	: SLZ597R	Accident Date	: 16/11/2019
TP Vehicle No	: SH8434L	Assignment Date	: 19/11/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 3
Date of Inspection	: 18/11/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,400.08
Revised Amount	:S\$	2,991.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,991.68
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/11/2019 09:24
Date Of Accident	16/11/2019 22:30
Exact Location Of Accident	GATEWAY AVE ROUNDABOUT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH8434L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	LEE KIAN BENG
NRIC No	S7831486I
Date Of Birth	30/10/1975
Occupation	OUTDOOR
Date Of Driving Pass	17/03/2016
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94898907
Fax Number	
Contact Number	
EMail Address	LKBGOO@GMAIL.COM

Address	BLK 186 BOON LAY AVE #08-116
Postcode	640186
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ597R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT

No. Of Passenger (Including Driver)

# **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/ACC SketchPlanform\_V3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/11/2019 at about 2230 hrs, I vehicle A at the roundabout junction in my lane at Sentosa Gateway ave. while I started to turn left lane, vehicle B suddenly cuts sharply into my lane and collided vehicle A right front portion. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305349769

OMER

S COMFORT TRANSPORTATION PTE LTD  
OMER NO. 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

(R)  
(P)

UNT CARD NO.


REGN NO.: SH 8434L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 18.11.2019 10:45
YR OF MANU 26.05.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU089891	COMPLETION DATE/TIME:

Tokio Marine

JOB DESCRIPTION

Accident Date: 16.11.2019  
NATURE: 3P 16.11.2019

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Idgement Slip

SH 8434L

LKE

RAM

Exit Pass

Vehicle No.:

SH 8434L

Service Advisor

Signature/Date

Name of Service Advisor

Date

igned to Service Reception upon collection

To be kept by Security Guard

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/11/2019
Vehicle Reg. No.:	SH8434L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	26/05/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU625541	Chassis No:	KMHLB41UMGU089891
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	Amount
Parts	2,839.08
Miscellaneous Items	11.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,400.08</b>
<b>+ GST 7.00% (S\$)</b>	<b>308.01</b>
<b>Nett Amount (S\$)</b>	<b>4,708.09</b>

**This claim is handled by: LIM KWOK ENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 18 Nov 2019)**Parts:** 143      HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH8434L/18/11/2019 17:51**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER RH X M	20.00	0.00	*619.00 FL
2	1		*FRT FENDER SHIELD RH X M	20.00	0.00	*169.80 FL
3	1		*FRT FENDER RETAINER RH X M	20.00	0.00	*9.20 FL
4	1		*FRT DOOR RH DD	20.00	0.00	*2,256.40 FL
5	1		*FRT WHEEL HUB CAP RH SCR	20.00	0.00	*150.70 FL
6	1		*FRT FENDER ADVERTISEMENT LOGO RH NEC	0.00	0.00	*100.00 F
7	1		*FRT DOOR ADVERTISEMENT LOGO RH NEC	0.00	0.00	*100.00 F
8	1		*FRT DOOR COMFORT LOGO RH NEC	0.00	0.00	*75.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,480.10</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>641.02</b>
<b>Total Parts (S\$)</b>	<b>2,839.08</b>

ComfortDelGro Engineering Pte Ltd/SH8434L/18/11/2019 17:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	580 560.00
2	SPRAY PAINTING CHARGE	New	400 700.00
3	TUFF KOTE	New	50 50.00
4	TRANSFER OF DOOR	New	80 120.00
5	FRT WHEEL ALIGNMENT	New	X 120.00
Gross Labour Cost (S\$)			1,550.00

ComfortDelGro Engineering Pte Ltd/SH8434L/18/11/2019 17:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 8434L

DATE 18/11/2019 14:22

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) <del>Xnn</del> Xnn			\$ 593.00
	Front Fender Shield (RH) Xnn			\$ 86.00
	Front Fender Retainer Xnn			\$ 9.20
	Front Door (RH) DD			\$ 1,345.00
	Front Wheel Hub Cap (RH) SC			\$ 145.00
	Rocker panel (e)			
	<b>SUB TOTAL</b>			<b>\$ 2,178.20</b>
	<b>LESS 20%</b>			<b>\$ 435.64</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,742.56</b>
	Front Fender Advertisement Logo (RH) nec			\$ 100.00
	Front Door Comfort Logo (RH) nec			\$ 75.00
	Front Door Advertisement Logo (RH) nec			\$ 100.00
				<b>\$ 275.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 560.00
	Spray Painting Charge		\$400	\$ 700.00
	Tuff Kote			\$ 50.00
	Transfer of Door			\$ 120.00
	FRT Wheel Alignment			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 1,550.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,567.56</b>
<div> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.

Our Job Ref No 305349769Date : 23.11.19ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr RAMVehicle Reg No. SH8434L CTPL16.11.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLZ597R

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%\$1,800.00**Final Lumpsum Repair cost**\$1,800.003. Estimated normal period for repairs: 3 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : RamDate : 26/11/19**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 8434L

DATE 18/11/2019 14:22

MAKE :

MODEL : HYUNDAI SONATA

LKE

Tokio Marine

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH) <del>Xnn</del> Xnn			\$ 593.00	
	Front Fender Shield (RH) Xnn			\$ 86.00	
	Front Fender Retainer Xnn			\$ 9.20	
	Front Door (RH) DD			\$ 1,345.00	
	Front Wheel Hub Cap (RH) X			\$ 145.00	
	ROCKER panel X (R)				
	SUB TOTAL			\$ 2,178.20	
	LESS 20%			\$ 435.64	
	DISCOUNTED TOTAL			\$ 1,742.56	
			1,490 -20%		
			1,192		
	Front Fender Advertisement Logo (RH) nec			\$ 100.00	Nett
	Front Door Comfort Logo (RH) nec			\$ 75.00	Nett
	Front Door Advertisement Logo (RH) nec			\$ 100.00	Nett
				\$ 275.00	
				\$ 275	
	Labour Charge				
	Panel Beating			\$ 560.00	\$280
	Spray Painting Charge			\$ 700.00	\$200
	Tuff Kote			\$ 50.00	\$20
	Transfer of Door			\$ 120.00	\$80
	FRT Wheel Alignment			\$ 120.00	Xnn
	Merimon Charge			\$ 11.00	
	TOTAL LABOUR			\$ 1,550.00	\$791
	ESTIMATE TOTAL			\$ 3,567.56	
			791 2,258 -20%		
			1,806.40		
			Ram CLKK		
			88622778		
			18/11/19		
			IASOWS		
			Paragon@CLKKauto.com		
			aft repair photo		
			4S		
			3		
			repair days		
			4S \$1,800		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Nov 2019 17:38 <a href="#">Sendback Est</a>	18 Nov 2019 17:51 <b>\$4,400.08</b>	19 Nov 2019 11:24 <a href="#">Edit Adj Rpt</a>	<b>\$1,800.00</b> <a href="#">Edit Estimates</a>	<b>\$1,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SH8434L	Date of Loss:	16/11/2019 22:00 - :59 [41 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1908982	Policy/Cover Note No.:	MT101452 (Comprehensive) Coverage: 20/04/2018 - 19/04/2020
Vehicle Reg. No. (Insured):	SLZ597R	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 28/11/2019]		

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

SH8434L (M1908982)  
[SLZ597R]  
TP  
CTPL  
Nov 16 2019 10:00PM  
[CTPL]  
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	18/11/19 17:51	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/11/19 09:11	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/11/19 17:51	General View		Load JPG	
2	20/11/19 17:51	General View		Load JPG	
3	20/11/19 17:51	General View		Load JPG	
4	20/11/19 17:51	General View		Load JPG	
5	20/11/19 17:51	General View		Load JPG	
6	20/11/19 17:51	General View		Load JPG	
7	20/11/19 17:51	General View		Load JPG	
8	20/11/19 17:51	General View		Load JPG	
9	20/11/19 17:51	General View		Load JPG	
10	20/11/19 17:51	General View		Load JPG	
11	20/11/19 17:51	General View		Load JPG	
12	20/11/19 17:51	General View		Load JPG	
13	20/11/19 17:51	General View		Load JPG	
14	20/11/19 17:51	General View		Load JPG	
15	20/11/19 17:51	General View		Load JPG	
16	20/11/19 17:51	General View		Load JPG	
17	20/11/19 17:51	General View		Load JPG	
18	20/11/19 17:51	General View		Load JPG	
19	20/11/19 17:51	General View		Load JPG	
20	20/11/19 17:51	General View		Load JPG	
21	20/11/19 17:51	General View		Load JPG	
22	20/11/19 17:51	General View		Load JPG	
23	20/11/19 17:51	General View		Load JPG	
24	20/11/19 17:51	General View		Load JPG	
25	20/11/19 17:51	General View		Load JPG	
26	20/11/19 17:51	General View		Load JPG	
27	20/11/19 17:51	General View		Load JPG	
28	20/11/19 17:51	General View		Load JPG	
29	20/11/19 17:51	General View		Load JPG	
30	20/11/19 17:51	General View		Load JPG	
31	20/11/19 17:51	General View		Load JPG	
32	20/11/19 17:51	General View		Load JPG	
33	20/11/19 17:52	Reinspection Photo		Load JPG	
34	20/11/19 17:52	Reinspection Photo		Load JPG	
35	20/11/19 17:52	Reinspection Photo		Load JPG	
36	20/11/19 17:52	Reinspection Photo		Load JPG	
37	20/11/19 17:52	Reinspection Photo		Load JPG	
38	20/11/19 17:52	Reinspection Photo		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
39	20/11/19 17:52	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	20/11/19 17:52	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	20/11/19 17:52	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	20/11/19 17:52	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail Print
1	27/11/19 14:32	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	18/11/19 17:53	E-filed GIA report		Load PDF
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail Print
1	29/11/19 20:00	Letter of Demand from Third Party		Load TIF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p><b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19020441/FYD3E2

Date: 23/12/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT101452

Claimant Vehicle No : SH8434L

Insured Vehicle No : SLZ597R

Date of Loss: 16/11/2019

Nature of Claim: TP Claim No: M1908982

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SH8434L

Make &amp; Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU625541

Reg. Date: 26/05/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU089891

Colour: Blue

Odometer: 409458 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,839.08	1,467.00	1,372.08	48.33
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,550.00	780.00	770.00	49.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,400.08</b>	<b>2,258.00</b>	<b>2,142.08</b>	<b>48.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>(S\$)</b>	4,400.08	1,800.00	2,600.08	59.09
<b>+ GST 7.00/7.00% (S\$)</b>	308.01	126.00	182.01	59.09
<b>Nett Amount (S\$)</b>	<b>4,708.09</b>	<b>1,926.00</b>	<b>2,782.09</b>	<b>59.09</b>

## INSPECTION

Date of Assignment: 19/11/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 18/11/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2019)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SH8434L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT FENDER RH	Not Necessary	619.00 FL	-	*- FL
2	1		*FRT FENDER SHIELD RH	Not Necessary	169.80 FL	-	*- FL
3	1		*FRT FENDER RETAINER RH	Not Necessary	9.20 FL	-	*- FL
4	1		*FRT DOOR RH	Dented	2,256.40 FL	-	*1,345.00 FL
5	1		*FRT WHEEL HUB CAP RH	Short Circuit	150.70 FL	-	*145.00 FL
6	1		*FRT FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS
7	1		*FRT DOOR ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS
8	1		*FRT DOOR COMFORT LOGO RH	Necessary	75.00 F	-	*75.00 FS
9	1		*ROCKER PANEL (NPA)	Repair	-	-	*- FL
					<b>Sub Total (S\$)</b>	<b>3,480.10</b>	<b>1,765.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>641.02</b>	<b>298.00</b>
					<b>Total Parts (S\$)</b>	<b>2,839.08</b>	<b>1,467.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	560.00	280.00
2	SPRAY PAINTING CHARGE	New	700.00	400.00
3	TUFF KOTE	New	50.00	20.00
4	TRANSFER OF DOOR	New	120.00	80.00
5	FRT WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,550.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;