

ASS. REC. BY:

REF: CS3/MS4/4020458/Gcd3⁵²

Special Instruction:

Survivor: Cuo QiongASSIGNMENT (Office)From (Person): Christina Wong of MSIG Date/Time: 19.11.19 16.56 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 2537A Insured: SLC 3977Dat Workshop m/s MSM Logistic Tel: 91074212of 160 Sh Ming Drvl #03-08Policy No: 29123571AT2 Claim No: 611730

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15.11.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 19.11.2019 @ 10.20am Person Contacted: Mr. Tan H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	PC 2537A - X
	SLC 3977D - X

PRS

ASSIGNMENT

From:

Date:

19/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PC2537A

at Workshop m/s

MSM Logistics

of

160 Sin Ming Drive #03-08

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Mr. Tang 91074212

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

'up'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC2537A

Yr Regn:

11 Jul 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

c.c

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

273430

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KPH/22300 20033

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

Survey held at

w/s

19-11-19

11:15

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Wt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

RECEIVED 27 NOV 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

-

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Waste (\$)

Survey Fee:

Transportation:

3 + PS \$1

Photos:

Other:

TOTAL

Report Format:

PRQ

Lump Sum / L&M

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2019		18 Nov 2019 16:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	LOW SHY TAR, ID: S8274377D		[Created by insurer]
Main Claimant:	COMMUTER-PLUS EXPRESS, Co. Reg. No.: 52807178E		
Vehicle Reg. No.:	PC2537A	Date of Loss:	15/11/2019 14:00 - :59 [64 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 611730	Policy/Cover Note No.:	29123577AT2 (Comprehensive) Coverage: 13/05/2019 - 12/05/2020
Vehicle Reg. No. (Insured):	SLC3977D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/11/2019]		
Adj Asg. Remarks:	on WP. Liab: NR. Disagree on SJE. Assign: LKK. Contact: Candice @ 6538 3611		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2019 13:52
Date Of Accident	15/11/2019 14:30
Exact Location Of Accident	CAVENAGH ROAD TOWARDS BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2537A
Insured/Policyholder	
Name Of Registered Owner	COMMUTER-PLUS EXPRESS
Co Reg No	52807178E
Email Address	COMMUTERPLUS@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90691234

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE COMMUTER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0
Cover Note Number	CN064005

Driver

Name of Driver	LAM KIEW KIN
NRIC No	S0170708F
Date Of Birth	07/11/1951
Occupation	INDOOR
Date Of Driving Pass	01/09/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97482887
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Name of Driver

NRIC/Passport Number

Contact Number

97895317

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN

A1-PC2537A
B - SLC 3977D
Bukit
Timah Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I ~~was~~ was driving ~~PC2537A~~ PC2537A Travelling Cavenagh Road to Bukit Timah Road at the First Lane. Suddenly vehicle SLC 3977D cut in to my lane and hit my left side of vehicle.

msmts@singnet.com.sg. (my workshop owner add).

Sending student's home when accident happen.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Business
Owner ID:	178E
Vehicle No.:	PC2537A
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2405433
Chassis No.:	KDH2230020033
Maximum Power Output:	-
Open Market Value:	\$37,156.00
Original Registration Date:	11 Jul 2014
First Registration Date:	11 Jul 2014
Transfer Count:	2
Actual ARF Paid:	\$1,858.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	10 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$36,648.00
COE Rebate Amount:	\$17,007.00
Total Rebate Amount:	\$17,007.00

The information contained herein is correct as at 19 Nov 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2019		18 Nov 2019 16:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOW SHY TAR, ID: S8274377D		
Main Claimant:	COMMUTER-PLUS EXPRESS, Co. Reg. No.: 52807178E		
Vehicle Reg. No.:	PC2537A	Date of Loss:	15/11/2019 14:00 - :59 [64 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 611730	Policy/Cover Note No.:	29123577AT2 (Comprehensive) Coverage: 13/05/2019 - 12/05/2020
Vehicle Reg. No. (Insured):	SLC3977D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Msm Logistics Pte Ltd- Sin Ming (HQ) 160 Sin Ming Drive #03-08 Sin Ming Auto City, 575722 Sin Ming - Tel: 91074212		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 19/11/2019]		
Adj Asg. Remarks:	on WP, Liab: NR, Disagree on SJE, Assign: LKK, Contact: Candice @ 6538 3611		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

8

Claim Documents

***PC2537A (611730)**
[SLC3977D]
TP
COMMUTER-PLUS EXPRESS
Nov 15 2019 2:00PM
[LOW SHY TAR]
Msm Logistics Pte Ltd- Sin Ming

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/19 09:41	General View	Load JPG	✓
2	20/11/19 09:41	General View	Load JPG	✓
3	20/11/19 09:41	General View	Load JPG	✓
4	20/11/19 09:41	General View	Load JPG	✓
5	20/11/19 09:41	General View	Load JPG	✓
6	20/11/19 09:41	General View	Load JPG	✓
7	20/11/19 09:41	General View	Load JPG	✓
8	20/11/19 09:41	General View	Load JPG	✓
9	20/11/19 09:41	General View	Load JPG	✓
10	20/11/19 09:41	General View	Load JPG	✓
11	20/11/19 09:41	General View	Load JPG	✓
12	20/11/19 09:41	General View	Load JPG	✓
13	20/11/19 09:41	General View	Load JPG	✓
14	20/11/19 09:41	General View	Load JPG	✓
15	20/11/19 09:41	General View	Load JPG	✓
16	20/11/19 09:41	General View	Load JPG	✓
17	20/11/19 09:41	General View	Load JPG	✓
18	20/11/19 09:41	General View	Load JPG	✓
19	20/11/19 09:41	General View	Load JPG	✓
20	20/11/19 09:41	General View	Load JPG	✓
21	20/11/19 09:41	General View	Load JPG	✓
22	20/11/19 09:41	General View	Load JPG	✓
23	20/11/19 09:41	General View	Load JPG	✓
24	20/11/19 09:41	General View	Load JPG	✓
25	20/11/19 09:41	General View	Load JPG	✓
26	20/11/19 09:41	General View	Load JPG	✓
27	20/11/19 09:41	General View	Load JPG	✓
28	20/11/19 09:41	General View	Load JPG	✓
29	20/11/19 09:41	General View	Load JPG	✓
30	20/11/19 09:41	General View	Load JPG	✓
31	20/11/19 09:42	Odometer Reading	Load JPG	✓
32	20/11/19 09:42	Chassis Number	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/11/19 16:05	TPD PC2537A - PRI & GIA REPORT	Load PDF	
2	18/11/19 16:05	TPD PC2537A - PRI (EMAIL)	Load PDF	
3	18/11/19 16:36	disagree on SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19020458/GCD3 S2
Date: 28/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29123577AT2
Claimant Vehicle No : PC2537A **Insured Vehicle No :** SLC3977D
Date of Loss: 15/11/2019 **Nature of Claim:** TP **Claim No:** 611730

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC2537A**
 Make & Model: TOYOTA HIACE, 3.0 D COMMUTER GL AT 2WD 4DR LWB (M) Engine No: 1KD2405433
 Reg. Date: 11/07/2014 (Man. Year: 2014) Chassis No: KDH2230020033
 Colour: Silver Odometer: 273430 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/11/2019
 Date Inspected: 19/11/2019 Inspected At: Msm Logistics Pte Ltd- Sin Ming (HQ)
 160 Sin Ming Drive #03-08 Sin Ming Auto City
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Nov 2019)

Parts: N/A TOYOTA HIACE 3.0 D COMMUTER GL AT 2WD 4DR LWB (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC2537A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >