

ASS. REC. BY:

REF:

es/FCI 19020463/Kyd3

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Jason Tea

of

FCI

Date/Time:

11:02am @ 19/11/2019

Estimated Cost:

Bill to:

OD/TP/WB/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 8177M

Insured:

SHB 6228R

at Workshop n/s

Supreme Auto

Tel:

9736 8619

of

176 Sin Ming Drive # 02-01

Policy No:

Claim No:

D1900716MFS#

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:29am @ 19/11/19

Person Contacted:

Mr. Chew

Vehicle IN/OUT

Date/Time

Action/Instruction

1st initial /

SLC 8177M-X

SHB 6228R-NAL / INCO 8010347/r3

DOA: 28/3/2008

27/13 11pm @ 1500 email (Red \$1690-35, 52%)

ASS. REC. BY:

REF:

F02/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s Supreme

of _____

Insured _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8135k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLC 8177 Yr Regn: 05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or A) Wagon
Make: Toy Well fm c.c. 2493Colour n. Black A/C: Insured / Std / NI / NASp. Reading 286.473 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AG1430 0057356Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Kpsen 235/50R18
R: DQVARTBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 5 mmL/Bal. 4 mm L/Bal. 5 mmD.O.A. 8/11/19 D.O.I. 19/11/19Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Acc

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to22/11 Sent Preli to Insurance E-Mail

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

1)

☐ : Final Report

Date/Time, File Return to?

2)

30/3/20 TypistAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Transportation

S + RS \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

\$1500f

130
50
90
11
241

MOTOR SURVEY ASSIGNMENT

Date	12-11-2019	Our Ref No. D19007164MFSH
Accident Date	08-11-2019	Claim Type. Third Party
Insured Vehicle	SHB6228R	Third Party Vehicle. SLC8177M
Survey Location	176 SIN MING DRIVE #02-01	
Contact Person.	CHEW KEONG	
Contact No.	64528211/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUPREME AUTO SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 22, 2019 10:53 AM
To: 'CWS Motor Claims'
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007164MFSH/1
Attachments: SLC8177M DOA 08112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLC8177M
Date of survey : 19/11/2019
Number of days : 3 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, November 19, 2019 11:48 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19007164MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 19 November 2019 11:02 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007164MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19007164MFSH

Date: 22 Nov 2019

Our Ref: CS/FCI19020463/Kyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLC8177M

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/11/2019 at the premises of M/s SUPREME AUTO SERVICE P/L, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,190.35 .
Revised Estimate Amount	: S\$ 1,854.73 .
"Check" Items Amount	: S\$ 131.92 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s rear door.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	048N
Vehicle Details	
Vehicle No.:	SLC8177M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5Z G-EDITION CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ARH699184
Chassis No.:	AGH300057356
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$40,943.00
Original Registration Date:	26 May 2016
First Registration Date:	26 May 2016
Transfer Count:	3
Actual ARF Paid:	\$49,321.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2026
PARF Rebate Amount:	\$36,990.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$31,290.00
Total Rebate Amount:	\$68,280.00

The information contained herein is correct as at 13 Jan 2020

OK

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

TIDAL CAPITAL PTE LTD

c/o 46 Lentor Plain
Singapore 786548

*Not Authorised
11 hrs @ 1500k
Resurvey After Painting
3 days*

Date: 19/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: SLC 8177 M</u>	
1 pc	rear bumper <i>1380.</i>	<i>Bulk Div</i> 1,889.70 ✓
1 pc	rear bumper retainer	<i>DIY</i> 86.20 ✓
1 pc	rear bumper lamp	<i>in</i> 175.90 ✓
1 pc	towing cover <i>62.00</i>	<i>Mr's</i> 102.00 ✓
	sub-total	2,253.80
	less 25%	563.45
	sub-total	1,690.35
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>3000</i> 500.00
	To spray painting on affected areas.	<i>4000</i> 580.00
	To install reverse sensors.	<i>600</i> 420.00
	total	3,190.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: