

ASS. REC. BY:

REF:

053/SMO19020465/God3m

Special Instruction:

Surveyor: Guo DingASSIGNMENT (Office)From (Person): Yong Kong Malwin

of

SMO

Date/Time:

18/11/19 @ 4:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 6702R

Insured:

SLJ 548S

at Workshop m/s

MJE Motor

Tel:

6454 2203

of

BLK7 Sin Ming Ind. Est 800 C # 01-94

Policy No:

Claim No:

CMTD1905334 / THE

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:58pm @ 18/11/19

Person Contacted:

JoyceVehicle IN / OUT

Date/Time	Action/Instruction	Estimate (X)
	<u>SMN 6702R - X</u>	
	<u>SLJ 548S - X</u>	
	<u>Dismantle: 19/11/2019</u>	
	<u>After repair: 25/11/2019</u>	

ASS. REC. BY:

Grl.

REF:

SMO

PRS

ASSIGNMENT

From:

Date:

19/11/19

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 6702R

at Workshop m/s

MJE MOTOR

of BLK 7 Bin Ming Ind. Est Rec C # 01-94

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN6702R

Yr Regn:

28 Feb 2017

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jaguar XE 2.0

C.C

1999

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

69149

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SAJABYANIH CP05028

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

11

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19-11-19

Survey held at

w/s

11:30

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 6000 - \$ 7000

RECEIVED 26 NOV 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

100

60+60

220

Report Format:

PRO.

Lump Sum / L&L: (\$)

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, 18 November 2019 4:11 PM
To: Oracle Law Corp; SUR; assignments
Cc: Henry, Irene James; Choo, Thelma
Subject: RE: Our Ref: SB/PO/Acc/2019-9194 Your Ref: CMTD1905334/THE

Without Prejudice

Dear Alvin,

We refer to your reply dated 18/11/2019.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to LKK Auto,

Please make arrangement to conduct survey for SMN6702R.

Detail as below;-

MJE Motor
BLK 7, Sin Ming Industrial Estate
Sector C, #01-94
S(575642)
Contact : 6454 2203

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompō SG



¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompō Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Monday, 18 November, 2019 2:41 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: RE: Our Ref: SB/PO/Acc/2019-9194 Your Ref: CMTD1905334/THE

Dear Melvin,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SMN 6702R, SLJ 548S, SLH 7853A & SMN 8484G ALONG THE KPE TOWARDS PIE AFTER TAMPINES ROAD EXIT ON 16-11-2019 @ 9.55 A.M.

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Monday, 18 November 2019 2:20 PM
To: Oracle Law Corp <mail@oraclelaw.sg>
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: Our Ref: SB/PO/Acc/2019-9194 Your Ref: Insurer of SLJ 548S Our ref : CMTD1905334/THE

Our Reference : MTD1905334/THE
Your Reference: SB/PO/Acc/2019-9194

Without Prejudice

Date: 18/11/2019

Attention:

Dear Alvin,

ACCIDENT INVOLVING SMN6702R & SLJ548S ON 16.11.2019

We refer to your Notice of Accident dated 18/11/2019.

Please be informed that Ms Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Monday, 18 November, 2019 9:36 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: Our Ref: SB/PO/Acc/2019-9194 Your Ref: Insurer of SLJ 548S

Dear Sir,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SMN 6702R, SLJ 548S, SLH 7853A & SMN 8484G ALONG THE KPE TOWARDS PIE AFTER TAMPINES ROAD EXIT ON 16-11-2019 @ 9.55 A.M.

Please refer to attachments the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	751W
Vehicle No.:	SMN6702R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Nov 2019
Vehicle Make:	JAGUAR
Vehicle Model:	XE 2.0 I4D TSS
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	161007W0222204DTD
Chassis No.:	SAJAB4AN1HCP05028
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$36,762.00
Original Registration Date:	28 Feb 2017
First Registration Date:	28 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$33,467.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2027
PARF Rebate Amount:	\$25,100.00
COE Expiry Date:	27 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$36,820.00
Total Rebate Amount:	\$61,920.00

The information contained herein is correct as at 19 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2019 14:04
Date Of Accident	16/11/2019 09:55
Exact Location Of Accident	KPE TOWARDS PIE AFTER TAMPINES ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN6702R
Insured/Policyholder	
Name Of Registered Owner	VIDA & PARTNERS PTE LTD
Co Reg No	201534751W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85222489
Vehicle Particulars	
Manufacturer	JAGUAR
Model	XE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108312817
Cover Note Number	
Driver	
Name of Driver	RYAN LIM WEE TONG (LIN WEIDONG)
NRIC No	S9643505C
Date Of Birth	27/11/1996
Occupation	OUTDOOR
Date Of Driving Pass	08/07/2016
Driving Experience	3 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85222489
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 201D PUNGGOL FIELD #07-270 SINGAPORE
Postcode	824201
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ548S
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	LEONARD LIM LIN GEE
NRIC/Passport Number	S7126468H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLH7853A
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	YUEN WEN JUN
NRIC/Passport Number	S8835076F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMN8484G
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along KPE toward PIE, after passing Tampines Rd exit, the vehicle in front of me stopped. So, I stopped too.

Suddenly, I felt an impact from the rear of my vehicle and I realised that the vehicle behind me, Vehicle B, collided into the rear of my vehicle. On top of that, there were vehicle C and D, also part of this main collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO19020465/Gcd3e2		
50 RAFFLES PLACE #05-01/06		Date: 28-11-2019		
SINGAPORE LAND TOWER SINGAPORE 048623				
Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLJ 548S	Veh. Inspected	SMN 6702R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905334/THE	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	18/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XE 2.0	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SAJAB4AN1HCP05028	Colour	BLACK	
Odometer	69149 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	16/11/2019	Inspect Date / Time	19/11/2019 (11:30 AM)	
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/SMO19020465/Gcd3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.